

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

25 SEP 2019

E S T I M A T E

Estimate No. : b1 52852 Date Estimated : 25/09/2019 Prepared By : Inthiran A/L Thurasamy		Page No. : 1 of 5	
- ESTIMATE REPAIR FOR - William Woo Siew Wing 26 Mei Hwan Crescent Singapore 568471		- ACCOUNT - 121 AIG Asia Pacific Insurance Pte. Ltd. 78 Shenton Way #08-16 Chartis Building Singapore 079120	
REGN. NO.	CHASSIS NO.	REGN. DATE	MILEAGE
SKB855J	WBAJX62060BJ23982	08/10/2018	0
DESCRIPTION To replace front bumper, air flap and attachments.		850 2,560.00	
Painting front bumper.		934 1,038.00	
To check electrical wiring systems at the front section for proper function including adjustments of headlights.		150 177.00	
To supply front emboss number plate. <i>4</i> ✓		83.00	
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.		150 177.00	
Sundries.		80.00	
Total Labour 1:		4,105.00	
DESCRIPTION FRT RH GRILLE (SPORT) ? Grille, fron ? Trim cover, <i>de</i> ✓ SET MOUNTING PDC/PMA SENSOR FRT (M) <i>ne</i> ✓ AIR FLAPS TOP ? LICENCE PLATE HOLDER (M) <i>4</i> ✓		QTY 1 1 1 1 1 1	PRIC 171.10 171.10 1,935.50 137.20 285.80 84.80
		VALUE 171.10 171.10 1,935.50 137.20 285.80 84.80	
Total Parts :		2,785.50	

Survey only
1/10 @ 10am
owner meeting

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 52852	Page No. : 2 of 5
Date Estimated : 25/09/2019	
Prepared By : Inthiran A/L Thurasamy	

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKB855J	WBAJX62060BJ23982	08/10/2018	630i GT	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	
Regn No. _____	Claim No. _____
Date & Time <u>01/10/19 @ 1000</u>	Excess S\$ _____
Surveyor's Name <u>Rasul</u>	Sign _____
Surveyor's Tel <u>90010068</u>	Authorised Yes / No _____
Authorised Date _____	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____	
Surveyor's E-mail _____	
No. of Working Days Recommend <u>3 days</u>	

Labour 1	:	4,105.00
Parts	:	2,785.50
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	482.34
Grand Total	:	<u>7,372.84</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **