

PRE-REPAIR INSPECTION REQUEST – SMC916M vs SJX8367U (OI) on D.O.A.: 13/09/2019

From: Hor, Yinnul
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, Subramaniam, Divya
Sent: Tuesday, 24 September, 2019 3:38:26 PM
Attachments:  [20190924150850330.pdf](#)

Hi,

Please refer to the enclosed request from **Esteem Performance Pte Ltd**.
Kindly carry out Policy coverage verification **first** before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.
*Kindly assist to assign **Kenneth Kong** as Single Joint Expert as requested.*

Thanks & Regards,

Hor Yin Rul (Viviane)

AIG

FNOL Adjuster I
Singapore FNOL | Claims Operations – Auto

Tel: 8001206556 | Ext: 1002208
Yinnul.Hor@aig.com | www.aig.sg

From: jenny chong [mailto:jenny@esteemperf.com.sg]
Sent: Tuesday, September 24, 2019 3:09 PM
To: AIG SGP, Claims-Survey
Cc: carmen lim; serence ctc; Kaeley Ng; Shanice Leong
Subject: [EXTERNAL] REQUEST FOR PRI SURVEY SMC916M

This message is from an external sender; be cautious with links and attachments.

Dear Sir/Madam,

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRE-ACTION PROCOAL FOR NON INJURY MOTOR ACCIDENT CASES (NIMA)

We act for Goldbell car rental pte ltd who has appointed the under-mentioned workshop to repair his motor vehicle no.SMC 916 M.

Please be informed that the said vehicle can be inspected at :

Name of workshop : Esteem Performance Pte Ltd

Address : BLK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-259 (S) 569536

Tel : 8799 0066 / 6566 2112
Fax : 6259 3326

We hereby give 2 clear days notice to conduct a pre-repair inspection of the said vehicle at the above-mentioned workshop during office hours.

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday. The above-mentioned workshop will commence repairs should you fail to conduct the pre-repair inspection.

We are prefer **LKK Auto Consultants Pte Ltd- KENNETH** to survey the car.

Freundliche Grüße / Best Regards

Jenny Chong

Senior Operation Executive | Operation Division
Esteem Performance Pte Ltd

P: 6484 1221
F: 6484 7829
E: jenny@esteemperf.com.sg

[5033 Ang Mo Kio Industrial Park 2 #01-259](#) (Head Office)
[385 Sin Ming Drive](#) Vicom Inspection Centre (Showroom)

www.esteemperformance.com



IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.