

Version:

INS. CASE OWNER:

LOH CHIEF HONG

CC4/AIG1901

6911

KH12

S3

LKK
IDAC:

Surveyor:

KENNETH

DOI:

ASSIGNMENT
20/10/19

Date / Time:

25/11/19

Registered in Merimen:

25/11/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SCR 3624A

Name of Insured:

THAM MATE LAW JIN

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

27/11/19

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

39612775659

Policy No.:

200011142-12

Make / Model:

TOYOTA

Place of Accident:

LEKHIP HIGHWAY

If NO. Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SWT 32311



INSRS:
WSP:
Tel:
Liability:
RMKS:

cheng
Hoe



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time		STAGE	DATE / PIC
		Non-Reporting 1st:	
		Non-Reporting 1st (2nd):	
		Non-Reporting 1st (Final):	
		Notification 1st (if non-pickup):	
		Call OI:	
		After call 1st to OI:	01/10/19 - vic
		Documentation Check List:	Handler Typist
		Notification 1st (if non-pickup):	
		After call 1st to OI:	
		Authorisation To Act:	
		Release Voucher:	
		Final Repair Bill:	
		Car Rental Invoice:	
		Towing Invoice:	
		LTG / GIA:	
		Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
		LOD:	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

PRELIMINARY ADVICE	Date/Time:	Sent By:	
FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	\$1,509.40	(2 days) Reduction:	11 %
FINAL SETTLEMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
Final Liability:	%	100 (Agreed / Assessed) BOLA S/N No.:	27
Repair Cost:	(w/acc) \$1,615.06		
Loss of Rental (LOR):	\$5 -	(days)	
Loss of Use (LOU):	\$5 120.00	(5 60 x 2 days)	
Loss of Income (LOI):	\$5 -	(\$ x days)	
LOR only ☐ LOU only ☒	LOR + LOU ☐ LOR + LOI ☐	[Tick only one]	
GIA/LTA Search	\$5 8.00		
Medical:	\$5 -		
Disbursement:	\$5 -	(e.g. Tow/ Independent)	
Legal Cost	\$5 -		
Total:	\$5 1,743.06	Global Sum \$5:	-
FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1:	\$5 1,743.06	Name 1:	CHENG HOE MOTOR PTE LTD
Payee 2: (Strike if N.A.)	\$5 -	Name 2:	-
Payee 3: (Strike if N.A.)	\$5 -	Name 3:	-

COPY SENT
30/11/2019

1) Claim status: Normal/Reject/Private Settle
2) Report Format:
3) Survey fee: \$320.00

ASS. REC. BY:

REF: 1161

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s

of

Insured:

Policy No.:

Claims No.:

Sum Insured:


Excess:

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Soon: _____

Consistent? : Yes or No

Est. Repairs: _____

02 days

Res.: Yes or No

Lum Sum: _____

1.31 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 File pass to

T/P 41,809.40

(C.R.D. 200.00 / 11%)

Veh No: _____

SVH 72314 Yr Regn: 11.16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Mit Laca

c.c. 1590

Colour: _____

M. Grey

A/C: Insured / Std / NI / NA

Sp. Reading: _____

73190

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

JMY SRCY1AGU005926

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NII / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

205/80R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Continental

Front

R/Bal. _____

mm

Rear

R/Bal. _____

mm

L/Bal. _____

mm

L/Bal. _____

mm

D.O.A. _____

23/9/19

D.O.I. _____

30/10/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

) S - RS. \$

) Fuel

) Others

TOTAL

Add Fee: _____

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Cheng Hoe Motor Pte Ltd

Blk 1019, Viahun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@sngnet.com.sg
GST:201001158E RCB NO:201001158E

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

Estimate No: ES1992183/AMK

Date: 30 Oct 2019

Policy No: DMPPHQ18-007769

Veh Reg No: SLH7231U

Make/Model: MITSUBISHI LANCER
EX 1.6 AT LED TAIL
LAMP

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 23/09/2019

TP Veh Reg No: SCR3624A

Chassis No: JMYSRCY1AGU005926

Engine No: 4A92CL7290

Reg. Date: 17/11/2016

Estimate Repair Cost to Vehicle No :SLH7231U

Description	U/Price	Quantity	List Price SS	Amount SS
Net Price				
1 REAR BUMPER	891.00	1 PC	891.00	—
2 REAR BUMPER CLIP	5.00	5 PC	25.00	—
			916.00	
		Less 10%	91.60	824.40
Special Net				
3 REVERSE SENSOR	200.00	1 SET	200.00	✓
4 REAR NUMBER PLATE	35.00	1 PC	35.00	✓
			235.00	235.00
Labour				
5 REMOVE & REFIX REAR BUMPER & ATTACHMENTS.KNOCKING & REPAIR REAR END PANEL & REALIGN THE SAME	350.00	1 LA	350.00	200
6 PUTTY & RESPRAY REAR BUMPER & ATTACHMENTS,REVERSE SENSORS & ALL AFFECTED AREAS	300.00	1 LA	300.00	250
			650.00	650.00
Total				SS 1,709.40
Add GST @ 7%				119.66
Total Amount Payable				SS 1,829.06

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

For Cheng Hoe Motor Pte Ltd

Dorlyn Li



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	497D
Vehicle Details	
Vehicle No.:	SLH7231U
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Sep 2019
Vehicle Make:	mitsubishi
Vehicle Model:	LANCER EX 1.6 AT LED TAIL LAMP
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	4A92CL7290
Chassis No.:	JMYSRCY1AGU005926
Maximum Power Output:	86.0 kW (115 bhp)
Open Market Value:	\$14,113.00
Original Registration Date:	17 Nov 2016
First Registration Date:	17 Nov 2016
Transfer Count:	0
Actual ARF Paid:	\$14,113.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Nov 2026
PARF Rebate Amount:	\$10,584.00
Intended COE Rebate Details	
COE Expiry Date:	16 Nov 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,991.00
COE Rebate Amount:	\$36,441.00
Total Rebate Amount:	\$47,025.00

The information contained herein is correct as at 24 Sep 2019

OK

PRE-REPAIR INSPECTION REQUEST – SLH7231U vs SCR3624A (OI) on D.O.A.: 23/09/2019

From: Hor, Yinnul
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, Subramaniam, Divy
Sent: 9/25/2019 10:09:14 AM

Hi,

Please refer to the enclosed request from **Cheng Hoe Motor Pte Ltd (AMK)**.

Claim no : 3961297256SG003
Case Owner : Loh Chee Heng

If you have any queries/concerns, please let us know.
*Kindly assist to assign **Kenneth Kong** as Single Joint Expert as requested.*

Thanks & Regards,

Hor Yin Rui (Viviane)
AIG
FNOL Adjuster I
Singapore FNOL | Claims Operations – Auto

Tel: 8001206558 | Ext: 1002208
Yinnul.Hor@aig.com | www.aig.sg

11:12am 25/9/19
VNI
P: Danylyn

From: chmamk@singnet.com.sg [mailto:chmamk@singnet.com.sg]
Sent: Wednesday, September 25, 2019 10:04 AM
To: Hor, Yinnul
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divyashni; chmamk@singnet.com.sg
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SCR3624A AND SLH7231U ON 23/09/2019

Hi All,

Our Selection as follow :

- Kenneth Kong (LKK Auto Consultants Pte Ltd)

Thank you.

Rgds

Dorlyn Li

Cheng Hoe Motor Pte Ltd (AMK)

Tel : 64812001

From: Hor, Yinnul
Sent: Wed, 25 Sep 2019 00:41:30 +0000
To: chmamk@singnet.com.sg
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, Subramaniam, Divyashni
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SCR3624A AND SLH7231U ON 23/09/2019

Without Prejudice

Your Reference : SLH7231U
Our Reference : 3961297256SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services

EC Looi	Automobile Inspection Services Pte Ltd
Pang Kinh Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rul (Viviane)
AIG
FNOL Adjuster I
Singapore FNOL | Claims Operations – Auto

Tel: 8001208558 | Ext: 1002208
Yinrul.Hor@aig.com | www.aig.sg

From: Cheng Hoe Motor Pte Ltd (AMK) [mailto:chmamk@singnet.com.sg]

Sent: Tuesday, September 24, 2019 4:52 PM

To: Hor, Yinrul; divyashni.subramaniam@sig.com; Mithoosingh, Aashweenjeetkaur; Lim, Sheng Yang; Parthiban, Theerthan; Chan, Yoke Shi; chmotor@singnet.com.sg; AIG SGP, Claims-Survey

Subject: [EXTERNAL] Repair Survey (Single Joint Expert) -SLH7231U, doa 23/09/19 (Yr insured SCR3624A)

This message is from an external sender; be cautious with links and attachments.

Dear Sir,

OUR CLIENT – SLH7231U
DOA – 23/09/2019 @ 0840HRS
YOUR INSURED : SCR3624A (THAM MAE LAN JILL)

Kindly provide us of your surveyor listing for the selection on the survey.

Thank you.

Regards
Darlyn Li
Cheng Hoe Motor Pte Ltd
Tel : 64812001
Fax : 64821296

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Print Received Message

This mail is associated with :

***SLH7231U (3961297256SG)**
[SCR3624A]
TP
TEE HWEE BOON
Sep 23 2019 12:00AM
[THAM MAE LAN JILL]
Cheng Hoe Motor Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 21/01/2020 08:48 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$1743.06) - SLH7231U - Claim Handler: Loh, Chee-Heng

Approved:1743.06.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Sep 2019 Edit Reg		25 Sep 2019 00:00 Edit Adj Rpt	\$1,509.40 Edit Estimates	\$1,509.40 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	THAM MAE LAN JILL, ID: S1601336F								
Main Claimant:	TEE HWEE BOON, ID: S2616497D								
Vehicle Reg. No.:	SLH7231U	Date of Loss:	23/09/2019 00:00 - :59 [34 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 3961297256SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SCR3624A	Policy No. (Claimant):	DMPPHQ18-007769						
		Excess:							
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com								
Claimant's Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 04/10/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (21/01/2020): Alert - Adj Mandate Approved (\$1743.06) - SLH7231U - Claim Handler: Loh, Chee-H... - AIG_SG (26/09/2019): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLH7231U (3961297256SG)
[SCR3624A]
TP
TEE HWEE BOON
Sep 23 2019 12:00AM
[THAM MAE LAN JILL]
Cheng Hoe Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser v	
Letters/Correspondences				
1 per page ☒				
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit
Assessment Reports				
1 per page ☒				
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/01/20 13:10	Adjuster Immediate Advice		Load HTM
Photos/Images				
3 per page ☒				
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/11/19 11:25	Odometer Reading		Load JPG
2	01/11/19 11:25	Chassis Number		Load JPG
3	01/11/19 11:25	General View		Load JPG
4	01/11/19 11:25	General View		Load JPG
5	01/11/19 11:25	General View		Load JPG
6	01/11/19 11:25	General View		Load JPG
7	01/11/19 11:25	General View		Load JPG
8	01/11/19 11:25	General View		Load JPG
9	01/11/19 11:25	General View		Load JPG
10	01/11/19 11:25	General View		Load JPG
11	01/11/19 11:25	General View		Load JPG
12	01/11/19 11:25	General View		Load JPG
13	01/11/19 11:25	General View		Load JPG
14	01/11/19 11:25	General View		Load JPG
15	01/11/19 11:25	General View		Load JPG
16	01/11/19 11:25	General View		Load JPG
17	01/11/19 11:25	General View		Load JPG
18	18/01/20 12:51	Reinspection Photo		Load JPG
19	18/01/20 12:51	Reinspection Photo		Load JPG
Documentation				
1 per page ☒				
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/09/19 15:44	EMAIL FROM AIG DD 25092019		Load PDF
2	30/09/19 09:07	TP GIA REPORT		Load PDF
3	01/10/19 15:31	EMAIL TO OI		Load PDF
4	01/10/19 15:31	LETTER TO OI		Load PDF
5	31/10/19 16:56	TP ESTIMATE- MARKED		Load PDF
6	18/01/20 12:58	TP LOD		Load PDF
7	21/01/20 19:39	EMAIL TO TP		Load PDF
8	04/02/20 11:37	WORKSHOP INVOICE		Load PDF
9	04/02/20 11:37	AUTHORISATION TO ACT FORM		Load PDF
10	04/02/20 11:37	Release Voucher		Load PDF
11	04/02/20 11:37	LTA SEARCH		Load PDF
12	04/02/20 11:37	LOD		Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	26/09/19 16:19	OI GIA REPORT		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^

v

Show Remarks To: ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SCR3624A (Insd veh)	Model:	MITSUBISHI LANCER 1.6 EX
	SLH7231U (TP veh)		AT LED TAIL LAMP (A)
Date of Accident:	23/09/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	1,829.06
Final Repair Cost	:	\$	1,615.06
Loss of Use	:	\$	120.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	8.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	1,743.06

2.00 days at \$60.00 per day
days

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop**: Agreed Liability _____ (%)

B) For **GIA Registered Workshop**: BOLA Applicable: Yes/ ~~No~~ BOLA Scenario No: _____
 27
 BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ (%)
 * Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Cheng Hoe Motor Pte Ltd	:	\$ 1,743.06
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

04 Feb

2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
 (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
 Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19016911/KHS3Q2

Date: 04/02/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SLH7231U

Insured Vehicle No : SCR3624A

Date of Loss: 23/09/2019

Nature of Claim: TP

Claim No: 3961297256SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLH7231U

Make & Model: MITSUBISHI LANCER, 1.6 EX AT LED TAIL LAMP (A)

Engine No: 4A92CL7290

Reg. Date: 17/11/2016 (Man. Year: 2016)

Chassis No: JMYSRCY1AGU005926

Colour: Metallic Grey

Odometer: 73190 km

Engine Capacity: 1590 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Continental 8 mm

Rear Left Side: Continental 8 mm

Front Right Side: Continental 8 mm

Rear Right Side: Continental 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,059.40	1,059.40	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	650.00	450.00	200.00	30.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,709.40	1,509.40	200.00	11.70
+ GST 7.00/7.00% (S\$)	119.66	105.66	14.00	11.70
Nett Amount (S\$)	1,829.06	1,615.06	214.00	11.70
+ Loss of Use (2.0 x S\$60.00/day) (S\$)		120.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		1,743.06		

INSPECTION

Date of Assignment: 25/09/2019

Date Inspected: 30/10/2019 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun
Industrial Park A
Singapore 768761

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	891.00 FN	*891.00 FN
2	5		*REAR BUMPER CLIP	Necessary	25.00 FN	*25.00 FN
3	1		*SET REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
4	1		*REAR NUMBER PLATE	Bent	35.00 FS	*35.00 FS
Sub Total (S\$)					1,151.00	1,151.00
- Nett Item Discount on N Items 10.00/10.00% (S\$)					91.60	91.60
Total Parts (S\$)					1,059.40	1,059.40

F=Franchise part. S=SpcNett. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIX REAR BUMPER & ATTACHMENTS ,KNOCKING & REPAIR REAR END PANEL & REALIGN THE SAME	New	350.00	200.00
2	PUTTY & RESPRAY REAR BUMPER & ATTACHMENTS ,REVERSE SENSORS & ALL AFFECTED AREAS	New	300.00	250.00
Gross Labour Cost (\$\$)			650.00	450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >