

Sherwin Beh (LKK Auto)

From: Kamaliah KAMIS (SPF) <Kamaliah_KAMIS@spf.gov.sg>
Sent: Wednesday, 25 September, 2019 4:04 PM
To: Sherwin Beh (LKK Auto); Naz (LKKAuto)
Cc: Bryan Ang (LKKAuto); SPF-TP FAIT; Norashikin DAUD (SPF); Cheng Eng TAN (SPF); Sufiyan KHAIRI (SPF)
Subject: Mechanical Inspection Report Request

Dear Sirs,

May I seek your assistance to perform a detailed mechanical inspection of the **8 vehicles** below: **[The ones marked in RED are deemed to be URGENT hence please EXPEDITE ON THESE REQUESTS]**

a) Case IAFP-IB-20190908 - Mechanical Inspection of Police Motor Car, QX297H (TP/IP/54567/2019)

On 30 August 2019 (Friday) sometime before 4.45 pm, the police motor car, QX297H (B1), was travelling straight along Bishan St 2 towards the direction of Marymount Rd on lane 2 of the 2-lanes road and was on his way to Tanglin Div. At this juncture, a grey motor car (A1) that was travelling directly ahead of B1, was seen making a left turn into Raffles Institution. Upon seeing that, B1 (IO from Tanglin Division, GIS 5) applied brake to slow down but to no avail, B1 claimed that the brakes were ineffective and this caused the police motor car to collide into the rear of A1. There was no injury reported for this accident however B1 claimed that there was a mechanical fault on his police motor car.

Vehicles to be inspected: QX297D - Driver (Potential Defendant)

IO In-Charge: SIO Kamaliah

b) Case IAFP-IB-20190908 - Mechanical Inspection of Motor Lorry, GBC6982L (TP/IP/40633/2019)

c) Case IAFP-IB-20190908 - Mechanical Inspection of E-Scooter (TP/IP/40633/2019)

On 29 June 2019 (Saturday) sometime before 6.57 pm, B1 (GBC6982L) was travelling straight along Ang Mo Kio Ave 10 towards the direction of Ang Mo Kio Ave 3 on lane 1 of the 2-lanes while traffic light was green light only, in B1's favour. Out of a sudden, B2 (pedestrian in e-scooter) crossed from B1's left side to right side. Hence, B1's frontal portion collided onto B2. As a result of the accident, B2 sustained head injuries and was conveyed to Tan Tock Seng Hospital (TTSH) in an unconscious state by an ambulance. B1 is currently warded in ICU.

Vehicles to be inspected: GBC6982L - Driver (Potential Defendant)
Pedestrian in E-Scooter - Victim (Seriously Injured)

IO In-Charge: SIO Norashikin

d) Case IAFP-IB-20190908 - Mechanical Inspection of Motor Lorry, GBA2169E (TP/IP/39437/2019)

e) Case IAFP-IB-20190908 - Mechanical Inspection of Motorcycle, FY8874P (TP/IP/39437/2019)

On 23 June 2019 (Sunday) at about 10.05 am, the deceased was riding motorcycle FY8874P along Banyan Avenue when the motorcycle collided onto the rear of a stationary motor lorry GBA2169E. As a result of the accident the rider was sent to NUH at an unconscious state and on 28 July 2019 the rider was pronounced dead at NUH.

Vehicles to be inspected: GBA2169E - Driver (Involved Party)

IO In-Charge: SIO Yazid

f) Case IAFP-IB-20190908 - Mechanical Inspection of Motor Car, SDJ5565D (TP/IP/ 50683/2019)

On 15 August 2019 (Thursday) at about 2.25 pm, the driver claimed that the steering wheel of his motor car, SDJ5565D, suddenly felt very stiff for no apparent reason which he could not control, causing it to lost control and collided onto the centre divider railing and a traffic light post along Sengkang East Road by Anchorvale Drive.

Vehicles to be inspected: SDJ5565D - Driver (Involved Party)

IO In-Charge: SIO Emmy Tan

g) Case IAFP-IB-20190908 - Mechanical Inspection of Motor Van, GBD730G (TP/IP/ 39969/2019)

On the 26 June 2019 (Wednesday) sometime around 6.38 a.m., the driver was driving the said motor van along a two-way road of Clementi Loop and made a right turn into a unit. In the midst of making a right turn in front of the said unit, the driver collided onto a pedestrian and caused serious injuries on the pedestrian. General inspection is required to inspect if there is/are any mechanical faults to the motor van.

Vehicles to be inspected: GBD730G - Driver (Potential Defendant)

IO In-Charge: IO Sufiyan Khairi

h) Case IAFP-IB-20190908 - Mechanical Inspection of Motorcycle, FBD7531B (TP/IP/ 56345/2019)

On 8 September 2019 (Sunday) sometime before 3.38a.m., the deceased was riding his motorcycle on unknown lane along Airport towards End near to Lamp post 38 when he struck the right kerbside and self-skidded. The deceased landed on lane 1 and sustained multiple injuries due to the accident. Hence, he was conveyed by an ambulance to SKGH however on the same day at 4.41am, the deceased was pronounced dead in the said hospital.

Vehicles to be inspected: FBD7531B - Rider (Deceased)

IO In-Charge: SIO Adrian Lim

2. These request has been approved by my management.
3. Thank you Sirs.

cc: FAIT Team, SIO Norashikin, SIO Emmy & IO Sufiyan, fyip

Best regards,

Kamaliah Kamis (Miss)
Senior Investigation Officer | Fatal Accident Investigation Team
Traffic Police Department | Singapore Police Force
DID: (65) 6547 6435 | FAX: (65) 6547 6352



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."