

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0852/2019/KK
Date : 12-Jul-19

Vehicle not IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

5 days - ok - jb - 8 Aug 20

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Clive Gordon Scott
Address : 2 Marina Blvd
#65-01
Singapore 018987
Telephone : HP +65 83188136
Type of Claim : OWN DAMAGE CLAIM
Policy No. : 1800096299
Vehicle No : **S 9105 CD**
Model Code : Audi Q5 2.0 TFSI QU
Model / Year : Aug-12
Engine No : CDN 282963
Chassis No : WAUZZZ8RXCA126012
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 7-Jul-19
Place of Accident : Aedmore Park Condo Basement 2 Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle S 9105 CD

S/n	Nature of Jobs	Estimated Charges			
1	To remove and transfer front wire harness for headlight, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N	\$ 480.00	\$	480.00
2	To dismantle and renew front bumper, lhs front fender and lhs headlight. Re-organise crash management components. Reinstall all parts removed.		\$ 2,800.00	\$	1,250.00
3	To respray front bumper, front bumper spoiler and lhs front fender.		\$ 3,000.00	\$	1,650.00
4	To renew lhs front rim and carry out wheel alignment.	S/N	\$ 280.00	\$	280.00
5	To carry out diagnostic check.	S/N	\$ 192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 6,752.00	\$	3,852.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. S 9105 CD

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER	\$ 2,432.00	\$ 1,945.60
2	FRONT BUMPER SPOILER	\$ 249.00	
3	FRONT BUMPER SIDE RETAINER - LH	\$ 569.00	
4	FRONT BUMPER AIR GUIDE DRILLE - LH	\$ 123.00	
5	FRONT BUMPER GUIDE SECTION	\$ 34.00	\$ 27.12
6	FRONT BUMPER REINFORCEMENT	\$ 598.00	
7	FOAM FILLER PIECE	\$ 103.00	
8	FRONT BUMPER SENSOR	\$ 231.00	
9	FRONT BUMPER SENSOR SEAL RING	NEC \$ 20.00	
10	FRONT FENDER - LH	4 \$ 913.00	\$ 730.00
11	FRONT FENDER ATTACHEMENT PARTS	\$ 61.00	
12	SEALING FRAME - LH	\$ 59.00	
13	FRONT FENDER BRACKET - LH	\$ 49.00	
14	FRONT FENDER BRACKET - CENTER	\$ 45.00	
15	POP ROVERT	6 \$ 108.00	
16	FRONT FENDER BRACE - LH	\$ 79.00	\$ 62.64
17	WHEEL HOUSING LINER	\$ 246.00	\$ 196.40
18	WHEEL HOUSING LINER ATTACHEMENT PARTS	\$ 94.00	\$ 74.96
19	WHEEL SPOILER	\$ 60.00	
20	HEADLIGHT MOUNTING	\$ 107.00	
SUB SPARE PARTS CHARGES :		\$ 6,180.00	\$ 3,036.72

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. S 9105 CD

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
		<i>c/f</i>	\$ 3,036.72
21	RETAINING PLATE	\$ 2,432.00	
22	HEADLIGHT GAS DISCHARGE	\$ 2,432.00	\$ 2,119.20
23	HALOGEN FOG LAMP	\$ 203.00	
24	HEADLIGHT LIFT CYLINDER	\$ 227.00	
25	ALUMINIUM RIM	\$ 819.00	\$ 844.00
26	RUBBER VALVE	\$ 819.00	
27	SUNDRIES	\$ 25.00	\$ 14.40
TOTAL SPARE PARTS CHARGES		\$ 10,027.00	\$ 6,014.32
TOTAL LABOUR CHARGES		\$ 6,752.00	\$ 3,852.00
GRAND TOTAL		\$ 16,779.00	\$ 9,866.32

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant