

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

26 SEP 2019

E S T I M A T E

Estimate No. : b1 52875
Date Estimated : 26/09/2019
Prepared By : Gary Poh Chai Hoon

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Ho Kah Siong
119 Fidelio Street

Singapore 458494

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKS123Z	WBA7E02010G244984	29/07/2016	730Li	0

DESCRIPTION

To replace rear bumper and attachment include knocking
cause by the accident.

850 1,700.00

Painting rear bumper

974 1,038.00

To check electrical wiring systems and lightings at the
rear section for proper function.

150 177.00

Sundries.

80.00

Total Labour 1: 2,995.00

DESCRIPTION

REAR BUMPER ADAPTER
REAR BUMPER CARRIER
REAR BUMPER CENTRE GUIDE
REAR LH MOUNT LATERAL
REAR RH MOUNT LATERAL
LH TRIM EXHAUST TAILPIPE X
RH TRIM EXHAUST TAILPIPE X
REAR BUMPER CENTRE GUARD
REAR BUMPER GUARD (chrome) CUT
LH RUBBER STRIP
RH RUBBER STRIP
REAR BUMPER COVER
REAR BUMPER TRIM PRIMED
REAR BUMPER PANEL PRIMED (PDC/PMA)
REAR BUMPER TOWING EYE COVER PRIMED X
REAR SILENCER HEAT INSULATOR X
Sound insula
HEAT INSULATOR FLOOR PANEL TRUNK
DECOUPING RING PDC TORQUE CONVERTER
ULTRASONIC TRANSDUCER JATOBA WB65

QTY	PRIC	VALUE
1	84.50	84.50
1	971.25	971.25
1	67.45	67.45
1	160.55	160.55
1	160.55	160.55
1	248.80	248.80
1	248.80	248.80
1	83.85	83.85
1	109.70	109.70
1	86.75	86.75
1	86.75	86.75
1	110.00	110.00
1	216.45	216.45
1	1,746.65	1,746.65
1	57.10	57.10
1	133.40	133.40
1	115.60	115.60
1	37.10	37.10
4	5.05	20.20
4	380.65	1,522.60

Total Parts : 6,268.05

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 52875
Date Estimated : 26/09/2019
Prepared By : Gary Poh Chai Hoon

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKS123Z	WBA7E02010G244984	29/07/2016	730Li	0

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	
Regn No. _____	Claim No. _____
Date&Time <u>15/10/15, 4.00pm</u>	Excess S\$ _____
Surveyor's Name <u>Steve (LKK)</u>	Sign _____
Surveyor's Tel <u>8322 8813</u>	Authorised Yes / No _____
Authorised Date _____	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No	
Surveyor's E-mail _____	
No. of Working Days Recommend _____	

*ml kpl
P/P
By Bel sy
3 dy*

Labour 1	:	2,995.00
Parts	:	6,268.05
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	648.41
Grand Total	:	9,911.46

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **