J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578, Defu Industrial Park C, SIngapore 539186 Tel: 6343-0934 Fax: 6343-0921

Email: jmartauto@gmail.com Registration No: 201400246D GST Reg. No: 201400246D

CC6/ALG19017072/Ad163

26-Sep-19

Our ref: TP/4755/19

WVG22711TZCW042208

TPALG.

Robin Soon Ban Huat

Jiale

RE: estimate cost for vehicle no: SKD 3157K

1 pc 1 pc 1 pc 2 pcs 1 pc 1 pc	Touran emblem 7 Tsi emblem rear bumper Vell drear bumper reflectors rear bumper lower spoiler Vell rear bumper reinforcment	d	\$	76.00 46.00 1360.00 220.00 462.00 619.00
1 pc	end panel Report		2563	1069.00 +
1 pc	end panel inner garnish Mc ~		2206-70	251.00 +.
			2300	4,103.00
		less 10%		410.30
				3,692.70
1 pc	reverse sensor			250.00 snett 2 ~
Panel beating	g. /			500.00 Zw
Spray paintin	g.			800.00-40> 830
Wiring.				30.00
				5,272.70
Plus 7% GST		Т	369.09	
				5,641.79

SD: five thousand six hundred forty-one & cents seventy-nine only.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Ling. 1/5 27/09/19.

tolel 313670

0.0 **阿斯斯斯**+ 46. + 1,360. 462. + 619 = 2,563. * 2,563° × 90 % 2,306.7 * 200 • + 200 • + 45-\$2500 400 . 8000 800. + 30 • = 830 • * 830. 3:136.7 3,136.7 x 80 % 2.509.36 *