

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Friday, 1 November 2019 9:01 AM
To: eqiprs@eqinsurance.com.sg
Cc: Admin A
Subject: <SEEK MANDATE>: You Ref: DM19HO02652/JT // LKK REF: CC4/EQI19017143/Upa3 [ACCIDENT INVOLVING GBH 2482M(OI-EQ) AND SMG 4818R(TP) ON 25/09/2019]
Attachments: LKK Survey Report & Photos.pdf; TP LOD & Docs.pdf

EQ ref : **DM19HO02652/JT**
LKK ref : CC4/EQI19017143/Upa3q2

Dear Sirs/Madam,

ACCIDENT INVOLVING GBH2482M(EQ-OI) AND SMG4818R(TP) ON 25/09/2019

We refer to the above matter.

The accident occurred when our insured driver reversed and hit onto third party vehicle. Liability is not in our driver's favour.

We seek your approval to offer Third Party repairer "**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**" at **\$13,183.49(all-in)**.

The summary is as follows: -

	Claimed Amount	Revised Amount
1. Cost of Repair	\$ 20,305.03	\$ 12,541.49
2. Loss of Rental (9days x \$120.00)(w/GST)	\$ 1,155.60	\$ 642.00 (5days x \$120.00)(w/GST)
3. Loss of Use for PRI (2days x \$120.00)	\$ 240.00	\$ -
Total	\$ 21,700.63	<u>\$ 13,183.49</u>

Surveyor recommended 4 days for repair + 1PRS = 5days.

Enclosed here with all the relevant documents for your perusal.

Kindly let us have your approval/instruction.

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)
Sent: Wednesday, 16 October 2019 9:14 AM
To: eqiprs@eqinsurance.com.sg
Cc: Admin A <admin-a@lkkauto.com>
Subject: You Ref: DM19HO02652/JT // LKK REF: CC4/EQI19017143/Upa3 [ACCIDENT INVOLVING GBH 2482M(OI-EQ) AND SMG 4818R(TP) ON 25/09/2019]

Dear Sirs/ Mdm,

We refer to the above matter.

Enclosed for your perusal is: -

- Estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Thank you.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)