

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
COMFORT TRANSPORTATION PTE LTD

Singapore

Claimant
Insurer: MS First Capital Insurance Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	28/09/2019
Vehicle Reg. No.:	SHB4088R	Driveable?	YES
Party At Fault:	UNKNOWN		
Driver (TP):	SIM BENG KWANG		

Make/Model:	HYUNDAI I40, 1.7 D CRDI (A)	Vehicle Reg. Date:	23/04/2015
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	D4FDEU495490	Chassis No:	KMHLB41UMFU068114
Odometer:	734188 KM		

Paint Type:

List Item Discount:	20.00 %
Total Loss?	NO
Est. Duration of Repair (day)	3

Description of Accident/Loss	REFER ATTACHED
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

COST OF CLAIMS

	Amount
Parts	1,106.58
Miscellaneous Items	11.00
Labour	730.00
Paintwork Labour	0.00
Towing	0.00

Gross Total (\$\$) **1,847.58**

Larry Ng

+ GST 7.00% (S\$)	129.33
-------------------	--------

Nett Amount (S\$)	1,976.91
-------------------	----------

This claim is handled by: NG NYUK PHIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Larry Ng

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 30 Sep 2019)**Parts:** 143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHB4088R/30/09/2019 14:34**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER ✓	20.00	0.00	*553.00 FL
2	10		*REAR BUMPER CLIPS ✓	20.00	0.00	*22.00 FL
3	1		*REAR BUMPER BRACKET - LH ✕	20.00	0.00	*35.60 FL
4	1		*REAR BUMPER UNDERCOVER ✕	20.00	0.00	*228.00 FL
5	1		*REVERSE SENSOR ✕	0	0.00	*135.70 FS
6	2		*ADVERTISEMENT - REAR FENDER RH/LH ✓	0	0.00	*200.00 FS
7	1		*ADVERTISEMENT - REAR BUMPER ✓	0	0.00	*50.00 FS
8	1		*REAR BUMPER RUBBER MAT ✓	0	0.00	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)**1,274.30****- List Item Discount on L Items (\$\$)****167.72****Total Parts (\$\$)****1,106.58**

ComfortDelGro Engineering Pte Ltd/SHB4088R/30/09/2019 14:34. Not valid without Reference section.
Generated using **Merimen e-Claims IEAS**

Larry Ng

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00 ✓
Sub Total (\$\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	280 350.00
2	SPRAY PAINTING	New	200 250.00
3	WIRING CHARGE	New	X 50.00
4	REMOVE/REFIX REVERSE SENSOR	New	30 80.00
Gross Labour Cost (\$\$)			730.00

ComfortDelGro Engineering Pte Ltd/SHB4088R/30/09/2019 14:34. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Larry Ng

Ka hui 16/11/19

✓

30/9/19

1520

2.00

4/5

After Repair photo

