

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 02 Oct 2019

Preliminary Advice

Insured Vehicle No	: YP9818T		
TP Vehicle No	: YP7723X	Accident Date	: 24/09/2019
Make	: MITSUBISHI CANTER	Assignment Date	: 01/10/2019
Date of Inspection	: 01/10/2019	Est. Duration of Repair	: 5 days
Inspection At	: LIU BROTHER AUTO ENGINEERING WORKSHOP (HQ) NO 1 KAKI BUKIT AVE 6 #01-01 SINGAPORE 417883 AUTOBAY SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,053.75
Revised Amount	:S\$	7,395.72
Check Items (Estimated)	:S\$	0.00
Total	:S\$	7,395.72

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP