

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
2	1	To Remove and Refit Rear Bumper Sensor.	80.00	0.00	80.00
3	1	To Dismantle and Refit Rear Windscreen Glass.	100.00	0.00	100.00
4	1	To Transfer Rear Tailgate.	80.00	0.00	80.00
5	1	To Remove And Refit Carpet And Trims On The Rear Section To Give Way To The Repair on The Rear Section.	100.00	0.00	100.00
6	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	900.00	0.00	900.00

Gross Labour Cost (S\$) 1,290.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	40.00	0.00	40.00
2	1	To Supply Spray Terostat Sealant On The Cutting Areas.	45.00	0.00	45.00
3	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	60.00	0.00	60.00
4	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	800.00	0.00	800.00

Gross Labour Cost (S\$) 945.00

< END OF ESTIMATES >

Steve (LKK) M-L Ref L 7/10/19, 12.30 on

4 day

P/P

Ry Ref Spy

P-1598-25

NI-270

L-1290

Supp-200

P/P-3358-25

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repairer must hence notify the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: