

ASS. REC. BY:

REF: CS/CT1 19017326/04f3/n2

Special Instruction:

Supervisor: Marcus

**ASSIGNMENT (Office)**

From (Person): Ong Chin Kiat of CTZ Date/Time: 2.10.19 11.50am

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMK 7807G Insured: YN 8855C

at Workshop m/s Focus Auto Tel: 6886 9097

of 1 Kaki Bukit Ave 6 #02-48

Policy No: DMCVSN30739019033 Claim No: SVM19D704559C02

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 26.9.2019

(Client's Record) sup!

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 2.10.19 11.55am Person Contacted: Aidah Vehicle: IN / OUT

Date/Time	Action/Instruction ( <input checked="" type="checkbox"/> ) Estimate.
	SMK 7807G - X
	YN 8855C - CS/CT1 19009592/T1vd3n2 DOA - 23/07/2019

Photoak

menin

(08/11/13) wef  
ASS. REC. BY: Marcus

REF:

CA/

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: SMK787G  
at Workshop m/s: Focus  
of \_\_\_\_\_  
Insured: \_\_\_\_\_  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

Veh No: SMK787G Yr Regn: 4 19  
Type: CA / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or CA  
Make: Mercedes Hybrid 1496  
Colour: Gold A/C: Insured / Std / NI / NA  
Sp. Reading: 37814 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: RU3 1227039  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: In order / Jammed / Leaked / Burnt or  
Brake: In order / Jammed / Leaked / Burnt or  
Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)  
Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Tyre Size: F: 215/60R16  
R: \_\_\_\_\_  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
R/Bal. 8 mm R/Bal. 8 mm  
L/Bal. 8 mm L/Bal. 8 mm  
D.O.A. 26/9/19 D.O.I. 1/10/19  
Survey held at \_\_\_\_\_

Bal. or Market Value: \_\_\_\_\_  
IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
Est. Repairs: 8 days Res.: Yes or No  
Lum Sum: 20 % 3 Val.: Yes or No  
CA / REV / REP. / 24 HRS  
Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
Rear & Rear w/screen sketched  
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction  
7/10/19 1/5 #9300 confirmed with MP way. (Red \$5558,44, 37%)

RECEIVED 09 OCT 2019

Date/Time, File Pass to?  : Preli. Report  
 : Final Report

Days Of Repair: 8  
Resurvey No. of Trip: 2

Date/Time, File Return to?  
2) 8/10/19 Typist

Add Fee:  : Site Insp (\$ \_\_\_\_\_) )  
 : Interview (\$ \_\_\_\_\_) )  
 : Tech. Invs (\$ \_\_\_\_\_) )  
 : Weekend (\$ \_\_\_\_\_) )

Report Format :  
Lump Sum I.B.I. (\$) \$9300/-

Survey Fee:	
Transportation:	
Photos	
Others	
TOTAL	<u>220</u>

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Oct 2019		02 Oct 2019 11:50 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>				<a href="#">[Created by insurer]</a>					
Insured:	<b>BESTCOAT CONTRACT SERVICES PTE LTD</b> , Co. Reg. No.: 199506291N								
Main Claimant:	<b>SUNRITA PTE LTD</b> , Co. Reg. No.: 196800361G								
Vehicle Reg. No.:	<b>SMK7807G</b>	Date of Loss:	26/09/2019 10:00 - :59 [5 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM19D204559C02</b>	Policy/Cover Note No.:	DMCVSN30759019033						
Vehicle Reg. No. (Insured):	<b>YN8855C</b>	Policy No. (Claimant):	5109065040						
		Excess:	S\$0.00						
Repairer:	<b>Focus Auto Pte Ltd (HQ)</b> 1 Kaki Bukit Ave 6, #02-48/50 Autobay, 417883 Kaki Bukit - Tel: 68869097								
Handling Insurer:	<b>China Talping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Ong Chin Kiat</b> ]								
Claimant's Insurer:	<b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... <b>[Final Rpt due 11/10/2019]</b>								
Driver/Custodian (Insured):	BALAN NEETHI (59 / Male), NRIC: F7992076L Email:								
<b>ASSOCIATED MAIL RECEIVED</b>				<a href="#">View All</a>   <a href="#">Compose Case Mail</a>					
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>									
<a href="#">View All</a>   <a href="#">Search Tasks</a>   <a href="#">Create New Task</a>   <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Proton vs. Perodua

2014 Honda Jazz / Fit (GK Series)

**Post an Advertisement**  
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

Fully Done Up 2017 Toyota C-HR G Model!



Probably The Best C-HR In SG. A lot Of Money And Effort Spent On This Head Turner Direct Owner StarAd



Browse by Category

« Back ( 1 2 ) Next »

Sort by Date Posted  20 results/page

28 vehicles

vezel

Advanced Search  Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	vezel		Any	Any	2019	Any	Any	Any	Available
	Honda	Vezel 1.5A X Sensing	\$90,988	\$8,680 /yr	15-Mar-2019	1,496 cc	-	SUV	Available
Comes With 5 Years Warranty, Do Not Miss This Beautiful Unit, Flawless And Excellent Condition, View To Believe, Please Call For Viewin... Vincar Pte Ltd Posted: 01-Oct-2019 Tags: 2019 Honda Vezel, 2019 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									
	Honda	Vezel 1.5A X Sensing	\$85,800	\$8,080 /yr	20-Jun-2019	1,496 cc	10 km	SUV	Available
5 Years Warranty! 3 x Free Servicing! 2019 Latest Model! VITAS Ready Stock Of White, Flexible Loan And High Trade In. Dynamic And R... Shuang Hup Credit Posted: 01-Oct-2019 Tags: 2019 Honda Vezel, 2019 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									
	Honda	Vezel 1.5A X	\$82,800	\$7,990 /yr	27-Mar-2019	1,496 cc	5,811 km	SUV	Available
3 Years Unlimited Mileage Warranty. 1 Owner With Low Mileage Of 5811km. Low Depre 7.9k Nego. Most Popular SUV For Your Family Us... Roadlink Auto Pte Ltd Posted: 30-Sep-2019 Tags: 2019 Honda Vezel, 2019 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									
	Honda	Vezel 1.5A X	\$81,800	\$7,540 /yr	27-Aug-2019	1,496 cc	73 km	SUV	Available
Banks/In House Available, Please Call For Financial And Updated Price. The Car Regency, Subsidy Of Thong Lee Trading Is Established 1... Posted: 29-Sep-2019 Tags: 2019 Honda Vezel, 2019 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									
	<b>Rear Bumper LED Styling</b> - enhances safety; more visibility - stand out from all the other Vezels / HR-V on the road More info about this product								
	Honda	Vezel 1.5A X Sensing	\$88,777	\$8,660 /yr	26-Mar-2019	1,496 cc	8 km	SUV	Available
New Model Vezel, Vitas Ready, Fast Deliver, High Accessories With, IRoad Recording Camera, High Trade In Your Existing Car, 5 Years... HTS Motor Posted: 29-Sep-2019 Tags: 2019 Honda Vezel, 2019 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									
	Honda	Vezel 1.5A X Sensing	\$88,777	\$8,760 /yr	21-Jan-2019	1,496 cc	8 km	SUV	Available
Almost 2018 New Model Vezel, Vitas Ready, Fast Deliver, High Accessories With GPS, IRoad Recording Camera, High Trade In Your Exist... HTS Motor Posted: 28-Sep-2019 Tags: 2019 Honda Vezel, 2019 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									

Compare

> **Back to OneMotoring****Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	361G
<b>Vehicle Details</b>	
Vehicle No.:	SMK7807G
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Oct 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL HYBRID 1.5X AUTO
Primary Colour:	Brown
Manufacturing Year:	2016
Engine No.:	LEB5927053
Chassis No.:	RU31227039
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$26,355.00
Original Registration Date:	24 Apr 2019
First Registration Date:	24 Apr 2019
Transfer Count:	0
Actual ARF Paid:	\$18,897.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Apr 2029
PARF Rebate Amount:	\$14,172.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	23 Apr 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$39,401.00
COE Rebate Amount:	\$37,671.00
<b>Total Rebate Amount:</b>	<b>\$51,843.00</b>

The information contained herein is correct as at 01 Oct 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	26/09/2019 15:43
Date Of Accident	26/09/2019 10:00
Exact Location Of Accident	ALONG PIE TOWARDS TUAS (BEFORE JLN BAHAR EXIT)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMK7807G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SUNRITA PTE LTD
Co Reg No	196800361G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-82183517
Alternative Phone No	OFFICE-82183517

### Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL HYBRID
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5109065040
Cover Note Number	24/04/2019 - 23/04/2020

### Driver

Name of Driver	LIM LIEH CHING
NRIC No	S7139173F
Date Of Birth	30/10/1971
Occupation	OUTDOOR
Date Of Driving Pass	16/03/1993
Driving Experience	26 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82183517
Fax Number	
Contact Number	
EEmail Address	LIMLC71@HOTMAIL.COM

Address	BLK 476D CHOA CHU KANG AVENUE 5 #10-59
Postcode	S684476
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : GUO XIAOZHU GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO POLICE REPORT ATTACHED.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN8855C
Vehicle Make/Model/Colour	NA
Details Of Properties	NA
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	BALAN MEETHI
NRIC/Passport Number	F7992076L
Contact Number	92721928

Address	NA
Postcode	NA
Insurance Company Name	
Nature Of Damage	NA
No. Of Passenger (Including Driver)	

**DETAILS OF INJURED PERSON 1**

Name	LIM LIEH CHING
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SMK7807G
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	BLK 476D CHOA CHU KANG AVENUE 5 #10-59
Postcode	S684476

**DETAILS OF INJURED PERSON 2**

Name	GUO XIAOZHU
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SMK7807G
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	BLK 476D CHOA CHU KANG AVENUE 5 #10-59
Postcode	S684476

# Accident Sketch Plan Pg. 1

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

26/9/19  
1525HRS


Driver's Signature  
(if driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Accident Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refu to police report. - T / 20190926 / 2013.

Insurance Co: N7116  
Vehicle No: SMK 78076 Date of Accident: 26/9/2019

Reporting Only  
 Own Damage Claim  
 Third Party Claim

Workshop Focus Auto P/L

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20190926/7013

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 26/09/2019 14:55	Vide Report No.:	Station Diary No.:
--	------------------	--------------------

Informant's Particulars			
Name of Informant: LIM LIEH CHING		Address: APT BLK 476D CHOA CHU KANG AVENUE 5 #10-59 SINGAPORE 684476	
ID Type / ID No.: NRIC NO / S7139173F		Contact No.: Home/Office:	Mobile: 82183517
Nationality: SINGAPORE CITIZEN		Email: LIMLC71@HOTMAIL.COM	
Sex: Male	Age: 47	Date of Birth: 30/10/1971	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: Working proprietor (transport, storage and courier)		Driving Licence Information: Class:	Date of Expiry:

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 26/09/2019 10:00	Type of Location: Straight Road
Location:  PAN ISLAND EXPRESSWAY				
Weather: Clear		Road Surface: Dry		Road Speed Limit: 90 Km/h
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SMK7807G	Car					0
YN8855C	Lorry	MITSUBISHI	FUSO	White	Slightly Damaged	1

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

**CONTINUATION OF REPORT**

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:  
Not applicable

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / TPIB /  
MOHAMAD ZULFAZDLI BIN ABDULLAH  
Contact No.: 65476204

Signature Of Informant:  
The identity of the person making this report has  
been authenticated by SingPass. No signature is  
required.

Date/Time:  
26/09/2019 14:55

Classification Of Case:

Authentication Stamp

NP168

**Certificate of Insurance**

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)  
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960  
ROAD TRANSPORT ACT, 1987 (MALAYSIA)  
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5109065040

Cover : drivo CLASSIC

1. Index mark and Registration Number of Vehicle : SMK7807G  
Chassis Number : RU31227039
2. Name of Policyholder : SUNRITA PRIVATE LIMITED
3. Effective Date of Insurance : 24 Apr 2019
4. Expiry Date of Insurance : 23 Apr 2020
5. Persons or Classes of Persons entitled to drive#  
(a) The Policyholder.  
(b) Any other person who is driving on the Policyholder's order or with his/her permission.  
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
6. Limitations as to Use#  
(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's or Hirer's business.

This Policy does not cover

- (a) Use for racing, pace-making, reliability trial or speed-testing.
  - (b) Use for the carriage of goods (other than samples) in connection with any trade or business.
  - (c) Use for any purpose in connection with the Motor Trade.
- # Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: YES
NCD PROTECTION	: NO
TRANSPORT ALLOWANCE	: NO
EXCESS WAIVER	: NO
PRIMARY DRIVER	: N/A
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: TECK WEI CREDIT PTE LTD
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : TECK WEI CREDIT PTE LTD, (00000572499)  
Date of Issue : 23 Apr 2019 09:24 hrs

德威信貸私人有限公司  
TECK WEI CREDIT PTE LTD  
Co., Reg. No. 200512300K  
210 Turf Club Road, The Grandstand  
Lot A8 Singapore 287995  
Tel: 6465 0020 Fax: 6465 0017  
Email: info@teckwei.com.sg

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:



Authorised Officer



Chief Executive

# FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883  
 TEL: 6886 9097 FAX: 6886 9095 Email: claims@focusauto.com.sg  
 GST:200712509E RCB NO:201004495R

*not Authorized  
 2/10/19  
 2/5 9700  
 800  
 Whipple Attorney*

M/S :

Estimate No: **EST0001007**  
 Date: 30 Sep 2019  
 Policy No:  
 Veh Reg No: **SMK7807G**  
 Make/Model: **HONDA VEZEL  
 HYBRID**  
 Chassis No: **RU31227039**  
 Engine No: **LEB5927053**  
 Reg. Date: **24/04/2019**

ATTN: Motor Claim Department

Your Ref No: **LIM LIEH CHING**  
 Claim Type: **Third Party**  
 Accident Date:

**Estimate Repair Cost to Vehicle No :SMK7807G**

PAGE:1/3

Description	U/Price	Quantity	List Price	Amount
				SS
<b>List Price</b>				
1 Rear Boot <i>953.00</i>	<i>Body</i> 1,100.00	1 PC	<del>1,100.00</del>	
2 Rear Boot Hinge	<i>11</i> 48.20	2 PC	<del>96.40</del>	
3 Rear Boot Shock Absorber	<i>11</i> 192.10	2 PC	<del>384.20</del>	
4 Rear Boot Rubber	<i>twi</i> 135.20	1 PC	<del>135.20</del>	
5 Rear Boot Lock	<i>twi/br</i> 181.90	1 PC	<del>181.90</del>	
6 Rear Boot Lock Catch	<i>11</i> 48.60	1 PC	<del>48.60</del>	
7 Rear Boot Emblem (VEZEL)	<i>RE</i> 56.20	1 PC	<del>56.20</del>	
8 Rear Boot Emblem (HYBRID)	<i>RE</i> 57.40	1 PC	<del>57.40</del>	
9 Rear Boot Reflector Lamp	<i>CR</i> 364.60	2 PC	<del>729.20</del>	
10 Rear Boot centre logo	<i>RE</i> 58.20	1 PCS	<del>58.20</del>	
11 Rear Boot Centre Garnish	<i>Surf/cra</i> 365.70	1 PC	<del>365.70</del>	
12 Rear Boot Inner Cover Board	<i>wsp/br</i> 368.20	1 PC	<del>368.20</del>	
13 Rear Boot Pull Handle Garnish	<i>imp</i> 50.40	1 PC	<del>50.40</del>	
14 Rear Windscreen <i>1280.00</i>	<i>sho/br</i> 1,350.00	1 PC	<del>1,350.00</del>	
15 Rear Windscreen Seal <i>64.80</i>	<i>RE</i> 120.00	1 PC	<del>120.00</del>	
16 Rear Wiper Motor	<i>11</i> 389.40	1 PC	<del>389.40</del>	
17 Rear Wiper Blade	<i>11</i> 60.20	1 PC	<del>60.20</del>	
18 Rear Windscreen Inner Side Garnish	<i>11</i> 104.20	2 PC	<del>208.40</del>	
19 Rear Fender Inner Side Garnish	<i>re/cra</i> 379.30	2 PC	<del>758.60</del>	
20 Rear Floor Panel <i>1120.00</i>	<i>crump/suc</i> 1,330.20	1 PC	<del>1,330.20</del>	
21 Rear Floor Panel Top Cover Board	<i>wsp/br</i> 428.70	1 PC	<del>428.70</del>	
22 Rear Tool Tray	<i>CR/twi</i> 326.90	1 PC	<del>326.90</del>	
23 Rear Tail Lamp	<i>CR</i> 486.20	2 PC	<del>972.40</del>	
24 Rear Tail Lamp Clipse	<i>11</i> 8.50	2 PC	<del>17.00</del>	
25 Roof Top Panel	<i>11</i> 104.20	2 PC	<del>208.40</del>	
26 Rear End Panel <i>517.40</i>	<i>Body</i> 614.30	1 PC	<del>614.30</del>	

# FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883  
 TEL: 6886 9097 FAX: 6886 9095 Email: claims@focusauto.com.sg  
 GST:200712509E RCB NO:201004495R

*Not Allowed here*  
*1/599300*  
*1/10/19*  
*Chap. Mr. M. S. S. S.*  
*S. S.*

M/S :

Estimate No: **EST0001007**

Date: 30 Sep 2019

Policy No:

Veh Reg No: **SMK7807G**

Make/Model: **HONDA VEZEL HYBRID**

Chassis No: **RU31227039**

Engine No: **LEB5927053**

Reg. Date: **24/04/2019**

ATTN: Motor Claim Department

Your Ref No: **LIM LIEH CHING**

Claim Type: **Third Party**

Accident Date:

**Estimate Repair Cost to Vehicle No :SMK7807G**

PAGE:2/3

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
<b>List Price</b>				
27 Rear End Panel Top Garnish	<i>Dis</i>	199.30	1 PCS	199.30 ✓
28 Rear Smart Sensor	<i>one</i>	259.20	1 PC	259.20 ✓
29 Rear Bumper	<i>Dis</i>	863.50	1 PC	<del>863.50</del> ✓
30 Rear Bumper Side Retainer	<i>11</i>	48.60	2 PC	97.20 ✓
31 Rear Bumper Side	<i>10/pc</i>	295.80	2 PC	591.60 ✓
32 Rear Bumper Under Cover	<i>magick</i>	186.40	1 PC	186.40 ✓
33 Rear Bumper Lower Clips	<i>see</i>	5.50	4 PC	22.00 ✓
34 Rear Wheel Arc Protector - LH	<i>1pc</i>	172.40	1 PC	172.40 ✓
35 Rear Exhaust Silencer	<i>11</i>	77.40	1 PC	77.40 X
36 Rear Exhaust Rubber	<i>11</i>	34.90	2 PC	69.80 X
37 Rear Exhaust Chrome Pipe	<i>11</i>	120.20	1 PC	120.20 X
38 Rear Boot Top Spoiler	<i>650. one</i>	786.20	1 PC	786.20 ✓
				13,861.30
		Less 20%		2,772.26 11,089.04
39 Rear Number Plate Lamp	<i>11</i>	42.20	2 PC	84.40 X
				84.40 84.40
<b>Special Net</b>				
40 Rear Windscreen Sticker - Private Hirer	<i>see</i>	80.00	1 PC	80.00 <i>20</i>
41 Rear Windscreen <i>Gum Sealant</i>	<i>see</i>	80.00	1 PC	80.00 <i>40</i>
42 Rear Bumper Sensor	<i>shold</i>	300.00	<i>1pc/set</i>	300.00 <i>200</i>
43 Rear Number Plate	<i>see</i>	50.00	1 PC	50.00 <i>0</i>
44 Rear Reverse Camera	<i>see</i>	45.00	1 PC	45.00 <i>0</i>
				555.00 555.00
<b>Labour</b>				
45 Towing	<i>11</i>	50.00	1 PC	50.00 X
46 Panel Beating		1,600.00	1 PC	1,600.00 <i>1200</i>
47 Check Wiring		80.00	1 PC	80.00 <i>30</i>

# FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883  
 TEL: 6886 9097 FAX: 6886 9095 Email: claims@focusauto.com.sg  
 GST:200712509E RCB NO:201004495R

M/S :

**Estimate No: EST0001007**

Date: 30 Sep 2019

Policy No:

Veh Reg No: **SMK7807G**

Make/Model: HONDA VEZEL  
HYBRID

Chassis No: RU31227039

Engine No: LEB5927053

Reg. Date: 24/04/2019

ATTN: Motor Claim Department

Your Ref No: LIM LIEH CHING

Claim Type: Third Party

Accident Date:

**Estimate Repair Cost to Vehicle No :SMK7807G**

PAGE:3/3

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
<b>List Price</b>				
48 Rust Proofing	80.00	1 PC	80.00	✓
49 To Remove & Refit Rear Windscreen	160.00	1 PC	160.00	120
50 To Remove & Replace Bumper Sensor	80.00	1 PC	80.00	50
51 To Remove & Replace Exhaust Silencer	80.00	1 PC	80.00	60
52 To Spray Painting	1,000.00	1 PC	1,000.00	900
			3,130.00	3,130.00

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
			Total	SS 14,858.44

TOTAL: SINGAPORE DOLLAR FOURTEEN THOUSAND EIGHT HUNDRED FIFTY EIGHT AND CENTS FORTY FOUR ONLY

2700

**For FOCUS AUTO PTE LTD**

LKK Auto Consultants hence notify the Receiver of the following:

- \* To be done before/after spray painting
- \* To repair damaged part(s) using resurvey
- \* To be done subject to confirmation
- \* This estimate is on a "Without Prejudice" basis
- \* No warranty is provided
- \* Supplementary work(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature: \_\_\_\_\_

Date: \_\_\_\_\_

AUTHORISED SIGNATURE

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19017326/UYF3N2

Date: 11/10/2019

**REFERENCE**

<b>Handling Insurer:</b>	China Taiping Insurance (Singapore) Pte. Ltd.	<b>Policy No:</b>	DMCVSN30759019033
<b>Claimant Vehicle No :</b>	SMK7807G	<b>Insured Vehicle No :</b>	YN8855C
<b>Date of Loss:</b>	26/09/2019	<b>Nature of Claim:</b>	TP
		<b>Claim No:</b>	SNM19D204559C02

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

<b>Reg No:</b>	SMK7807G	<b>Engine No:</b>	LEB5927053
<b>Make &amp; Model:</b>	HONDA VEZEL, 1.5 HYBRID X (A)	<b>Chassis No:</b>	RU31227039
<b>Reg. Date:</b>	24/04/2019 (Man. Year: 2016)	<b>Odometer:</b>	37814 km
<b>Colour:</b>	Gold		
<b>Engine Capacity:</b>	1496 cc		
<b>Market Value/New Car Price:</b>	N/A		
<b>Sum Insured (\$\$):</b>	Market Value/New Car Price		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

<b>General Condition:</b>		<b>Steering (Serviceable):</b>	Yes	<b>Footbrake (Serviceable):</b>	Yes
<b>Handbrake (Serviceable):</b>	Yes	<b>Engine Modification:</b>	No	<b>Pre-accident Condition:</b>	

**CONDITION OF TYRES**

<b>Front Tyre Size:</b>	215/60R16	<b>Rear Tyre Size:</b>	215/60R16
<b>Front Left Side:</b>	Dunlop 8 mm	<b>Rear Left Side:</b>	Dunlop 8 mm
<b>Front Right Side:</b>	Dunlop 8 mm	<b>Rear Right Side:</b>	Dunlop 8 mm

The above values represent the remaining tyre treads depth

**COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %	
Parts	11,728.44	9,240.88	2,487.56	21.21	
Miscellaneous Items	0.00	0.00	0.00		
Labour	3,130.00	2,440.00	690.00	22.04	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
<b>Calculated Gross Total (\$\$)</b>	<b>14,858.44</b>	<b>11,680.88</b>	<b>3,177.56</b>	<b>21.39</b>	
<b>Approved Total (Overridden) (\$\$)</b>		<b>9,300.00</b>			
	<b>(\$\$)</b>	14,858.44	9,300.00	5,558.44	37.41
	<b>+ GST 7.00/7.00% (\$\$)</b>	1,040.09	651.00	389.09	37.41
	<b>Nett Amount (\$\$)</b>	<b>15,898.53</b>	<b>9,951.00</b>	<b>5,947.53</b>	<b>37.41</b>

**INSPECTION**

<b>Date of Assignment:</b>	02/10/2019		
<b>Date Inspected:</b>	01/10/2019	<b>Inspected At:</b>	Focus Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #02-48/50 Autobay Singapore 417883
<b>Estimated Period of Repair:</b>	8.0 days		

Adjuster: MARCUS CHUA

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

*knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 10 Oct 2019)	
<b>Parts:</b> M1-SUV	HONDA VEZEL 1.5 HYBRID X (A) (Catalogue:Merimen Singapore 1.0)	
<b>Labour:</b> Repairer's	(Price-denominated Standard List)	
<b>Print Code:</b>	(Unsubmitted, no print-code for SMK7807G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.		

### Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BOOT	Badly Dented	1,100.00 FL	*953.00 FL
2	2	*REAR BOOT HINGE	Not Necessary	96.40 FL	*- FL
3	2	*REAR BOOT SHOCK ABSORBER	Not Necessary	384.20 FL	*- FL
4	1	*REAR BOOT RUBBER	Twisted	135.20 FL	*135.20 FL
5	1	*REAR BOOT LOCK	Twisted/Bent	181.90 FL	*181.90 FL
6	1	*REAR BOOT LOCK CATCH	Not Necessary	48.60 FL	*- FL
7	1	*REAR BOOT EMBLEM (VEZEL)	Necessary	56.20 FL	*56.20 FL
8	1	*REAR BOOT EMBLEM (HYBRID)	Necessary	57.40 FL	*57.40 FL
9	2	*REAR BOOT REFLECTOR LAMP	Cracked	729.20 FL	*729.20 FL
10	1	*REAR BOOT CENTRE LOGO	Necessary	58.20 FL	*58.20 FL
11	1	*REAR BOOT CENTRE GARNISH	Bent/Cracked	365.70 FL	*365.70 FL
12	1	*REAR BOOT INNER COVER BOARD	Warped/Deformed	368.20 FL	*368.20 FL
13	1	*REAR BOOT PULL HANDLE GARNISH	Twisted	50.40 FL	*50.40 FL
14	1	*REAR WINDSCREEN	Shattered	1,350.00 FL	*1,280.00 FL
15	1	*REAR WINDSCREEN SEAL	Necessary	120.00 FL	*64.80 FL
16	1	*REAR WIPER MOTOR	Not Necessary	389.40 FL	*- FL
17	1	*REAR WIPER BLADE	Not Necessary	60.20 FL	*- FL
18	2	*REAR WINDSCREEN INNER SIDE GARNISH	Not Necessary	208.40 FL	*- FL
19	2	*REAR FENDER INNER SIDE GARNISH	Deformed/Cracked	758.60 FL	*758.60 FL
20	1	*REAR FLOOR PANEL	Crumpled/Buckled	1,330.20 FL	*1,120.00 FL
21	1	*REAR FLOOR PANEL TOP COVER BOARD	Warped	428.70 FL	*428.70 FL
22	1	*REAR TOOL TRAY	Cracked/Twisted	326.90 FL	*326.90 FL
23	2	*REAR TAIL LAMP	Cracked	972.40 FL	*972.40 FL
24	2	*REAR TAIL LAMP CLIPSE	Not Necessary	17.00 FL	*- FL
25	2	*ROOF TOP PANEL	Not Necessary	208.40 FL	*- FL
26	1	*REAR END PANEL	Badly Dented	614.30 FL	*517.40 FL
27	1	*REAR END PANEL TOP GARNISH	Distorted	199.30 FL	*199.30 FL
28	1	*REAR SMART SENSOR	Cracked	259.20 FL	*259.20 FL
29	1	*REAR BUMPER	Distorted	863.50 FL	*721.00 FL
30	2	*REAR BUMPER SIDE RETAINER	Not Necessary	97.20 FL	*- FL
31	2	*REAR BUMPER SIDE	Dented/Deformed	591.60 FL	*591.60 FL
32	1	*REAR BUMPER UNDER COVER	Warped	186.40 FL	*186.40 FL
33	4	*REAR BUMPER LOWER CLIPSE	Necessary	22.00 FL	*22.00 FL
34	1	*REAR WHEEL ARC PROTECTOR-LH	Torn	172.40 FL	*172.40 FL
35	1	*REAR EXHAUST SILENCER	Not Necessary	77.40 FL	*- FL
36	2	*REAR EXHAUST RUBBER	Not Necessary	69.80 FL	*- FL
37	1	*REAR EXHAUST CHROME PIPE	Not Necessary	120.20 FL	*- FL
38	1	*REAR BOOT TOP SPOILER	Cracked	786.20 FL	*650.00 FL
39	2	*REAR NUMBER PLATE LAMP	Not Necessary	84.40 FS	*- FS
40	1	*REAR WINDSCREEN STICKER-PRIVATE HIRER	Necessary	80.00 FS	*20.00 FS
41	1	*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
42	1	*SET REAR BUMPER SENSOR	Shorted	300.00 FS	*200.00 FS
43	1	*REAR NUMBER PLATE	Serviceable	50.00 FS	*- FS
44	1	*REAR REVERSE CAMERA	Serviceable	45.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
F=Franchise part. S=SpcNett. L=ListItemDisc.							
					<b>Sub Total (\$\$)</b>	<b>14,500.70</b>	<b>11,486.10</b>
					<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>2,772.26</b>	<b>2,245.22</b>
					<b>Total Parts (\$\$)</b>	<b>11,728.44</b>	<b>9,240.88</b>

Report was unsubmitted during this print-out.

### Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TOWING	New	50.00	0.00
2	PANEL BEATING	New	1,600.00	1,200.00
3	CHECK WIRING	New	80.00	30.00
4	RUST PROOFING	New	80.00	80.00
5	TO REMOVE & REFIT REAR WINDSCREEN	New	160.00	120.00
6	TO REMOVE & REPLACE BUMPER SENSOR	New	80.00	50.00
7	TO REMOVE & REPLACE EXHAUST SILENSER	New	80.00	60.00
8	TO SPRAY PAINTING	New	1,000.00	900.00
<b>Gross Labour Cost (S\$)</b>			<b>3,130.00</b>	<b>2,440.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >