

2/8/2002

ASS. REC. BY:

REF:

CS/SMO1967349/ US f3<sup>n2</sup>

Special Instruction:

Surveyor: MARCUS

ASSIGNMENT (Office)

From (Person): Gnoh Pau Loong of SMODate/Time: 2.10.19 14.37p.m

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SKD 1635KInsured: SDS 6600at Workshop m/s Yew Tee AutomobileTel: 67623113of Blk 29 Kaki Bukit Road 4 #01-61Policy No: DIGMTPV01001224Claim No: CHM71902396

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

Make of Veh:  
(Client's Record)D.O.A. 27.4.2019

CA / REV / REP. / REV 24 HRS

"rup"

H.O.D. Endorsement:

Date/Time: 2.10.19 2.55pmPerson Contacted: mayVehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SKD 1635K - C03/msg/4003024/ Agt 3 ROA - 17/02/2014
	SDS 6600 - X

ASS. REC. BY:

REF: SMO

## ASSIGNMENT

From:

Date:

4. 10. 2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKD 1635K

at Workshop m/s

Yew Tee Automobile

of 25 Kaki Bukit Road 4 #01-61 Synergy

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

11.00 am Owner using

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2

days

Res.: Yes or No

Lum Sum:

1.51

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

rup

Vehicle: IN / OUT

Date:

Person Contacted:

17A25962

Veh No:

SKD 1635K

Yr Regn:

11, 11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA7

Make:

Honda Stream

c.c

1799

Colour:

silver

A/C:

Insured / Std / NI / NA

Sp. Reading

185267

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

RN 61087011

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

215/50 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

27/4/19

D.O.I.

4/10/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

2/5 then

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4/10/19

confirmed final by \$560 with may

(\$ 2,781.80 Red - 83%)

RECEIVED 4 OCT 2019

Date/Time, File Pass to?

1)

4/10/19

Date/Time, File Return to?

2)

Rep. Format:

Lump Sum / P/P

☐ : Preli. Report☒ : Final Report

Days Of Repair:

2 /

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

250

11

261

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: GNOH PAU LOONG

Date: 04 Oct 2019

**Preliminary Advice**

Insured Vehicle No	: SDS6260D	Accident Date	: 27/04/2019
TP Vehicle No	: SKD1635K	Assignment Date	: 02/10/2019
Make	: HONDA STREAM	Est. Duration of Repair	: 2 days
Date of Inspection	: 04/10/2019		
Inspection At	: Yew Tee Automobile Tech Pte Ltd (Kaki Bukit) Blk 25 Kaki Bukit Road 4, #01-61 SYNERGY @ KAKI BUKIT Singapore 417800		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages o/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,341.80
Revised Amount	:S\$	560.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	560.00
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : TP : WP

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 May 2019		02 Oct 2019 14:37 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>LIM KONG LENG</b> , ID: S1318769Z								
Main Claimant:	<b>LIM BOON SENG</b> , ID: S7819719F								
Vehicle Reg. No.:	<b>SKD1635K</b>	Date of Loss:	27/04/2019 12:00 - :59						
Claim Type:	<b>TP / CMTD1902396</b>	Policy/Cover Note No.:	D19MTPV01001224 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SDS6260D</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)</b> Blk 25 Kaki Bukit Road 4, #01-61 SYNERGY @ KAKI BUKIT, 417800 Kaki Bukit - Tel: 67023113								
Handling Insurer:	<b>Sompo Insurance Singapore Pte. Ltd. (HQ)</b> - Tel: 6461 6555 ... [Handled by <b>GNOH PAU LOONG</b> - 63295217]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... <b>[Final Rpt due 11/10/2019]</b>								
Driver/Custodian (Insured):	<b>CHEE HUEY MIEN</b> (), NRIC: S1403079D, Tel: +6592303136 Email:								
Adj Asg. Remarks:	<b>MAY 6702 3113</b>								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a> </span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

YOUR NEW BMW AWAITS WITH CARS@EXPO DEALS

Find out more

Post an Advertisement

Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

\$59000 Honda Jazz Aug 2017 low mileage and low usage

Cheapest in market, zero  
accident and scratch. View the  
ultra economical car  
StarAdAutoInn  
An Inspiration For Car Buyersclick here to view  
our **PRISTINE USED CARS**  
at **GREAT PRICES**

Browse by Category

Sort by Date Posted 20 results/page

1 vehicles

Stream

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	Stream		Any	Any	2011	Any	Any	Any	Available
	Honda	Stream 1.8A Style Edition	\$28,555	\$10,960 /yr	16-Mar-2011	1,799 cc	124,695 km	MPV	Available
(High Specification Style Edition Model!) Purchase Comes With 6 Months Certified Pre Owned Car Warranty With 24/7 Roadside Assistan...									
Sincere Motoring Pte Ltd									
Posted: 01-Oct-2019 Tags: 2011 Honda Stream, 2011.honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda									

Save this search criteria, to get email alerts whenever a match is found.

For old advertisements, view Expired ads

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Stream, Stream Singapore, used Stream Singapore, used Stream, used vehicles Singapore or even buy used Stream Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

Compare

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 719F

### Vehicle Details

Vehicle No.: SKD1635K  
Vehicle to be Exported: No  
Intended Deregistration Date: 04 Oct 2019  
Vehicle Make: HONDA  
Vehicle Model: STREAM 1.8 A  
Primary Colour: Silver  
Manufacturing Year: 2008  
Engine No.: R18A1796444  
Chassis No.: RN61087011  
Maximum Power Output: 103.0 kW (138 bhp)  
Open Market Value: \$21,681.00  
Original Registration Date: 01 Nov 2011  
First Registration Date: 01 Nov 2011  
Transfer Count: 1  
Actual ARF Paid: \$21,681.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 31 Oct 2021  
PARF Rebate Amount: \$13,008.00

### Intended COE Rebate Details

COE Expiry Date: 31 Oct 2021  
COE Category: E - Open Category  
COE Period(Years): 10  
QP Paid: \$62,502.00  
COE Rebate Amount: \$12,954.00  
**Total Rebate Amount: \$25,962.00**

The information contained herein is correct as at 04 Oct 2019

OK

**Yew Tee Automobile Tech Pte Ltd** (Co.Reg.No.200311009C)

Synergy@kb 25 Kaki Bukit Road 4 #01-60/61  
Singapore 417800

Tel: 67023113 Fax: 67023773 Email: YTKB

**INSURER :****PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	
Policy No:	5104960871	Date of Loss:	27/04/2019
Vehicle Reg. No.:	<b>SKD1635K</b>	Driveable?	no
Driver Age:	03/07/1978	Third Party Vehicle No.:	SDS6260D
Any Injuries?	no	Contact No:	97692605
Insured/Claimant:	LIM BOON SENG	Driver:	LIM BOON SENG

Make/Model:	Honda, Stream	Vehicle Reg. Date:	01 Nov 2011
Vehicle Colour:		Engine Number:	
Chassis No:	RN61087011	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	

**Description of Accident/loss****Remarks:**

Present Location: Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)-YTKB

**COST OF CLAIMS**

	Amount
Parts	1,756.80
Miscellaneous Items	0.00
Labour	880.00
Paintwork Labour	705.00
Towing	0.00
<b>Gross Total(S\$):</b>	<b>3,341.80</b>
<b>GST 7.00%(S\$):</b>	<b>233.93</b>
<b>Nett Amount(S\$):</b>	<b>3,575.73</b>

This claim is handled by: Sky Toh T C

UKK Auto Consultants hence notify the Repairer of the following:

- To rectify before/after spray painting
- To rectify damaged part(s) during recovery
- Parts of loss are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No litigation/meditation(s) is allowed
- Supplementary item(s) must be re-approved and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Not Authorized  
2/2/19

Take photo After rep -

2 day

4/10/19

P/P \$ 560/-

**REPAIR DETAILS****Estimates On Parts**

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR RH FENDER	958.00	-20.00	766.40
2	1	REAR BUMPER	688.00	-20.00	550.40
3	1	REAR RH RIM	300.00	-20.00	240.00
4	1	REAR RH TYRE	250.00	-20.00	200.00
<b>Total Parts (\$\$)</b>					<b>1,756.80</b>

**Estimates of Miscellaneous Items**

No.	Qty	Particulars	Amount	%Disc	After Disc
<b>Sub Total (\$\$)</b>					<b>0.00</b>

**Estimates On Labour**

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	800.00	0.00	800.00
2	1	To Conduct Computer Wheel Alignment.	80.00	0.00	80.00
<b>Gross Labour Cost (\$\$)</b>					<b>880.00</b>

**Estimates On Paint Work Labour**

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	60.00	0.00	60.00
2	1	To Supply Spray Terostat Sealant On The Cutting Areas.	45.00	0.00	45.00
3	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	600.00	0.00	600.00
<b>Gross Labour Cost (\$\$)</b>					<b>705.00</b>

&lt; END OF ESTIMATES &gt;



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19017349/USF3N2  
Date: 08/10/2019

## REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTPV01001224
Claimant Vehicle No :	SKD1635K	Insured Vehicle No :	SDS6260D
Date of Loss:	27/04/2019	Nature of Claim:	TP
		Claim No:	CMTD1902396

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SKD1635K	Engine No:	R18A1796444
Make & Model:	HONDA STREAM, 1.7 (A)	Chassis No:	RN61087011
Reg. Date:	01/11/2011 (Man. Year: 2008)	Odometer:	185267 km
Colour:	Silver		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	215/50R17	Rear Tyre Size:	215/50R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,756.80	0.00	1,756.80	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,585.00	560.00	1,025.00	64.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>3,341.80</b>	<b>560.00</b>	<b>2,781.80</b>	<b>83.24</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>233.93</b>	<b>39.20</b>	<b>194.73</b>	<b>83.24</b>
<b>Nett Amount (S\$)</b>	<b>3,575.73</b>	<b>599.20</b>	<b>2,976.53</b>	<b>83.24</b>

## INSPECTION

Date of Assignment:	02/10/2019	
Date Inspected:	04/10/2019	Inspected At:
		Yew Tee Automobile Tech Pte Ltd (Kaki Bukit) Blk 25 Kaki Bukit Road 4, #01-61 SYNERGY @ KAKI BUKIT Singapore 417800

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 08 Oct 2019)
<b>Parts:</b> M1-MPV	HONDA STREAM 1.7 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SKD1635K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH FENDER	Repair	958.00 FL	*- FL
2	1		*REAR BUMPER	Repair	688.00 FL	*- FL
3	1		*REAR RH RIM	Repair	300.00 FL	*- FL
4	1		*REAR RH TYRE	Not Necessary	250.00 FL	*- FL
					<b>Sub Total (\$\$)</b>	<b>2,196.00 0.00</b>
					<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>439.20 0.00</b>
					<b>Total Parts (\$\$)</b>	<b>1,756.80 0.00</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS,STRAIGHTEN,KNOCK OUT,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS.TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	800.00	100.00
2	TO CONDUCT COMPUTER WHEEL ALIGNMENT	New	80.00	60.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION	New	60.00	0.00
4	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS	New	45.00	0.00
5	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS.PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER,CLEANING AND SANDING OF SURFACES,FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	600.00	400.00
Gross Labour Cost (S\$)			1,585.00	560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >