

20711



PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Selamatshahh
CLAIM DEPARTMENT
DID : 66547519
FAX :

Date : 03/10/2019

To : INDIA INTERNATIONAL INSURANCE PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : NEO SENG WEE

: AIG ASIA PACIFIC INSURANCE PTE. LTD.

Certificate No : 1800071237

Accident Date : 15/09/2019

Vehicle No : SLQ-5623-M

Make & Model : HONDA FREED 1.5L E AT

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
-----	-------------	-------------------	---------------

List Item

1	FRONT BUMPER <i>de</i>	1,014.10	
1	FRONT BUMPER RETAINER LH <i>X SVC</i>	44.70	
10	FRONT BUMPER CLIPS <i>nu</i>	50.00	

Sub Total

1108.80

Discount 20% On Parts

(221.76)

Labour & Misc

LABOUR TO FACILITATE REPAIR

700 400.00

TO RESPRAY AFFECTED AREAS

200 400.00

Date : 03/10/2019
 To : INDIA INTERNATIONAL INSURANCE PTE LTD
ESTIMATION
 Attn : Motor Claim Department FAX :

Owner : NEO SENG WEE
 : AIG ASIA PACIFIC INSURANCE PTE. LTD.
 Certificate No : 1800071237 Accident Date : 15/09/2019
 Vehicle No : SLQ-5623-M Make & Model : HONDA FREED 1.5L E AT

ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
-----	-------------	-------------------	---------------

Sub Total

800.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Remarks:

1,687.04

2 days - p/p - Resurvey before paint

SUB TOTAL
 GST 7.0 % 118.09
 TOTAL 1,805.13

Surveyor's name: Rasid - 170 900 10068
 Principal's name: NEO SENG WEE
 Survey Date & Time: 04/10/19 @ 0955

Date : 12/11/2019

To : INDIA INTERNATIONAL INSURANCE PTE LTD

Attn : Motor Claim Department

FAX :

Owner : NEO SENG WEE

Insured By : AIG ASIA PACIFIC INSURANCE PTE. LTD.

Certificate No : 1800071237 Accident Date : 15/09/2019

Vehicle No : SLQ-5623-M Make & Model : HONDA FREED 1.5L E AT

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
List Item			
1	FRONT BUMPER	1014.10	1014.10
1	FRONT BUMPER RETAINER LH	44.70	0.00
10	FRONT BUMPER CLIPS	50.00	50.00
	Sub Total	1108.80	1064.10
	Discount 20% On Parts	(0.00)	(212.82)
Labour & Misc			
	LABOUR TO FACILITATE REPAIR	400.00	200.00
	TO RESPRAY AFFECTED AREAS	400.00	200.00
	Sub Total	800.00	400.00

Date : 12/11/2019
To : **INDIA INTERNATIONAL INSURANCE PTE LTD**

Attn : **Motor Claim Department** FAX :

Owner : NEO SENG WEE
Insured By : AIG ASIA PACIFIC INSURANCE PTE. LTD.
Certificate No : 1800071237 Accident Date : 15/09/2019
Vehicle No : SLQ-5623-M Make & Model : HONDA FREED 1.5L E AT

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
	Sub Total	1,687.04	1,251.28
	GST 7.0 %	118.09	87.59
	Total	1,805.13	1,338.87

Surveyor Name : RASUL - LKK

Date & Time : 04/10/2019 9:55:00 AM

Selamatshahh

PAGE: 2

CLAIM DEPARTMENT

DID : 66547519

FAX :