

ASSIGNMENT

From

Date 2/10

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKJ 1543K

at Workshop n/s Premium Auto.

at 281 Alexandra Rd

Insured:

Policy No

Claims No:

Sum Insured:

Excess: 1500

(Client's Record)

10am-11am

Make of Veh:

George wing

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

163K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKJ 1543K

Yr Regn: 2018 / FEB

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi Q5 Sport 2.0TFSI

c.c. 1984

Colour:

BLUE

A/C: Insured / Std / NI / NA

Sp. Reading:

20203

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WAUZZZF40J2071216

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

235/35R19

R:

1.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

CONTINENTAL

Front

Rear

R/Bal

6

mm

R/Bal

6

mm

L/Bal

6

mm

L/Bal

6

mm

D.O.A.

28/01/19

D.O.I.

02/10/19

Survey held at

PREMIUM

Des. of Damages: Fnt / Rear / O/S / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

SKJ 1543K - <

RECEIVED 06 MAR 2020

03/10/19

@ 10:12 am revised PA to AIG v/c merimen

03/10/19

@ 10:22 am mandate request authorize repair to AIG

v/c merimen

7/10/19

Rece approved \$10,243 from Victor by merimen

7/10/19

Informed George c/A & \$1500 by email

Rasul Confirmed P/P \$9,522.00 @ 5 days with Bass.
(\$8,152.00 Real - 86%)

Date/Time: File Page 107



Prel. Report

11 Typ 4



Final Report

Date/Time: File Page 107

9

Add'l Fee:



Site Insp. (\$



Interview (\$



Tech. Insp. (\$



Witness (\$

Report Form 1

Comp & Ins 1.5.0

\$9,522/- P/P

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

200

3 + 15.00

11

Phone:

Video:

Total:

211

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Nadaraja, Deeban

Date: 04 Oct 2019

Preliminary Advice

Vehicle No	: SKJ1543K	Accident Date	: 28/09/2019
Make	: AUDI Q5	Policy No.	: 1800006977
Assignment Date	: 03/10/2019	Excess	: S\$1,500.00
Date of Inspection	: 02/10/2019	Est. Duration of Repair	: 5 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,674.00
Revised Amount	:S\$	10,243.00
Check Items (Estimated)	:S\$	1,371.00
Total	:S\$	11,614.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	163,000.00
COE / PARF Rebate	:S\$	78,893.00
Salvage Value	:S\$	
Margin for Repair	:S\$	84,107.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :



LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 03 Oct 2019

Preliminary Advice

Vehicle No	: SKJ1543K	Accident Date	: 28/09/2019
Make	: AUDI Q5	Policy No.	: 1800006977
Assignment Date	: 03/10/2019	Excess	: S\$0.00
Date of Inspection	: 02/10/2019	Est. Duration of Repair	: 6 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,674.00
Revised Amount	:S\$	12,005.00
Check Items (Estimated)	:S\$	1,371.00
Total	:S\$	13,376.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	163,000.00
COE / PARF Rebate	:S\$	78,893.00
Salvage Value	:S\$	
Margin for Repair	:S\$	84,107.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Thursday, 19 December 2019 6:28 pm
To: jiajee.yap@premiumauto.com.sg
Cc: SUR
Subject: RE: FINAL REVISION - SKJ1543K - OD AIG - SURVEYED 02 OCT 19

Dear Jia Yee,

Confirmed final fig \$ 9,522.00 @ 5 days of repairs before excess \$ 1,500/- & GST.

Kindly expedite the discharge voucher and tax invoice to us for close case.

"Best Wishes for Merry Christmas & Happy New Year 2020"

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jiajee.yap@premiumauto.com.sg <jiajee.yap@premiumauto.com.sg>
Sent: Tuesday, 17 December 2019 11:32 am
To: Rasul (LKKAuto) <Rasul@lkkauto.com>
Cc: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Subject: FINAL REVISION - SKJ1543K - OD AIG - SURVEYED 02 OCT 19

Hi Rasul and all,

Revised estimate is attached.

Please confirm repair cost of \$9522.00 @ 5 days

Your early closure is well appreciated.

Thanks & Best Regard
JiaYee Yap
Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902273W)
55 Ubi Road 1 Road Singapore 408699

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 7 October 2019 1:53 PM
To: Claims; SUR
Cc: (nora.khai@premiumauto.com.sg)
Subject: RE: OD CLAIMS FOR SKJ 1543 K -DOA: 28/9/2019

Dear George,

As instructed by our client , please proceed to repair the **insured vehicle SKJ 1543K (Excess S1500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler **on behalf of Shirley**

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>
Sent: Saturday, 28 September 2019 5:23 PM
To: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: claims@premiumauto.com.sg
Subject: OD CLAIMS FOR SKJ 1543 K

Dear all,

Please register Own policy claims for the above mentioned vehicle.

Kindly arrange for survey on 2 of Oct @ 10am. Owner waiting

Address : 281 Alexandra Road Singapore 159938

Thank you.

Best Regards,
George Wong
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)
281 Alexandra Road Singapore 159938

p. +65 6366 2323, option 1

e. Claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom 281 Alexandra Road Singapore 159938 p. +65 68362223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

View Received Message

This mail is associated with :

***SKJ1543K (3215235247SG)**

OD

Sep 28 2019 1:00PM

[WEIBEL OTTO]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 07/10/2019 12:40 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$10243.00) - SKJ1543K - Claim Handler: Nadaraja, Deeban

Approved:10243.00:Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

Re: SLZ9362S/ TP / 3215235247SG



Shirley Hiew (LKK Auto)

Fri 4/10/2019 5:49 PM

To: Koh, Victor-CK <Victor-CK.Koh@aig.com>; SUR <sur@lkkauto.com>; Bryan Ang (LKKAuto) <bryanang@lkkauto.com>
Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>

Hi Victor,

According to our surveyor, in order not to delay authorization, we have reviewed and re-seek mandate less both door handle, rear LH fender & rear LH wheel arch. Labour & spray paint reduce to \$ 1,000.00 & \$ 1,375.00.

However subject to Premium clarification with their driver.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Sent: Friday, 4 October 2019 3:50 PM

To: Koh, Victor-CK <Victor-CK.Koh@aig.com>; SUR <sur@lkkauto.com>; Bryan Ang (LKKAuto) <bryanang@lkkauto.com>

Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>

Subject: Re: SLZ9362S/ TP / 3215235247SG

Hi Victor,

We will check and revert.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)


From: Koh, Victor-CK <Victor-CK.Koh@aig.com>

Sent: Friday, 4 October 2019 3:11 PM

To: SUR <sur@lkkauto.com>; Bryan Ang (LKKAuto) <bryanang@lkkauto.com>

Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>

Subject: SLZ9362S/ TP / 3215235247SG

Hi

Kindly re-confirm on the consistent damage parts. I believe some parts given are not consistent with the accident.

Attach is the TP damage photos. To re-adjust labour and parts and re-submit for mandate approval.

Thanks & Regards

Victor Koh
AIG
Claims Technical Controller
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120
Tel +65 6419 1785 | Fax +65 68357416
Victor-ck.koh@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

SLZ9362S/ TP / 3215235247SG

Koh, Victor-CK <Victor-CK.Koh@aig.com>

Fri 4/10/2019 3:12 PM

To: SUR <sur@lkkauto.com>; Bryan Ang (LKKAuto) <bryanang@lkkauto.com>

Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>

1 attachments (1 MB)

SLZ9362S.pdf;

Hi

Kindly re-confirm on the consistent damage parts. I believe some parts given are not consistent with the accident.

Attach is the TP damage photos. To re-adjust labour and parts and re-submit for mandate approval.

Thanks & Regards

Victor Koh

AIG

Claims Technical Controller

Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120

Tel +65 6419 1785 | Fax +65 68357416

Victor-ck.koh@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

In order not to delay endorsement,

WE have reviewed and re-subc
less
mandate less these ~~and parts~~

Subject to Plummer
clarification with
the ~~new~~ MIA.

Noted and re-confirm that and
(both door handle, rear LH fender
& rear LH wheel arch) is not consistent
to the accident (labour & spray paint
reduce to 1000 & 137.5) and no. of
repairs is 4-5 days)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	386E
Vehicle Details	
Vehicle No.:	SKJ1543K
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Oct 2019
Vehicle Make:	AUDI
Vehicle Model:	Q5 SPORT 2.0 TFSI QU S TRONIC
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	DAX023434
Chassis No.:	WAUZZZFV0J2071216
Maximum Power Output:	185.0 kW (248 bhp)
Open Market Value:	\$44,883.00
Original Registration Date:	06 Feb 2018
First Registration Date:	06 Feb 2018
Transfer Count:	0
Actual ARF Paid:	\$54,837.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Feb 2028
PARF Rebate Amount:	\$41,127.00
Intended COE Rebate Details	
COE Expiry Date:	05 Feb 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,289.00
COE Rebate Amount:	\$37,766.00
Total Rebate Amount:	\$78,893.00

The information contained herein is correct as at 03 Oct 2019

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	386E
Vehicle Details	
Vehicle No.:	SKJ1543K
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Oct 2019
Vehicle Make:	AUDI
Vehicle Model:	Q5 SPORT 2.0 TFSI QU 5 TRONIC
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	DAX023434
Chassis No.:	WAUZZZF0J2071216
Maximum Power Output:	185.0 kW (248 bhp)
Open Market Value:	\$44,883.00
Original Registration Date:	06 Feb 2018
First Registration Date:	06 Feb 2018
Transfer Count:	0
Actual ARF Paid:	\$54,837.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Feb 2028
PARF Rebate Amount:	\$41,127.00
Intended COE Rebate Details	
COE Expiry Date:	05 Feb 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,289.00
COE Rebate Amount:	\$37,766.00
Total Rebate Amount:	\$78,893.00

The information contained herein is correct as at 03 Oct 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/09/2019 16:54
Date Of Accident	28/09/2019 13:45
Exact Location Of Accident	BOULEVARD TO NICOLE HIGHWAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKJ1543K
Insured/Policyholder	
Name Of Registered Owner	WEIBEL OTTO
NRIC No	S2633386E
Email Address	WEIBEL.OTTO@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96651579
Alternative Phone No	OFFICE-96651579

Vehicle Particulars

Manufacturer	AUDI
Model	Q5 2.0 TFSI
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800006977
Cover Note Number	

Driver

Name of Driver	WEIBEL OTTO
NRIC No	S2633386E
Date Of Birth	26/11/1946
Occupation	INDOOR
Date Of Driving Pass	24/02/1986
Driving Experience	33 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96651579
Fax Number	
Contact Number	OFFICE-96651579
Email Address	WEIBEL.OTTO@GMAIL.COM

Address	BRADDEL HILL #03-58, BRADDEL VIEW
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I'M OTTO WEIBEL DRIVE FROM STATION BOULEVARD TO NICOLE HIGHWAY AT AROUND 1.45PM, 28 OF SEPT 2019, WHEN A MERCEDES NO. SLZ 9362 S DRIVED BY MR. TAI CHUNG HAO, COLLIDED WITH MY CAR ON THE LEFT SIDE.

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLZ9362S
Vehicle Make/Model/Colour	MERCEDES
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAI CHUNG HAO
NRIC/Passport Number	S8660375F
Contact Number	90211731
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan #2

SKETCH PLAN



A - SKJ 1543K
B - SLZ 9362S

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I'm Otto Weibel drive from
Station Boulevard to Nicole Highway at
around 1.45pm 28 Sept. 2019
When a Mercedes No SLZ 9362 S
Driven by Mr. Lai Ching Hao
collided with my car on the left side

DECLARATION

(We declare the foregoing particulars are true to every respect)

Policyholder's Signature

Date & Time:

28 Sept. 2019

3.10pm

Driver's Signature

(If driver is not the policyholder)

Date & Time:


28 Sept. 2019

3.10pm

Reporting Centre Personnel's Signature

Name: Wally James SKJ 1543K

NRIC/PIN No: G248243K



Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time: 3.20 PM
28 Sept. 2015

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Wendy Kishita Sanku Kany
NRIC/IN No.: 22587183X



Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP:14109

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1171/2019/KK
Date : 30-Sep-19

Vehicle Not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Weibel Otto
Address : Blk 10M Bradell Hill
: #03-58
Singapore 579731
Telephone : HP +65 96651579
Type of Claim : Own Damage Claims
Policy No. : 1800006977
Vehicle No : **SKJ 1543 K**
Model Code : Audi Q5 SPORT 2.0 TFSI
Model / Year : 06-02-18
Engine No : DAX 023434
Chassis No : WAUZZZF0J2071216
Mileage :
Date In :
Estimated By : Johnny Boo / Allan Wu
Accident Date : 28-Sep-19
Place of Accident : Boulevard To Nicole Highway

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKJ 1543 K

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer lhs front door and lhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N \$ 560.00	
2	To dismanle and renew lhs front door and lhs rear door. To repair lhs rear fender. Re-organise crash management components. Reinstall all parts removed.	\$ 2,800.00	1250 1000
3	To respray lhs front door, lhs rear door, door handle, door covers, lhs rear fender and lhs rear wheel arch trim.	\$ 4,400.00	2100
4	To carry out diagnostic checks.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 7,952.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKJ 1543 K

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT DOOR <i>bt</i>	\$ 2,829.00	2263.20
2	FRONT DOOR SEAL - OUTER ? <i>neu</i>	\$ 185.00	✓147.60
3	BONDING AGENT <i>neu</i>	\$ 45.00	35.92
4	CLEANING SOLUTION <i>neu</i>	\$ 65.00	51.68
5	FRONT DOOR ATTACHMENT PARTS ? <i>X svc</i>	\$ 239.00	X
6	FRONT DOOR CATCH <i>X svc</i>	\$ 132.00	
7	FRONT DOOR COVER - LH <i>see</i>	\$ 661.00	528.80
8	REAR DOOR <i>bt</i>	\$ 2,829.00	2263.20
9	REAR DOOR BRACKET SEAL ? <i>X svc</i>	\$ 40.00	X
10	REAR DOOR SEAL - OUTER ? <i>neu</i>	\$ 190.00	✓152.00
11	BONDING AGENT <i>neu</i>	\$ 45.00	35.92
12	CLEANING SOLUTION <i>neu tan</i>	\$ 65.00	X
13	REAR DOOR SEALING STRIP ? <i>X svc</i>	\$ 15.00	X
14	REAR DOOR ATTACHMENT PARTS ? <i>X svc</i>	\$ 201.00	X
15	REAR DOOR CATCH <i>X svc</i>	\$ 132.00	
16	REAR DOOR SEAL - OUTER LH ? <i>X svc</i>	\$ 201.00	X
17	REAR DOOR COVER - LH <i>cr</i>	\$ 577.00	✓461.20
18	SILL PANEL SEAL - LH <i>X svc</i>	\$ 234.00	
19	DOOR HANDLE TRIM PLATE - LH <i>X svc</i>	\$ 250.00	
20	REAR WHEEL COVER - LH <i>neu tan</i>	\$ 487.00	
21	SUNDRIES ? <i>neu</i>	\$ 300.00	✓30.48
TOTAL SPARE PARTS CHARGES		\$ 9,722.00	
TOTAL LABOUR CHARGES		\$ 7,952.00	
GRAND TOTAL		\$ 17,674.00	

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Rasul - Hp 90010068

: 02/10/17 @ 1110

: 6 days 4-5 days

: Resy before paint

5 days

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

UAC Auto Consultancy hereby notify the Repaire of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal recourse(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repaire:

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP:14109

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1171/2019/KK
Date	:	30-Sep-19

Vehicle Not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Rasul,

5 days - ok - Jy - 28 Nov 2019

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Weibel Otto
Address	:	Blk 10M Braddell Hill
	:	#03-58
	:	Singapore 579731
Telephone	:	HP +65 96651579
Type of Claim	:	Own Damage Claims
Policy No.	:	1800006977
Vehicle No	:	SKJ 1543 K
Model Code	:	Audi Q5 SPORT 2.0 TFSI
Model / Year	:	06/02/2018
Engine No	:	DAX 023434
Chassis No	:	WAUZZZF0J2071216
Mileage	:	
Date In	:	
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	28-Sep-19
Place of Accident	:	Boulevard To Nicole Highway

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKJ 1543 K

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer lhs front door and lhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N	\$ 560.00	\$ 560.00
2	To dismanle and renew lhs front door and lhs rear door. To repair lhs rear fender. Re-organise crash management components. Reinstall all parts removed.		\$ 2,800.00	\$ 1,000.00
3	To respray lhs front door, lhs rear door, door handle, door covers, lhs rear fender and lhs rear wheel arch trim.		\$ 4,400.00	\$ 1,800.00
4	To carry out diagnostic checks.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 7,952.00	\$ 3,552.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKJ 1543 K

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT DOOR	\$ 2,829.00	\$ 2,263.20
2	FRONT DOOR SEAL - OUTER	NEC \$ 185.00	\$ 147.60
3	BONDING AGENT	\$ 45.00	\$ 35.92
4	CLEANING SOLUTION	\$ 65.00	\$ 51.68
5	FRONT DOOR ATTACHMENT PARTS	\$ 239.00	
6	FRONT DOOR CATCH	\$ 132.00	
7	FRONT DOOR COVER - LH	\$ 661.00	\$ 528.80
8	REAR DOOR	\$ 2,829.00	\$ 2,263.20
9	REAR DOOR BRACKET SEAL	\$ 40.00	
10	REAR DOOR SEAL - OUTER	NEC \$ 190.00	\$ 152.00
11	BONDING AGENT	\$ 45.00	\$ 35.92
12	CLEANING SOLUTION	\$ 65.00	
13	REAR DOOR SEALING STRIP	\$ 15.00	
14	REAR DOOR ATTACHEMENT PARTS	\$ 201.00	
15	REAR DOOR CATCH	\$ 132.00	
16	REAR DOOR SEAL - OUTER LH	\$ 201.00	
17	REAR DOOR COVER - LH	\$ 577.00	\$ 461.20
18	SILL PANEL SEAL - LH	\$ 234.00	
19	DOOR HANDLE TRIM PLATE - LH	\$ 250.00	
20	REAR WHEEL COVER - LH	\$ 487.00	
21	SUNDRIES	\$ 300.00	\$ 30.48
TOTAL SPARE PARTS CHARGES		\$ 9,722.00	\$ 5,970.00
TOTAL LABOUR CHARGES		\$ 7,952.00	\$ 3,552.00
GRAND TOTAL		\$ 17,674.00	\$ 9,522.00

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved.
Spare parts are Special Nett.

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SKJ 1543 K

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1171/2019/NH

28th February 2020

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SKJ 1543 K, Audi Q5 SPORT 2.0 TFSI QU S-TRONIC.

With reference to the above-mentioned vehicle, no. **SKJ 1543 K**, claimant, **Mr. Weibel Otto**, please find the related document per attached.

1. A copy of the Original invoice no. 85014915 – S\$ 8,583.54.
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – SKJ 1543 K

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6386 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6386 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6386 2323
Main Telefax 6941 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email: customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 15:08

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: B5014915 Date: 27/02/2020 Order: SKJ1543K Term: 30	Account: A0006 (T O) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No: SKJ1543K (V 36533) Regn Date: 06/02/2018 Mileage: 21449 WIP No.: 14109

Model: Q5 SPORT 2.0 TFSI qu S tronic Chassis: WAUZZZF0J2071216 Engine: DAX 023434 Dept: U

You have been assisted by :- UB-Kelvin Khoo (138)

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-1500.00	1.00	-1,500.00
S	BODYWORK	M: TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOOR MULTI LOCK SYSEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES	560.00	1.00	560.00
S	BODYWORK	M: TO DISMANTLE AND RENEW LHS FRONT DOOR AND REAR DOOR.TO REPAIR LHS REAR FENDER. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	1000.00	1.00	1,000.00
S	BODYWORK	M: TO RESPRAY LHS FRONT DOOR,LHS REAR DOOR, DOOR COVER AND LHS WHEEL ARCH TRIM.	1800.00	1.00	1,800.00
S	BODYWORK	M: TO CARRY OUT DIANOSTIC CHECK	192.00	1.00	192.00
X	A80A831051H STL	DOOR(LAST)	Less 020%	1.00	2829.00
X	A80A837911G	SEAL	Less 020%	1.00	184.50
X	AD 355205A2	BONDAGENT	Less 020%	1.00	44.90
X	A80A853959A GRU	(A) (SK) COVER 10/10/1	Less 020%	1.00	661.00
X	A80A833051B STL	(A) (SK) DOOR 10/10/19	Less 020%	1.00	2829.00
X	A80A839151A	(A) (SK) BRACKET 10/10	Less 020%	1.00	38.10
X	A80A839911B	(SK) SEAL	Less 020%	1.00	190.00
X	AD 355205A2	BONDAGENT	Less 020%	1.00	44.90
X	AD 00940104	CLEANER	Less 020%	1.00	64.60
X	A80A853969A GRU	(A) (SK) COVER 21/10/1	Less 020%	1.00	576.50
Parts 5,970.00					Sub-Total 8,022.00
Labour 0.00					7% GST 561.54
Sublet 3,552.00					Grand Total 8,583.54
Menus 0.00					
Lubricant 0.00					



2/2

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SKJ 1543 K

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1171/2019/TG
25 October 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi Q5 SPORT 2.0 TFSI
Vehicle Chassis No. : WAUZZZFY0J2071216
Vehicle Regn No. : **SKJ 1543 K**
Vehicle Mileage : 20784 KM
Vehicle Owner : Mr. Weibel Otto
Certificate No : 1800006977
Own Damage Excess : **S\$ 1605.00 (inclusive 7% GST)**
Accident Date : 28/09/2019
Place : Boulevard to Nicole Highway
Repair Cost : \$ 8583.54
WIP No. : 14109
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time : 2.30 pm
Date : 20/10/2019

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Oct 2019		03 Oct 2019 09:31 Edit Adj Rpt	S\$9,522.00 Edit Estimates	S\$9,522.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured: **WEIBEL OTTO**, ID: S2633386E, Tel: +6596651579, Email: WEIBEL.OTTO@GMAIL.COM

Vehicle Reg. No.: **SKJ1543K** Date of Loss: 28/09/2019 13:00 - :59
[19 Months and 22 Days From LTA Reg Date (Man Yr)]

Claim Type: **OD / 3215235247SG** Policy/Cover Note No.: 1800006977 (Comprehensive)

Excess: S\$1,500.00

Repairer: **Premium Automobiles Pte Ltd (UBI)** 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911

Handling Insurer: **AIG Asia Pacific Insurance Pte. Ltd. (SG)** - Tel: 65-6419-3000 ... [Handled by **Nadaraja, Deeban**]

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **MOHD RASUL**] ... **[Final Rpt due 14/10/2019]**

Driver/Custodian: WEIBEL OTTO (72 / Male) , NRIC: S2633386E, Tel: +6596651579 Email: WEIBEL.OTTO@GMAIL.COM

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (07/10/2019): Alert - Adj Mandate Approved (S\$10243.00) - SKJ1543K - Claim Handler: Nadaraja, ...
- AIG_SG (04/10/2019): Alert - Adj Mandate Maintained - SKJ1543K - Claim Handler: Nadaraja, Deeban
- AIG_SG (04/10/2019): SKJ1543K / OD / 28/09/2019 / Coverage & Excess update

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKJ1543K (3215235247SG)

OD

Sep 28 2019 1:00PM

[WEIBEL OTTO]

Premium Automobiles Pte Ltd

Upload Documents			Upload Photos		Compose New Letter	Upload Video	Upload Audio	View		View in Browser
Assessment Reports								1 per page		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	03/10/19 10:12	Adjuster Immediate Advice						Load HTM		
2	04/10/19 17:44	Adjuster Immediate Advice						Load HTM		
Photos/Images								3 per page		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	03/10/19 10:21	General View						Load JPG		
2	03/10/19 10:21	General View						Load JPG		
3	03/10/19 10:21	General View						Load JPG		
4	03/10/19 10:21	General View						Load JPG		
5	03/10/19 10:21	General View						Load JPG		
6	03/10/19 10:21	General View						Load JPG		
7	03/10/19 10:21	General View						Load JPG		
8	03/10/19 10:21	General View						Load JPG		
9	03/10/19 10:21	General View						Load JPG		
10	03/10/19 10:21	General View						Load JPG		
11	03/10/19 10:21	General View						Load JPG		
12	03/10/19 10:21	General View						Load JPG		
13	03/10/19 10:21	General View						Load JPG		
14	03/10/19 10:21	General View						Load JPG		
15	03/10/19 10:21	General View						Load JPG		
16	03/10/19 10:21	General View						Load JPG		
17	03/10/19 10:21	General View						Load JPG		
18	03/10/19 10:21	General View						Load JPG		
19	03/10/19 10:21	General View						Load JPG		
20	03/10/19 10:21	General View						Load JPG		
21	03/10/19 10:21	General View						Load JPG		
22	03/10/19 10:21	General View						Load JPG		
23	03/10/19 10:21	General View						Load JPG		
24	03/10/19 10:21	General View						Load JPG		
25	03/10/19 10:21	General View						Load JPG		
26	03/10/19 10:21	General View						Load JPG		
27	03/10/19 10:21	General View						Load JPG		
28	03/10/19 10:21	General View						Load JPG		
29	03/10/19 10:21	General View						Load JPG		
30	03/10/19 10:21	General View						Load JPG		
31	03/10/19 10:21	General View						Load JPG		
32	03/10/19 10:21	General View						Load JPG		
33	03/10/19 10:21	General View						Load JPG		
34	03/10/19 10:21	General View						Load JPG		
35	03/10/19 10:21	General View						Load JPG		
36	03/10/19 10:21	General View						Load JPG		
37	16/12/19 17:21	Reinspection Photo						Load JPG		

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	16/12/19 17:21	Reinspection Photo	Load JPG	☒
39	16/12/19 17:21	Reinspection Photo	Load JPG	☒
40	16/12/19 17:21	Reinspection Photo	Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/10/19 10:20	SKJ 1543K GIA.pdf	Load PDF	
2	03/10/19 10:20	ESTIMATE.pdf	Load PDF	
3	04/10/19 10:55	DRIVING & CI.pdf	Load PDF	
4	04/10/19 17:42	ESTIMATE 1.pdf	Load PDF	
5	19/12/19 15:44	ESTIMATE MARKED.pdf	Load PDF	
6	09/03/20 09:27	WORKSHOP INVOICE	Load PDF	
7	09/03/20 09:27	DISCHARGE VOUCHER	Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	06/12/19 18:31	Accident Statement	Load HTM	
2	06/12/19 18:34	Accident Statement	Load HTM	
3	06/12/19 18:35	Accident Statement	Load HTM	
4	06/12/19 18:36	Accident Statement	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	28/09/19 17:08	Accident Photo	Load JPG	☒
2	28/09/19 17:08	Accident Photo	Load JPG	☒
3	28/09/19 17:08	Accident Photo	Load JPG	☒
4	28/09/19 17:08	Accident Photo	Load JPG	☒
5	28/09/19 17:08	Accident Photo	Load JPG	☒
6	28/09/19 17:08	Accident Photo	Load JPG	☒
7	28/09/19 17:08	Accident Photo	Load JPG	☒
8	28/09/19 17:08	Accident Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	28/09/19 17:04	Sketch Plan	Load JPG	☒
2	28/09/19 17:04	Sketch Plan #2	Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19017394/R1SF3N2

Date: 09/03/2020

REFERENCE

Insured/Claimant:	WEIBEL OTTO	Policy No:	1800006977	
Date of Loss:	28/09/2019	Nature of Claim:	OD	Claim No: 3215235247SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKJ1543K	Engine No:	DAX023434
Make & Model:	AUDI Q5, 2.0 TFSI Quattro (A)	Chassis No:	WAUZZZF0J2071216
Reg. Date:	06/02/2018 (Man. Year: 2017)	Odometer:	20203 km
Colour:	Blue		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$163,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55R19	Rear Tyre Size:	235/55R19
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,722.00	5,970.00	3,752.00	38.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,952.00	3,552.00	4,400.00	55.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,674.00	9,522.00	8,152.00	46.12
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
(S\$)	16,174.00	8,022.00	8,152.00	50.40
+ GST 7.00/7.00% (S\$)	1,132.18	561.54	570.64	50.40
Nett Amount (S\$)	17,306.18	8,583.54	8,722.64	50.40

INSPECTION

Date of Assignment: 03/10/2019

Date Inspected: 02/10/2019 Inspected At:

281 Alexandra Road
Repairer: Premium Automobiles Pte Ltd
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR	Bent	2,829.00 FS	*2,263.20 FS
2	1		*FRONT DOOR SEAL-OUTER	Necessary	185.00 FS	*147.60 FS
3	1		*BONDING AGENT	Necessary	45.00 FS	*35.92 FS
4	1		*CLEANING SOLUTION	Necessary	65.00 FS	*51.68 FS
5	1		*FRONT DOOR ATTACHMENT PARTS	Serviceable	239.00 FS	*- FS
6	1		*FRONT DOOR CATCH	Serviceable	132.00 FS	*- FS
7	1		*FRONT DOOR COVER-LH	Scratched	661.00 FS	*528.80 FS
8	1		*REAR DOOR	Bent	2,829.00 FS	*2,263.20 FS
9	1		*REAR DOOR BRACKET SEAL	Serviceable	40.00 FS	*- FS
10	1		*REAR DOOR SEAL-OUTER	Necessary	190.00 FS	*152.00 FS
11	1		*BONDING AGENT	Necessary	45.00 FS	*35.92 FS
12	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS
13	1		*REAR DOOR SEALING STRIP	Serviceable	15.00 FS	*- FS
14	1		*REAR DOOR ATTACHMENT PARTS	Serviceable	201.00 FS	*- FS
15	1		*REAR DOOR CATCH	Serviceable	132.00 FS	*- FS
16	1		*REAR DOOR SEAL-OUTER LH	Serviceable	201.00 FS	*- FS
17	1		*REAR DOOR COVER-LH	Cracked	577.00 FS	*461.20 FS
18	1		*SILL PANEL SEAL-LH	Serviceable	234.00 FS	*- FS
19	1		*DOOR HANDLE TRIM PLATE-LH	Serviceable	250.00 FS	*- FS
20	1		*REAR WHEEL COVER-LH	Not Necessary	487.00 FS	*- FS
21	1		*SUNDRIES	Necessary	300.00 FS	*30.48 FS

F=Franchise part, S=SpcNett.

Total Parts (S\$)	9,722.00	5,970.00
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES	New	560.00	560.00
2	TO DISMANTLE AND RENEW LHS FRONT DOOR AND LHS REAR DOOR.TO REPAIR LHS REAR FENDER.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,800.00	1,000.00
3	TO RESPRAY LHS FRONT DOOR,LHS REAR DOOR,DOOR HANDLE,DOOR COVERS,LHS REAR FENDER AND LHS REAR WHEEL ARCH TRIM	New	4,400.00	1,800.00
4	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (S\$)			7,952.00	3,552.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >