

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

03 OCT 2019

Estimate No. : b1 52943
Date Estimated : 03/10/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Lee Chee Wan
66C Lorong Marican

Singapore 415911

- ACCOUNT -

121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDE8136R	WBA7E22060GD99707	27/11/2015	740Li	0

DESCRIPTION

To replace front bumper, fender left and attachments.

VALUE

Painting front bumper and fender left.

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

To replace tyre and wheel rim including balancing. (1x).

To check steering geometry and conduct wheel alignment according to BMW specification (1X)

To carry out body cavity preservation. (Per panel).

Sundries.

TO REPLACE LEFT LED AHL HEADLIGHT 481

Total Labour 1: 5,838.00

DESCRIPTION

ALLOY RIM 8.5JX19 V SPK 620
FRT LH SIDE PANEL ALUMINIUM
FRT RH 1 SIDE PANEL BRACKET
SET MOUNTS PDC SENSOR FRT
GUIDE LH BOTTOM
GUIDE TOP LH
FRT BUMPER PANEL PRIMED (PDC/PMA)
DECOUPING RING PDC TORQUE CONVERTER
ULTRASONIC SENSOR MINERALWEISS(WA96)

QTY	PRIC	VALUE
1	1,305.95	1,305.95
1	1,298.50	1,298.50
1	34.95	34.95
1	69.00	69.00
1	40.50	40.50
1	40.50	40.50
1	1,612.90	1,612.90
4	5.05	20.20
1	368.80	368.80

DEFORMED

Total Parts : 4,791.30

SUPPLEMENTARY

*ADJUSTABLE BLIND RIVET Necessary

6.60 FS *6.60 FS

12 5 *RIVET Necessary

2.50 FS *2.50 FS

13 1 *LH HEADLIGHT LED AHL HIGH (ICON LIG)-cut

5,876.80 FS *5,876.80 FS

Performance Motors Limited

A Sime Darby Motors Company

Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

**GST REG. NO : M2 - 0020081 - X****E S T I M A T E**

Estimate No. : **b1 52943**
Date Estimated : **03/10/2019**
Prepared By : **Inthiran A/L Thurasamy**

Page No. : **2 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDE8136R	WBA7E22060GD99707	27/11/2015	740Li	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date&Time 5/11/2019 4pm Excess S\$ _____Surveyor's Name Tan Jiah Sign Tan JiahSurveyor's Tel 97493729 Authorised Yes / No _____Authorised Date WP Time _____RESURVEY PARTS PHOTO BY SURVEYOR ☒ Yes / No PML Yes / No _____Surveyor's E-mail tanjiah@lkkauto.comNo. of Working Days Recommend 5 days

Labour 1	:	5,838.00
Parts	:	4,791.30
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	744.05
Grand Total	:	11,373.35

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **