



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

AIGAsia Insured's Veh No : GY9645R
Date of Accident : 28 September 2019

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

LKK Auto Consultants hence note the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Mr Ling Moong Siew

Date : 30 September 2019

Estimate To Repair SH3031Z - Toyota PRIUS TAXI
Chassis No : JTDKN36U201822198

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	o/s headlamp / CNA	\$ 1,099.50
02	1 pc	front bumper / Cut	\$ 486.50
03	1 pc	o/s front bumper side retainer / ee	\$ 77.00
04	10 ps	front bumper clips @ \$4.50 / MC	\$ 45.00
05	1 pc	o/s front bumper indication lamp X NN	\$ 516.70
06	1 pc	o/s front fender X repair	\$ 733.00
07	1 pc	o/s front fender inner cowling X	\$ 172.90
08	6 ps	front fender inner cowling clips @ \$4.50 X NN	\$ 27.00
09	1 pc	front fender Hybrid badge / MC	\$ 56.80
10	1 pc	o/s front wheel hub cap X	\$ 85.00
11	1 pc	o/s front shock absorber X NN	\$ 394.20
		Less 25 %	\$ 3,693.60
			\$ 923.40
			\$ 2,770.20
		<u>SPECIAL NETT ITEMS</u>	
12	1 pc	o/s front wheel tyre X NN	\$ 250.00
			\$ 250.00
		<u>LABOUR & MISC. CHARGES</u>	
01		To drop front suspension undercarriage parts, remove and renewal of the necessary parts, to perform final checking and testing.	\$ 150.00
02		To check electrical lighting concerned.	\$ 60.00
03		To rust-proofing of the affected areas.	\$ 120.00
04		To check steering geometry and computer wheel alignment.	\$ 80.00
05		To transfer of tyre, rim and on wheel balancing.	\$ 30.00
06		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 700.00
07		Putty and spray painting of the affected portion.	\$ 700.00
			\$ 1,840.00
		Total	\$ 4,860.20

4 Days.

lumpsum repair

20% : 1700

After repair photos.

Guo Qiang - 82880282

02/10/19.

175.3
1301.48
X
X NN
30
X
X NN
X
400.
400.