

ASSIGNMENT

Surveyor:

MARCUS

DOI: 03/10/2019

Date/Time: 03/10/2019

Registered in Merimen: 03/10/2019

Pre-assign / CCU / FTE



Insured Vehicle No. SHC 2421U

Claim No. :

Name of Insured COMFORT TRANSPORTATION PTE LTD

Policy No. :

MCOM0015

Insured Tel No. : HP:

Make / Model :

TOYOTA PRIUS HYBRID 4G

Excess Sec II :SS

D.O.A : 01/10/2019 08:30

Place of Accident : SLIP RD FROM WOODLANDS AVE 5 TO WOODLANDS AVE 3

Is driver the owner?

(YES / NO)

Nature of Accident :

If NO, Driver Name / Age : ISKANDAR BIN HAMZAH

OI GIA REPORT YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : +65-94494702

(V/L: YES / NO)

Insured Liability :

%

Final ? Yes / No

SJT 7174L



INSRS:

WSP: PRECISE AUTO

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/Time

SJT 7174L - NA/INC10023419/Ac2; DOA: 19/11/10
SHC 2421U - CC3/III18013881/K1eb3q2; DOA: 27/7/18
- NA/INC15001214/r3; DOA: 20/1/15

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA :

Medical Bill:

PBR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days) Reduction:

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed)

BOLA S/N No. : 27

If NO or B 28, Ass. Lia :

Repair Cost:

SS

6955.00

Loss of Rental (LOR):

SS

1100.00

(11 days)

X#10

Loss of Use (LOU):

SS

(S

x

days)

Loss of Income (LOI):

SS

(S

x

days)

LOR only ☐ LOU only ☐

LOR + LOU ☐

LOR + LOI ☐

(Tick only one)

GIA/LTA Search

SS

37.00

Medical:

SS

-

Disbursement:

SS

-

Legal Cost

SS

-

Total:

SS

8092.00

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

8092.00

Name 1:

Precise Auto Service

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Non-Report/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$ 500.00

CORRECT

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO.: 35766600C GST REG. NO.: 35766600C

30-10-19

Accident Date : 01-10-2019

OUR REF : SJT 7174L/T/19

JOYRIDE CAR RENTAL PTE LTD

1 Kaki Bukit Ave 6

#02-34

Singapore 417883

NZT260

Lkb- Mercedes

01-10-19 to 19-10-19

Not Authorized
date
3/10/19
4/5 = 6500/
8day.

ESTIMATE BILL ON VEH. NO. : SJT 7174L

MODEL : TOYOTA ALLION 1.5

CHASSIS NO. : NZT2603032846

LIST ITEM

| | | | |
|------------------------------|---------------|---------|------------|
| Boot Lid | | But/suc | 880.20 ✓ |
| Boot Lid Hinge | 2pcs @ 181.70 | su | 363.40 X |
| Boot Lid Stopper | 2pcs @ 53.90 | 11 | 107.80 X |
| Boot Lid Weather Stripe | | twi | 188.63 ✓ |
| Boot Lid Lock | 399.20 | twi | 581.10 ✓ |
| Boot Lid Lock Striker | | 11 | 121.10 X |
| Boot Lid Lock Cable | | 11 | 131.85 X |
| Boot Lid Chrome Clips | 4pcs @ 12.90 | 11 | 51.60 X |
| Boot Lid Badge | | su | 41.00 ✓ |
| Boot Lid Emblem "Allion" | | su | 51.00 ✓ |
| Boot Lid Emblem "A15" | | su | 41.00 ✓ |
| Boot Lid Outer Buzzer Sensor | | 11 | 181.20 X |
| Rear Bumper Fascia | 981.10 | Dis | 1,210.20 ✓ |
| Rear Bumper Side Retainer | 2pcs @ 121.20 | But | 242.40 ✓ |
| Rear Bumper Bracket | 2pcs @ 131.10 | But | 262.20 ✓ |

| | | | | |
|------------------------------------|---------------|---------------------|-------------|-----------------------|
| Rear Bumper Reflector | 2pcs @ 83.90 | | o/s one | 167.80 /pc |
| Rear Bumper Clips | 10pcs @ 12.90 | 50 | nr | 129.00 |
| Rear Bumper Stay - N/S & O/S | 2pcs @ 131.70 | | reqd | 263.40 X |
| Tail Lamp Assy | 2pcs @ 283.15 | | cna | 566.30 / |
| Tail Lamp Side Clips | 2pcs @ 12.90 | | nn | 25.80 X |
| Tail Lamp Clips | 4pcs @ 12.90 | | nn | 51.60 X |
| Tail Lamp Base Panel | 2pcs @ 201.80 | | n | 403.60 X |
| Tail Lamp Sealant | 2pcs @ 50.00 | | nn | 100.00 X |
| Rear End Panel | | | 306.30 | 508.20 / |
| Rear End Panel Top Trim | | | 7m | 233.85 / |
| Rear End Panel Top Trim Clips | 5pcs @ 12.90 | | nn | 64.50 X |
| Rear Fender Inner Trim Board | 2pcs @ 537.81 | 488.10 x 2 = 976.20 | del/n | 1,075.62 / |
| Rear Fender Inner Trim Board Clips | 16pcs @ 12.90 | | nn | 206.40 X |
| Rear Floor Panel Board | | | Torn | 381.25 / |
| Exhaust Silencer | | | n | 781.85 X |
| Exhaust Silencer Hook | 2pcs @ 32.90 | | nn | 65.80 X |
| Rear Floor Panel | | | crushed/suc | 1,210.10 / |
| Rear Sub Chassis Member - RH | | | R | 481.55 X |
| Rear Floor Panel Insulator Cloth | | | nr | 561.80 ¹⁵⁰ |

11,713.10

Less Discount 25% :

2,928.28

8,784.83

SPECIAL NETT ITEM

Reverse Sensor with Control Unit 1 set


shorted 2005.0 380.00

LABOUR CHARGE

Towing

nn X 80.00

| | | |
|--|-----------------------|------------------------------|
| To remove & refix exhaust silencer & straighten exhaust center pipe. | 11 | 280.00 X |
| To check & reconnect snap wiring | 30 | 80.00 |
| To tuff coat affected areas | 90 | 200.00 |
| To adjust chassis alignment on car O liner | 11 X | 380.00 |
| To remove & refix interior upholstery | 80 | 200.00 |
| To remove & refix reverse sensor | 50 | 180.00 |
| To remove & refix boot lid mechanism | 60 | 250.00 |
| To respray affected areas | 1200 | 1,800.00 |
| To renew damaged parts, straighten & repair rear fender, rear chassis frame member & aligned all parts | 1200 | 1,800.00 |
| | | <hr/> 14,414.83 |
| | GST 7% : | <hr/> 1,009.04 |
| | TOTAL AMOUNT : | <hr/> 15,423.86 <hr/> |
| | 2760 | |



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars | |
|---|--------------------------|
| Owner ID Type: | Company |
| Owner ID: | 065H |
| Vehicle Details | |
| Vehicle No.: | SJT7174L |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 04 Nov 2019 |
| Vehicle Make: | TOYOTA |
| Vehicle Model: | ALLION 1.5 A |
| Primary Colour: | Black |
| Manufacturing Year: | 2008 |
| Engine No.: | 1NZD193100 |
| Chassis No.: | NZT2603032846 |
| Maximum Power Output: | 81.0 kW (108 bhp) |
| Open Market Value: | \$20,133.00 |
| Original Registration Date: | 27 Oct 2009 |
| First Registration Date: | 27 Oct 2009 |
| Transfer Count: | 2 |
| Actual ARF Paid: | \$20,133.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Forfeited |
| PARF Eligibility Expiry Date: | - |
| PARF Rebate Amount: | \$0.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 26 Oct 2024 |
| COE Category: | A - Car (1600cc & below) |
| COE Period(Years): | 5 |
| PQP Paid: | \$15,287.00 |
| COE Rebate Amount: | \$15,213.00 |
| Total Rebate Amount: | \$15,213.00 |
| Message | |
| Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier. | |

The information contained herein is correct as at 04 Nov 2019

OK



Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Lowest Deprec! Lowest Selling Price! Lowest Interest!



2.88% P.A. By Trusted Inhouse
Financing! \$530 Monthly! \$0
Admin Fee! 100% Approval!
StarAd

Lake View
Credit Pte Ltd

> Low price
> Specialist
> Easy loan
> All terms

Browse by Category ▼

Sort by Date Posted

17 vehicles

Allion

Advanced Search

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh T

Search Selection

Allion

Any

Any

2009

Any

Any



**Toyota Allion 1.8A (COE till
05/2029)**

\$57,800**\$6,020 /yr****12-May-2009****1,797 cc****207,000 km**

St

Low Risk Purchase, An Ideal Choice For Daily Commute. Call Our Sales Consultants For A Viewing Today!

Inchcape Pre-Owned

Posted: 03-Oct-2019 Tags: 2009 Toyota Allion, 2009 toyota allion, Toyota Allion, toyota allion, Toyota, Allion, allion, Used Toyota



**Toyota Allion 1.5A (COE till
04/2029)**

\$43,333**\$4,520 /yr****05-May-2009****1,496 cc****160,000 km**

Sc

100% Loan Available. New Paintwork. Wear And Tear All Replaced. Very Well Maintained By Previous Owner. A Reliable And Fuel Saving Vehicle. Better Than Toyota Altis. Made In Japan. Call Now To Arrange For A Viewing Before Its Sold.

Posted: 02-Oct-2019 Tags: 2009 Toyota Allion, 2009 toyota allion, Toyota Allion, toyota allion, Toyota, Allion, allion, Used Toyota



**Toyota Allion 1.5A (COE till
09/2024)**

\$32,800**\$6,570 /yr****06-Oct-2009****1,496 cc****116,226 km**

Si

Reliable Japanese Sedan With Keyless Entry/Push Start. Best Condition And Ownership In Town. 11,000km Mileage Clocked Annually Only, Under-Usage Low Mileage. Fully Done Up To Showroom Unit Standard, Don't Hesitate Anymore. New Paintwork. New Tyres. 6 Mo...

Posted: 01-Oct-2019 Tags: 2009 Toyota Allion, 2009 toyota allion, Toyota Allion, toyota allion, Toyota, Allion, allion, Used Toyota



**Toyota Allion 1.5A (COE till
09/2029)**

\$47,500**\$4,760 /yr****27-Sep-2009****1,496 cc****115,000 km**

Si

Well Maintained And Comes In Showroom Condition. We Provide Flexible Loan From Bank/In House. No Major Repairs Needed.

Ka-Hup Vehicles Trading

Posted: 01-Oct-2019 Tags: 2009 Toyota Allion, 2009 toyota allion, Toyota Allion, toyota allion, Toyota, Allion, allion, Used Toyota

**GET YOUR
COE
RENEWAL
LOAN**

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town with approval in 2 days without effort! Enquire today.

Compare

**Toyota Allion 1.5A (COE till
02/24)**

\$31,800**\$6,600 /yr****29-Jul-2009****1,496 cc**

-

Si

10/4/2019

Used Allion Car & Used Cars & Vehicles Singapore - sgCarMart



Tip Top Condition With Full Servicing Done Up! New Leather And Also New Paintwork! 100% Loan Available As Well! PHV Drivers Are Welcome Too! High And Fast Approval Rate From Our Very In-House Loan! Don't Hesitate To Call One Of Our Friendly Salesman To Arra...

ABWIN (1994) Pte Ltd

Posted: 01-Oct-2019 Tags: 2009 Toyota Allion, 2009 toyota allion, Toyota Allion, toyota allion, Toyota, Allion, allion, Used Toyota



Toyota Allion 1.5A (New 10-yr COE) \$48,888 \$4,880 /yr 11-Sep-2009 1,496 cc 100,000 km St

Elegant New White Paintwork! Meticulously Well Maintained By Previous Owner With No Further Repair Needed. Guaranteed Accident Free! Very Low Mileage Done! We Provide Various Flexible Loan! All Trade In Are Welcome. Please Contact Our Friendly Sales Consultan...

Creative Auto

Posted: 23-Sep-2019 Tags: 2009 Toyota Allion, 2009 toyota allion, Toyota Allion, toyota allion, Toyota, Allion, allion, Used Toyota



Toyota Allion 1.5A (COE till 01/2024) \$27,888 \$6,550 /yr 06-Jan-2009 1,496 cc 106,000 km St

High Loan Available! We Provide Various Loan Scheme Cater To All Individuals Needs, Mileage Only 10k Km Clocked Yearly, New Road Tax. Ring Our Knowledgeable Salesman For A Viewing Or Test Drive. All Trade In Welcome!

Creative Auto

Posted: 22-Sep-2019 Tags: 2009 Toyota Allion, 2009 toyota allion, Toyota Allion, toyota allion, Toyota, Allion, allion, Used Toyota



Toyota Allion 1.5A (COE till 02/2024) \$31,200 \$7,190 /yr 05-Feb-2009 1,496 cc - St

Excellent And Original Condition, Well Maintained Interior And Exterior, Call Now For Viewing.

Posted: 20-Sep-2019 Tags: 2009 Toyota Allion, 2009 toyota allion, Toyota Allion, toyota allion, Toyota, Allion, allion, Used Toyota



Toyota Allion 1.5A (New 10-yr COE) \$47,300 \$4,730 /yr 18-Sep-2009 1,496 cc 103,000 km St

Comes With Bidded Carplate 90 Option, Cheapest In Market. 6 Months Warranty. New Paint Work. Well Maintained With Wear And Tear All Replaced. Best Value For Money! Drive With No Worries. Free 1 Servicing. 100% Loan Approval! Bank And In House Loan Available!...

Posted: 17-Sep-2019 Tags: 2009 Toyota Allion, 2009 toyota allion, Toyota Allion, toyota allion, Toyota, Allion, allion, Used Toyota



Toyota Allion 1.5A (New 5-yr COE) \$33,500 \$6,690 /yr 05-Nov-2009 1,496 cc 130,000 km St

Look No Further. Low Deprecation! Very Well Maintained. No Repair Needed. Cheaper Than Renting A Car! Bank And In-House Loan Available. Call Now To Arrange For A Viewing Before Its Sold.

Posted: 10-Sep-2019 Tags: 2009 Toyota Allion, 2009 toyota allion, Toyota Allion, toyota allion, Toyota, Allion, allion, Used Toyota



Find the right car through consignment.

Purchase pre-loved, owner consigned cars at affordable prices through our dedicated consignment agents. Arrange a test drive today.

Find out more!



Toyota Allion 1.5A (New 5-yr COE) \$33,888 \$6,770 /yr 27-Aug-2009 1,496 cc 101,000 km St

Free 1 Servicing Upon Purchase! Up To 2 Years Warranty Engine And Gearbox! 100% Loan Approval! Bank And In House Loan Available! No Gimmicks! Trade-In Welcome! Best Value For Money! Well Maintained, Excellent Condition! Don't Miss It, View To Believe! Contact U...

JDM Cars

Posted: 10-Sep-2019 Tags: 2009 Toyota Allion, 2009 toyota allion, Toyota Allion, toyota allion, Toyota, Allion, allion, Used Toyota



Toyota Allion 1.5A (COE till 08/2024) \$31,800 \$6,490 /yr 28-Aug-2009 1,496 cc 153,000 km St

Great Condition. Well Maintained By Previous Owner. View To Believe. Bank Loan/Loan/In House Loan Available! Private Hirers/Trade In Most Welcome! Call/SMS/WhatsApp Our Friendly Sales Reps Today To Arrange For Viewing And Test Drive.

ed: 08-Sep-2019 Tags: 2009 Toyota Allion, 2009 toyota allion, Toyota Allion, toyota allion, Toyota, Allion, allion, Used Toyota

Compare

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

| | |
|----------------|---------|
| Owner ID Type: | Company |
| Owner ID: | 065H |

Vehicle Details

| | |
|-------------------------------|-------------------|
| Vehicle No.: | SJT7174L |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 04 Oct 2019 |
| Vehicle Make: | TOYOTA |
| Vehicle Model: | ALLION 1.5 A |
| Primary Colour: | Black |
| Manufacturing Year: | 2008 |
| Engine No.: | 1NZD193100 |
| Chassis No.: | NZT2603032846 |
| Maximum Power Output: | 81.0 kW (108 bhp) |
| Open Market Value: | \$20,133.00 |
| Original Registration Date: | 27 Oct 2009 |
| First Registration Date: | 27 Oct 2009 |
| Transfer Count: | 2 |
| Actual ARF Paid: | \$20,133.00 |

Intended PARF Rebate Details

| | |
|-------------------------------|-------------|
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 26 Oct 2019 |
| PARF Rebate Amount: | \$10,066.00 |

Intended COE Rebate Details

| | |
|-----------------------------|--------------------------|
| COE Expiry Date: | 26 Oct 2019 |
| COE Category: | A - Car (1600cc & below) |
| COE Period(Years): | 10 |
| QP Paid: | \$18,899.00 |
| COE Rebate Amount: | \$111.00 |
| Total Rebate Amount: | \$10,177.00 |

The information contained herein is correct as at 04 Oct 2019

OK

17445/UP
Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Thursday, 3 October 2019 8:44 AM
To: Precise Auto Service; 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: Zuhaidah Samsuri
Subject: RE: Pre-repair Inspection for SJT 7174L. Your Insured Vehicle no : SHC 2421U on 01-10-2019 Along Woodlands Ave 5 Exit to Ave 3
Attachments: 02102019100338.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SJT7174L and let us have your report urgently.

This claim will be handled by Ms Aida.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

p. Arine
T: 9.00am
v: ✓
E: ✓

From: Precise Auto Service [mailto:Support@preciseauto.sg]
Sent: 02 October, 2019 3:45 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Re: Pre-repair Inspection for SJT 7174L. Your Insured Vehicle no : SHC 2421U on 01-10-2019 Along Woodlands Ave 5 Exit to Ave 3

Dear Sir,

We refer to your email on dated 02-10-2019.

Please be informed that we would like to select *Mr. Marcus Chua from LKK Auto Consultants Pte Ltd* as our SJE.

Thank You.

Best Regards
Arine

On Wed, 2 Oct 2019 at 11:56, Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee



64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext – 248

From: Precise Auto Service [<mailto:Support@preciseauto.sg>]

Sent: 02 October, 2019 10:10 AM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: Pre-repair Inspection for SJT 7174L. Your Insured Vehicle no : SHC 2421U on 01-10-2019 Along Woodlands Ave 5 Exit to Ave 3

Dear Sir,

We refer to the above mentioned matter, herewith enclosed 2 days notice for your attention.

Kindly arrange a date and time to do a PRI for our client vehicle (*SJT 7174L*) in our workshop ASAP.

Thank You

Best Regards

Arine

--

T : 6745 7367 | **F** : 6841 3390

E : support@preciseauto.sg

W: www.preciseauto.sg

A : No.1 Kaki Bukit Ave 6, #02-33/34/36 AutoBay @ Kaki Bukit, Singapore 417883



Follow us on social media:



<https://www.instagram.com/preciseautosvs/>



<https://twitter.com/preciseautosvs>



<https://www.facebook.com/PreciseAutoService/>

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

T : 6745 7367 | F : 6841 3390


E : support@preciseauto.sg

W : www.preciseauto.sg


A : No.1 Kaki Bukit Ave 6, #02-33/34/36 AutoBay @ Kaki Bukit, Singapore 417883




Follow us on social media:



<https://www.instagram.com/preciseautosvs/>



<https://twitter.com/preciseautosvs>



<https://www.facebook.com/PreciseAutoService/>

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Hsiao Tong (LKKAUTO)

From: Precise Auto Service <Support@preciseauto.sg>
Sent: Friday, 3 January 2020 1:25 PM
To: Hsiao Tong (LKKAUTO)
Subject: Re: ACCIDENT INVOLVING VEHICLE NO. SJT 7174L AND SHC 2421U ON 01/10/2019 //LKK REF: CC4/III19017445/Upa3

Without Prejudice

Dear Hsiao Tong

We are agreeable to accept your offer email dated 20/12/2019.

Waiting for DV.

Thank you

Best Regards
Yan Hong

On Fri, 20 Dec 2019 at 08:42, Hsiao Tong (LKKAUTO) <chewht@lkkauto.com> wrote:

Without Prejudice

Dear Sirs/Mdm,

We refer to your below email.

We are prepared to revise our offer as follows: -

| | |
|--|--------------------|
| 1. Cost of Repair (w/GST) | \$ 6,955.00 |
| 2. Loss of Rental (11days x \$100.00)* | \$ 1,100.00 |
| 3. LTA/ GIA Search Fee | \$ 37.00 |
| Total | \$ 8,092.00 |

*8 recommendation repair days + 1Sunday + 2PRS = 11days

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

"Best Wishes for Merry Christmas, and Happy New Year 2020"

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Precise Auto Service <Support@preciseauto.sg>

Sent: Tuesday, 17 December 2019 2:06 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: Re: ACCIDENT INVOLVING VEHICLE NO. SJT 7174L AND SHC 2421U ON 01/10/2019 //LKK REF: CC4/III19017445/Upa3

Dear Hsiao Tong

We refer to your email dated 11/12/2019.

Our request as follows: -

| | |
|---------------------------------------|--------------------|
| 1. Cost of Repair (w/GST) | \$ 6,955.00 |
| 2. Loss of Rental (14days x \$100.00) | \$ 1,400.00* |
| 3. LTA/ GIA Search Fee | \$ 37.00 |
| Total | \$ 8,392.00 |

*8 days for repair + 2 days waiting for PRI + 4 days weekend

Thank you

Best Regards
Yan Hong

On Wed, 11 Dec 2019 at 10:03, Hsiao Tong (LKKAUTO) <chewht@lkkauto.com> wrote:

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement as follows: -

| | |
|---------------------------------------|--------------------|
| 1. Cost of Repair (w/GST) | \$ 6,955.00 |
| 2. Loss of Rental (10days x \$100.00) | \$ 1,000.00 |
| 3. LTA/ GIA Search Fee | \$ 37.00 |
| Total | \$ 7,992.00 |

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

"Best Wishes for Merry Christmas, and Happy New Year 2020"

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Precise Auto Service <Support@preciseauto.sg>

Sent: Tuesday, 5 November 2019 3:52 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: ACCIDENT INVOLVING VEHICLE NO. SJT 7174L AND SHC 2421U ON 01/10/2019

Without Prejudice

Your Ref. : -

Vehicle No. : SJT 7174L/T/19(SJE)

M/s India International Insurance Pte Ltd

Dear Ms. Hsiao Tong

-

RE : ACCIDENT INVOLVING VEHICLE NO. SJT 7174L AND SHC 2421U ON 01/10/2019

We are the repairer for vehicle no. **SJT 7174L** and instructed by the owner, **Joyride Car Rental Pte Ltd**, on his behalf to submit the claims against your insured's vehicle no. **SHC 2421U** that was involved in the above mentioned accident.

The accident was clearly caused by your insured's negligence. In order to save the legal cost, we will process the claim to you directly as follows:

| | | |
|--|--------------------|-----------------|
| 1. Cost of Repair (Surveyed By Mr. Marcus) | \$ 6,955.00 | (Including GST) |
| 2. Car Rental (18 days X \$120.00) | \$ 2,160.00 | |
| 3. LTA / GIA Search Fee | \$ 37.00 | |
| Total : | \$ 9,152.00 | |

Please let us have your payment in our favour of "**Precise Auto Service**".

Your prompt reply of the above claims will be much appreciated.

Thank You

Best Regards

Yan Hong

T : 6745 7367 | F : 6841 3390


E : support@preciseauto.sg

W: www.preciseauto.sg


A : No.1 Kaki Bukit Ave 6, #02-33/34/36 AutoBay @ Kaki Bukit, Singapore 417883



Follow us on social media:



<https://www.instagram.com/preciseautosvs/>



<https://twitter.com/preciseautosvs>



<https://www.facebook.com/PreciseAutoService/>

T : 6745 7367 | **F :** 6841 3390

E : support@preciseauto.sg

W: www.preciseauto.sg

A : No.1 Kaki Bukit Ave 6, #02-33/34/36 AutoBay @ Kaki Bukit, Singapore 417883



Follow us on social media:



<https://www.instagram.com/preciseautosvs/>



<https://twitter.com/preciseautosvs>



<https://www.facebook.com/PreciseAutoService/>

"Best Wishes for Merry Christmas, and Happy New Year 2020 !"

T : 6745 7367 | **F :** 6841 3390

E : support@preciseauto.sg

W : www.preciseauto.sg

A : No.1 Kaki Bukit Ave 6, #02-33/34/36 AutoBay @ Kaki Bukit, Singapore 417883



Follow us on social media:



<https://www.instagram.com/preciseautosvs/>



<https://twitter.com/preciseautosvs>



<https://www.facebook.com/PreciseAutoService/>

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|---|---------------|--|--|--|------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
| Main | 03 Oct 2019 Edit Reg | | 03 Oct 2019 00:00 Edit Adj Rpt | \$56,500.00 Edit Estimates | \$56,500.00 View Rpt | | Pending for Survey Report Cancel Case |












































| Main | Reference | Claim Details | Documents | Show All | | | | | |
|--|--|------------------------|--|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by adjuster] | | | | | | | | | |
| Insured: | COMFORT TRANSPORTATION PTE LTD, ID: - | | | | | | | | |
| Main Claimant: | JOYRIDE CAR RENTAL PTE LTD, Co. Reg. No.: 201842065H | | | | | | | | |
| Vehicle Reg. No.: | SJT7174L | Date of Loss: | 01/10/2019 08:00 - :59 [119 Months and 4 Days From LTA Reg Date (Man Yr)] | | | | | | |
| Claim Type: | TP / MCT19100002 | Policy/Cover Note No.: | MCOM0015 | | | | | | |
| Vehicle Reg. No. (Insured): | SHC2421U | Policy No. (Claimant): | 5107628585 | | | | | | |
| | | Excess: | | | | | | | |
| Repairer: | Precise Auto Service (HQ) No 1 Kaki Bukit Ave 6, #02-34/36, 417883 Kaki Bukit - Tel: 67457367 | | | | | | | | |
| Handling Insurer: | India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070] | | | | | | | | |
| Claimant's Insurer: | NTUC Income Insurance Co-operative Ltd (HQ) - Tel: | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 14/10/2019] | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| <ul style="list-style-type: none"> III_SG (04/12/2019): Alert - Adj Mandate Approved (\$58092.00) - SJT7174L - Claim Handler: Zuhaidah Bt... III_SG (15/10/2019): Alert - Adj Mandate Approved (\$50.00) - SJT7174L - Claim Handler: Zuhaidah Bte S... | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |























































Claim Documents














*SJT7174L (MCT19100002)
[SHC2421U]
TP
JOYRIDE CAR RENTAL PTE LTD
Oct 1 2019 8:00AM
[COMFORT TRANSPORTATION PTE LTD]
Precise Auto Service

Upload Documents | Upload Photos | Compose New Letter

View View in Browser

| Photos/Images | | | 3 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|--|-------------------------------------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 03/12/19 09:47 | Odometer Reading |  Load JPG | <input checked="" type="checkbox"/> |
| 2 | 03/12/19 09:47 | Chassis Number |  Load JPG | <input checked="" type="checkbox"/> |
| 3 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 4 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 5 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 6 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 7 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 8 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 9 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 10 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 11 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 12 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 13 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 14 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 15 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 16 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 17 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 18 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 19 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 20 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 21 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 22 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 23 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 24 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 25 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 26 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 27 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 28 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 29 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 30 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 31 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 32 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 33 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 34 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 35 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 36 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 37 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 38 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 39 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 40 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 41 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 42 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 43 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |

| Photos/Images | | | 3 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|--|-------------------------------------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 44 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 45 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 46 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 47 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 48 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 49 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 50 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 51 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 52 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 53 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 54 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 55 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 56 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 57 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 58 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 59 | 03/12/19 09:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 60 | 03/12/19 09:47 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 61 | 03/12/19 09:47 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 62 | 03/12/19 09:47 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 63 | 03/12/19 09:47 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 64 | 03/12/19 09:47 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 65 | 03/12/19 09:47 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 66 | 03/12/19 09:47 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 67 | 03/12/19 09:47 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 68 | 03/12/19 09:47 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 69 | 03/12/19 09:47 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 70 | 03/12/19 09:47 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 71 | 03/12/19 09:47 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 72 | 03/12/19 09:47 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 73 | 03/12/19 09:47 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 74 | 03/12/19 09:47 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 75 | 03/12/19 09:47 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 76 | 03/12/19 09:47 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 77 | 03/12/19 09:47 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 78 | 03/12/19 09:47 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 79 | 03/12/19 09:47 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 80 | 03/12/19 09:47 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 81 | 03/12/19 09:47 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 82 | 03/12/19 09:47 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 83 | 03/12/19 09:47 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 84 | 03/12/19 09:47 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 85 | 03/12/19 09:47 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 86 | 03/12/19 09:47 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 87 | 03/12/19 09:47 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 88 | 03/12/19 09:47 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 89 | 03/12/19 09:47 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 90 | 03/12/19 09:47 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 91 | 03/12/19 09:47 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 92 | 03/12/19 09:47 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 93 | 03/12/19 09:47 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 94 | 03/12/19 09:47 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 95 | 03/12/19 09:47 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 96 | 03/12/19 09:47 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 97 | 03/12/19 09:47 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 98 | 03/12/19 09:47 | Photo After Spray | Load JPG | <input checked="" type="checkbox"/> |
| 99 | 03/12/19 09:47 | Photo After Spray | Load JPG | <input checked="" type="checkbox"/> |

| Photos/Images | | | 3 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|--|---|-------------------------------------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| Documentation | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 03/10/19 17:38 | NOTIFICATION FROM WORKSHOP + LTA SEARCH |  | Load PDF |
| 2 | 03/10/19 17:38 | EMAIL FROM III DD 03.10.19 |  | Load PDF |
| 3 | 11/10/19 11:57 | TP GIA REPORT |  | Load PDF |
| 4 | 11/10/19 11:57 | TP POLICE REPORT |  | Load PDF |
| 5 | 26/11/19 14:03 | WORKSHOP INVOICE |  | Load PDF |
| 6 | 26/11/19 14:03 | RENTAL RECEIPT |  | Load PDF |
| 7 | 26/11/19 14:03 | LTA SEARCH |  | Load PDF |
| 8 | 26/11/19 14:03 | GIA SEARCH |  | Load PDF |
| 9 | 26/11/19 14:03 | LOD |  | Load PDF |
| 10 | 03/12/19 09:46 | PARF_COE REBATE. |  | Load PDF |
| 11 | 20/01/20 08:48 | AUTHORISATION TO ACT FORM |  | Load PDF |
| 12 | 20/01/20 08:48 | DISCHARGE VOUCHER |  | Load PDF |
| No | Finalized On | India International Insurance Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 04/10/19 08:41 | Singapore Accident Statement |  | Load PDF |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. | | | |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div> | | | |
| Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> | | | |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19017445/UPA3Q2

Date: 20/01/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant Vehicle No: SGT7174L Insured Vehicle No: SHC2421U
 Date of Loss: 01/10/2019 Nature of Claim: TP Claim No: MCT19100002

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGT7174L
 Make & Model: TOYOTA ALLION, 1.5 (A) Engine No: 1NZD193100
 Reg. Date: 27/10/2009 (Man. Year: 2008) Chassis No: NZT2603032846
 Colour: Black Odometer: 191220 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/70 R14 Rear Tyre Size: 185/70 R14
 Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
 Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|------------------|-----------------|-----------------|--------------|
| Parts | 9,164.82 | 5,634.90 | 3,529.92 | 38.52 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 5,250.00 | 2,710.00 | 2,540.00 | 48.38 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 14,414.82 | 8,344.90 | 6,069.92 | 42.11 |
| Approved Total (Overridden) (S\$) | | 6,500.00 | | |
| (S\$) | 14,414.82 | 6,500.00 | 7,914.82 | 54.91 |
| + GST 7.00/7.00% (S\$) | 1,009.04 | 455.00 | 554.04 | 54.91 |
| Nett Amount (S\$) | 15,423.86 | 6,955.00 | 8,468.86 | 54.91 |
| + Car Rental (11.0 x S\$100.00/day) (S\$) | | 1,100.00 | | |
| + Doc/Search Fee (S\$) | | 37.00 | | |
| Nett Liability (S\$) | | 8,092.00 | | |

INSPECTION

Date of Assignment: 03/10/2019
 Date Inspected: 03/10/2019 Inspected At: Precise Auto Service (HQ)
 No 1 Kaki Bukit Ave 6, #02-34/36
 Singapore 417883
 Estimated Period of Repair: 8.0 days

Adjuster: MARCUS CHUA

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

SPECIAL REMARKS

Please note that third party vehicle COE expiry date is 26 Oct 2024.

Market Value: \$28,000.00(est) less LTA Rebate: \$15,213.00(est) = Nett Value :\$12,787.00(est)

REPAIR DETAILS

| | | |
|----------------------|--|---|
| Reference | | |
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 26 Nov 2019) |
| Parts: | 143 | TOYOTA ALLION 1.5 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SJT7174L) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---------------------------------------|--------------------|-------------|--------------|
| 1 | 1 | | *BOOT LID | Bent / Buckled | 880.20 FL | *880.20 FL |
| 2 | 2 | | *BOOT LID HINGE | Serviceable | 363.40 FL | *- FL |
| 3 | 2 | | *BOOT LID STOPPER | Not Necessary | 107.80 FL | *- FL |
| 4 | 1 | | *BOOT LID WEATHER STRIPE | Twisted | 188.63 FL | *188.63 FL |
| 5 | 1 | | *BOOT LID LOCK | Twisted | 561.10 FL | *399.20 FL |
| 6 | 1 | | *BOOT LID LOCK STRIKER | Not Necessary | 121.10 FL | *- FL |
| 7 | 1 | | *BOOT LID LOCK CABLE | Not Necessary | 131.85 FL | *- FL |
| 8 | 4 | | *BOOT LID CHROME CLIPS | Not Necessary | 51.60 FL | *- FL |
| 9 | 1 | | *BOOT LID BADGE | Necessary | 41.00 FL | *41.00 FL |
| 10 | 1 | | *BOOT LID EMBLEM ALLION | Necessary | 51.00 FL | *51.00 FL |
| 11 | 1 | | *BOOT LID EMBLEM A15 | Necessary | 41.00 FL | *41.00 FL |
| 12 | 1 | | *BOOT LID OUTER BUZZER SENSOR | Not Necessary | 181.20 FL | *- FL |
| 13 | 1 | | *REAR BUMPER FASCIA | Distorted | 1,210.20 FL | *981.10 FL |
| 14 | 2 | | *REAR BUMPER SIDE RETAINER | Bent | 242.40 FL | *242.40 FL |
| 15 | 2 | | *REAR BUMPER BRACKET | Bent | 262.20 FL | *262.20 FL |
| 16 | 1 | | *REAR BUMPER REFLECTOR | O/S Cracked | 167.80 FL | *83.90 FL |
| 17 | 10 | | *REAR BUMPER CLIPS | Necessary | 129.00 FL | *50.00 FL |
| 18 | 2 | | *REAR BUMPER STAY -N/S & O/S | Repeated | 263.40 FL | *- FL |
| 19 | 2 | | *TAIL LAMP ASSY | Cracked | 566.30 FL | *566.30 FL |
| 20 | 2 | | *TAIL LAMP SIDE CLIPS | Not Necessary | 25.80 FL | *- FL |
| 21 | 4 | | *TAIL LAMP CLIPS | Not Necessary | 51.60 FL | *- FL |
| 22 | 2 | | *TAIL LAMP BASE PANEL | Repair | 403.60 FL | *- FL |
| 23 | 2 | | *TAIL LAMP SEALANT | Not Necessary | 100.00 FL | *- FL |
| 24 | 1 | | *REAR END PANEL | Badly Dented | 508.20 FL | *508.20 FL |
| 25 | 1 | | *REAR END PANEL TOP TRIM | Twisted | 233.85 FL | *233.85 FL |
| 26 | 5 | | *REAR END PANEL TOP TRIM CLIPS | Not Necessary | 64.50 FL | *- FL |
| 27 | 2 | | *REAR FENDER INNER TRIM BOARD | Deformed / Torn | 1,075.62 FL | *976.20 FL |
| 28 | 16 | | *REAR FENDER INNER TRIM BOARD CLIPS | Not Necessary | 206.40 FL | *- FL |
| 29 | 1 | | *REAR FLOOR PANEL BOARD | Torn | 381.25 FL | *381.25 FL |
| 30 | 1 | | *EXHAUST SILENCER | Repair | 781.85 FL | *- FL |
| 31 | 2 | | *EXHAUST SILENCER HOOK | Not Necessary | 65.80 FL | *- FL |
| 32 | 1 | | *REAR FLOOR PANEL | Crumpled / Buckled | 1,210.10 FL | *1,210.10 FL |
| 33 | 1 | | *REAR SUB CHASSI MEMBER -RH | Repair | 481.55 FL | *- FL |
| 34 | 1 | | *REAR FLOOR PANEL INSULATOR CLOTH | Necessary | 561.80 FL | *150.00 FL |
| 35 | 1 | | *SET REVERSE SENSOR WITH CONTROL UNIT | Shorted | 380.00 FS | *200.00 FS |

F=Franchise part. S=SpccNett. L=ListItemDisc.

Sub Total (S\$) **12,093.10** **7,446.53**
 - List Item Discount on L Items 25.00/25.00% (S\$) **2,928.28** **1,811.63**

Total Parts (S\$) **9,164.82** **5,634.90**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|---|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TOWING | New | 80.00 | 0.00 |
| 2 | TO REMOVE & REFIX EXHAUST SILENCER & STRAIGHTEN EXHAUST CENTER PIPE | New | 280.00 | 0.00 |
| 3 | TO CHECK & RECONNECT SNAP WIRING | New | 80.00 | 30.00 |
| 4 | TO TUFF COAT AFFECTED AREAS | New | 200.00 | 90.00 |
| 5 | TO ADJUST CHASSIS ALIGNMENT ON CAR O LINER | New | 380.00 | 0.00 |
| 6 | TO REMOVE & REFIX INTERIOR UPHOLSTERY | New | 200.00 | 80.00 |
| 7 | TO REMOVE & REFIX REVERSE SENSOR | New | 180.00 | 50.00 |
| 8 | TO REMOVE & REFIX BOOT LID MECHANISM | New | 250.00 | 60.00 |
| 9 | TO RESPRAY AFFECTED AREAS | New | 1,800.00 | 1,200.00 |
| 10 | TO RENEW DAMAGED PARTS ,STRAIGHTEN & REPAIR REAR FENDER,REAR CHASSIS FRAME MEMBER & ALIGNED ALL PARTS | New | 1,800.00 | 1,200.00 |
| Gross Labour Cost (S\$) | | | 5,250.00 | 2,710.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >