

GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

THE CARHUB
8 KAKI BUKIT AVE 4
05-25 PREMIER @ KB
Singapore 415875

04th Oct 2019

TP Chin
Khanchan

Accident date: 01ST October 2019

Estimated repair cost for vehicle no: SJK6106M TOYOTA VIOS (A) '08 / COE TIL 2023

S/n	Qty	Items	U/price	Amount	
1	1	Rear Tail Lamp-RH <i>cracked</i>		\$333.70	✓
2	4	Rear Tail Lamp Clips <i>new</i>	\$6.50	\$26.00	✓
3	1	Rear Tail Lamp Panel <i>not new</i>		\$281.10	X
4	1	Rear Bumper <i>totu</i>		\$581.75	✓
5	8	Rear Bumper Clips <i>new</i>	\$6.50	\$52.00	30
6	1	Rear Bumper Reverse Sensor <i>2</i>		\$350.00	X
7	1	Rear Bumper Bracket <i>new</i>		\$131.70	X
8	1	Rear Bumper Side Reflector -RH		\$83.10	X
9	1	Rear Bumper inner sponge <i>new</i>		\$0.00	X
10	1	Rear Bumper reinforcement <i>new</i>		\$0.00	X
11	1	Rear Fender- RH <i>Distorted</i>		\$972.40	✓
12	1	Rear Fender Inner Trim Board-RH <i>new</i>		\$325.10	X
13	10	Rear Fender Inner Trim Board Clips <i>new</i>	\$6.50	\$65.00	X
14	1	rear fender mud -shiled <i>new</i>		\$112.10	X
15	2	rear fender mud shiled clips <i>new</i>	\$12.90	\$25.80	X
16	1	Rear door <i>new</i>		\$1,020.00	X
17	1	rear door handle <i>new</i>		\$155.20	X
18	1	Rear door center protector <i>new</i>		\$158.20	X
19	1	Rear tire-RH <i>Deland</i>		\$350.00	180(SN)
20	1	Rear axle assy <i>Best</i>		\$2,350.00	1670
21	1	Rear rim <i>int</i>		\$400.00	✓
22	1	Rear shock absorber-RH <i>Best</i>		\$380.20	✓
23	1	Rear Axle bearing-RH <i>Best</i>		\$358.00	✓

4752.05

Subtotal :-

\$8,511.35

Labour charges

To remove & refit cushion

3564.03

SN: 180

\$150.00 80

To remove & refit reverse sensor

\$100.00 50

to remove & refix rear undercarriage with axle assy

\$280.00 280

To check wiring

\$60.00 30

Wheel alignment (computer)

\$120.00 80

Tuff kote

\$120.00 60

Panel beating

\$1,000.00 600

Spray painting

\$1,000.00 600

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Subtotal :-

\$2,830.00

Total:-

\$11,341.35