

ASS. REC. BY:

REF: CS/CT2 1901483/RIV-f3

Special Instruction:

Survivor: Rasul

ASSIGNMENT (Office)

From (Person):

Tan Kah Leong

of

CT1

Date/Time:

4.10.19 9.01A.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMK 9809M

Insured:

PL 8398 U

at Workshop m/s

Cyber & Carriage

Tel:

65684501 / 81680997

of

209 Pandan Garden

Policy No:

1900083403

Claim No:

SNM 1917 20412102

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

1.10.2019

CA / REV / REP. / REV 24 HRS

Date/Time:

4.10.19 9.30A.m

Person Contacted:

Kevin Leong

Vehicle:

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SMK 9809M - x

PL 8398 U - x

19/11/19

@4.30pm Kevin said vehicle still under repair

11/1/2020

Final fig \$ 19,726 confirmed by email (Ref 3639, 1690)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Oct 2019		04 Oct 2019 09:01 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS		[Created by insurer]		
Insured:				
Main Claimant:		YAN BIN, ID: G6243500W		
Vehicle Reg. No.:		SMK9809M	Date of Loss:	01/10/2019 08:00 - :59
Claim Type:		TP / SNM19D204621C02	Policy/Cover Note No.:	DMB15N30583219000
Vehicle Reg. No. (Insured):		PC8398U	Policy No. (Claimant):	1900083403
		Excess:	S\$1,500.00	
Repairer:		Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens, 609339 West Coast - Tel: 65684501/65684518		
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]		
Claimant's Insurer:		AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 15/10/2019]		
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail		
There are no mail for this case.				
ALL ASSOCIATED TASKS				
		View All	Search Tasks	Create New Task Complete
Due Date	Priority	Type	Task Group	Subject
			Handler	Assigned By
			Completed On	Created On
			Done?	
No results.				

Nivitha (LKK Auto)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Friday, 4 October 2019 8:58 AM
To: Kevin Leong Wai Kit; assignments
Subject: RE: OUR REF: SNM19D204621-PC8398U-TKL- TP CLAIM : SMK9809M AGAINST YOUR INSURED : PC8398U DOA : 01.10.2019

WITHOUT PREJUDICE

Dear Sirs,

We refer to your email dated 23.08.2019.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis.

Aside to LKK,

Please refer to the email below & proceed to survey the third party vehicle.

Thank you.

Regards

Tan Kah Leong

Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Kevin Leong Wai Kit [mailto:kevin.leong@cyclecarriage.com.sg]
Sent: Thursday, October 3, 2019 6:54 PM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Subject: RE: OUR REF: SNM19D204621-PC8398U-TKL- TP CLAIM : SMK9809M AGAINST YOUR INSURED : PC8398U DOA : 01.10.2019

Dear Kah Leong,

We choose : 5. XING QUO QIANG

Thank You & Best regards

Kevin Leong
Claim Division Operations
209 Pandan Gardens
Singapore 609339

Cycle & Carriage Singapore • 209 Pandan Gardens, Singapore 609339
T: +65 6568 4501 • F: +65 6565 1240 • H: +65 81680997 • www.cyclecarriage.com.sg

 A member of the Jardine Cycle & Carriage Group

From: Tan Kah Leong [<mailto:KahLeong.Tan@sg.cntaiping.com>]

Sent: Thursday, 3 October, 2019 5:40 PM

To: Kevin Leong Wai Kit

Subject: RE: OUR REF: SNM19D204621-PC8398U-TKL- TP CLAIM : SMK9809M AGAINST YOUR INSURED : PC8398U
DOA : 01.10.2019

This email was sent from outside of your organisation

Without Prejudice

Dear Sirs,

Please see attached and let us know if you agree with SJE.

Thank you.

Regards

Tan Kah Leong

Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Thursday, October 3, 2019 5:24 PM

To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>;
kevin.leong@cyclecarriage.com.sg

Subject: OUR REF: SNM19D204621-PC8398U-TKL- TP CLAIM : SMK9809M AGAINST YOUR INSURED : PC8398U DOA :
01.10.2019

Dear Kah Leong,

Please conduct PRS for SMK9809M.

Note : officer in charge – Kah Leong 63896193

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Kevin Leong Wai Kit [<mailto:kevin.leong@cyclecarriage.com.sg>]

Sent: Thursday, 3 October, 2019 11:41 AM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: Andre Chow En De <andre.chow@cyclecarriage.com.sg>; Don Bong Kiong Hua

<kionghua.bong@cyclecarriage.com.sg>; Coco Lu Ting <coco.lu@cyclecarriage.com.sg>; Edwin Abcede Caina <edwin.caina@cyclecarriage.com.sg>

Subject: TP CLAIM : SMK9809M AGAINST YOUR INSURED : PC8398U DOA : 01.10.2019

Dear All,

Our Client : **SMK9809M** vs your insured : **PC8398U**

Above attach SAS report and repair quotation for your reference.

Please let us have the liability.

Please arrange for survey on this Car
Vehicle already in workshop.

Thank You & Best regards

Kevin Leong
Claim Division Operations
209 Pandan Gardens
Singapore 609339



Cycle & Carriage Singapore • 209 Pandan Gardens, Singapore 609339
T: +65 6568 4501 • F: +65 6565 1240 • H: +65 81680997 • www.cyclecarriage.com.sg

 A member of the Jardine Cycle & Carriage Group

From: PGMFP06@cyclecarriage.com.sg [<mailto:PGMFP06@cyclecarriage.com.sg>]

Sent: Thursday, 3 October, 2019 11:29 AM

To: Kevin Leong Wai Kit
Subject:

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/10/2019 14:20
Date Of Accident	01/10/2019 08:10
Exact Location Of Accident	ALONG PIONEER ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMK9809M
Insured/Policyholder	
Name Of Registered Owner	YAN BIN
Passport No/FIN	G6243500W
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96928935
Alternative Phone No	OTHERS-96928935

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	ATTRAGE-1.2 CVT (A)
Exact Purpose for which vehicle was being used at time of accident	PERSONAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1900083403
Cover Note Number	

Driver

Name of Driver	YI QIN
Passport No/FIN	G8456024W
Date Of Birth	24/12/1985
Occupation	INDOOR
Date Of Driving Pass	05/06/2018
Driving Experience	1 YEAR AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96928935
Fax Number	
Contact Number	
EMail Address	YIQIN.1314.COM@163.COM

Address	26 WOODLANDS CRESCENT #04-28
Postcode	738084
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PC8398U
Vehicle Make/Model/Colour	TOYOTA/SILVER OR GREY
Details Of Properties	FRONT DENTED
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	KULANDAI AROOKIA DOSS
NRIC/Passport Number	
Contact Number	91371065
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:




Driver's Signature
(if driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I drive normally & stop at traffic light (red).
 back ^{other} ~~the~~ Car ^{Non} ~~stop~~ & hit rear of my car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Yan Bin

Policyholder's Signature
 Date & Time:

C/PO

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

[Signature]

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
YAN BIN	Cust No/Name KCV11174/YAN BIN
26 WOODLANDS CRESCENT	Reg No/Reg Date SMK9809M / 30/04/201
#04-28	Date In/Mileage 02/10/2019/ 10005
SINGAPORE 738084	Chassis No MMBSTA13AKH001555
Contact No	Engine No 3A92UHS1389
02/10/	Make/Model MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim W05 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	
KCV11174	CRDVCH	04/10/2019/ 10:45	QUK	282 / Kevin Leong	45850	
Description of Goods / Services			Qty	Unit Price	Disc%	Amount
E PNT88000		TO RENEW REAR BUMPER, REAR BOOT, REAR RH FENDER, REAR END PANEL, REAR FLOOR/PANEL & AFFECTED AREA TO REPAIR ON REAR LH FENDER	✓	4950		6050.00
E PNT98000		PAINT WORK ON REAR BUMPER, REAR BOOT, REAR END PANEL, REAR FLOOR PANEL REAR RH FENDER, REAR LH FENDER, REAR(SPOILER & BODYKIT,)	✓	2940		3380.00
E PNT88000		TO REMOVE & INSTALL REAR BOOT COMPONENT	✓	275		550.00
E PNT88000		REMOVE & INSTALL REAR PARKING ASSIST	✓	80		120.00
E PNT88000		TO REMOVE & INSTALL REAR WINDSCREEN GLASS FOR FACILITATE REPAIR	✓	230		250.00
E PNT88000		REMOVE & INSTALL REAR SEAT COMPARTMENT FOR FACILITATE REPAIR	✓	275		550.00
M SUNDRY		TO APPLY SEALANT ON REAR WINDSCREEN GLASS	✓			80.00
M SUNDRY		PERFORM RUST PREVENTION	✓	350		400.00
M SUNDRY		TO APPLY BODY SEALANT	✓	240		400.00
M SUNDRY		TO SUPPLY C & C EMBLEM	✓			50.00
A 54900099		CHECK ELECTRICAL SYSTEM	✓			80.00
A 10028901		TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST ???-REPORT	✓			200.00
M SUNDRY		SUNDRIES	✓	30		50.00
M SUNDRY		TO APPLY REAR TUFF COAST ON UNDER BODY	✓	80		120.00
M SUNDRY			✓	40		80.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
YAN BIN	Cust No/Name KCV11174/YAN BIN
26 WOODLANDS CRESCENT	Reg No/Reg Date SMK9809M / 30/04/201
#04-28	Date In/Mileage 02/10/2019/ 10005
SINGAPORE 738084	Chassis No MMBSTA13AKH001555
Contact No	Engine No 3A92UHS1389
02/10/	Make/Model MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim W05 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KCV11174	CRDVCH	04/10/2019/ 10:45	QUK	282 / Kevin Leong	45850
Description of Goods / Services					
	Qty	Unit Price	Disc%	Amount	
TO APPLY SEALANT ON REAR SPOILER & REAR BODYKIT				80 150.00	
E PNT88000					
TO REMOVE & INSTALL BODYKIT					
M LAMP ASSY, COMB, RR LH <i>ca</i>	1.00	335.00	00.00	335.00	
P LAMP ASSY, COMB, RR RH <i>ca</i>	1.00	335.00	00.00	335.00	
M REFLECTOR <i>? x su</i>	1.00	23.00	00.00	23.00	
M REFLECTOR <i>? x su</i>	1.00	23.00	00.00	23.00	
M LAMP ASSY, LICENSE PLATE <i>? x su</i>	1.00	51.00	00.00	51.00	
M BRACKET, RR BUMPER, LH <i>ne</i>	1.00	28.00	00.00	28.00	
M BRACKET, RR BUMPER, RH <i>ne</i>	1.00	28.00	00.00	28.00	
M FACE, RR BUMPER <i>de</i>	1.00	748.00	00.00	748.00	
M PANEL, QTR, OTR RH <i>su</i>	1.00	763.00	00.00	763.00	
M FLOOR, RR <i>bt</i>	1.00	956.00	00.00	956.00	
M PANEL, RR END <i>bt</i>	1.00	425.00	00.00	425.00	
M GLASS, RR WINDOW <i>x an</i>	1.00	544.00	00.00	544.00	
M STOPPER, WINDSHIELD GLASS <i>ne</i>	2.00	3.00	00.00	6.00	
M SPACER, RR WINDOW <i>ne x an</i>	3.00	9.00	00.00	27.00	
M PANEL, TRUNK LID <i>bt</i>	1.00	791.00	00.00	791.00	
M WEATHERSTRIP, TRUNK LID <i>ne</i>	1.00	157.00	00.00	157.00	
M HINGE, TRUNK LID, LH <i>? bt</i>	1.00	203.00	00.00	203.00	
M HINGE, TRUNK LID, RH <i>? bt</i>	1.00	203.00	00.00	203.00	
M LATCH, TRUNK LID <i>bt</i>	1.00	218.00	00.00	218.00	
M SHIELD, RR WHEELHOUSE, LH <i>? x su</i>	1.00	40.00	00.00	40.00	
M MUD GUARD, RR LH <i>? x su</i>	1.00	41.00	00.00	41.00	
M MUD GUARD, RR RH <i>? x su</i>	1.00	41.00	00.00	41.00	
M SHIELD, RR WHEELHOUSE, RH <i>? x su</i>	1.00	40.00	00.00	40.00	
M GARNISH, RR END PANEL <i>de</i>	1.00	336.00	00.00	336.00	
M MARK, THREE-DIA <i>ne</i>	1.00	69.00	00.00	69.00	
M MARK, ATTRAGE <i>ne</i>	1.00	21.00	00.00	21.00	
M TRIM, RR END <i>su</i>	1.00	66.00	00.00	66.00	
M BOARD, TRUNK ROOM FLOOR <i>ca</i>	1.00	195.00	00.00	195.00	
M CARPET, TRUNK ROOM <i>x su</i>	1.00	170.00	00.00	170.00	
M UNPAINTED BODYKITS <i>ca</i>	1.00	1110.00	00.00	1110.00	

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
YAN BIN	Cust No/Name KCV11174/YAN BIN
26 WOODLANDS CRESCENT	Reg No/Reg Date SMK9809M / 30/04/201
#04-28	Date In/Mileage 02/10/2019/ 10005
SINGAPORE 738084	Chassis No MMBSTA13AKH001555
Contact No	Engine No 3A92UHS1389
02/10/	Make/Model MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim W05 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KCV11174	CRDVCH	04/10/2019/ 10:45	QUK	282 / Kevin Leong	45850

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M SHARK FIN ANTENNA,ATTRAGE <i>Xan</i>	1.00	123.00	00.00	123.00

Estimate

[Signature]
7/10/19

SURVEYOR NAME: *Rasul - 17p 90010065*

SURVEYOR SIGNATURE: *[Signature]*

DATE: *04/10/19 @ 1045*

REMARKS: *16-17 days* *19 days*
Repy before paint
23,365

Confirm & accepted by

7% GST on	Nett 20606.00	20,606.00
		1442.42
Total Payable		22,048.42

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Exceptional Journeys

Surveyor : RASUL LKK
Claim : TP CHINA TAIPING
DOA : 01.10.2019
Emailed : 15.01.2020, 3pm
Date survey : 04.10.2019

VEHICLE NO : SMK 9809 M
MODEL : MIT ATTRAGE 1.2
WIP : 45850

Material	:	\$	<u>7,876.00</u>
Labour	:	\$	<u>11,850.00</u>
Sub-Total	:	\$	<u>19,726.00</u>
	:		<u>-</u>
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>19,726.00</u>
GST 7%	:	\$	<u>1,380.82</u>
Grand Total	:	\$	<u>21,106.82</u>
Finalise By/Date	:		<u>LOI / 15/01/2020</u>

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☒ REPAIR TOOK 19 WORKING DAYS + 8 Days (4) Weekends
+ 1 Days (1) Public Holiday
TOTAL DAYS REPAIR TOOK = 28

☒ TP claim PC8398U

☒ Claim GIA / LTA fee \$2.00

☒ Claim Loss of ☐ Use / ☒ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report -



CYCLE & CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
YAN BIN	Cust No/Name	KCV11174/YAN BIN
26 WOODLANDS CRESCENT	Reg No/Reg Date	SMK9809M / 30/04/2019
#04-28	Date In/Mileage	02/10/2019/ 10005
SINGAPORE 738084	Chassis/Package	MMBSTA13AKH001555 /DC17P
Contact No Mobile: 93270024	Engine No	3A92UHS1389
02/10/2019	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	W05 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00040	Cash	15/01/2020/ 14:39	TLK	260 / AiTing	45850
Description of Goods / Services					Qty Unit Price Disc% Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE REAR BUMPER, REAR BOOT, REAR FLOOR, REAR END PANEL, RH REAR FENDER, REAR BODY KIT, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME					✓ 4950.00
E PNT98000 RESPRAY ON REAR BUMPER, REAR BOOT, REAR END PANEL, REAR FLOOR PANEL RH REAR FENDER, LH REAR FENDER, REAR SPOILER, REAR BODY KIT, AND ALL OTHER AFFECTED AREAS TO THE SAME					✓ 2940.00
E PNT88000 REMOVE & INSTALL REAR BOOT COMPONENTS TO NEW PANEL					✓ 275.00
E PNT88000 REMOVE & INSTALL REAR PARKING ASSIST TO FACILITATE REPAIR					✓ 80.00
E PNT88000 REMOVE & INSTALL REAR WINDSCREEN GLASS TO FACILITATE REPAIR, AND CONDUCT WATER LEAK TEST					✓ 230.00
E PNT88000 REMOVE & INSTALL REAR SEAT COMPARTMENT TO FACILITATE REPAIR					✓ 275.00
M SUNDRY APPLY SEALANT ON REAR WINDSCREEN GLASS					✓ 80.00
M SUNDRY PERFORM RUST PREVENTION ON AFFECTED AREAS					✓ 350.00
M SUNDRY APPLY BODY SEALANT ON AFFECTED AREAS					✓ 240.00
M SUNDRY SUPPLY C & C EMBLEM					✓ 50.00
A 54900099 CHECK WIRING AND ELECTRICAL SYSTEM					✓ 80.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE					✓ 200.00
M SUNDRY SUNDRIES					✓ 30.00
M SUNDRY APPLY REAR TUFF COAT ON UNDER BODY					✓ 80.00

This is not an official tax invoice.
This is a computer generated document, no signature is required.

PRO-FORMA INVOICE

Co Reg No : 1977014696

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
YAN BIN	Cust No/Name KCV11174/YAN BIN
26 WOODLANDS CRESCENT	Reg No/Reg Date SMK9809M / 30/04/2019
#04-28	Date In/Mileage 02/10/2019/ 10005
SINGAPORE 738084	Chassis/Package MMBSTA13AKH001555 /DC17P
Contact No Mobile: 93270024	Engine No 3A92UHS1389
02/10/2019	Make/Model MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim W05 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CTP00040	Cash	15/01/2020/ 14:39	TLK	260 / A1Ting	45850			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M SUNDRY								40.00
APPLY SEALANT ON REAR SPOILER & REAR BODY KIT								80.00
E PNT88000								550.00
REMOVE & INSTALL REAR BODY KIT TO FACILITATE REPAIR								1100.00
A 13900099								220.00
REMOVE & INSTALL FUEL TANK TO FACILITATE REPAIR								
E PNT88000								
REPLACE LH REAR FENDER, LH REAR TAILLAMP PANEL, RH REAR TAILLAMP PANEL								
S SPECIALISTJOB								
SUPPLY ONE SET OF REVERSE SENSOR								
X LAMP ASSY, COMB, RR LH					1.00	335.00	00.00	335.00
X LAMP ASSY, COMB, RR RH					1.00	335.00	00.00	335.00
X BRACKET, RR BUMPER, LH					1.00	28.00	00.00	28.00
X BRACKET, RR BUMPER, RH					1.00	28.00	00.00	28.00
X FACE, RR BUMPER					1.00	748.00	00.00	748.00
X PANEL, QTR, OTR RH					1.00	763.00	00.00	763.00
X FLOOR, RR					1.00	956.00	00.00	956.00
X PANEL, RR END					1.00	425.00	00.00	425.00
X PANEL, TRUNK LID					1.00	791.00	00.00	791.00
X WEATHERSTRIP, TRUNK LID					1.00	157.00	00.00	157.00
X HINGE, TRUNK LID, LH					1.00	203.00	00.00	203.00
X HINGE, TRUNK LID, RH					1.00	203.00	00.00	203.00
X LATCH, TRUNK LID					1.00	218.00	00.00	218.00
X GARNISH, RR END PANEL					1.00	336.00	00.00	336.00
X MARK, THREE-DIA					1.00	69.00	00.00	69.00
X MARK, ATTRAGE					1.00	21.00	00.00	21.00
X TRIM, RR END					1.00	66.00	00.00	66.00
X BOARD, TRUNK ROOM FLOOR					1.00	195.00	00.00	195.00
X BODY KIT, ATTRAGE, A66					1.00	1110.00	00.00	1110.00
X PANEL, QTR, OTR LH					1.00	755.00	00.00	755.00
X PANEL, RR COMB LAMP HSG, LH					1.00	60.00	00.00	60.00
X PANEL, RR COMB LAMP HSG, RH					1.00	60.00	00.00	60.00

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 1977014696

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
YAN BIN	Cust No/Name	KCV11174/YAN BIN
26 WOODLANDS CRESCENT	Reg No/Reg Date	SMK9809M / 30/04/2019
#04-28	Date In/Mileage	02/10/2019/ 10005
SINGAPORE 738084	Chassis/Package	MMB5TA13AKH001555 /DC17P
Contact No Mobile: 93270024	Engine No	3A92UHS1389
02/10/2019	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	W05 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00040	Cash	15/01/2020/ 14:39	TLK	260 / AiTing	45850

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
✓ X SILENCER, FLOOR → Supp (A)	1.00	14.00	00.00	14.00

Pro Forma

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	7,876.00	Nett	19,726.00
Labour	10,760.00	7% GST on	1380.82
Standard Menu	0.00		
Specialist Job	220.00	Total Payable	21,106.82
Diagnostics Job	0.00		
Sundry/Others	870.00		
Total(w/o GST)	19,726.00		

This is not an official tax invoice.
This is a computer generated document, no signature is required.



Exceptional Journeys

INSURANCE CO. : CHINA TAIPING


Supplementary Parts For Registration No.: SMK 9809 M

	<u>Materials</u>	<u>Cost (\$)</u>
1	Panel, Qtr, Otr LH <i>See</i> ✓	755.00
2	Panel, RR comb lamp Hsg, LH <i>lt</i> ✓	60.00
3	Panel, RR comb lamp Hsg, RH <i>st</i> ✓	60.00
4	Silencer, floor <i>see</i> ✓	14.00
	Total Materials	889.00

	<u>Labour</u>	<u>Cost (\$)</u>
1	Remove & install fuel tank to facilitate repair	550.00 ✓
2	Replace LH rear fender, LH rear taillamp panel, RH rear taillamp panel	1100.00 ✓
3	Supply one set of reverse sensor	220.00 ✓
	Total Labour	1,870.00
	Taxable Amount	2,759.00
	7% GST	193.13
	Grand total	<u>2,952.13</u>

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD


LOI AI TING
SENIOR OFFICER - ADMIN
TEL: 6568 4556 / 6568 4501
FAX: 6567 5258 / 6565 1240

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 17 January 2020 10:22 AM
To: Loi Ai Ting; Kevin Leong Wai Kit; SUR
Cc: Jojo Cheng; Songcuan JR Lauro Araos; Andre Chow En De; Rasul (LKKAuto)
Subject: RE: SMK9809M, finalisation (Mit WIP: 45850)

Dear Ai Ting,

WITHOUT PREJUDICE

Finalize amount \$19,726 before GST @ 19 working days

Kindly send Final invoice and all supporting documents directly to CHINA TAIPING

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Loi Ai Ting <aiting.loi@cyclecarriage.com.sg>
Sent: Wednesday, 15 January 2020 4:12 PM
To: Kevin Leong Wai Kit <kevin.leong@cyclecarriage.com.sg>
Cc: Jojo Cheng <jojo.cheng@cyclecarriage.com.sg>; Songcuan JR Lauro Araos <lauro.songcuan@cyclecarriage.com.sg>; Andre Chow En De <andre.chow@cyclecarriage.com.sg>; Rasul (LKKAuto) <Rasul@lkkauto.com>
Subject: RE: SMK9809M, finalisation (Mit WIP: 45850)

Hi, Kevin,

Please assist to forward any before paint photos to Rasul.

Thanks.

Best Regards,

Loi Ai Ting
Senior Officer - Admin



CYCLE & CARRIAGE

Exceptional Journeys

Cycle & Carriage Singapore • 209 Pandan Gardens, Singapore 609339
T: +65 6568 4556 • F: +65 6565 1240 • www.cyclecarriage.com.sg

 A member of the Jardine Cycle & Carriage Group

From: Rasul (LKKAUTO) [<mailto:Rasul@lkkauto.com>]
Sent: Wednesday, 15 January, 2020 4:03 PM
To: Loi Ai Ting
Cc: Jojo Cheng; Songcuan JR Lauro Araos; Andre Chow En De
Subject: RE: SMK9809M, finalisation (Mit WIP: 45850)

This email was sent from outside of your organisation

Hi Ai Ting,

Kindly forward the resurvey before paint photos

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Loi Ai Ting [<mailto:aiting.loi@cyclecarriage.com.sg>]
Sent: Wednesday, 15 January, 2020 3:15 PM
To: Rasul (LKKAUTO)
Cc: Admin A; Admin-D (LKKAUTO); Jojo Cheng; Songcuan JR Lauro Araos; Andre Chow En De
Subject: SMK9809M, finalisation (Mit WIP: 45850)

Hi, Rasul,

Kindly confirm finalised amount at \$21,106.82, after GST.

Thanks.

Best Regards,

Loi Ai Ting
Senior Officer - Admin



CYCLE & CARRIAGE

Exceptional Journeys

Cycle & Carriage Singapore • 209 Pandan Gardens, Singapore 609339
T: +65 6568 4556 • F: +65 6565 1240 • www.cyclecarriage.com.sg

A member of the Jardine Cycle & Carriage Group

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Oct 2019		04 Oct 2019 09:01 Edit Adj Rpt	S\$19,726.00 Edit Estimates	S\$19,726.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: -, ID: -									
Main Claimant: YAN BIN , ID: G6243500W									
Vehicle Reg. No.: SMK9809M		Date of Loss: 01/10/2019 08:00 - :59 [5 Months and 1 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM19D204621C02		Policy/Cover Note No.: DMB1SN30583219000							
Vehicle Reg. No. (Insured): PC8398U		Policy No. (Claimant): 1900083403							
		Excess: S\$1,500.00							
Repairer: Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens, 609339 West Coast - Tel: 65684501/65684518									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]									
Claimant's Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 15/10/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMK9809M (SNM19D204621C02)
[PC8398U]

TP

YAN BIN

Oct 1 2019 8:00AM

[-]

Cycle & Carriage Automotive Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Video

1 per page

☒

No	Finalized On	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)	Thumbnail	Print
1	01/10/19 14:25	Video - Accident [Linked Accident Report Documents]	Load MP4	

Photos/Images

3 per page

☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/01/20 10:10	General View	Load PDF	
2	17/01/20 10:11	Reinspection Photo (1)	Load PDF	
3	17/01/20 10:11	Reinspection Photo (2)	Load PDF	

Documentation

1 per page

☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/01/20 08:46	SUPPLEMENTARY PART	Load PDF	

Linked Accident Report Documents

View View in Browser

Video										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)						Thumbnail	Print		
1	01/10/19 14:25	Video - Accident							Load MP4		

Assessment Reports











1 per page☒

No	Finalized On	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)						Thumbnail	Print
1	11/10/19 13:35	Addendum Sheet							Load JPG <input checked="" type="checkbox"/>
2	06/12/19 18:40	Accident Statement							Load HTM
3	06/12/19 18:40	Accident Statement							Load HTM
4	06/12/19 18:40	Accident Statement							Load HTM
5	06/12/19 18:42	Accident Statement							Load HTM
6	06/12/19 18:42	Accident Statement							Load HTM
7	06/12/19 18:42	Accident Statement							Load HTM
8	06/12/19 18:44	Accident Statement							Load HTM
9	06/12/19 18:46	Accident Statement							Load HTM

Photos/Images

3 per page☒

No	Finalized On	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)						Thumbnail	Print
1	01/10/19 14:27	Accident Photo							Load JPG <input checked="" type="checkbox"/>
2	01/10/19 14:27	Accident Photo							Load JPG <input checked="" type="checkbox"/>
3	01/10/19 14:27	Accident Photo							Load JPG <input checked="" type="checkbox"/>
4	01/10/19 14:27	Accident Photo							Load JPG <input checked="" type="checkbox"/>
5	01/10/19 14:27	Accident Photo							Load JPG <input checked="" type="checkbox"/>
6	01/10/19 14:27	Accident Photo							Load JPG <input checked="" type="checkbox"/>
7	01/10/19 14:27	Accident Photo							Load JPG <input checked="" type="checkbox"/>
8	01/10/19 14:27	Accident Photo							Load JPG <input checked="" type="checkbox"/>
9	01/10/19 14:27	Accident Photo							Load JPG <input checked="" type="checkbox"/>
10	01/10/19 14:27	Accident Photo							Load JPG <input checked="" type="checkbox"/>
11	01/10/19 14:27	Accident Photo							Load JPG <input checked="" type="checkbox"/>
12	01/10/19 14:27	Accident Photo							Load JPG <input checked="" type="checkbox"/>
13	01/10/19 14:27	Accident Photo							Load JPG <input checked="" type="checkbox"/>
14	01/10/19 14:27	Accident Photo							Load JPG <input checked="" type="checkbox"/>

Video				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)		Thumbnail	Print
					<input checked="" type="checkbox"/>
15	01/10/19 14:27	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
16	01/10/19 14:27	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
17	01/10/19 14:27	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
18	01/10/19 14:27	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
19	01/10/19 14:27	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
20	01/10/19 14:27	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
21	01/10/19 14:27	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
22	01/10/19 14:27	Identification Card		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)		Thumbnail	Print
1	01/10/19 14:25	Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
2	01/10/19 14:25	Sketch Plan #2		Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119017483/R1VF3Q2

Date: 23/01/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SN30583219000
Claimant Vehicle No :	SMK9809M	Insured Vehicle No :	PC8398U
Date of Loss:	01/10/2019	Nature of Claim:	TP
		Claim No:	SNM19D204621C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK9809M	Engine No:	3A92UHS1389
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Chassis No:	MMBSTA13AKH001555
Reg. Date:	30/04/2019 (Man. Year: 2018)	Odometer:	10005 km
Colour:	Grey		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,105.00	7,956.00	1,149.00	12.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,260.00	11,770.00	2,490.00	17.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	23,365.00	19,726.00	3,639.00	15.57
+ GST 7.00/7.00% (S\$)	1,635.55	1,380.82	254.73	15.57
Nett Amount (S\$)	25,000.55	21,106.82	3,893.73	15.57

INSPECTION

Date of Assignment:	04/10/2019	
Date Inspected:	04/10/2019 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	19.0 days	

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 22 Jan 2020)	
Parts:	N/A	MITSUBISHI ATTRAGE 1.2 CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMK9809M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*C&C EMBLEM	Necessary	50.00 FS	*50.00 FS
2	1		*SUNDRIES	Necessary	50.00 FS	*30.00 FS
3	1		*LAMP ASSY ,COMB ,RR LH	Cracked	335.00 FS	*335.00 FS
4	1		*LAMP ASSY ,COMB ,RR RH	Cracked	335.00 FS	*335.00 FS
5	1		*REFLECTOR	Serviceable	23.00 FS	*- FS
6	1		*REFLECTOR	Serviceable	23.00 FS	*- FS
7	1		*LAMP ASSY ,LICENSE PLATE	Serviceable	51.00 FS	*- FS
8	1		*BRACKET ,RR BUMPER ,LH	Necessary	28.00 FS	*28.00 FS
9	1		*BRACKET ,RR BUMPER ,RH	Necessary	28.00 FS	*28.00 FS
10	1		*FACE ,RR BUMPER	Deformed	748.00 FS	*748.00 FS
11	1		*PANEL ,QTR ,OTR RH	Buckled	763.00 FS	*763.00 FS
12	1		*FLOOR ,RR	Bent	956.00 FS	*956.00 FS
13	1		*PANEL ,RR END	Bent	425.00 FS	*425.00 FS
14	1		*GLASS ,RR WINDOW	Not Necessary	544.00 FS	*- FS
15	2		*STOPPER ,WINDSHIELD GLASS	Not Necessary	6.00 FS	*- FS
16	3		*SPACER ,RR WINDOW	Not Necessary	27.00 FS	*- FS
17	1		*PANEL ,TRUNK LID	Bent	791.00 FS	*791.00 FS
18	1		*WEATHERSTRIP ,TRUNK LID	Necessary	157.00 FS	*157.00 FS
19	1		*HINGE ,TRUNK LID ,LH	Bent	203.00 FS	*203.00 FS
20	1		*HINGE ,TRUNK LID ,RH	Bent	203.00 FS	*203.00 FS
21	1		*LATCH ,TRUNK LID	Bent	218.00 FS	*218.00 FS
22	1		*SHIELD ,RR WHEELHOUSE ,LH	Serviceable	40.00 FS	*- FS
23	1		*MUD GUARD ,RR LH	Serviceable	41.00 FS	*- FS
24	1		*MUD GUARD ,RR RH	Serviceable	41.00 FS	*- FS
25	1		*SHIELD ,RR WHEELHOUSE ,RH	Serviceable	40.00 FS	*- FS
26	1		*GARNISH ,RR END PANEL	Deformed	336.00 FS	*336.00 FS
27	1		*MARK ,THREE- DIA	Necessary	69.00 FS	*69.00 FS
28	1		*MARK ,ATTRAGE	Necessary	21.00 FS	*21.00 FS
29	1		*TRIM ,RR END	Deformed	66.00 FS	*66.00 FS
30	1		*BOARD ,TRUNK ROOM FLOOR	Cracked	195.00 FS	*195.00 FS
31	1		*CARPET ,TRUNK ROOM	Serviceable	170.00 FS	*- FS
32	1		*UNPAINTED BODYKITS	Cracked	1,110.00 FS	*1,110.00 FS
33	1		*SHARK FIN ANTENNA ,ATTRAGE	Not Necessary	123.00 FS	*- FS
34	1		*PANEL ,QTR ,OTR LH	Buckled	755.00 FS	*755.00 FS
35	1		*PANEL ,RR COMB LAMP HSG ,LH	Bent	60.00 FS	*60.00 FS
36	1		*PANEL ,RR COMB LAMP HSG ,RH	Bent	60.00 FS	*60.00 FS
37	1		*SILENCER ,FLOOR	Necessary	14.00 FS	*14.00 FS
Total Parts (\$\$)					9,105.00	7,956.00

F=Franchise part, S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW REAR BUMPER ,REAR BOOT ,REAR RH FENDER ,REAR END PANEL ,REAR FLOOR PANEL & AFFECTED AREA TO REPAIR ON REAR LH FENDER	New	6,050.00	4,950.00
2	PAINT WORK ON REAR BUMPER ,REAR BOOT ,REAR END PANEL,REAR FLOOR PANEL REAR RH FENDER ,REAR LH FENDER ,REAR SPOILER & BODYKIT	New	3,360.00	2,940.00
3	TO REMOVE & INSTALL REAR BOOT COMPONENT	New	550.00	275.00
4	REMOVE & INSTALL REAR PARKING ASSIST	New	120.00	80.00
5	TO REMOVE & INSTALL REAR WINDSCREEN GLASS FOR FACILITATE REPAIR	New	250.00	230.00
6	REMOVE & INSTALL REAR SEAT COMPARTMENT FOR FACELITATE REPAIR	New	550.00	275.00
7	TO APPLY SEALANT ON REAR WINDSCREEN GLASS	New	80.00	80.00
8	PERFORM RUST PREVENTION	New	400.00	350.00
9	TO APPLY BODY SEALANT	New	400.00	240.00
10	CHECK ELECTRICAL SYSTEM	New	80.00	80.00
11	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	200.00	200.00
12	TO APPLY REAR TUFF COAST ON UNDER BODY	New	120.00	80.00
13	TO APPLY SEALANT ON REAR SPOILER & REAR BODYKIT	New	80.00	40.00
14	TO REMOVE & INSTALL BODYKIT	New	150.00	80.00
15	REMOVE & INSTALL FUEL TANK TO FACILITATE REPAIR	New	550.00	550.00
16	REPLACE LH REAR FENDER ,LH REAR TAILLAMP PANEL ,RH REAR TAILLAMP PANEL	New	1,100.00	1,100.00
17	SUPPLY ONE SET OF REVERSE SENSOR	New	220.00	220.00
Gross Labour Cost (\$\$)			14,260.00	11,770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >