

00 -

BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
 ROC/ GST Reg No.: 200007407G

Date: 1 Oct 2019

ASSESSMENT FOR REPAIR: HONDA CB400SF MANUAL - FBK6195A

Chassis No.: NC421603953
 Engine No.: NC42E1203953

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Front wheel axle	110 \$115.00 ? / BT
1 pc	Front left fork assy	\$1,088.00 X scr ^q X R
1 pc	Front right fork assy	\$1,088.00 X scr ^q Svc
1 pc	Front left brake disk	320 \$350.00 scr ^q BT
1 pc	Front Right brake disk	\$350.00 X scr ^q Svc
1 pc	Front fork steering head crown	\$450.00 X scr ^q Svc
1 pc	Front fork steering stem	\$490.00 X scr ^q Svc
2 pcs	Steering stem bearing @ \$45.00	\$90.00 X scr ^q Svc
1 pc	Brake lever	120 \$145.00 / BR
1 pc	Steering handle	160 \$180.00 scr ^q BT
1 pc	Right front signal	120 \$145.00 / scr
1 pc	Right handle bar balancer	\$55.00 / scr
1 pc	View mirror right	\$140.00 / scr
1 pc	Meter assy	\$980.00 X scr ^q Svc ^{? Outer cover item in supplementary}
1 pc	Brake pedal assy	\$165.00 / scr
1 set	Right crash bar	200 \$220.00 / scr
1 pc	Right rear footrest holder	\$265.00 scr ^q BT
1 pc	Exhaust slider	\$105.00 / scr
1 pc	Rear right footrest	80 \$95.00 / scr
1 pc	Front right footrest	80 \$95.00 / scr
4 pcs	Exhaust gasket @ \$15.00	\$60.00 X scr ^q reuse
1 pc	Exhaust assembly	1,780 \$1,880.00 ? check exhaust mufflers to buy separately
	Less discount 10%	\$8,551.00 \$855.10 \$7,695.90
	Special nett items	
1 pc	Front sport rim	\$790.00 scr ^q X R
1 pc	Box rack	\$195.00 X scr ^q Svc
1 pc	Top case	\$300.00 / scr
1)	Towing charges	250 \$100.00 80
	Replace, realign and adjust above damaged parts, check wiring and lighting system	\$700.00 150 300
2)	To replace and balance front wheel rim	\$150.00 scr ^q Repair front rim
3)	To knock, straighten chassis & body balancing	nn X \$450.00 scr ^q
4)	To remove/refit, replace (if damage) check and straighten front fork tubes.	\$180.00 ^q 300 Repair and adjust front fork
	Total Estimate	<u>\$10,560.90</u>

11274-90