

08/11/13 wef

ASS. REC. BY: Marcus

REF:

CC3/MSG/1017503/USF3N2

MS16/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

have GIA LTA28779 745 hrs

3/10/19 Email GIA to MSG
11/11/19 L/S * 14,000 confirmed with the
(\$ 26,711.86 Red - 66%)

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Rear

R/Bal.

L/Bal.

D.O.A.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)



: Preli. Report



: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$ 14,000/ 45)

250

11

261

RECEIVED 12 NOV 2019

11/11/2019

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 7 October 2019 11:16 AM
To: SUR; motorsurvey@sg.msig-asia.com
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 3/10/2019, YP 6923S (TP VEHICLE), XD 5839J (OI VEHICLE)
Attachments: GIA.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle YP 6923S at M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 on 4/10/2019

Enclosed herewith a copy of TP's GIA report and estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

Veron Chen | Case Handler on behalf of Shirley

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

Enjoy our
30th Anniversary
rebates worth
more than \$30,000.



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

03/2015 BMW X4 XDRIVE28I AWD LED SR NAV HUD at ...



PML Fully Agent Service, 100%
No Accident, Good Condition.
Please Call 91739289
StarAd

- Free VICOM evaluation
- Free grooming and 6 months maintenance
- In-house workshop ensures quality service
- Member of SVTA and hire purchase association
- 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD








Browse by Category

Sort by Date Posted 20 results/page

9 vehicles

Mitsubishi Canter

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Mitsubishi Canter		Any	Any	2017	Any	Any	Any	Available
	Mitsubishi	Fuso Canter FEB71	\$57,800	\$7,780 /yr	07-Mar-2017	2,998 cc	-	Truck	Available
Fuel Type: Diesel Laden Weight Up To 4 TONS. Full Checker Plate. Goldbell Service. Well Maintain. \$0 Drive-away, Over-loan, Over-trade. Previous Owner... ABWIN Bus Pte Ltd Posted: 04-Oct-2019 Tags: 2017 Mitsubishi Fuso, 2017 mitsubishi fuso, Mitsubishi Fuso, mitsubishi fuso, Mitsubishi, Fuso, fuso, Used Mitsubishi									
	Mitsubishi	Fuso Canter FEB21	\$63,800	\$8,430 /yr	28-Apr-2017	2,998 cc	79,120 km	Truck	Available
Fuel Type: Diesel Cheapest Depreciation In Town, Less Than \$9k Depreciation Per Month For A 14 Feet Lorry With Box And Tailgate. Condition Like Almost... ABWIN (1994) Pte Ltd Posted: 04-Oct-2019 Tags: 2017 Mitsubishi Fuso, 2017 mitsubishi fuso, Mitsubishi Fuso, mitsubishi fuso, Mitsubishi, Fuso, fuso, Used Mitsubishi									
	Mitsubishi	Fuso Canter 3.0M	\$63,800	\$7,740 /yr	29-Dec-2017	2,998 cc	-	Truck	Available
Fuel Type: Diesel 1 Owner Only. 14 Feet With Full Canopy, Can Drive With Class 3 Licence. Carry Up To 2.5 Ton Of Goods. 100% Loan OK. In House Loan... ABWIN Bus Pte Ltd Posted: 03-Oct-2019 Tags: 2017 Mitsubishi Fuso, 2017 mitsubishi fuso, Mitsubishi Fuso, mitsubishi fuso, Mitsubishi, Fuso, fuso, Used Mitsubishi									
	Mitsubishi	Fuso Canter FEB21	-	N.A	22-Aug-2017	2,998 cc	68,322 km	Truck	Available
Fuel Type: Diesel Auction Closing Time: 9th Oct 2019 at 11:00 PM GST Registered. 2 Keys Available. Road Tax Expiry On 21/08/2019. Mileage Of 68322Km. Mitsubishi Canter FEB21ER4SDEB (CBU), Maxi... Posted: 02-Oct-2019 Tags: 2017 Mitsubishi Fuso, 2017 mitsubishi fuso, Mitsubishi Fuso, mitsubishi fuso, Mitsubishi, Fuso, fuso, Used Mitsubishi									
	Goldbell Engineering Pte Ltd (Mitsubishi Fuso) - New Car Dealers Goldbell Engineering has been the authorised distributor of Mitsubishi Fuso trucks and buses in Singapore since the 1981 More info about this shop								
	Mitsubishi	Fuso Canter FEB50	\$51,000	\$6,830 /yr	23-Mar-2017	2,998 cc	66,000 km	Truck	Available
Fuel Type: Diesel New Canopy, New Paint, No Need VPC, Dereg Value \$32k. Posted: 27-Sep-2019 Tags: 2017 Mitsubishi Fuso, 2017 mitsubishi fuso, Mitsubishi Fuso, mitsubishi fuso, Mitsubishi, Fuso, fuso, Used Mitsubishi									
	Mitsubishi	Fuso Canter FEB71	\$68,800	\$9,190 /yr	30-Mar-2017	2,998 cc	42,585 km	Truck	Available
Fuel Type: Diesel Low Mileage! Only 18k Km Per Year. Excellent Condition, Well Maintained By Previous Owner. Loan Available. Checkered Flooring Box Wi... Posted: 17-Sep-2019 Tags: 2017 Mitsubishi Fuso, 2017 mitsubishi fuso, Mitsubishi Fuso, mitsubishi fuso, Mitsubishi, Fuso, fuso, Used Mitsubishi									

Compare

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	010M
Vehicle Details	
Vehicle No.:	YP6923S
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Oct 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	CANTER FEB21ER4SDEB (CBU)
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	4P10C75330
Chassis No.:	FEB21EA21447
Maximum Power Output:	-
Open Market Value:	\$33,567.00
Original Registration Date:	25 Jul 2017
First Registration Date:	25 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$1,679.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	24 Jul 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$36,879.00
COE Rebate Amount:	\$28,779.00
Total Rebate Amount:	\$28,779.00

The information contained herein is correct as at 04 Oct 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/10/2019 14:23
Date Of Accident	03/10/2019 17:10
Exact Location Of Accident	PIONEER RD OUTSIDE TTJ DESIGN & ENGINEERING PTE LT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YP6923S
Insured/Policyholder	
Name Of Registered Owner	UNIVERSAL M & E PTE LTD
Co Reg No	201405010M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-96127961

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	CANTER
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN3046771901
Cover Note Number	

Driver

Name of Driver	PAUL NADAR ANAND
NRIC No	G2009186Q
Date Of Birth	15/02/1987
Occupation	OUTDOOR
Date Of Driving Pass	30/01/2015
Driving Experience	4 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96127961
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	11 TECH PARK CRES
Postcode	638121
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD5839J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	XE3552T
-----------------------------	---------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

PAUL NADAR ANAND

Approximate Age

Injuries Sustain

BODY

Injured person in which vehicle?

YP6923S

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

Accident Sketch Plan

SKETCH PLAN

A. YP 6923 S
B. XD 5839 J
C. XE 3552 T

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 03.10.2019 at about 17.07. I was travelling along Pioneer Road
Outside TJS Design & Engineering Pte Ltd. I slowed down. Suddenly I
felt an impact from my rear and my car moved forward and hit Vehicle C
I was involved in a 3 vehicles chain collision
I got 2 day MC

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

P. L. L.

Driver's Signature
(If driver is not the policyholder)
Date & Time:

for

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

FASTECH AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46,48,50 AUTOBAY
SINGAPORE 417883

Not Authorized
RKR
2/5 = 14,000/
4/10/19
8 dy.

VEHICLE NO: YP 6923S

QTY	PARTICULAR
1 PCS	TAILGATE 1800
1 PCS	TAILGATE 'FUSO' STICKER
1 PCS	TAILGATE LOWER MEMBER 699.50
1 PCS	TAILLAMP O/S
1 PCS	DROPSIDE GATE LOWER MEMBER O/S 899.10
1 PCS	REAR 'L' PANEL O/S
1 PCS	REAR 'L' PANEL STOPPER O/S
1 PCS	DROPSIDE PANEL O/S
1 PCS	FRONT PANEL 1559.60
1 SET	FRONT PANEL 'FUSO' EMBLEM 86.50
1 PCS	FRONT WIPER PANEL GARNISH 715.35
1 PCS	FRONT GRILLE 618.32
1 PCS	FRONT GRILLE LOGO
1 PCS	FRONT GRILLE 'CANTER' EMBLEM
1 PCS	FRONT CORNER PANEL O/S
1 PCS	FRONT SIGNAL LAMP O/S 315.42
2 PCS	HEADLAMPS @\$905.00 730.28
1 PCS	FRONT SIDE LAMP O/S 245.96
1 PCS	FRONT WINDSCREEN RUBBER
1 PCS	FRONT BUMPER
1 PCS	FRONT BUMPER SIDE PROTECTOR O/S
2 PCS	FRONT CABIN MOUNTINGS @\$380.50
1 PCS	FRONT CABIN MOUNTING CENTRE BEAM 1021.10
3 PCS	FRONT CLUTCH PIPES @\$105.00
1 PCS	FRONT DOOR O/S
1 PCS	FRONT DOOR INNER TRIM BOARD O/S
1 PCS	FRONT DOOR INNER LOCK O/S
1 PCS	AIR CON BLOWER
1 PCS	AIR CON HEATER ASSY 2251.35
1 PCS	BRAKE BOOSTER 1200.00
1 PCS	BRAKE MASTER PUMP
1 PCS	DASHBORAD
1 PCS	POWER STEERING BOX
1 PCS	STEERING COLUMN SHAFT
1 PCS	FRONT CABIN REAR FILTER HOSE 285.11

S.NETT

1 PCS	TAILGATE 60KM/H STICKER
1 PCS	TAILGATE '21 PAX' STICKER
1 PCS	REAR STEP BAR PANEL
1 PCS	REAR SAFETY BAR

LABOUR CHARGES

TO CHECK WIRING

TO DISMANTLE & REFIX FRONT WINDSCREEN

DD/Bent	\$2,998.00	✓
ner	\$155.20	✓
ser	\$899.00	✓
cm	\$285.50	✓
ser/ser	\$1,021.00	✓
ser	\$166.80	✓
cu7	\$65.00	✓
n	\$4,988.20	X
so dy m	\$1,688.10	✓
ner	\$126.20	✓
cm	\$866.20	✓
cm	\$1,102.50	✓
ner	\$66.80	✓
rec	\$68.00	✓
cm	\$485.50	✓
ser	\$380.50	✓
o/s cm	\$1,810.00	1 PC
cm	\$366.50	✓
11	\$509.20	X
n	\$1,033.30	X
cu7	\$315.20	✓
o/s m	\$761.00	1 PC
ser	\$1,212.00	✓
ser	\$315.00	1 PC
ser/ser	\$1,827.61	✓
cm	\$586.10	✓
twi	\$399.50	✓
ser	\$1,866.20	X
cm	\$2,450.00	✓
so/ser	\$1,550.20	✓
ser	\$392.60	X
ser	\$1,021.45	X
11	\$515.30	X
twi	\$488.20	✓
cu7	\$300.00	✓
	\$33,081.86	

17822.80
13367.1

ner	\$20.00	10 S.N
ner	\$20.00	10 S.N
ser	\$800.00	400 S.N
11	\$1,200.00	X

\$80.00 30
\$150.00 80

TO DISMANTLE & REFIX FRONT DASHBOARD	\$300.00	220
TO DISMANTLE & REPLACING FRONT BRAKE BOOSTER	\$180.00	80
TO REMOVE & REFIX A/C COOLING SYSTEM & ref. filter conges	\$150.00	100
TO SPRAY RUST PROOFING	\$150.00	80
TO REMOVE , REFIX & REALIGN FRONT CABIN	\$380.00	X
LABOUR FOR PANEL BEATING & REPLACING PARTS	\$2,200.00	1600
TO PUTTY & SPRAY PAINTING	\$2,000.00	1600
TOTAL	\$40,711.86	

3790

17591
12053

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG19017503/USF3N2

Date: 12/11/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VCC/19-000308
Claimant Vehicle No :	YP6923S	Insured Vehicle No :	XD5839J
Date of Loss:	03/10/2019	Nature of Claim:	TP
		Claim No:	MSC/V/19-001216

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP6923S	Engine No:	4P10C75330
Make & Model:	MITSUBISHI CANTER, 3.0 D FEB21ER4SDEB (CBU) (M)	Chassis No:	FEB21EA21447
Reg. Date:	25/07/2017 (Man. Year: 2017)	Odometer:	225180 km
Colour:	White		
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15	Rear Tyre Size:	195R15(D)
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5/5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	35,121.86	13,787.10	21,334.76	60.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,590.00	3,790.00	1,800.00	32.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	40,711.86	17,577.10	23,134.76	56.83
Approved Total (Overridden) (\$\$)		14,000.00		
(\$\$)	40,711.86	14,000.00	26,711.86	65.61
+ GST 7.00/7.00% (\$\$)	2,849.83	980.00	1,869.83	65.61
Nett Amount (\$\$)	43,561.69	14,980.00	28,581.69	65.61

INSPECTION

Date of Assignment:	07/10/2019	
Date Inspected:	04/10/2019 Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883

Estimated Period of Repair: 8.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 12 Nov 2019)
Parts:	N/A MITSUBISHI CANTER 3.0 D FEB21ER4SDEB (CBU) (M) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP6923S)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented/Bent	2,998.00 F	*1,800.00 FL
2	1		*TAILGATE FUSO STICKER	Necessary	155.20 F	*155.20 FL
3	1		*TAILGATE LOWER MEMBER	Bent	899.00 F	*699.50 FL
4	1		*TAILLAMP O/S	Cracked	285.50 F	*285.50 FL
5	1		*DROPSIDE GATE LOWER MEMBER O/S	Bent/Buckled	1,021.00 F	*899.10 FL
6	1		*REAR L PANEL O/S	Bent	166.80 F	*166.80 FL
7	1		*REAR L PANEL STOPPER O/S	Cut	65.00 F	*65.00 FL
8	1		*DROPSIDE PANEL O/S	Repair	4,988.20 F	*- FL
9	1		*FRONT PANEL	Badly Dented	1,688.10 F	*1,559.60 FL
10	1		*FRONT WIPER PANEL GARNISH	Cracked	866.20 F	*715.35 FL
11	1		*SET FRONT PANEL FUSO EMBLEM	Necessary	126.20 F	*86.50 FL
12	1		*FRONT GRILLE	Cracked	1,102.50 F	*618.32 FL
13	1		*FRONT GRILLE LOGO	Necessary	66.80 F	*66.80 FL
14	1		*FRONT GRILLE CANTER EMBLEM	Necessary	68.00 F	*68.00 FL
15	1		*FRONT CORNER PANEL O/S	Cracked	485.50 F	*485.50 FL
16	1		*FRONT SIGNAL LAMP O/S	Broken	380.50 F	*315.42 FL
17	1		*HEADLAMPS	O/s Cracked	1,810.00 F	*730.58 FL
18	1		*FRONT SIDE LAMP O/S	Cracked	366.50 F	*245.96 FL
19	1		*FRONT WINDSCREEN RUBBER	Not Necessary	509.20 F	*- FL
20	1		*FRONT BUMPER	Repair	1,033.30 F	*- FL
21	1		*FRONT BUMPER SIDE PROTECTOR O/S	Cut	315.20 F	*315.20 FL
22	1		*FRONT CABIN MOUNTINGS	O/s Twisted	761.00 F	*380.50 FL
23	1		*FRONT CABIN MOUNTING CENTRE BEAM	Bent	1,212.00 F	*1,021.10 FL
24	1		*FRONT CLUTCH PIPES (3 Pcs)	Bent (1 Pc only)	315.00 F	*105.00 FL
25	1		*FRONT DOOR O/S	Bent/Buckled	1,827.61 F	*1,827.61 FL
26	1		*FRONT DOOR INNER TRIM BOARD O/S	Cracked	586.10 F	*586.10 FL
27	1		*FRONT DOOR INNER LOCK O/S	Twisted	399.50 F	*399.50 FL
28	1		*AIR CON BLOWER	Serviceable	1,866.20 F	*- FL
29	1		*AIR CON HEATER ASSY	Cracked	2,450.00 F	*2,251.35 FL
30	1		*BRAKE BOOSTER	Dented/Jammed	1,550.20 F	*1,200.00 FL
31	1		*BRAKE MASTER PUMP	Serviceable	392.60 F	*- FL
32	1		*DASHBOARD	Serviceable	1,021.45 F	*- FL
33	1		*POWER STEERING BOX	Not Necessary	515.30 F	*- FL
34	1		*STEERING COLUMN SHAFT	Twisted	488.20 F	*488.20 FL
35	1		*FRONT CABIN REAR FILTER HOSE	Cut	300.00 F	*285.11 FL
36	1		*TAILGATE 60KM/H STICKER	Necessary	20.00 FS	*10.00 FS
37	1		*TAILGATE 21 PAX STICKER	Necessary	20.00 FS	*10.00 FS
38	1		*REAR STEP BAR PANEL	Bent	800.00 FS	*400.00 FS
39	1		*REAR SAFETY BAR	Not Necessary	1,200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 35,121.86 18,242.80
 - List Item Discount on L Items 0.00/25.00% (\$\$) 0.00 4,455.70

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	13,787.10
					35,121.86	

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REFIX FRONT WINDSCREEN	New	150.00	80.00
3	TO DISMANTLE & REFIX FRONT DASHBOARD	New	300.00	220.00
4	TO DISMANTLE & REPLACING FRONT BRAKE BOOSTER	New	180.00	80.00
5	TO REMOVE & REFIX A/C COOLING SYSTEM & REFILL AIR CON GAS	New	150.00	100.00
6	TO SPRAY RUST PROOFING	New	150.00	80.00
7	TO REMOVE,REFIX & REALIGN FRONT CABIN	New	380.00	0.00
8	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	2,200.00	1,600.00
9	TO PUTTY & SPRAY PAINTING	New	2,000.00	1,600.00
Gross Labour Cost (S\$)			5,590.00	3,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >