

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: EQ Insurance Company Ltd
5 Maxwell Road, #17-00 Tower Block
MND Complex
Singapore 069110

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jamie Tay

Date: 07 Oct 2019

Preliminary Advice

Insured Vehicle No	: GBE5927T		
TP Vehicle No	: SHC1290L	Accident Date	: 02/10/2019
Make	: HYUNDAI SONATA	Assignment Date	: 04/10/2019
Date of Inspection	: 04/10/2019	Est. Duration of Repair	: 3.00
Inspection At	: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG) 59 LOYANG DRIVE SINGAPORE 508969		

Point of Impact / General Description of Damages

The vehicle sustained impact / damagesO/S front... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,414.12
Revised Amount	:S\$	3,182.12
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,182.12
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have not authorized repairs.