

15/04/2019

INS. CASE OWNER:

CC 3 / CTI1901 7/10/19, KLEB 7/10/19

LOG:  
IDAC:

Surveyor: KALVIN

DOI: 7/10/19

Date / Time: 7/10/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.: GEG 5165P  
Name of Insured: SUPREME AUSTRALIAN MEATS DLL  
Insured Tel No.: HP: 7/10/19  
Excess Sec II : \$5  
Is driver the owner? ( YES / NO )  
If NO. Driver Name / Age: ANAND CHANDRAN  
Driver Tel No.: (V/L: YES / NO )

Claim No.: SWM1A6W466  
Policy No.: DMUSN2055661901  
Make / Model: TOYOTA  
Place of Accident: LILMONTI 9285

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO  
Insured Liability: % Final ? Yes / No

SHC 83975



INSRS:  
WSP: WGE  
Tel: m  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

| Date/ Time | STAGE                            | DATE/ PIC                           |
|------------|----------------------------------|-------------------------------------|
|            | Non-Reporting hr (1st):          |                                     |
|            | Non-Reporting hr (2nd):          |                                     |
|            | Non-Reporting hr (Final):        |                                     |
|            | Notification hr (if non-pickup): |                                     |
|            | Call OI:                         | ASNEZ 31.10.19                      |
|            | After call hr to OI:             |                                     |
|            | Documentation Check List:        | Handler Typist                      |
|            | Notification hr (if non-pickup)  | <input type="checkbox"/>            |
|            | After call hr to OI:             | <input checked="" type="checkbox"/> |
|            | Authorisation To Act:            | <input checked="" type="checkbox"/> |
|            | Release Voucher:                 | <input checked="" type="checkbox"/> |
|            | Final Repair Bill:               | <input checked="" type="checkbox"/> |
|            | Car Rental Invoice:              | <input checked="" type="checkbox"/> |
|            | Towing Invoice:                  | <input type="checkbox"/>            |
|            | LTA / GIA :                      | <input checked="" type="checkbox"/> |
|            | Medical Bill:                    | <input type="checkbox"/>            |
|            | PIR:                             | <input type="checkbox"/>            |
|            | Mandate/Reject Instruction:      | <input type="checkbox"/>            |
|            | LOD:                             | <input checked="" type="checkbox"/> |
|            | Payment Breakdown Form:          | <input type="checkbox"/>            |
|            | Post-Repair Photos:              | <input checked="" type="checkbox"/> |
|            | Others:                          | <input type="checkbox"/>            |

|                                                                                                                                                      |                     |                                          |
|------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------|------------------------------------------|
| <b>PRELIMINARY ADVICE</b>                                                                                                                            | Date/Time:          | Sent By:                                 |
| <b>FINALIZATION</b>                                                                                                                                  | Date/Time:          | Confirm with:                            |
| Repair Cost:                                                                                                                                         | \$51,300            | ( 2 days) Reduction: 2% %                |
| <b>FINAL SETTLEMENT</b>                                                                                                                              | Date/Time: 13.11.19 | Confirm with: CATHY HEE                  |
| Final Liability:                                                                                                                                     | % 100               | (Agreed / Assessed) BOLA S/N No. : 27    |
| Repair Cost:                                                                                                                                         | \$51,391.00         | OLD RPR ENDED TP.                        |
| Loss of Rental (LOR):                                                                                                                                | \$5 221.34          | ( 2 days) x \$110.67                     |
| Loss of Use (LOU):                                                                                                                                   | \$5 -               | (5 x 2 days)                             |
| Loss of Income (LOI):                                                                                                                                | \$5 100.00          | (\$ 50 x 2 days)                         |
| LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOU <input checked="" type="checkbox"/> |                     | (Tick only one)                          |
| GIA/LTA Search                                                                                                                                       | \$5 149             |                                          |
| Medical:                                                                                                                                             | \$5 -               |                                          |
| Disbursement:                                                                                                                                        | \$5 -               | (e.g. Tow/ Independent )                 |
| Legal Cost                                                                                                                                           | \$5 -               |                                          |
| <b>Total:</b>                                                                                                                                        | \$5 1,719.83        | <b>Global Sum \$5:</b>                   |
| <b>FINAL PAYMENT</b>                                                                                                                                 | Date/Time: 13.11.19 | Confirm with: CATHY HEE                  |
| Payee 1:                                                                                                                                             | \$5 1,719.83        | Name 1: COMFORTBOARD ENGINEERING PTE LTD |
| Payee 2: (Strike if N.A.)                                                                                                                            | \$5 -               | Name 2:                                  |
| Payee 3: (Strike if N.A.)                                                                                                                            | \$5 -               | Name 3:                                  |





Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised  
Our ref: CC3/CTI19017525/K1eb3

Date: 04.10.2019

The Motor Claims Department  
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SHC8397S**

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 03.10.2019 at the premises of M/s ComfortDelGro Engineering Pte Ltd and have the following to report:-

|                          |       |          |
|--------------------------|-------|----------|
| Workshop Estimate Amount | : S\$ | 1,753.84 |
| Revised Estimate Amount  | : S\$ | 1,610.00 |
| "Check" Items Amount     | : S\$ | 56.96    |
| Market Value             | : S\$ | -        |
| LTA Reimbursement Value  | : S\$ | -        |
| Nett Value               | : S\$ | -        |

Description of Damage:

The vehicle sustained damages at the  
Rear N/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 2 days

Yours faithfully,

KALVIN ANG  
Licensed Appraiser

REPAIR ESTIMATE\*

VEHICLE NO : SHC 8397S

DATE 3/10/2019 15:07

MAKE :

MODEL : HYUNDAI i40

| Qty                                                                                                                                                                                                            | Parts Description/ Labour              | Type | Unit Price | Amount                  |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------|------|------------|-------------------------|
|                                                                                                                                                                                                                | Rear Bumper                            |      |            | \$ 553.00               |
|                                                                                                                                                                                                                | Rear Bumper Clip 10 pcs                |      |            | \$ 22.00                |
|                                                                                                                                                                                                                | Rear Bumper Bracket                    |      | \$ 35.60   | \$ 71.20                |
|                                                                                                                                                                                                                | Rear Bumper Under Cover                |      |            | \$ 228.00               |
|                                                                                                                                                                                                                | Rear Bumper Reflector Lamp (LH)        |      |            | \$ 30.60                |
|                                                                                                                                                                                                                | <i>Rear Bumper x repair</i>            |      |            |                         |
|                                                                                                                                                                                                                | <b>SUB TOTAL</b>                       |      |            | <b>\$ 904.80</b>        |
|                                                                                                                                                                                                                | <b>LESS 20%</b>                        |      |            | <b>\$ 180.96</b>        |
|                                                                                                                                                                                                                | <b>DISCOUNTED TOTAL</b>                |      |            | <b>\$ 723.84</b>        |
|                                                                                                                                                                                                                | <br>                                   |      |            |                         |
|                                                                                                                                                                                                                | Rear Bumper Advertisement Logo         |      |            | \$ 50.00                |
|                                                                                                                                                                                                                | Rear Bumper Rubber Mat                 |      |            | \$ 50.00                |
|                                                                                                                                                                                                                | Rear Fender Advertisement Logo (LH/RH) |      | \$ 100.00  | \$ 200.00               |
|                                                                                                                                                                                                                | <i>Rear Bumper/ Fender sticker</i>     |      |            | <i>\$ 70</i>            |
|                                                                                                                                                                                                                |                                        |      |            | <b>\$ 300.00</b>        |
|                                                                                                                                                                                                                | <br>                                   |      |            |                         |
|                                                                                                                                                                                                                | <b>Labour Charge</b>                   |      |            |                         |
|                                                                                                                                                                                                                | Panel Beating                          |      |            | <del>\$ 50.00</del> 420 |
|                                                                                                                                                                                                                | Spray Painting Charge                  |      |            | <del>\$ 50.00</del> 400 |
|                                                                                                                                                                                                                | Wiring Charge                          |      |            | \$ 50.00                |
|                                                                                                                                                                                                                | Remove/Refix Reverse Sensor            |      |            | <del>\$ 80.00</del> 70  |
|                                                                                                                                                                                                                | <b>TOTAL LABOUR</b>                    |      |            | <b>\$ 730.00</b>        |
|                                                                                                                                                                                                                | <b>ESTIMATE TOTAL</b>                  |      |            | <b>\$ 1,753.84</b>      |
|                                                                                                                                                                                                                | <br>                                   |      |            |                         |
|                                                                                                                                                                                                                | <i>Kelvin (KK)</i>                     |      |            |                         |
|                                                                                                                                                                                                                | <i>3/10/19 1535</i>                    |      |            |                         |
|                                                                                                                                                                                                                | <i>2 Days</i>                          |      |            |                         |
|                                                                                                                                                                                                                | <i>4/5</i>                             |      |            |                         |
|                                                                                                                                                                                                                | <i>After Repair photo</i>              |      |            |                         |
| This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. |                                        |      |            |                         |

COMFORTDELGRO  
ENGINEERING

Our Job Ref No 305338513

Date : 07.10.19

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK

Fax :

Attn : Mr KALVIN ANG

Vehicle Reg No. SHC8397S CTPL

03.10.19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA 686 516SP
2. The finalized amount shall be:
- (a) Spare Parts after List discount
- (b) Labour Charges
- Total for Part-By-Part Repair Cost**
- (c) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: 20% \$1,300.00  
**Final Lumpsum Repair cost** \$1,300.00

3. Estimated normal period for repairs: 2 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and  
finalized amountSignature : AKSignature : Kalvin

Name : LIM KWOK ENG

Name : Kalvin

Tel : 62148316

Date : 8/10/19

Fax : 65468156

## For Official Use Only

| Item                                                 | Amount | Document Attached Yes or No | Confirm By (Signature) | Remarks |
|------------------------------------------------------|--------|-----------------------------|------------------------|---------|
| 1. Rental Rate P/Day                                 |        | YES                         |                        |         |
| 2. Loss of Income Paid                               |        | NO                          |                        |         |
| 3. Survey Fees                                       |        |                             |                        |         |
| 4. LTA Search Fee                                    | \$7.49 |                             |                        |         |
| 5. Medical Fees (on behalf of driver, if applicable) |        |                             |                        |         |
| 6. Overrun                                           |        |                             |                        |         |

Remarks:

member of COMFORTDELGRO

Date/Time: 03.10.2019 15:16 Page : 1


Team: ARC Repair TP(CLS0)1 JOB CARD Sales Order: JC NO: 305338513

|               |                                |                                 |                                |
|---------------|--------------------------------|---------------------------------|--------------------------------|
| OMER          | COMFORT TRANSPORTATION PTE LTD | REGN NO: SHC8397S               | MILEAGE                        |
| S             | 7010045                        | MAKE: HYUNDAI                   | FUEL                           |
| OMER NO:      | 383 SIN MING DRIVE             | MODEL: I-40                     | E 1/2 F                        |
| ESS           | Singapore SINGAPORE 575717     | YR OF MANU: 06.08.2015          | DATE/TIME IN: 03.10.2019 13:05 |
| (R)           | 65508755                       | CHASSIS CODE: RMHLB41UMGU076903 | TARGET DATE                    |
| (P)           |                                |                                 | COMPLETION DATE/TIME           |
| SUNT CARD NO: |                                |                                 |                                |

CHINA

Accident Date: 03.10.2019  
NATURE: 3P 03.10.2019

JOB DESCRIPTION

| S/NO | LABOR CODE | DESCRIPTION                                                                          |
|------|------------|--------------------------------------------------------------------------------------|
|      |            |  |

RECEIVED & PASSED OUT BY: \_\_\_\_\_

|                                                       |                                     |
|-------------------------------------------------------|-------------------------------------|
| SERVICE ADVISOR                                       | CUSTOMER'S SIGNATURE                |
| <p>Signature/Date</p> <p>Signature: <i>Kalvin</i></p> | <p>Signature: _____</p>             |
| <p>Vehicle No.: SHC8397S</p>                          | <p>Vehicle No.: SHC8397S</p>        |
| <p>Name of Service Advisor</p>                        | <p>Date</p>                         |
| <p>Returned to Service Reception upon collection</p>  | <p>To be kept by Security Guard</p> |

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SHC 8397S

DATE 3/10/2019 15:07

MAKE :

MODEL : HYUNDAI i40

| Qty | Parts Description/ Labour                                                                                                                                                                                                                                                                                                                                                                                                                                                   | Type | Unit Price | Amount                   |      |
|-----|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|------------|--------------------------|------|
|     | Rear Bumper                                                                                                                                                                                                                                                                                                                                                                                                                                                                 |      |            | \$ 553.00                |      |
|     | Rear Bumper Clip 10 pcs                                                                                                                                                                                                                                                                                                                                                                                                                                                     |      |            | \$ 22.00                 |      |
|     | Rear Bumper Bracket                                                                                                                                                                                                                                                                                                                                                                                                                                                         |      | \$ 35.60   | \$ 71.20                 |      |
|     | Rear Bumper Under Cover                                                                                                                                                                                                                                                                                                                                                                                                                                                     |      |            | \$ 228.00                |      |
|     | Rear Bumper Reflector Lamp (LH)                                                                                                                                                                                                                                                                                                                                                                                                                                             |      |            | \$ 30.60                 |      |
|     | <i>Rear Bumper x repair</i>                                                                                                                                                                                                                                                                                                                                                                                                                                                 |      |            |                          |      |
|     | <b>SUB TOTAL</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                            |      |            | <b>\$ 904.80</b>         |      |
|     | <b>LESS 20%</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                             |      |            | <b>\$ 180.96</b>         |      |
|     | <b>DISCOUNTED TOTAL</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                     |      |            | <b>\$ 723.84</b>         |      |
|     | <br>                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |      |            |                          |      |
|     | Rear Bumper Advertisement Logo                                                                                                                                                                                                                                                                                                                                                                                                                                              |      |            | \$ 50.00                 | Nett |
|     | Rear Bumper Rubber Mat                                                                                                                                                                                                                                                                                                                                                                                                                                                      |      |            | \$ 50.00                 | Nett |
|     | Rear Fender Advertisement Logo (LH/RH)                                                                                                                                                                                                                                                                                                                                                                                                                                      |      | \$ 100.00  | \$ 200.00                | Nett |
|     | <i>conform sticker</i>                                                                                                                                                                                                                                                                                                                                                                                                                                                      |      |            |                          |      |
|     |                                                                                                                                                                                                                                                                                                                                                                                                                                                                             |      |            | <b>\$ 300.00</b>         |      |
|     | <br>                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |      |            |                          |      |
|     | <b>Labour Charge</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                        |      |            |                          |      |
|     | Panel Beating                                                                                                                                                                                                                                                                                                                                                                                                                                                               |      |            | <del>\$ 200.00</del> 420 |      |
|     | Spray Painting Charge                                                                                                                                                                                                                                                                                                                                                                                                                                                       |      |            | <del>\$ 200.00</del> 400 |      |
|     | Wiring Charge                                                                                                                                                                                                                                                                                                                                                                                                                                                               |      |            | \$ 50.00                 | X    |
|     | Remove/Refix Reverse Sensor                                                                                                                                                                                                                                                                                                                                                                                                                                                 |      |            | \$ 80.00                 | 70   |
|     | <b>TOTAL LABOUR</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                         |      |            | <b>\$ 730.00</b>         |      |
|     | <br>                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |      |            |                          |      |
|     | <b>ESTIMATE TOTAL</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                       |      |            | <b>\$ 1,753.84</b>       |      |
|     | <br>                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |      |            |                          |      |
|     | <i>Kalvin (KKE)</i>                                                                                                                                                                                                                                                                                                                                                                                                                                                         |      |            |                          |      |
|     | <i>3/10/19 15:55 L</i>                                                                                                                                                                                                                                                                                                                                                                                                                                                      |      |            |                          |      |
|     | <i>2 Days</i>                                                                                                                                                                                                                                                                                                                                                                                                                                                               |      |            |                          |      |
|     | <i>4/5</i>                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |      |            |                          |      |
|     | <i>After Repair photo</i>                                                                                                                                                                                                                                                                                                                                                                                                                                                   |      |            |                          |      |
|     | <ul style="list-style-type: none"> <li>• This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</li> <li>• Parts are subject to availability.</li> <li>• Third party liability.</li> <li>• No illegal modification.</li> <li>• Supplementary work is subject to final approval by the insurance company.</li> </ul> |      |            |                          |      |
|     | Acknowledged by Repairer<br>Signature: _____<br>Date: _____                                                                                                                                                                                                                                                                                                                                                                                                                 |      |            |                          |      |

## Shu Pei (LKKAuto)

---

**From:** Irene Tay <irene.tay@sg.cntaiping.com>  
**Sent:** Tuesday, 15 October 2019 3:03 PM  
**To:** Shu Pei (LKKAuto); Asher Sng (LKKAuto)  
**Subject:** RE: OUR REF: SNM19D204662-GBG5165P-THP -Direct Settlement - Accident Involving GBG5165P (OI : CTI - TBA) and SHC8397S (TP : LKK REF - CC3/CTI19017525/K1eb3) on 03.10.2019  
**Attachments:** 20191015145948.pdf

Dear LKK,

Enclosed herewith our insured GIA Report for your attention.

Regards,

**Irene Tay**

Executive

Claims Department (Motor Division)

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896192 | F:(65) 62247478/62247175

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** Claims Dept of CTI

**Sent:** Friday, October 4, 2019 5:54 PM

**To:** Irene Tay <irene.tay@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; Shu Pei (LKKAuto) <shupeil@lkkauto.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>

**Subject:** OUR REF: SNM19D204662-GBG5165P-THP -Direct Settlement - Accident Involving GBG5165P (OI : CTI - TBA) and SHC8397S (TP : LKK REF - CC3/CTI19017525/K1eb3) on 03.10.2019

Dear Irene,

Please revert LKK.

Note : officer in charge – Irene Tay

Regards,

Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI19017525/K1eb3q2

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 25-11-2019



Code : CTI

## 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                  |                |            |
|--------------|------------------|----------------|------------|
| Insured Veh. | GBG 5165P        | Veh. Inspected | SHC 8397S  |
| Policy No.   | DMCVSN3055661901 | Coverage (\$)  | 0.00       |
| Claim No.    | SNM19D204662     | Excess (\$)    | 0.00       |
| Assign From  |                  | Assign Date    | 03/10/2019 |

## 2. Vehicle Particulars & Condition

|              |                   |              |                    |
|--------------|-------------------|--------------|--------------------|
| Make & Model | HYUNDAI I40       | c.c          | 1685               |
| Engine No.   | HIDDEN            | Year of Reg. | 2015               |
| Chassis No.  | KMHLB41UMGU076903 | Colour       | BLUE               |
| Odometer     | 691254            | Steering     | IN ORDER           |
| Brakes       | IN ORDER          | Modification | STANDARD ALLOY RIM |
| General      | FAIR              |              |                    |

## 3. Conditions of Tyres

|                | Size       | Make    | Balance |
|----------------|------------|---------|---------|
| R/H Front Tyre | 205/60 R16 | HANKOOK | 7 mm    |
| L/H Front Tyre | 205/60 R16 | HANKOOK | 7 mm    |
| R/H Rear Tyre  | 205/60 R16 | HANKOOK | 7 mm    |
| L/H Rear Tyre  | 205/60 R16 | HANKOOK | 7 mm    |

## 4. Description of Damages

|                                                                                |
|--------------------------------------------------------------------------------|
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.<br>DAMAGES SEE DETAILS. |
|--------------------------------------------------------------------------------|

## 5. General Information

|                |                                                                          |                 |            |
|----------------|--------------------------------------------------------------------------|-----------------|------------|
| Accident Date  | 03/10/2019                                                               | Inspection Date | 03/10/2019 |
| Survey held at | COMFORTDELGRO ENGINEERING PTE LTD<br>59 LOYANG DRIVE<br>SINGAPORE 508969 |                 |            |

## 5a. Remarks

|                                                                                                                                        |
|----------------------------------------------------------------------------------------------------------------------------------------|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|----------------------------------------------------------------------------------------------------------------------------------------|

## 5b. Estimate Days of Repair

|                                     |                |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 2 Working Days |
|-------------------------------------|----------------|

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8397S**

| Qty | Description of Parts                                                        | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-----------------------------------------------------------------------------|----------------------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b>                                          |                      |                           |                   |
| 1   | REAR BUMPER                                                                 | CRACKED              | 553.00                    | 553.00            |
| 10  | REAR BUMPER CLIP                                                            | NECESSARY            | 22.00                     | 22.00             |
| 2   | REAR BUMPER BRACKET @\$35.60                                                | SERVICEABLE          | 71.20                     | -                 |
| 1   | REAR BUMPER UNDER COVER                                                     | SERVICEABLE          | 228.00                    | -                 |
| 1   | REAR BUMPER REFLECTOR LAMP (LH)                                             | SERVICEABLE          | 30.60                     | -                 |
| 1   | REAR BOOTLID (NPA)                                                          | TO REPAIR SEE LABOUR | -                         | -                 |
|     | LESS 20% DISCOUNT                                                           |                      | -180.96                   | -115.00           |
|     |                                                                             |                      | 723.84                    | 460.00            |
|     | <b><u>SPECIAL NETT ITEMS</u></b>                                            |                      |                           |                   |
| 1   | REAR BUMPER ADVERTISEMENT LOGO (SN)                                         | NECESSARY            | 50.00                     | 50.00             |
| 1   | REAR BUMPER RUBBER MAT (SN)                                                 | NECESSARY            | 50.00                     | 50.00             |
| 2   | REAR FENDER ADVERTISEMENT LOGO (LH/RH) @\$100.00 (SN)                       | NECESSARY            | 200.00                    | 200.00            |
| 1   | REAR BOOTLID COMFORT STICKER (SN)                                           | NECESSARY            | 30.00                     | 30.00             |
|     |                                                                             |                      | 330.00                    | 330.00            |
|     | <b><u>LABOUR</u></b>                                                        |                      |                           |                   |
|     | PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BOOTLID .                     |                      | 500.00                    | 420.00            |
|     | SPRAY PAINTING CHARGE .                                                     |                      | 500.00                    | 400.00            |
|     | WIRING CHARGE.                                                              | NOT NECESSARY        | 50.00                     | -                 |
|     | REMOVE/REFIX REVERSE SENSOR .                                               |                      | 80.00                     | 30.00             |
|     |                                                                             |                      | 1,130.00                  | 850.00            |
|     | <b>GRAND TOTAL</b>                                                          |                      | <b>2,183.84</b>           | <b>1,640.00</b>   |
|     | <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |                      |                           | <b>1,300.00</b>   |

Report Ref No. CC3/CT19017525/K1eb3q2

**KALVIN ANG WEI KUN**

Automotive Assessor / Investigator

**HO LEONG CHUAN**

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.