

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

23-Oct-19

SUPPLEMENTARY REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1477 K

1 pc	Aircon condensor	<i>— Bud</i>	\$	745.10
1 pc	End panel top garnish	<i>— on</i>	\$	90.00
			\$	835.10
		Less 20%	\$	167.02
			\$	668.08

S/NETT

1 pc	Rear bumper top protector	<i>— rec</i>	\$	80.00 <i>50</i>
		Total	\$	748.08

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)