



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref : CS3/INC19015594/Usf3s2-1

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556

Date : 10-10-2019



Code : INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKK 3114Y	Veh. Inspected	SKZ 4065U
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1060472-002	Excess (\$)	0.00
Assign From	MOTOR INCOME	Assign Date	05/10/2019

### 2. Vehicle Particulars & Condition

Make & Model	MAZDA 5	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JM6CW1071G0123017	Colour	GREY
Odometer	100034	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	MICHELIN	7 mm
L/H Front Tyre	205/55 R16	MICHELIN	7 mm
R/H Rear Tyre	205/55 R16	MICHELIN	7 mm
L/H Rear Tyre	205/55 R16	MICHELIN	7 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND N/S BODY. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	31/08/2019	Inspection Date	03/09/2019
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------