

12/10/19

ASS. REC. BY:

REF: CS/CTI/1017577/V9d3

02

Special Instruction:

Surveyor: MERTUS

ASSIGNMENT (Office)

Menmen

From (Person): Tan Kah Leung

of CTI

Date/Time: 4/10/19 @ 6.08pm

Estimated Cost:

Bill to:

GD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBJ 20064

Insured:

YN 728P

at Workshop n/s

Auto City

Tel:

846 8855

of

32 Jerla Bukit Crescent

Policy No:

DMCVSN19206719000

Claim No:

SNM19D204630C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 30/09/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:50am @ 7/10/19

Person Contacted:

Raymond

Vehicle IN OUT

Date/Time	Action/Instruction
	13/10/19 ✓
	GBJ 20064-X
	YN 728P-X

(08/11/12) web

ASS. REC. BY: *MORCUS*

REF:

ASSIGNMENT

From: _____
Estimated Cost: _____

Date: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *63J 20064*at Workshop m/s *Auto City*

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: *63k.*

IDAC Accident Report: _____

Consistent? : Yes or No

GLA / PR Seer: _____

Consistent? : Yes or No

Est. Repairs: *4* days

Res.: Yes or No

Lum Sum: *20* %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

474C

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: *63J 20064*Yr Regn: *1119*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or *(M)*Make: *Toyota Dyna*C.C. *2982*Colour: *silver*

A/C: Insured / Std / NI / NA

Sp. Reading: *17813*

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *JTFAT35410K212400*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: *NA* / S/Rim / STD A/Rim orTyre Size: F: *195/75R15*R: *155R12*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. *6* mmR/Bal. *6/6* mmL/Bal. *6* mmL/Bal. *6/6* mmD.O.A. *30/9/19*D.O.I. *9/10/19*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

LTA 22668

RECEIVED 1 OCT 2019

*18/10/19 confirmed L/S \$2600 with back
check \$4005.47, 61%*

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair: *4*Resurvey No. of Trip: *1*

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) \$ + R\$ \$

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format: *mer-TP*Lump Sum / I.B.I. (\$) *2600*

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Oct 2019		04 Oct 2019 18:08 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:									
Main Claimant:		RML GENERAL CONTRACTOR, Co. Reg. No.: 530991133							
Vehicle Reg. No.:		GBJ2006U Date of Loss: 30/09/2019 11:00 - :59							
Claim Type:		TP / SNM19D204630C02 Policy/Cover Note No.: DMCVSN19206719000							
Vehicle Reg. No. (Insured):		YN728P Policy No. (Claimant): 1900009014							
		Excess: S\$500.00							
Repairer:		Auto City Pte Ltd (HQ) 32 KAKI BUKIT CRESCENT, 416262 Kaki Bukit - Tel: 6846 8855							
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]							
Claimant's Insurer:		AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 15/10/2019]							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Friday, 4 October 2019 6:02 PM
To: ct-admin@visionlawllc.com; assignments
Subject: RE: SNM19D204630-YN728P-TKL - FW: Scan Image
Attachments: 0099_001.pdf

WITHOUT PREJUDICE

Dear Sirs,

We refer to your email dated 04.10.2019.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis.

Aside to LKK,

Please refer to the email below & proceed to survey the third party vehicle.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI
Sent: Friday, October 4, 2019 4:38 PM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; ct-admin@visionlawllc.com
Subject: SNM19D204630-YN728P-TKL - FW: Scan Image

Dear Kah leong,

Fya

Thank you

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: ct-admin@visionlawllc.com [<mailto:ct-admin@visionlawllc.com>]

Sent: Friday, October 04, 2019 4:18 PM

To: Claims Dept of CTI; khleong.tan@sg.cntaiping.com

Subject: Scan Image

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths
Agents for Trade Marks
(Incorporated with limited liability)

ERIC HO CHING BOON
WONG KENG LEONG RAYNEY
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAM
ANJALI DIO MUNTANDY
ANG KIM NOI DIANE
RAVENDRA KRISHNASAMY
TAN YINXIAN, SELWYN
CHEONG YUNHUI, CLARUSNA
SONIA LIM WEI LET

Unique Entity Number :200721148H
✓ **HEAD OFFICE:** 133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch: 490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

✓ HEAD OFFICE

TEL : (65) 65342811 (Hunting)
FAX ✓ : (65) 65358802 (General)
: (65) 65355905 (Litigation)
E-mail : jactan@visionlawllc.com

BRANCH

TEL : 65 63580703
FAX : 65 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE- KINDLY REPLY TO HEAD OFFICE FOR THIS MATTER

Our Ref: AM.jt.ins.A94.GBJ2006U.19 (sj)
Your Ref: **SNM19D204630C02**

04 October 2019

CHINA TAIPING INSURANCE (S'PORE) PTE LTD

3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Attention: Motor Claims Department

BY FAX: 6224 7175

email: claimsdept@sg.cntaiping.com
email: kahleong.tan@sg.cntaiping.com

Dear Sirs,

ACCIDENT INVOLVING GBJ 2006 U & YN 728 P ON 30 SEPTEMBER 2019 ALONG DEFU LANE 3 NO 9 AT ABOUT 1130 HOURS (NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)

We refer to your email 04 October 2019 of even date informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of Marcus Chua as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

Venue: Auto City Pte Ltd
32 Kaki Bukit Crescent
Singapore 416262
Contact Person: Raymond (6846-8855)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

ANJALI M
(HEAD OFFICE)

FOR SURVEYOR

Please initial here after completion of pre-repair inspection.
Thank you.

1st Survey on _____
Appointed surveyor : _____
(Name & Signature)

2nd Survey on _____
Appointed surveyor : _____
(Name & Signature)

3rd Survey on _____
Appointed Surveyor : _____
(Name & signature)

cc: GBJ 2006 U – by fax: 6846-7307 only

NB.: Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude our client from claiming injury-related damages arising from this accident.

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

Find out more



Post an Advertisement
Set it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Volvo V40 T2 2016 July 26 \$72,500.



34500 Km. Serviced At
Authorised Dealer Only. Always
Indoor Parking.
Direct Owner - StarAd



Browse by Category

Back (1 2 3 4 5) Next >

Sort by Date Posted

20 results/page

92 vehicles

toyota dyna

Advanced Search

Submit

	Make	Model	Price	Deprecation	Reg Date	Eng Cap	Milage	Veh Type	Status
Search Selection	toyota dyna		Any	Any	2019	Any	Any	Any	Available
	Toyota Dyna	150 3.0M	\$67,888	\$6,850 /yr	02-Sep-2019	2,982 cc	-	Truck	Available
Fuel Type: Diesel Cheapest In Town! Ready Stock! 1st Owner! Price Are Nett And Included GST! Loan 100% And 7 Years Instalment Plan! Warranty 3 Yr... SG Motor Link Pte Ltd Posted: 09-Oct-2019 Tags: 2019 Toyota Dyna, 2019 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	Toyota Dyna	150 3.0M	\$67,800	\$6,830 /yr	12-Sep-2019	2,982 cc	71 km	Truck	Available
Fuel Type: Diesel Almost Brand New! Ready Stock! Warranty 3 Years/100,000km. Servicing 2+6 Times! Loan Up To 100%. SG Motor Link Pte Ltd Posted: 09-Oct-2019 Tags: 2019 Toyota Dyna, 2019 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	Toyota Dyna	150 3.0M	\$64,800	\$6,570 /yr	16-Aug-2019	2,982 cc	-	Truck	Available
Fuel Type: Diesel You Will Be The First Owner! New Euro 6 Toyota Dyna! 3 Years/100,000KM Warranty And 8 x Servicing By Borneo Motors. Comes With... Posted: 09-Oct-2019 Tags: 2019 Toyota Dyna, 2019 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	Toyota Dyna	150 3.0M	\$67,500	\$7,290 /yr	09-Jan-2019	2,982 cc	-	Truck	Available
Fuel Type: Diesel 100% Loan Available. Lowest Interest Rates. Best Price For Trade In. Call Now Before Prices Go Up. QFai Auto Pte Ltd Posted: 09-Oct-2019 Tags: 2019 Toyota Dyna, 2019 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	Modelista Version 2 Complete Bodykit Mod V2 direct bolt on kit More info about this product								
	Toyota Dyna	150 3.0M	\$66,988	\$6,870 /yr	09-Jul-2019	2,982 cc	-	Truck	Available
Fuel Type: Diesel Back By Popular Demand! Most Reliable Brand New 10 Feet Lorry Comes With Excellent Fuel Efficiency And A Spacious Cabin To Fulfill Y... ABWIN Bus Pte Ltd Posted: 08-Oct-2019 Tags: 2019 Toyota Dyna, 2019 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	Toyota Dyna	150 3.0M	\$66,988	\$6,790 /yr	19-Aug-2019	2,982 cc	-	Truck	Available
Fuel Type: Diesel Limited Stock Offer. Price Include COE & GST. Immediate Registration. Auto Transmission Available. Full Loan, High Trade-in. Call Now... ABWIN Bus Pte Ltd Posted: 08-Oct-2019 Tags: 2019 Toyota Dyna, 2019 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	Toyota Dyna	150 3.0M	\$67,800	\$6,830 /yr	09-Sep-2019	2,982 cc	-	Truck	Available
Fuel Type: Diesel Real Price, No More Top Up, Price Includes COE, GST, ARF, Admin Fees Etc. 100% Loan Available, Very Low Interest, Guaranteed Appro... SG Motor Link Pte Ltd Posted: 08-Oct-2019 Tags: 2019 Toyota Dyna, 2019 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
Compare	Toyota Dyna	150 3.0M	\$67,800	\$6,910 /yr	01-Aug-2019	2,982 cc	-	Truck	Available

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	474L
Vehicle Details	
Vehicle No.:	GBJ2006U
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 5MT
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	1KD2838763
Chassis No.:	JTFAT35Y10K212400
Maximum Power Output:	-
Open Market Value:	\$27,082.00
Original Registration Date:	30 Jan 2019
First Registration Date:	30 Jan 2019
Transfer Count:	0
Actual ARF Paid:	\$1,355.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 Jan 2029
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$24,365.00
COE Rebate Amount:	\$22,668.00
Total Rebate Amount:	\$22,668.00

The information contained herein is correct as at 09 Oct 2019

OK

Auto City Ptd Ltd

32 Kaki Bukit Crescent, Singapore 416262

Tel: 6846 8855 (Raymond)

not attached
date
9/10/19
4/542600
4dy.

Vehicle number: GBJ2006U

Vehicle Made & Model: TOYOTA DYNA

Qty	List Items		Amount \$
1	Front cab panel	50% DD	1,395.50 —
1	Front cab panel emblem "DYNA"	nu	89.95 —
1	Front corner panel - RH	n	512.60 X
1	Front grille	scr	573.16 —
1	Front grille logo	11	89.55 X
1	Front headlamp - RH	11	978.45 X
1	Front wiper panel	11	591.60 X
1	Front windscreen rubber	nu	361.20 —
1	Front side mirror - LH	scr/nlc	441.95 X
Sub-total			5,033.96
Less 25%			1,258.49
Total List			3,775.47
			249.81

Labour charges

To remove, refix front windscreen	60	120.00
To remove, refix front dashboard	160	300.00
To check front electrical wiring	20	50.00
To respray undercoating	30	80.00
To respray painting and etc	600	1,080.00
Panel beating, cut, weld remove & replacing above parts	600	1,200.00
Total Labour		2,830.00

LKK Auto Consultants hence notify the Receiver of the following:

- To remove before/after spray painting
- To remove damaged parts (if any) remove
- Parts removed subject to confirmation
- This work is on a "Without Prejudice" basis
- The Receiver's condition(s) is agreed
- Supplementary work(s) must be approved and is subject to final approval from Insurance Company

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

6,605.47

Signature
Date

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119017577/UQD3N2

Date: 18/10/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN19206719000	
Claimant Vehicle No :	GBJ2006U	Insured Vehicle No :	YN728P	
Date of Loss:	30/09/2019	Nature of Claim:	TP	Claim No: SNM19D204630C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ2006U	Engine No:	1KD2838763
Make & Model:	TOYOTA DYNA 1.5T, 3.0 (A)	Chassis No:	JTFAT35Y10K212400
Reg. Date:	30/01/2019 (Man. Year: 2018)	Odometer:	17813 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/75R15	Rear Tyre Size:	155 R12(D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,775.47	1,814.86	1,960.61	51.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,830.00	1,470.00	1,360.00	48.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,605.47	3,284.86	3,320.61	50.27
Approved Total (Overridden) (S\$)		2,600.00		
(S\$)	6,605.47	2,600.00	4,005.47	60.64
+ GST 7.00/7.00% (S\$)	462.38	182.00	280.38	60.64
Nett Amount (S\$)	7,067.85	2,782.00	4,285.85	60.64

INSPECTION

Date of Assignment:	04/10/2019	Inspected At:	Auto City Pte Ltd (HQ)
Date Inspected:	09/10/2019		32 KAKI BUKIT CRESCENT
			Singapore 416262
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 18 Oct 2019)	
Parts:	N/A	TOYOTA DYNA 1.5T 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ2006U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT CAB PANEL	Badly Dented	1,395.50 FL	*1,395.50 FL
2	1		*FRONT CAB PANEL EMBLEM DYNA	Necessary	89.95 FL	*89.95 FL
3	1		*FRONT CORNER PANEL-RH	Repair	512.60 FL	*- FL
4	1		*FRONT GRILLE	Scratched	573.16 FL	*573.16 FL
5	1		*FRONT GRILLE LOGO	Not Necessary	89.55 FL	*- FL
6	1		*FRONT HEADLAMP-RH	Not Necessary	978.45 FL	*- FL
7	1		*FRONT WIPER PANEL	Not Necessary	591.60 FL	*- FL
8	1		*FRONT WINDSCREEN RUBBER	Necessary	361.20 FL	*361.20 FL
9	1		*FRONT SIDE MIRROR-LH (SCRATCHED)	Not Consistent With The Impact	441.95 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	5,033.96	2,419.81
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,258.49	604.95
Total Parts (\$\$)	3,775.47	1,814.86

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REFIX FRONT WINDSCREEN	New	120.00	60.00
2	TO REMOVE,REFIX FRONT DASHBOARD	New	300.00	160.00
3	TO CHECK FRONT ELECTRICAL WIRING	New	50.00	20.00
4	TO RESPRAY UNDERCOATING	New	80.00	30.00
5	TO RESPRAY PAINTING AND ETC	New	1,080.00	600.00
6	PANEL BEATING,CUT,WELD REMOVE & REPLACING ABOVE PARTS	New	1,200.00	600.00
Gross Labour Cost (\$\$)			2,830.00	1,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >