

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: India International Insurance Pte Ltd

Accident Date : 02.10.2019

Not Authorized
Call 845006 Max
Running After Paint
11 days

Third Party

Policy No:

07.10.2019

Date:

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair to "Honda Jazz" Reg. No. SJY8163K Claiming Against Your Insured Veh. No. SHC8332D			
1pc	Tailgate		845.00 ✓
1pc	Tailgate Glass Moulding Top		50.00 ✓
1pc	Tailgate Glass Moulding Lower		50.00 ✓
1pc	Tailgate Badge "Jazz"		28.00 ✓
1pc	Tailgate Lock		198.00 ✓
1pc	Tailgate Lock Catch		28.50 ✓
1pc	Tailgate Weatherstrip		101.00 ✓
1pc	Tailgate Trim Board		112.00 ✓
10pcs	Tailgate Trim Board Clips	5.00	50.00 ✓
1pc	Tailgate Stopper LH		13.00 ✓
1pc	Rear Bumper		485.00 ✓
10pcs	Rear Bumper Clips	3.80	38.00 ✓
2pcs	Rear Bumper Brackets	18.00	36.00 ✓
2pcs	Rear Bumper Top Retainers	18.00	36.00 ✓
1pc	Rear Bumper Lower Diffuser Cover		300.00 ✓
1pc	Rear Bumper Tow Cover		18.50 ✓
2pcs	Rear Bumper Corner Retainers	110.00	220.00 ✓
2pcs	Taillamps	383.00	766.00 ✓
2pcs	Taillamps Gasket	26.00	52.00 ✓
2pcs	Taillamps Lock Clips	15.00	30.00 ✓
1pc	Taillamps Panel LH		146.00 ✓
1pc	End Panel		303.00 ✓
1pc	End Panel Garnish		65.00 ✓
1pc	Spare Tyre Panel		830.00 ✓
1pc	Spare Tyre Panel Insulation		195.00 ✓
1pc	Spare Tyre Top Board		209.00 ✓
1pc	Rear Styrofoam Storage Box		290.00 ✓
1pc	Rear Fender Inner Trim Boards	255.00	510.00 ✓
1pc	Rear Exhaust Silencer		533.00 X
1pc	Rear Exhaust Silencer Gasket		28.00 X
Less 25%			6,566.00
			1,641.50
			4,924.50
	Rear Number Plate		45.00 SN X
	Tailgate Glass Sealant		50.00 SN
	Tailgate Glass Fastener		50.00 SN
	Rear Bumper Reverse Sensor		280.00 SN
C/F			5,349.50

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO

To: India International Insurance Pte Ltd

Accident Date : 02.10.2019

Third Party
Policy No: _____
Date: 07.10.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair to "Honda Jazz" Reg. No. SJY8163K Claiming Against Your Insured Veh. No. SHC8332D		
		B/F	5,349.50
	To Conduct Front Electrical Check, Reverse Sensors, Module, etc		120.00 501
	To Dismantle / Transfer Tailgate Fitting / Ancillary Accessories		150.00 601
	To Dismantle / Refit Tailgate Glass / Ancillary Accessories		160.00 1201
	To Dismantle / Refit Trunk Compartment Boards & Trims		80.00 601
	To Supply Rear Body Panel Sealant		80.00 601
	To Repair / Replace Exhaust Silencer		150.00 601
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		150.00 901
	Labour Charge - Panel Beating, Repairing Of Rear Chassis Member, Inner Panel, Floor Panel, Rear Fender etc. Cnt, Weld End Panel, Spare Tyre Panel and Parts Replacement		12001 1,600.00
	To Respray Affected Areas		12001 1,500.00
		Total :	<u>9,339.50</u>