

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 14969

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1204/2019/NS
Date : 7-Oct-19

Vehicle IN workshop. Kindly arrange for survey.

Your insured veh no. : SKS 2486 M

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ong Kok Kiong
Address : 95 Prince Charles Crescent
#04-09
Singapore 159027
Telephone : (HP) +65 97879653
Type of Claim : Third Party Claims
Policy No. : 1900016808
Vehicle No : **SFV 8092 U**
Model Code : Audi A5 Coupe 2.0 TFSI S Tronic
Model / Year : Feb-19
Engine No : CVK 076379
Chassis No : WAUZZZF57KA026822
Mileage : 7146
Date In : 7-Oct-19
Estimated By : Johnny Boo / Allan Wu
Accident Date : 6-Oct-19
Place of Accident : Along AYE Towards Tuas Direction

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SFV 8092 U

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00 ✓	
2	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio components.	S/N \$ 480.00 ?	
3	To dismantle and renew rear bumper and rear lid. To repair lhs rear fender. To cut out and reweld end panelling. Re-organise rear crash management components. Reinstall all parts removed.	\$ 5,200.00 ✓ 1250.	
4	To respray rear bumper, rear lid, lhs rear fender, end panelling, and spare wheel housing. ✓ x ✓	\$ 4,900.00 ✓ 1650.	
5	To remove and renew lhs rear exhaust silencer. To align to position.	S/N \$ 480.00 ?	
6	To carry out diagnostic checks.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 11,612.00	

⑦. To reapply Paint Protection Film for rear bumper, rear boot and rear fender.

\$ 2530.00 .

1550 .

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFV 8092 U

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER <i>Del'd</i>	\$ 2,311.00	✓
2	REAR BUMPER FIXING PARTS <i>new</i>	\$ 150.00	+
3	REAR BUMPER SECURING STRIP <i>?</i>	\$ 203.00	?
4	REAR BUMPER TRIM <i>crushed</i>	\$ 928.00	✓
5	REAR LIGHT REFLECTOR - LH <i>?</i>	\$ 38.00	?
6	REAR BUMPER CARRIER <i>?</i>	\$ 819.00	?
7	REAR BUMPER SEAL <i>?</i>	2 \$ 25.00	?
8	REAR BUMPER GUIDE SECTION - LH / RH <i>new</i>	2 \$ 80.00	+
9	REAR BUMPER GUIDE SECTION - LH / RH <i>new</i>	2 \$ 40.00	+
10	AERIAL RETAINER - LH <i>?</i>	\$ 23.00	?
11	TELEPHONE AERIAL <i>?</i>	\$ 164.00	?
12	REAR PARKING AID SENSOR - INNER / OUTER <i>?</i>	2 \$ 462.00	?
13	REAR PARKING AID SEAL RING <i>?</i>	4 \$ 12.00	?
14	REAR BUMPER WIRING SET <i>new</i>	\$ 618.00	+
15	BOOT LID CONTROL UNIT <i>new</i>	\$ 381.00	+
16	REAR LID <i>Dented</i>	\$ 2,449.00	✓
17	REAR LID HINGE - LH / RH <i>new</i>	2 \$ 762.00	+
18	REAR LID ATTACHMENT PARTS <i>?</i>	\$ 154.00	?
19	REAR LID LOCK <i>new</i>	\$ 210.00	+
20	LID LOCK PUSH BUTTON <i>new</i>	\$ 1,230.00	+
SUB-TOTAL SPARE PARTS		: \$ 11,059.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No SFV 8092 U

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
21	REAR LID LOCK STRIKER <i>new</i>	\$ 30.00	+
22	REAR LID ANTI THEFT GUARD COVER - INNER <i>new</i>	\$ 58.00	+
23	REAR LID FLAP GASKET <i>new</i>	2 \$ 207.00	+
24	PACKING ADHESIVE <i>new</i>	2 \$ 18.00	✓
25	AUDI EMBLEM <i>2 new</i>	4 \$ 127.00	✓
26	A5 INSCRIPTION <i>2 new</i>	\$ 87.00	✓
27	REAR CROSS PANEL ?	3 \$ 329.00	?
28	CROSS PANEL REINFORCEMENT ?	6 \$ 577.00	?
29	LED LICENCE PLATE LIGHT <i>new</i>	2 \$ 92.00	+
30	LED TAIL LIGHT - LH <i>3 new</i>	\$ 931.00	+
31	TAIL LIGHT TRIM - LH <i>3 new</i>	\$ 27.00	+
32	EXHAUST TAILPIPER TRIM SET <i>new</i>	\$ 153.00	✓
33	REAR SILENCER - LH ?	\$ 813.00	?
34	REAR SILENCER DUAL CLIP ?	\$ 45.00	?
35	EXHAUST SILENCER BRACKET ?	\$ 38.00	?
36	ACRYLIC SEALANT ?	S/N \$ 180.00	?
37	CAVITY WAX ?	S/N \$ 140.00	?
38	STONE CHIP ?	S/N \$ 180.00	?
39	REAR NO PLATE <i>new</i>	S/N \$ 40.00	+
40	SUNDRIES	\$ 400.00	?
TOTAL SPARE PARTS		: \$ 15,531.00	
TOTAL LABOUR CHARGES		: \$ 11,612.00	
GRAND TOTAL		: \$ 27,143.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 08/10/19
Authorised Date :
Excess Cost :
Liability :
Remarks : Not authorised, 05 Days (Without End Panel)
08 Days (With End Panel)

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant



C. R. N: 201536586N

INVOICE

Bill To:

Name :

Mr. Ong

Contact Number :

9787 9053

Address :

DATE:

7/Mar/19

INVOICE #

5D 19111

Vehicle Make/Model/Colour :

Audi A5 Black

Vehicle Registration Number :

SFV 8092 U

TERM: Nets / Cash / Credit

DESCRIPTION	AMOUNT
STEK Paint Protection Film - Extreme Plus Package (10 Year Warranty)	\$ 5,400.00
De-Chrome -	
* Gloss Black	\$ 150.00
*Carbon	\$ 50.00
Remarks (if any):	
Car Maintenance Tips:	
1. Wash your car regularly with mild car soap (Recommended once a week)	
2. Avoid doing any further polishing and using wax as it will void your warranty	
3. The warranty does not extend coverage cause by misuse, accident, missapplication, normal wear and tear, or dents from road debris impact, collisions and/ or intentional damage of any kind.	
	\$ 5,600.00



Bill To:

Name :

Contact Number :

Address :

Mr. Ong

9787 9053

DATE:

7 October, 2019

INVOICE #

Quotation

Vehicle Make/Model/Colour :

Vehicle Registration Number :

Audi A5 Black

SFV 8092 U

TERM:

1550