

ASS. REC. BY:

REF: 08/FCI/1017625/Vt d3n2 Special Instructions:

Surveyor: Marcus

ASSIGNMENT (Office)

From Person: Joanne Yong of FCI

Date/Time: 2:57pm 7/10/19

Estimated Cost: Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMJ 3181J Insured: SH 903AT

at Workshop m/s: SME MOTOR Tel: 6747 6106

of 1 Kaki Bukit Ave 6 #02-15

Policy No: Claim No: D19006379MFC4

Sum Insured: Excess:

Make of Veh: D.O.A. 8/10/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS (DS)

H.O.D. Endorsement:

Date/Time: 3:11pm 7/10/19 Person Contacted: Pei ying Vehicle IN / OUT

Date/Time Action/Instruction 1:31pm 7/10/19 ✓✓

SMJ 3181J-X

SH 903AT-CC-1/PWD/802/1192/Klob 342

2019.07.11/2018

02/10@5:12pm. sent preli aduse via email.

REF: FCI

WOL: 1101, BY:

Marcus

ASSIGNMENT

From: #

Date:

21/10/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SMJ 3181J

at Workshop m/s

SME MOTOR

of

1 kaki Bukit Ave 6 # 02-15

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

11:30am - 12pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

76 k.

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res:

Yes or No

Lum Sum:

1.5.1 %

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

(DS)

LIA 47760

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMJ 3181J

Yr Regn:

11/15

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

A/

Make:

Audi A4

C.C 1798

Colour:

3/40k

A/C:

Insured / Std / NI / NA

Sp. Reading

50569

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WAU2228KXFA179722

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Ban / STD A/Rim or

Tyre Size:

F:

R:

245/40 R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

2/10/19

D.O.I.

2/10/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

No second hand parts.

24/10/19 confirmed final fig 2710.50 with AMVing (Red: 878.50, 23%)

RECEIVED 25 OCT 2019

Date/Time, File Plus 107



Prel. Report

11/25/10 Typast



Final Report

Date/Time, File Plus 107

2)

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Inve (\$



Wheel and (\$

Survey Fee:

130

Transportation:

50

3 x RS: 50

50

Photos

22

Others:

TOTAL

252

Report Format:

TP

Lump Sum / 107:

2710.50



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL.: (065) 62563561 FAX : (065) 62564315

Your Ref: D19006379MFSH

Date: 22/10/2019

Our Ref: CS/FCI19017625/Utd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SMJ 3181J

Please be informed that we had conducted the inspection of the abovementioned vehicle 22/10/2019 at the premises of M/s SME Motor have the following to report: -

Workshop Estimate Amount	: S\$ <u>3,529.00</u>
Revised Estimate Amount	: S\$ <u>3,160.50</u>
"Check" Items Amount	: S\$ <u>00.00</u>
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the
o/s rear portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Marcus Chua
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	04-10-2019	Our Ref No. D19006379MFSH
Accident Date	02-10-2019	Claim Type. Third Party
Insured Vehicle	SH9037T	Third Party Vehicle. SMJ3181J
Survey Location	1 KAKI BUKIT AVE 6 BLK D #02-15/16/17/18AUTOBAY @ KAKI BUKIT	
Contact Person.	PEI YING	
Contact No.	67476106/ 0	Fax No. 67442368
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SME MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 22 October 2019 5:12 PM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments
Cc: 'Joanne Yong'; SUR
Subject: RE: SURVEY ASSESSMENT - D19006379MFSH/1
Attachments: PRELI ADVISED OF SMJ 3181J.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SMJ 3181J**
Number of days (estimated) : 3 days

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Monday, 7 October 2019 3:18 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong' <Joanneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19006379MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 7 October 2019 2:57 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong

Denise Tay (LKKAUTO)

From: Carrine Leong <carrine.leong@premiumauto.com.sg>
Sent: Tuesday, 22 October 2019 5:44 PM
To: Denise Tay (LKKAUTO)
Subject: RE: Audi A4 PART PRICE CHECK

Hi Denise,

For C.NO WAUZZZ8KXFA179722 Rear Bumper is \$2100.00

Thanks & Best Regard
Carrine Leong
Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183
e. carrine.leong@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]
Sent: Tuesday, 22 October, 2019 4:43 PM
To: Carrine Leong <carrine.leong@premiumauto.com.sg>
Subject: Audi A4 PART PRICE CHECK

Dear Carrine,

Can help me check part price?

SMJ 3181J 2015 MODEL

C.NO WAUZZZ8KFA179722

Rear bumper

List price and cost price

Best Regards,

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 685I

Vehicle Details

Vehicle No.: SMJ3181J

Vehicle to be Exported: No

Intended Deregistration Date: 21 Oct 2019

Vehicle Make: AUDI

Vehicle Model: A4 1.8 TFSI MU ATTRACTION

Primary Colour: Black

Manufacturing Year: 2015

Engine No.: CJE113711

Chassis No.: WAUZZZ8KXFA179722

Maximum Power Output: 125.0 kW (167 bhp)

Open Market Value: \$29,472.00

Original Registration Date: 30 Nov 2015

First Registration Date: 30 Nov 2015

Transfer Count: 1

Actual ARF Paid: \$28,261.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 29 Nov 2025

PARF Rebate Amount: \$21,195.00

Intended COE Rebate Details

COE Expiry Date: 29 Nov 2025

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$60,000.00

COE Rebate Amount: \$36,565.00

Total Rebate Amount: \$57,760.00

The information contained herein is correct as at 21 Oct 2019

OK

LETTER OF UNDERTAKING

I/We, ERAWANY KINTI ABOUL RAHAT, the owner of vehicle no. SMJ 287

My/Our Insurance is under M/s AXA Insurance Pte Ltd, I/we shall decide whether to claim under my/our Policy or against the Third Party and if the former shall submit such a claim to M/s AXA Insurance Pte Ltd with all relevant facts and documents **within 14(fourteen) days of occurrence or discovery of damage.**

My/Our Third Party claim is handle by my/our preferred workshop, SME MOTOR

Signed and Acknowledge by:



.....
Nric no. & signature of policyholder

.....
Company stamp

03/10/19
.....
Date

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
GST:201119451E RCB NO:201119451E

M/S: MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD #16-01
CITY HOUSE
Singapore 068877
TEL: 65073848 **FAX:** 65073849
ATTN: Motor Claim Department
Your Ref No: 19/FC/TP-207 (10)
Claim Type: Third Party
Accident Date: 02/10/2019
TP Veh Reg No: SH9037T

Estimate No: EST0005074
Date: 04 Oct 2019
Policy No: P2293025
Veh Reg No: SMJ3181J
Make/Model: AUDI A4
Chasis No: WAUZZZ8KXFA179722
Engine No: CJE113711
Reg. Date: 30/11/2015

Estimate Repair Cost to Vehicle No :SMJ3181J

Description	Quantity	List Price	Amount
		<u>SS</u>	<u>SS</u>
List Price			
1 REAR BUMPER	2100 1 PC	2,600.00	✓
2 REAR BUMPER RETAINER RH	1 PC	165.00	✓
3 REAR BUMPER CLIP	10 PC	45.00	✓
		2,810.00	
	Less 10%	281.00	2,529.00
Labour			
4 LABOUR CHARGE	1 UNIT	500.00	380
5 SPRAY PAINTING	1 UNIT	500.00	400
		1,000.00	1,000.00
Total			SS 3,529.00
Add GST @ 7%			247.03
Total Amount Payable			SS 3,776.03

TOTAL: SINGAPORE DOLLAR THREE THOUSAND SEVEN HUNDRED SEVENTY SIX AND CENTS THREE ONLY

For SME Motor Pte Ltd

AUTHORISED SIGNATURE

Not Acknowledged
Halter
try H/s
the 1st before party.
21/10/19
3dy.

p- 2145
107
1930.50
2710.50

LKK Auto Consultants hence notify the Repairer of the following:

- To rectify before/after spray painting
- To ensure damaged part(s) during resurvey
- Repairs must be subject to confirmation
- Work to be carried out on a "Wincof Freezone" basis
- Excess of 10% (one-tenth) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19017625/Utd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 29-10-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 9037T	Veh. Inspected	SMJ 3181J	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19006379MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	07/10/2019	
2. Vehicle Particulars & Condition				
Make & Model	AUDI A4 (A)	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	WAUZZZ8KXFA179722	Colour	BLACK	
Odometer	50569	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/40 R18	PIRELLI	7 mm	
L/H Front Tyre	245/40 R18	PIRELLI	7 mm	
R/H Rear Tyre	245/40 R18	PIRELLI	7 mm	
L/H Rear Tyre	245/40 R18	PIRELLI	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/10/2019	Inspection Date	21/10/2019	
Survey held at	SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMJ 3181J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DISTORTED	2,600.00	2,100.00
1	REAR BUMPER RETAINER RH	NOT NECESSARY	165.00	-
10	REAR BUMPER CLIP	NECESSARY	45.00	45.00
	LESS 10% DISCOUNT		-281.00	-214.50
			2,529.00	1,930.50
	LABOUR			
	LABOUR CHARGE.		500.00	380.00
	SPRAY PAINTING.		500.00	400.00
			1,000.00	780.00
	GRAND TOTAL		3,529.00	2,710.50
	RECOMMENDED COST OF REPAIRS			2,710.50

Report Ref No. CS/FCI19017625/Utd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.