



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 09/10/2019

### Survey Details:

Date of loss	7-Oct-19
Date of appointment	8-Oct-19
Date of survey	8-Oct-19
Location of survey	Raaim Car Bodyworks Pte Ltd

### Vehicle Details:

Claim Type:	Third party
Vehicle number	SMA 3163J
Make and Model	MAZDA 2 SEDAN 1.5
Date of registration	31/5/2018
Excess	
Market Value	\$63,000
Parf Rebate	\$37,992
Nett Loss	\$25,008

### Repair details:

Initial Estimate	TBA
------------------	-----

### Proposed/Revised repair cost:

Parts	\$	-
Check items (estimate)	\$	-
Labour	\$	-
<b>Total</b>	<b>\$</b>	<b>-</b>
<b>Lump Sum(if applicable)</b>	<b>\$</b>	<b>-</b>
<b>Number of days for repair</b>		<b>TBA</b>



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

**Remarks:**

*We have not authorized repairs.*

**Mandate:**

Liability(TP)	%	
Proposed repair cost	TBA	
Loss of use		no. of days
Loss of rental		no. of days
Loss of income		no. of days
LTA search fees		
Others		
<b>Proposed Total</b>	<b>TBA</b>	