



方本摩哆私人有限公司
Poon Poong Motors Pte Ltd

BLK 176, SIN MING DRIVE, #05-15, SIN MING AUTOCARE, SINGAPORE 575721
Tel:(65) 6453 2235 (24 hrs), (65) 6457 8186 Fax:(65) 6452 0022

M/S: QBE

Our Ref: EST 2019-9789E/HEN

Date : 04.10.2019

Dear Sir/Mdm

Insured Vehicle	SJS9789E
Insured	CDM RENTAL & LEASING
Accident Date	12.09.2019
Policy Number	

Parts Replacement Estimate

No	Product	Qty		Disc	Ext Price
1	Rear Bumper	1			680.00
2	Exhaust (Before Cat)	1			950.00
3	Rear Bumper	1			550.00
4	RL Bumper Retainer	1			150.00
5	RL Bumper Reflector	1			110.00
6	Rear Boot	1			1180.00
7	End Panel	1			365.00
8	RL Fender Inner Housing	1			580.00
9	Reverse Sensor	2			95.00
10	Clip	10	\$2.00		20.00
11	Honda Logo	1			35.00
12	Fit Logo	1			25.00
13	RR Bumper Retainer	1			150.00
14	End Panel Top Garnish	1			190.00
15	RL Wheel Housing Garnish	1			350.00
16	Boot Door Inner Garnish	1			210.00
17	Boot Lock	1			150.00
18	Spare Tyre Trunk	1			450.00
19	Tail Light left	1			350.00
20	Tail Light Right	1			350.00
21	Rear Fender Left	1			400.00
22	Rear Fender Right	1			400.00

Subtotal (Parts): **\$7740.00**

Labour Charges

No	Labour Description	Price
1	To remove, refit damage parts and welding	1800.00
2	To remove and refit boot windscreen	180.00
3	Paintwork	1000.00
4		

Total (labour) \$2980.00

Total (parts & labour) \$10720.00

Add GST 7% \$750.40

Grand Total \$11470.40

Henry Khoo
96356799