

22/03/2003

ASS. REC. BY:

REF:

es/CTI19017733/Byd3ST

Special Instruction:

Surveyor:

Mr HM

ASSIGNMENT (Office)

Meinmen

From (Person):

Ong chin kiat

of

CTI

Date/Time:

8/10/1909.38am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJR 8917P

Insured:

GBA 6530T

at Workshop m/s

Team Autopro

Tel:

62881955

of

385 Sin Ming Drive #01-02

Policy No:

DMCVSN/9332919000

Claim No:

SNM19D204629C02

Sum Insured:

Excess:

Make of Veic:

D.O.A.

30/9/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:31am 8/10/19

Person Contacted:

penek

Vehicle

☒ IN ☐ OUT

Date/Time

Action/Instruction

Tehmyl

Ins: 160 Sin Ming Drive #01-14

SJR 8917P-NBA/CTI19017/72/Y

DUA: 30/9/2019

GBA 6530T-NBA/CTI19017/72/Y

DUA: 30/9/2019

ASSIGNMENT

From:

Date:

8/10/2019

Estimated Cost:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SJR 8917P

at Workshop m/s

Team Autopro

of

160 Sin Ming Drive # 01-14

Insured:

Policy No.

Claim No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lump Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS (up)

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SJR 8917P

Yr Regn: 20/7/2009

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Kia Cerato Forte

cc 1591

Colour:

White

A/C: Insured / Std / NI / NA

Sp. Reading

253815

T/Radio: Insured / Std / NI / NA

Eng/No:

G4FC9H259744

C/No:

KNAFH221395081603

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 215/45 R17 FIRENZA

R: 215/45 R17 TRIANGLE

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FIRENZA FRT / TRIANGLE Rear

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

30/3/2019

D.O.I.

8/10/19

Survey held at

Team Autopro

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Range 6,000/- - 7,000/-
12/3	4S \$4900/- (Red \$8822.40, 64%) 4S A900/- COR Seen 10/10/19 Try to remove RHR Jumper as repair 27/02/2020 RECEIVED 13 MAR 2020 TERMIN 3/10/19
	MV 27,000/- PV 12,946/- NV 14,054/-

Date/Time, File Pass to?

☐ : Preli Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

13/3/20 Typist

Report Format:

Comp Sum LDR: \$4900/-

Days Of Repair:

Resurvey No. of Trip:

2

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)
☐ : Other (\$)
☐ : TOTAL

Survey Fee:

Transportation:

3 x RS: \$

Folio:

Other:

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Oct 2019		08 Oct 2019 09:38 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	ABS LEASING SERVICES PTE LTD, Co. Reg. No.: 201819528D		
Main Claimant:	ECHAN STUDIO, Co. Reg. No.: 53243454D		
Vehicle Reg. No.:	SJR8917P	Date of Loss:	30/09/2019 08:00 - :59 [122 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D204629C02	Policy/Cover Note No.:	DMCVSN19332919000
Vehicle Reg. No. (Insured):	GBA6530T	Policy No. (Claimant):	DMHCSN1915501900
		Excess:	S\$0.00
Repairer:	Team Autopro Pte Ltd (Sin Ming) 385 Sin Ming Drive, #01-02 Vicom Inspection Centre, 575718 Sin Ming - Tel: 62581955		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]		
Claimant's Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 17/10/2019]		
Driver/Custodian (Insured):	MUHAMMAD HAFIZ BIN ITHNIN (28 / Male) , NRIC: S9132619A Email:		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.



ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/09/2019 15:50
Date Of Accident	30/09/2019 08:30
Exact Location Of Accident	PIE BEFORE BKE EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJR8917P
Insured/Policyholder	
Name Of Registered Owner	ECHAN STUDIO
Co Reg No	53243454D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94998324
Alternative Phone No	OFFICE-94998324

Vehicle Particulars

Manufacturer	KIA
Model	CERATO FORTE-1.6 A/T ABS AB 2WD 4DR (A)
Exact Purpose for which vehicle was being used at time of accident	WORKING PURPOSES
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMHCSN1915501900
Cover Note Number	

Driver

Name of Driver	MOHAMED AZRIN BIN HAMID
NRIC No	S7348740D
Date Of Birth	07/10/1973
Occupation	OUTDOOR
Date Of Driving Pass	26/03/2014
Driving Experience	5 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94998324
Fax Number	
Contact Number	OTHERS-94998324
EEmail Address	NOEMAIL

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	454D
Vehicle Details	
Vehicle No.:	SJR8917P
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Oct 2019
Vehicle Make:	KIA
Vehicle Model:	CERATO EX FORTE 1.6L A/T ABS AB 2WD 4DR
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	G4FC9H259744
Chassis No.:	KNAFH221395081603
Maximum Power Output:	92.7 kW (124 bhp)
Open Market Value:	\$11,277.00
Original Registration Date:	20 Jul 2009
First Registration Date:	20 Jul 2009
Transfer Count:	4
Actual ARF Paid:	\$11,277.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 May 2024
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$13,943.00
COE Rebate Amount:	\$12,946.00
Total Rebate Amount:	\$12,946.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 09 Oct 2019

OK

Dep 5,770/yr
481/mth

MV 27,000/2
PV 12,946/2
NV 14,054/2

Kelim
9/10/19

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

Current Latest Face-lift Model, Free Servicing 2023.



Current Latest Face-lift Model
BMW 218i Convertible Sport Line
With M-Body-Kit,
HTS Motor StarAd

PRIME MOTOR & LEASING
ICHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES
With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Browse by Category

« Back (1 2 3 4 5 ... 11) Next »

Sort by Date Posted 20 results/page

204 vehicles

Kia Cerato

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Kia Cerato	Any	Any	> 10 year(s) old	Any	Any	Any	All
	Kia Cerato Forte 1.6A SX (COE till 06/2024)	\$27,300	\$5,770 /yr	02-Jul-2009	1,591 cc	120,555 km	Sedan	Available
Excellent Condition With 100% Accident Free. View To Believe. Clean & Neat Interior And Exterior With New Paintwork. Wear & Tear Changed. No Repair Is Needed. Drive With Peace Of Mind. Genuine Selling & No Hidden Cost. Flexible Bank And In-House Full Loan Avail...								
Ka-Hup Vehicles Trading								
Posted: 09-Oct-2019 Tags: 2009 Kia Cerato, 2009 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia								
	Kia Cerato 1.6A (COE till 12/2028)	\$32,800	\$3,550 /yr	29-Dec-2008	1,591 cc	-	Sedan	Available
Cheapest Kia Cerato In The Market! AA Trust Certified Pre-Owned Vehicle! Very Well Maintained By Previous Owner! Unit Comes With Legal Exhaust Pipe! Spacious Boot And Legroom Space For All! This Is The Perfect Sedan For Everyone! Flexible Bank And In House Loa...								
AA Trust Automotive								
Posted: 09-Oct-2019 Tags: 2008 Kia Cerato, 2008 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia								
	Kia Cerato Forte 1.6A EX (New 5-yr COE)	\$32,800	\$6,550 /yr	06-Oct-2009	1,591 cc	107,000 km	Sedan	Available
2 Years Warranty, High Loan Available, Free 3 x Servicing, Warranty Not By 3rd Party Workshop, Price Stated Above Is Actual Selling Price, Fully Refurbished, Guarantee Accident Free, STA OR VICOM Evaluation Are Welcome, Purchase With Official Certificate With A Pea...								
Carway								
Posted: 09-Oct-2019 Tags: 2009 Kia Cerato, 2009 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia								
	Kia Cerato Forte 1.6A SX (New 5-yr COE)	\$29,800	\$5,950 /yr	30-Sep-2009	1,591 cc	92,000 km	Sedan	Available
COE Specialist With More Than 150 Positive Reviews Offering 6 Months Warranty And Road Tax Just For You! 100% Immediate Loan Approval! Highest Specs Topped With Full Bodykit! Very Well Maintained By Previous With Weekly Cleaning And Upholstery Care! Vehicl...								
Posted: 08-Oct-2019 Tags: 2009 Kia Cerato, 2009 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia								
GET YOUR COE RENEWAL LOAN								
Is your COE expiring? Let us help you renew it!								
Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.								
	Kia Cerato Forte 1.6M EX (COE till 05/2024)	\$26,000	\$5,610 /yr	27-May-2009	1,591 cc	96,000 km	Sedan	Available
Consignment Code: A432. Flexible And Attractive Loan Available. Trade In Available For Your Car! No Hidden Costs. For Further Information Or If You Have Any Questions Please Do Not Hesitate To Contact Us.								
Posted: 08-Oct-2019 Tags: 2009 Kia Cerato, 2009 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia								
	Kia Cerato Forte 1.6A SX (COE till 09/2024)	\$27,800	\$5,610 /yr	22-Sep-2009	1,591 cc	110,000 km	Sedan	Available
Owned This Car With 90% Loan Amount Shown! Various Financial Plan To Cater Individual Needs, Flawless Interior & Exterior Conditions, Very Low Mileage Done! Meticulously Well Maintained With Regular Servicing Done, One Of Our Company Carefully Selected Range Of C...								
Posted: 08-Oct-2019 Tags: 2009 Kia Cerato, 2009 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia								
Compare	Kia Cerato Forte 1.6A SX (COE till 09/2024)	\$29,800	\$5,980 /yr	02-Oct-2009	1,591 cc	115,286 km	Sedan	Available

SJE :

Date of Survey :

Date of ReSurvey :

Contacts :

After-Paint:

 Vehicle Nos : **SJR 8917 P**

 Model : **KIA CERATO**

Year :

Chassis No :

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	BOOTLID <i>RT ✓</i>	1	\$ 854.00	\$ 673.50 854.00
2	BOOTLID SPOILER <i>BR ✓</i>	1	\$ 357.00	\$ 357.00 ✓ 357.00
3	BOOTLID LOGO	1	\$ 62.00	\$ 46.00 62.00
4	BOOTLID EMBLEM 'CERATO' <i>NEC ✓</i>	1	\$ 58.00	\$ 40.80 58.00
5	BOOTLID EMBLEM 'C&C'	1	\$ 49.00	\$ 25.00 49.00
6	BOOTLID REFLECTOR <i>RH CUT ✓</i>	1	\$ 342.00	\$ 135.80 342.00
7	BOOTLID REFLECTOR INNER SPONGE <i>NDMX</i>	1	\$ 40.00	\$ -40.00
8	BOOTLID LOCK <i>DD ✓?</i>	1	\$ 186.00	\$ 186.00 ✓ 186.00
9	BOOTLID STRIKER <i>NDMX?</i>	1	\$ 38.00	\$ 38.00
10	BOOTLID WEATHER STRIP <i>TN ✓</i>	1	\$ 98.00	\$ 98.00 ✓ 98.00
11	BOOTLID INNER TRIM <i>SVC X</i>	1	\$ 168.00	\$ -168.00
12	BOOTLID RUBBER STOPPER <i>SVC X</i>	4	\$ 20.00	\$ -80.00
13	BOOTLID HINGE <i>BT ✓</i>	2	\$ 68.00 150.00	\$ 136.00 300.00
14	BOOTLID HINGE SPRING <i>SVC X</i>	2	\$ 250.00	\$ 500.00
15	REAR BUMPER <i>CUT ✓</i>	1	\$ 988.00	\$ 601.00 988.00
16	REAR BUMPER SIDE RETAINER <i>NEC ✓</i>	2	\$ 38.50 75.00	\$ 77.00 150.00
17	REAR BUMPER REINFORCEMENT <i>BR ✓?</i>	1	\$ 360.00	\$ 360.00 ✓ 360.00
18	REAR BUMPER REINFORCEMENT BRACKET <i>NDM X</i>	2	\$ 224.00	\$ 448.00
19	REAR BUMPER SPONGE <i>BR ✓?</i>	1	\$ 187.00	\$ 134.97 187.00
20	REAR BUMPER LOWER SKIRT <i>BR ✓</i>	1	\$ 389.00	\$ 389.00 ✓ 389.00
21	REAR BUMPER DIFFUSER <i>CUT ✓</i>	1	\$ 258.00	\$ 242.50 258.00
22	REAR END PANEL <i>NDM X</i>	1	\$ 282.00	\$ -282.00
23	REAR END PANEL TOP GARNISH <i>DL ✓</i>	1	\$ 56.00	\$ 56.00 ✓ 56.00
24	TAIL LAMP <i>RH BR ✓</i>	1	\$ 836.00	\$ 298.60 836.00
25	TAIL LAMP INNER SPONGE <i>NDMX</i>	1	\$ 60.00	\$ 60.00
26	TAIL LAMP PANEL <i>NDMX?</i>	1	\$ 330.00	\$ -330.00
27	TAIL LAMP LOWER BRACKET <i>L?</i>	1	\$ 92.00	\$ -92.00
28	REAR FENDER <i>RH BT ✓</i>	1	\$ 794.00	\$ RX 794.00 ✓ 794.00
29	REAR FENDER INNER TRIM <i>NDMX</i>	1	\$ 236.00	\$ -236.00
30	REAR FENDER INNER COWLING <i>TN ✓</i>	1	\$ 199.00	\$ 98.00 199.00
31	REAR EXHAUST SILENCER <i>/ pipe BT ✓</i>	1	\$ 685.00	\$ 570.00 685.00
32	REAR EXHAUST MOUNTING <i>NDMX</i>	1	\$ 106.00	\$ 106.00
33	REAR EXHAUST PIPE GASKET <i>NEC ✓</i>	1	\$ 67.00	\$ 67.00 ✓ 67.00
34	REAR EXHAUST PIPE HEAT PLATE <i>NAX</i>	1	\$ 81.00	\$ 81.00

Parts Sub Total : \$ 4590.57 9,736.00

DISC

10%

PARTS TOTAL : \$ 4131.51 8,762.40

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	EXHAUST CHROME PIPE <i>SVCIX</i>	1	\$ 240.00	\$ 240.00
2	BOOTLID NO PLATE WITYH COVER <i>SVCX</i>	1	\$ 80.00	\$ 80.00
3	BOOTLID REFLECTOR CLIPS <i>NDMX</i>	10	\$ 5.00	\$ 50.00
4	BOOTLID INNER TRIM CLIPS	10	\$ 5.00	\$ 50.00
5	REAR BUMPER CLIPS <i>NECV</i>	10	\$ 5.00	\$ 30.00 50.00
6	REAR BUMPER REVERSE SENSORS <i>DL</i>	2	\$ 200.00	\$ 200.00 400.00
7	REAR BUMPER STAY <i>NDMX?</i>	5	\$ 58.00	\$ 290.00
8	REAR END PANEL TOP GARNISH CLIPS <i>NECV</i>	10	\$ 5.00	\$ 30.00 50.00
9	TAIL LAMP INNER SPONGE CLIPS <i>NAX</i>	10	\$ 5.00	\$ 50.00
10	REAR FENDER INNER TRIM CLIPS <i>NECV</i>	10	\$ 5.00	\$ 30.00 50.00
SPECIAL NETT TOTAL :				\$ 290.00 1,310.00

Nos.	LABOUR	S\$
1	R&R UPHOLSTERTY	\$ 100.00
2	R&R REVERSE SENSOR	\$ 60.00 100.00
3	R&REXHAUST PIPE	\$ 50.00 150.00
4	PANEL BEATING	\$ 800.00 1,500.00
5	RUST PROOFING	\$ 60.00 150.00
6	SPRAY PAINTINHG	\$ 800.00 1,500.00
7	CHECK WIRING	\$ 50 150.00
LABOUR TOTAL :		\$ 1820.00 3,650.00

PARTS TOTAL : \$ 4131.51 8,762.40
 SPECIAL NETT TOTAL : \$ 290.00 1,310.00
 LABOUR TOTAL : \$ 1820.00 3,650.00
GRAND TOTAL : \$ 6241.51 13,722.40

Trim
1400hrs *8/10/19*
? Photo

Lump sum repair
Repair days 5

Resurvey on 9/10/19

Trim
1600hrs

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

@ 20%
6241.51
1248.30
4993.20

4/3 4900/2
Trim
10/10/19

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Oct 2019		08 Oct 2019 09:38 Edit Adj Rpt	S\$4,900.00 Edit Estimates	S\$4,900.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	ABS LEASING SERVICES PTE LTD, Co. Reg. No.: 201819528D			
Main Claimant:	ECHAN STUDIO, Co. Reg. No.: 53243454D			
Vehicle Reg. No.:	SJR8917P	Date of Loss:	30/09/2019 08:00 - :59 [122 Months and 10 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / SNM19D204629C02	Policy/Cover Note No.:	DMCVSN19332919000	
Vehicle Reg. No. (Insured):	GBA6530T	Policy No. (Claimant):	DMHCSN1915501900	
		Excess:	S\$0.00	
Repairer:	Team Autopro Pte Ltd (Sin Ming) 385 Sin Ming Drive, #01-02 Vicom Inspection Centre, 575718 Sin Ming - Tel: 62581955			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]			
Claimant's Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 17/10/2019]			
Driver/Custodian (Insured):	MUHAMMAD HAFIZ BIN ITHNIN (28 / Male), NRIC: S9132619A Email:			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJR8917P (SNM19D204629C02)
[GBA6530T]
TP
ECHAN STUDIO
Sep 30 2019 8:00AM
[ABS LEASING SERVICES PTE LTD]
Team Autopro Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/03/20 10:23	General View	Load JPG	☒
2	13/03/20 10:23	General View	Load JPG	☒
3	13/03/20 10:23	General View	Load JPG	☒
4	13/03/20 10:23	General View	Load JPG	☒
5	13/03/20 10:23	General View	Load JPG	☒
6	13/03/20 10:23	General View	Load JPG	☒
7	13/03/20 10:23	General View	Load JPG	☒
8	13/03/20 10:23	General View	Load JPG	☒
9	13/03/20 10:23	General View	Load JPG	☒
10	13/03/20 10:23	General View	Load JPG	☒
11	13/03/20 10:23	General View	Load JPG	☒
12	13/03/20 10:23	General View	Load JPG	☒
13	13/03/20 10:23	General View	Load JPG	☒
14	13/03/20 10:23	General View	Load JPG	☒
15	13/03/20 10:23	General View	Load JPG	☒
16	13/03/20 10:23	General View	Load JPG	☒
17	13/03/20 10:23	General View	Load JPG	☒
18	13/03/20 10:23	General View	Load JPG	☒
19	13/03/20 10:23	General View	Load JPG	☒
20	13/03/20 10:23	General View	Load JPG	☒
21	13/03/20 10:23	General View	Load JPG	☒
22	13/03/20 10:23	General View	Load JPG	☒
23	13/03/20 10:23	General View	Load JPG	☒
24	13/03/20 10:23	General View	Load JPG	☒
25	13/03/20 10:23	General View	Load JPG	☒
26	13/03/20 10:23	General View	Load JPG	☒
27	13/03/20 10:23	General View	Load JPG	☒
28	13/03/20 10:23	General View	Load JPG	☒
29	13/03/20 10:23	General View	Load JPG	☒
30	13/03/20 10:23	General View	Load JPG	☒
31	13/03/20 10:23	General View	Load JPG	☒
32	13/03/20 10:23	General View	Load JPG	☒
33	13/03/20 10:23	General View	Load JPG	☒
34	13/03/20 10:23	General View	Load JPG	☒
35	13/03/20 10:23	General View	Load JPG	☒

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	13/03/20 10:23	General View	 Load JPG	☒
37	13/03/20 10:23	General View	 Load JPG	☒
38	13/03/20 10:23	General View	 Load JPG	☒
39	13/03/20 10:23	General View	 Load JPG	☒
40	13/03/20 10:23	General View	 Load JPG	☒
41	13/03/20 10:23	General View	 Load JPG	☒
42	13/03/20 10:23	General View	 Load JPG	☒
43	13/03/20 10:23	General View	 Load JPG	☒
44	13/03/20 10:23	General View	 Load JPG	☒
45	13/03/20 10:23	General View	 Load JPG	☒
46	13/03/20 10:23	General View	 Load JPG	☒
47	13/03/20 10:23	General View	 Load JPG	☒
48	13/03/20 10:23	General View	 Load JPG	☒
49	13/03/20 10:23	General View	 Load JPG	☒
50	13/03/20 10:23	General View	 Load JPG	☒
51	13/03/20 10:23	General View	 Load JPG	☒
52	13/03/20 10:23	General View	 Load JPG	☒
53	13/03/20 10:23	General View	 Load JPG	☒
54	13/03/20 10:23	General View	 Load JPG	☒
55	13/03/20 10:23	General View	 Load JPG	☒
56	13/03/20 10:23	General View	 Load JPG	☒
57	13/03/20 10:23	General View	 Load JPG	☒
58	13/03/20 10:23	General View	 Load JPG	☒
59	13/03/20 10:23	General View	 Load JPG	☒
60	13/03/20 10:23	General View	 Load JPG	☒
61	13/03/20 10:23	General View	 Load JPG	☒
62	13/03/20 10:23	General View	 Load JPG	☒
63	13/03/20 10:23	General View	 Load JPG	☒
64	13/03/20 10:23	General View	 Load JPG	☒
65	13/03/20 10:23	General View	 Load JPG	☒
66	13/03/20 10:23	General View	 Load JPG	☒
67	13/03/20 10:23	General View	 Load JPG	☒
68	13/03/20 10:23	General View	 Load JPG	☒
69	13/03/20 10:23	General View	 Load JPG	☒
70	13/03/20 10:23	General View	 Load JPG	☒
71	13/03/20 10:23	General View	 Load JPG	☒
72	13/03/20 10:23	General View	 Load JPG	☒
73	13/03/20 10:23	General View	 Load JPG	☒
74	13/03/20 10:23	General View	 Load JPG	☒
75	13/03/20 10:23	General View	 Load JPG	☒
76	13/03/20 10:23	General View	 Load JPG	☒
77	13/03/20 10:23	General View	 Load JPG	☒
78	13/03/20 10:23	General View	 Load JPG	☒
79	13/03/20 10:23	General View	 Load JPG	☒
80	13/03/20 10:23	General View	 Load JPG	☒
81	13/03/20 10:23	General View	 Load JPG	☒
82	13/03/20 10:23	General View	 Load JPG	☒
83	13/03/20 10:23	General View	Load JPG	☒

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	13/03/20 10:23	General View	 Load JPG	☒
85	13/03/20 10:23	General View	 Load JPG	☒
86	13/03/20 10:25	Reinspection Photo	 Load JPG	☒
87	13/03/20 10:25	Reinspection Photo	 Load JPG	☒
88	13/03/20 10:25	Reinspection Photo	 Load JPG	☒
89	13/03/20 10:25	Reinspection Photo	 Load JPG	☒
90	13/03/20 10:25	Reinspection Photo	 Load JPG	☒
91	13/03/20 10:25	Reinspection Photo	 Load JPG	☒
92	13/03/20 10:25	Reinspection Photo	 Load JPG	☒
93	13/03/20 10:25	Reinspection Photo	 Load JPG	☒
94	13/03/20 10:25	Reinspection Photo	 Load JPG	☒
95	13/03/20 10:25	Reinspection Photo	 Load JPG	☒
96	13/03/20 10:25	Reinspection Photo	 Load JPG	☒
97	13/03/20 10:25	Reinspection Photo	 Load JPG	☒
98	13/03/20 10:25	Reinspection Photo	 Load JPG	☒
99	13/03/20 10:25	Reinspection Photo	 Load JPG	☒
100	13/03/20 10:25	Reinspection Photo	 Load JPG	☒
101	13/03/20 10:25	Reinspection Photo	 Load JPG	☒
102	13/03/20 10:25	Reinspection Photo	 Load JPG	☒
103	13/03/20 10:25	Reinspection Photo	 Load JPG	☒
104	13/03/20 10:25	Reinspection Photo	 Load JPG	☒
105	13/03/20 10:25	Reinspection Photo	 Load JPG	☒
106	13/03/20 10:25	Reinspection Photo	 Load JPG	☒
107	13/03/20 10:25	Reinspection Photo	 Load JPG	☒
108	13/03/20 10:25	Reinspection Photo	 Load JPG	☒
109	13/03/20 10:25	Reinspection Photo	 Load JPG	☒
110	13/03/20 10:25	Reinspection Photo	 Load JPG	☒
111	13/03/20 10:25	Reinspection Photo	 Load JPG	☒
112	13/03/20 10:25	Reinspection Photo	 Load JPG	☒
113	13/03/20 10:25	Reinspection Photo	 Load JPG	☒
114	13/03/20 10:25	Reinspection Photo	 Load JPG	☒
115	13/03/20 10:25	Reinspection Photo	 Load JPG	☒
116	13/03/20 10:25	Reinspection Photo	 Load JPG	☒
117	13/03/20 10:25	Reinspection Photo	 Load JPG	☒
118	13/03/20 10:25	Reinspection Photo	 Load JPG	☒
119	13/03/20 10:25	Reinspection Photo	 Load JPG	☒
120	13/03/20 10:25	Reinspection Photo	 Load JPG	☒
121	13/03/20 10:25	Reinspection Photo	 Load JPG	☒
122	13/03/20 10:25	Reinspection Photo	 Load JPG	☒
Documentation			1 per page ▼	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	08/10/19 09:38	INSD GBA6530T GIA REPORT	 Load PDF	
2	08/10/19 09:38	PRI	 Load PDF	
3	08/10/19 09:38	PRS 8917 GBA6530T	 Load PDF	

Linked Accident Report Documents

View

Assessment Reports			1 per page ▼	☒
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
1	06/12/19 18:34	Accident Statement	 Load HTM	☒
2	06/12/19 18:36	Accident Statement	 Load HTM	☒
3	06/12/19 18:37	Accident Statement	 Load HTM	☒
4	06/12/19 18:39	Accident Statement	 Load HTM	☒
Photos/Images			3 per page ▼	☒
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
1	30/09/19 15:58	Accident Photo	 Load JPG	☒
2	30/09/19 15:58	Accident Photo	 Load JPG	☒
3	30/09/19 15:58	Accident Photo	 Load JPG	☒
4	30/09/19 15:58	Accident Photo	 Load JPG	☒
5	30/09/19 15:58	Accident Photo	 Load JPG	☒
6	30/09/19 15:58	Accident Photo	 Load JPG	☒
7	30/09/19 15:58	Accident Photo	 Load JPG	☒
8	30/09/19 15:58	Accident Photo	 Load JPG	☒
9	30/09/19 15:58	Accident Photo	 Load JPG	☒
10	30/09/19 15:58	Accident Photo	 Load JPG	☒
11	30/09/19 15:58	Accident Photo	 Load JPG	☒
12	30/09/19 15:58	Accident Photo	 Load JPG	☒
13	30/09/19 15:58	Accident Photo	 Load JPG	☒
Documentation			1 per page ▼	☒
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
1	30/09/19 16:02	Sketch Plan	 Load JPG	☒
2	30/09/19 16:02	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119017733/BYD3S2
Date: 13/03/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN19332919000

Claimant Vehicle No: SJR8917P Insured Vehicle No: GBA6530T

Date of Loss: 30/09/2019 Nature of Claim: TP Claim No: SNM19D204629C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJR8917P

Make & Model: KIA CERATO FORTE, 1.6 A/T ABS AB 2WD 4DR (A) Engine No: G4FC9H259744

Reg. Date: 20/07/2009 (Man. Year: 2009) Chassis No: KNAFH221395081603

Colour: White Odometer: 253815 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/45 R17 Rear Tyre Size: 215/45 R17

Front Left Side: Firenza 6 mm Rear Left Side: Triangle 6 mm

Front Right Side: Firenza 6 mm Rear Right Side: Triangle 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,072.40	4,421.51	5,650.89	56.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,650.00	1,820.00	1,830.00	50.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,722.40	6,241.51	7,480.89	54.52
Approved Total (Overridden) (S\$)		4,900.00		
Nett Amount (S\$)	13,722.40	4,900.00	8,822.40	64.29

INSPECTION

Date of Assignment: 08/10/2019

Date Inspected: 08/10/2019 Inspected At: 160 Sin Ming Drive #01-14
Singapore 575722
Repairer: Team Autopro Pte Ltd

Estimated Period of Repair: 5.0 days

Adjuster: Lim Teow Guan

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Mar 2020)

Parts: 143 KIA CERATO FORTE 1.6 A/T ABS AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJR8917P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	854.00 FL	*673.50 FL
2	1		*BOOTLID SPOILER	Broken	357.00 FL	*357.00 FL
3	1		*BOOTLID LOGO	Necessary	62.00 FL	*46.00 FL
4	1		*BOOTLID EMBLEM ASSY	Necessary	58.00 FL	*40.00 FL
5	1		*BOOTLID EMBLEM C&C	Necessary	49.00 FL	*25.00 FL
6	1		*BOOTLID REFLECTOR RH	Cut	342.00 FL	*135.00 FL
7	1		*BOOTLID REFLECTOR INNER SPONGE	Not Damaged	40.00 FL	*- FL
8	1		*BOOTLID LOCK	Dented	186.00 FL	*186.00 FL
9	1		*BOOTLID STRIKER	Not Damaged	38.00 FL	*- FL
10	1		*BOOTLID WEATHERSTRIP	Torn	98.00 FL	*98.00 FL
11	1		*BOOTLID INNER TRIM	Serviceable	168.00 FL	*- FL
12	4		*BOOTLID RUBBER STOPPER	Serviceable	80.00 FL	*- FL
13	2		*BOOTLID HINGE	Bent	300.00 FL	*136.00 FL
14	2		*BOOTLID HINGE SPRING	Serviceable	500.00 FL	*- FL
15	1		*REAR BUMPER	Cut	988.00 FL	*601.00 FL
16	2		*REAR BUMPER SIDE RETAINER	Necessary	150.00 FL	*77.00 FL
17	1		*REAR BUMPER REINFORCEMENT	Broken	360.00 FL	*360.00 FL
18	2		*REAR BUMPER REINFORCEMENT BRACKET	Not Damaged	448.00 FL	*- FL
19	1		*REAR BUMPER SPONGE	Broken	187.00 FL	*134.97 FL
20	1		*REAR BUMPER LOWER SKIRT	Broken	389.00 FL	*389.00 FL
21	1		*REAR BUMPER DIFFUSER	Cut	258.00 FL	*242.50 FL
22	1		*REAR END PANEL	Not Damaged	282.00 FL	*- FL
23	1		*REAR END PANEL TOP GARNISH	Dislodged	56.00 FL	*56.00 FL
24	1		*TAIL LAMP	Broken	836.00 FL	*298.60 FL
25	1		*TAIL LAMP INNER SPONGE	Not Damaged	60.00 FL	*- FL
26	1		*TAIL LAMP PANEL	Not Damaged	330.00 FL	*- FL
27	1		*TAIL LAMP LOWER BRACKET	Not Damaged	92.00 FL	*- FL
28	1		*REAR FENDER RH	Repair	794.00 FL	*- FL
29	1		*REAR FENDER INNER TRIM	Not Damaged	236.00 FL	*- FL
30	1		*REAR FENDER INNER COWLING	Torn	199.00 FL	*98.00 FL
31	1		*REAR EXHAUST SILENCER / PIPE	Bent	685.00 FL	*570.00 FL
32	1		*REAR EXHAUST MOUNTING	Not Damaged	106.00 FL	*- FL
33	1		*REAR EXHAUST PIPE GASKET	Necessary	67.00 FL	*67.00 FL
34	1		*REAR EXHAUST PIPE HEAT PLATE	Not Applicable	81.00 FL	*- FL
35	1		*EXHAUST CHROME PIPE	Serviceable	240.00 FS	*- FS
36	1		*BOOTLID NO PLATE WITH COVER	Serviceable	80.00 FS	*- FS
37	10		*BOOTLID REFLECTOR CLIPS	Not Damaged	50.00 FS	*- FS
38	10		*BOOTLID INNER TRIM CLIPS	Not Damaged	50.00 FS	*- FS
39	10		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
40	2		*REAR BUMPER REVERSE SENSORS	Dislodged	400.00 FS	*200.00 FS
41	5		*REAR BUMPER STAY	Not Damaged	290.00 FS	*- FS
42	10		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	10		*TAIL LAMP INNER SPONGE CLIPS	Not Applicable	50.00 FS	*- FS
44	10		*REAR FENDER INNER TRIM CLIPS	Necessary	50.00 FS	*30.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					11,046.00	4,880.57
- List Item Discount on L Items 10.00/10.00% (\$\$)					973.60	459.06
Total Parts (\$\$)					10,072.40	4,421.51

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R UPHOLSTERY.	New	100.00	0.00
2	R&R REVERSE SENSOR.	New	100.00	60.00
3	R&R EXHAUST PIPE.	New	150.00	50.00
4	PANEL BEATING.	New	1,500.00	800.00
5	RUST PROOFING.	New	150.00	60.00
6	SPRAY PAINTING.	New	1,500.00	800.00
7	CHECK WIRING.	New	150.00	50.00
Gross Labour Cost (S\$)			3,650.00	1,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >