

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

08 OCT 2019

E S T I M A T E

Estimate No. : b1 52987
Date Estimated : 07/10/2019
Prepared By : Joseph Yaguel

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Seth Tanuja Devi Mrs Surajanathan
11 Jalan Mata Ayer
#04-64 Euphony Gardens

Singapore 759154

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKJ549B	WBA1A120X0VV23840	21/12/2012	116iA/5	0

DESCRIPTIONVALUE

Replacing rear bumper panel and attachments, rework
bootlid

1700 / 2,125.00

Spray rear bumper and bootlid

1730 / 1,923.00

To remove and install boot compartment carpet and garnish
to facilitate repairs.

230 / 271.00

To check electrical wiring systems and lightings at the
rear section for proper function.

150 / 171.00

Sundries

? / 150.00

To supply rear emboss number plate.

54 / 83.00

Total Labour 1: **4,729.00**DESCRIPTIONQTYPRICVALUE

REAR BUMPER CARRIER ?

1

416.45

416.45

RR BUMPER CENTER GUIDE ?

1

55.75

55.75

RR BUMPER LH SIDE GUIDE ?

1

52.95

52.95

RR BUMPER RH SIDE GUIDE ?

1

52.95

52.95

DECORATIVE STRIP (LINE URBAN) *sea*

1

114.40

114.40

REAR BUMPER PRIMED (LINES) *de*

1

966.65

966.65

DECOUPLING RING PDC TORQUE CONVERTE *m*

4

5.05

20.20

Total Parts : **1,679.35**

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 52987
Date Estimated : 07/10/2019
Prepared By : Joseph Yaguel

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKJ549B	WBA1A120X0VV23840	21/12/2012	116ia/5	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / <u>3rd Party</u> / Uninsured losses / Direct Settlement	
Regn No. _____	Claim No. _____
Date & Time <u>04/11/19 @ 1030</u>	Excess S\$ _____
Surveyor's Name <u>PMR</u>	Sign _____
Surveyor's Tel <u>90010068</u>	Authorised Yes / No _____
Authorised Date _____	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____	
Surveyor's E-mail _____	
No. of Working Days Recommend <u>4-5 days</u>	



Labour 1	:	4,729.00
Parts	:	1,679.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	448.58
Grand Total	:	<u>6,856.93</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **