

2/20/2019

ASS. REC. BY:

REF:

CS/ICS19017740/ A9A3¹⁷²

Special Instructions:

Surveyor:

Adnan

ASSIGNMENT (Office)

From (Person):

Elizabeth Chew

of

ECICS

Date/Time:

8-10-19 4:01 p.m.

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFT 26A

Insured:

SJN 3634J

at Workshop in/s

SM Automotive

Tel:

67479241

of

1 Kaki Bukit Ave 6 Bldg C #01-43

Policy No:

Claim No:

DMP01900260H/02/CT

Sum Insured:

Excess:

Make of Veh:

D.O.A

6-10-2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time:

8-10-19 4:57 p.m.

Person Contacted:

Sukkyi

Vehicle IN/OUT

H.O.P. Employment:

Date/Time

Action/Instruction

(✓) Estimate

SFT 26A - CS ASM 190063061 Dec 13-2

RPA: 06/04/2019

SJN 3634J-X

09/10/19 @ 4:40pm Informed Elizabeth, we are pending for estimate from repairs
 LS \$9000, 6 days (Red \$18749.75, 68%)

Summer Lee (LKK Auto)

From: ECICS Claims <claims@ecics.com.sg>
Sent: Tuesday, 8 October, 2019 4:01 PM
To: Admin-D (LKKAuto); SUR; assignments
Cc: ECICS Claims
Subject: FW: SFT26A CLAIMING AGAINST SJN3634J DOA:06.10.19
Attachments: SFT26A.PDF; SJN3634J.PDF; SFT26A PRI.PDF

Dear LKK,

Please refer to the below email and conduct PRI.

We attached our insured and third party GIA reports for your attention.

Thank you.

Best regards

Elizabeth Chew

AVP | Claims



DID (65) 6303 0182

Tel (65) 6337 4779

Email elizabeth_chew@ecics.com.sg Web www.ecics.com.sg

Address 10 Eunos Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

From: sm automotive [mailto:sm_automotive@hotmail.com]
Sent: Tuesday, 8 October 2019 2:45 PM
To: ECICS Claims
Subject: Re: SFT26A CLAIMING AGAINST SJN3634J DOA:06.10.19

Without Prejudice

Hi Elizabeth

Please arrange for 4. LKK Auto Consultants

Regards,

Sukyi Chong

SM AUTOMOTIVE

1 Kaki Bukit Ave 6

Blk C #01-43

Singapore 417883

Tel: 6747 9241 Fax: 6741 7276

From: ECICS Claims <claims@ecics.com.sg>
Sent: Tuesday, October 8, 2019 2:37 PM
To: sm_automotive@hotmail.com <sm_automotive@hotmail.com>

Cc: ECICS Claims <claims@ecics.com.sg>

Subject: FW: SFT26A CLAIMING AGAINST SJN3634J DOA:06.10.19

WITHOUT PREJUDICE

Dear Sukyi,

We refer to your emails below.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client's workshop. We propose to use one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:

1. Ajax Inspection Services Pte Ltd
2. Appraisals Associates Pte Ltd
3. Infiniti Appraisal Services
4. LKK Auto Consultants

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Thank you.

Best regards

Elizabeth Chew

AVP | Claims



DID (65) 6303 0182

Tel (65) 6337 4779

Email elizabeth_chew@ecics.com.sg Web www.ecics.com.sg

Address 10 Eunus Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

From: sm automotive [mailto:sm_automotive@hotmail.com]

Sent: Tuesday, 8 October 2019 8:57 AM

To: ECICS Claims

Subject: Re: SFT26A CLAIMING AGAINST SJN3634J DOA:06.10.19

Without Prejudice - gentle reminder

Hi Motor Claim Dept

Please send us your surveyor list, thanks.

Regards,

Sukyi Chong

SM AUTOMOTIVE

1 Kaki Bukit Ave 6

Blk C #01-43

Singapore 417883
Tel: 6747 9241 Fax: 6741 7276

From: sm automotive
Sent: Monday, October 7, 2019 1:47 PM
To: claims@ecics.com.sg <claims@ecics.com.sg>
Subject: SFT26A CLAIMING AGAINST SJN3634J DOA:06.10.19

Without Prejudice

Hi Motor Claim Dept

Please send us your surveyor list,thanks.

Regards,

Sukyi Chong
SM AUTOMOTIVE

1 Kaki Bukit Ave 6
Blk C #01-43
Singapore 417883
Tel: 6747 9241 Fax: 6741 7276

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Wednesday, 9 October 2019 4:40 PM
To: do-not-reply@merimen.com
Cc: SUR
Subject: TP VEHICLE SFT 26A (DOA: 06/10/2019)

This mail is associated with :

***SFT26A**
[SJN3634J]

TP
ERIC ANG WEI MING
Oct 6 2019 3:00PM

Sm Automotive - Kaki Bukit

Dear Elizabeth,

Please be informed that we have inspected the vehicle SFT 26A on 08/10/2019.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)




This email has been checked for viruses by AVG antivirus software.
www.avg.com


FOR SALE BY OWNER

Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

 [Post an Ad](#)
 [Advertiser Login](#)
 [Ways of Selling](#)

New 5 Years Renewal Coe Honda Stream 1.8A


 2.88% P.A., \$0 Admin, \$0 Down, Monthly From \$688, 2 Years Warranty Engine StarAd



KA-HUP
VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND
HOTLINE: 6741 9997 [View our sites](#)

Browse by Category   Save Search  Print  Sort by Date Posted  20 results/page

▶ Search 730

 [Advanced Search](#)

Search View All

Make ▼ Model ▼ Price ▼ Depreciation ▼ **Rep Dots** ▼ End Cap ▼ Mileage ▼ Veh Type ▼ Status ▼

Search Selection	730	Any	Any	2011	Any	Any	Any	Available
------------------	-----	-----	-----	------	-----	-----	-----	-----------



<input type="checkbox"/>	BMW 7 Series 730Li Sunroof	\$56,288	\$16,110 /yr	28-Feb-2011	2,996 cc	114,000 km	Luxury	Available
--------------------------	----------------------------	----------	--------------	-------------	----------	------------	--------	-----------

Fully PMU, Maintained Unit With Near Perfect Interior, Single Owner And Accident Free. Trade Ins Are Welcomed And Flexible Loan Available With Offer Interest Rates Of 2.28%. Call Now To Check This Beautiful Unit Now.

 Printed: 05-OCT-2018 Page: 2011 BMW 730L, 2011 BMW 730L, BMW 730L, BMW 730L, BMW 730L, BMW 730L, BMW 730L, BMW 730L



BMW 7 Series 730Li Sunroof	\$62,800	\$16,320 /yr	03-May-2011	2,996 cc	94,800 km	Luxury	Available
--	----------	--------------	-------------	----------	-----------	--------	-----------

PHIL Unit! Management And Company Unit! Nothing Were Compromise Under The Watchful Eyes Of BMW Engineers. Luxurious And Rear Towhous Style Cabin With Additional Lecroom. Well Maintained By Owner. Extended Warranty Available. 100% Accident-Free! We Offer

Car Buyers Automotive Pte Ltd

 Project: 27-Sep-2019 Type: 2011 BMW 730L, 2011 BMW 750L, BMW 730L, BMW 730L, BMW 730L, BMW 730L, BMW 730L



BMW 7 Series 730Li Sunroof	\$64,500	\$15,030 /yr	26-Aug-2011	2,996 cc	103,000 km	Luxury	Available
--	----------	--------------	-------------	----------	------------	--------	-----------

Lowest Depreciation. 1 Owner. Excellent Condition!

Received: 23 April 2019; Accepted: 23 May 2019; Published: 25 May 2019



<input type="checkbox"/> BMW 7 Series 730Li Sunroof	\$68,500	\$15,600 /yr	11-Nov-2011	2,996 cc	119,899 km	Luxury	Available
---	----------	--------------	-------------	----------	------------	--------	-----------

Very Well Maintain By Owner, View To Appreciate, PML Unit, Sunroof, Accident Free, No Repair Needed, High Trade In And Loan Available. Hurry.

 [Printed: 04-Oct-2019](#) [Tags:](#) [2011 BMW 730L](#), [2011 BMW 730i](#), [BMW 730Li](#), [BMW 730i](#), [BMW 730L](#), [730i](#), [used BMW](#)

**GET YOUR
COE
RENEWAL
LOAN**

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



 BMW 7 Series 730Li Sunroof	\$69,800	\$15,730 /yr	15-Nov-2011	2,996 cc	125,556 km	Luxury	Available
--	----------	--------------	-------------	----------	------------	--------	-----------

Driven By A Retired Lawyer, This Bmw Is Extremely Well Maintained Due To His Strict Level Of Regular Servicing And During His Pastimes, He Practice Polishing On This Bmw Everyday To Keep Fit And Healthy. This Car Is On Fire Sales Because He Is Migrating To Canada Soo.

 Powered by BMW
 2011 BMW 730L, 2011 BMW 730i, BMW 730Li, BMW 730i, BMW 730L, 730i, Used BMW



	BMW 7 Series 730Li Sunroof	\$76,800	\$18,540 /yr	07-Dec-2011	2,996 cc	90,000 km	Luxury	Available
---	----------------------------	----------	--------------	-------------	----------	-----------	--------	-----------

Well Maintained, Excellent Condition, Accident Free, Bank And In House Loan Available, Trade In Are Welcome, Powerful Engine And Smooth Transmission. Buy With Confidence! Call Us Now To Make An Appointment To Viewing.

Car Search

Author: 05-06-2018 Page: 2011 BMW F30L; 2011 Serie F30S, BMW F30J, BMW F30H, BMW F30U, F30F, G400 BMW



<input type="checkbox"/>	BMW 7 Series 730Li Sunroof	\$72,888	\$16,690 /yr	09-Dec-2011	2,99% cc	88,000 km	Luxury	Available
--------------------------	----------------------------	----------	--------------	-------------	----------	-----------	--------	-----------

Good Condition. Well Maintained, New Interior Leather, More Than Enough Leg Room For Passengers. Consignment Unit, Trade-In Welcome. Loan And Insurance Available. Call Now For Viewing Appointment.

Prem Roy Motoring

 [https://doi.org/10.1016/j.sbspro.2015.06.001](#)

Compare (4) ©

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 540A

Vehicle Details

Vehicle No.: SFT26A
Vehicle to be Exported: No
Intended Deregistration Date: 07 Oct 2019
Vehicle Make: B.M.W.
Vehicle Model: 730LI AT ABS D/AB 2WD 4DR
NAV HID SR

Primary Colour: Blue
Manufacturing Year: 2011
Engine No.: 11497741N52B30AF
Chassis No.: WBAKB22020CN74932
Maximum Power Output: 190.0 kW (254 bhp)
Open Market Value: \$71,770.00
Original Registration Date: 29 Sep 2011
First Registration Date: 29 Sep 2011
Transfer Count: 4
Actual ARF Paid: \$71,770.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 28 Sep 2021
PARF Rebate Amount: \$39,473.00

Intended COE Rebate Details

COE Expiry Date: 28 Sep 2021
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$65,589.00
COE Rebate Amount: \$12,442.00
Total Rebate Amount: \$51,915.00

The information contained herein is correct as at 07 Oct 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/10/2019 16:55
Date Of Accident	06/10/2019 15:00
Exact Location Of Accident	BUANGKOK EAST DR SLIP RD SERANGOON RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFT26A
Insured/Policyholder	
Name Of Registered Owner	ERIC ANG WEI MING
NRIC No	S8227540A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97407787
Alternative Phone No	OFFICE-97407787

Vehicle Particulars

Manufacturer	BMW
Model	730
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA460570
Cover Note Number	

Driver

Name of Driver	ERIC ANG WEI MING
NRIC No	S8227540A
Date Of Birth	25/08/1982
Occupation	INDOOR
Date Of Driving Pass	12/03/2001
Driving Experience	18 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97407787
Fax Number	
Contact Number	OFFICE-97407787
Email Address	NOEMAIL

Address	12 UPPER SERANGOON CRESCENT #16-35
Postcode	534030
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : DENISE WONG GENDER: : FEMALE
Passenger 2	NAME: : ASHTON ANG GENDER: : MALE
Passenger 3	NAME: : ARIEL ANG GENDER: : FEMALE
Passenger 4	NAME: : ANGGI EKA SETIANI GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG THE SLIP ROAD BUANGKOK EAST TO SERANGOON ROAD. WHEN I STOP TO GIVE WAY TO ONCOMING TRAFFIC, WHEN SUDDENLY, ONE M/CAR (SJN3634J) CAME FROM MY REAR AND COLLIDED ONTO THE REAR PORTION OF MY VEHICLE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJN3634J
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B

Vehicle Category	PRIVATE CAR
Name of Driver	AARON SIN
NRIC/Passport Number	
Contact Number	85226622
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NIC/FIN No.:

SKETCH PLAN





DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


I WAS TRAVELLING ALONG THE SKIP ROAD BUNKER FAST TO SEAWARD ROAD WHEN I STOP TO GIVE WAY TO ONCOMING TRAFFIC, WHEN SUDDENLY ONE MOTOR 3JN 3634J CAME FROM MY RAMP AND COLLIDED ONTO THE REAR PORTION OF MY VEHICLE.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

LETTER OF UNDERTAKING

I/We, AKK WEI MIN, the owner of vehicle no. 8F1 26 H

My/Our Insurance is under M/s AXA Insurance Pte Ltd, I/we shall decide whether to claim under my/our Policy or against the Third Party and if the former shall submit such a claim to M/s AXA Insurance Pte Ltd with all relevant facts and documents within 14(fourteen) days of occurrence or discovery of damage.

My/Our Third Party claim is handle by my/our preferred workshop, SM AUTO

Signed and Acknowledge by:


Nric no. & signature of policyholder

Company stamp

07/10/2017
Date



redefining / insurance

AXA Insurance Pte Ltd
 1800 880 4888 (Within Singapore)
 (65) 6880 4889 (International)
 (65) 6880 4740
 customer.care@axa.com.sg
 www.axa.com.sg

Certificate of Insurance

account number
 11048

Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) Motor Vehicles (Third-Party Risks and Compensation) Rules, 1987 Road Transport Act, 1987 (Malaysia)
 Motor Vehicles (Third-Party Risks) Rules, 1985 (Malaysia)

Policy details

Policyholder name	ANG WEIMING	Certificate number	GA460570 / 1
Cover	Comprehensive	Chassis number	WBAKB22020CN74932
Plan name	Peace	Engine number	11497741N52B30AF
NCD applicable	50%		
Vehicle registration number	SFT26A		
Period of Insurance	from 12/04/2019 to 11/04/2020 (both dates inclusive)		
Finance loan company	Maybank Singapore Limited		

Persons or classes of persons entitled to drive*

- (a) The Policyholder
 (b) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

* Limitations rendered inoperative by Section 6 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS Windscreen Excess

Not Applicable

An Additional Excess is applicable as follows:

- \$5,500 for unlicensed Authorized Driver
- \$5,500 for declared Young and Inexperienced Driver
- \$5,500 for undeclared Young and Inexperienced Drivers. This additional excess is reduced to \$2,500 if you have chosen AXA Premium Workshops.

Additional clauses & endorsements to your policy

Nil

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA Insurance Pte Ltd

Authorised signature

Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act (Cap. 189). The Premium Warranty Clause requires the premium to be paid in full within a specific period (during which there would be no liability under the policy, renewal certificate, endorsements etc).

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

ERIC ANG WEIMING

08/10/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPE CICS:

Xiao Chen:

Accident date: 06/10/2019

Estimated repair cost for vehicle no: SFT26A BMW 740Li 3.0 A '11

chassis: WBAKB22020CN74932

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>dent</i>		\$1,939.40 ✓
2	2	Rear Boot Lid Hinge <i>new</i>	\$178.15	\$356.30 +
3	1	Rear Boot Lid Emblem Logo <i>2 pcs</i>		\$67.80 ✓
4	1	Rear Boot Lid 730Li Logo		\$61.05 ✓
5	1	Rear Boot Lid Number Plate Garnish <i>dent</i>		\$452.05 ✓
6	1	Rear Boot Lid Inner Lock <i>dent</i>		\$425.35 ✓
7	1	Rear Boot Lid Inner Rubber <i>new</i>		\$187.00 x
8	2	Rear Boot Lid Side Reflector <i>new</i>	\$426.15	\$852.30 +
9	2	Rear Tail Lamp <i>dent</i>	\$721.50	\$1,443.00 ✓
10	2	Rear Tail Lamp Lower Bracket <i>new</i>	\$50.20	\$100.40 +
11	4	Rear Tail Lamp Clip <i>new</i>	\$8.00	\$32.00 ✓
12	1	Rear Bumper <i>dent</i>		\$1,916.10 ✓
13	10	Rear Bumper Clip <i>new</i>	\$6.50	\$65.00 30
14	2	Rear Bumper Side Retainer <i>dent</i>	\$197.95	\$395.90 ✓
15	2	Rear Bumper Side Reflector <i>cracked</i>	\$45.35	\$90.70 ✓
16	1	Rear Bumper Top Bracket <i>dent</i>		\$285.35 ✓
17	1	Rear Bumper Reinforcement <i>dent</i>		\$781.30 ✓
18	4	Rear Bumper Reverse Sensor <i>2 pieces dent</i>	\$232.00	\$928.00 464
19	4	Rear Bumper Reverse Sensor Bracket Holder <i>2 pieces dent</i>	\$62.50	\$250.00 125
20	1	Rear Bumper Garnish Cover <i>dent</i>		\$219.00 ✓
21	1	Rear R/H Bumper Under Cover <i>dent</i>		\$283.10 ✓
22	2	Rear Fender Inner Trim Board <i>new</i>	\$436.80	\$873.60 +
23	16	Rear Fender Inner Trim Board Clip <i>new</i>	\$6.50	\$104.00 +
24	1	Rear End Panel <i>repair</i>		\$941.25 x
25	1	Rear End Panel Top Garnish <i>dent</i>		\$175.75 ✓
26	1	Rear Spare Tyre Panel Top Cover <i>new</i>		\$622.60 +
27	1	Rear Spare Tyre Panel Sealant <i>2 pieces</i>		\$450.00 +
28	2	Rear Exhaust	\$1,546.30	\$3,092.60 +

29	1	Rear Centre Exhaust	2		\$1,950.95 +
30	2	Rear Exhaust Chrome Pipe	1x	\$298.35	\$596.70 +
31	2	Rear Exhaust Mounting	2	\$62.85	\$125.70 +
32	1	Rear L/H Exhaust Aluminium Cover			\$125.00 +

9186.85

8727.50

Subtotal :- \$20,189.25

Labour charges

To remove & refit cushion \$280.00 80

To remove & refit reverse sensor \$100.00 80

To remove & refit rear & centre exhaust \$380.00 +

To reset computer \$450.00 150

To check wiring \$100.00 30

Towing fee \$100.00 +

Tuff kote \$150.00 50

Panel beating \$1,600.00 750

Spray painting \$1,600.00 900

To transfer bootlid fittings. 100
180

Subtotal :- \$4,760.00

Total :- \$24,949.25

27929.25

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No modification(s) is allowed
- Item(s) must be resurveyed and approval from Insurance Company

Adrian Lj Supplimentary: 384,
4/5 08/10/19. total 11252.25

to

06 hys

4/5 91k

91k

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

ERIC ANG WEIMING

08/10/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 06/10/2019

Supplementary repair cost for vehicle no: SFT26A BMW 740Li 3.0 A '11

CHASSIS: WBAKB22020CN74932

S/n	Qty	Items	U/price	Amount
1	2	Rear Bumper Side Bracket <i>He ne</i>	\$215.00	\$430.00 <i>X</i>
2	1	Rear Bumper Inner Cover <i>crack</i>		\$95.00 <i>✓</i>
3	1	Rear Bumper Reinforcement Outer Cover <i>crack</i>		\$84.00 <i>✓</i>
4	1	Rear Antenna <i>Damaged</i>		\$226.00 <i>✓</i>
5	1	Rear Absorber Pump <i>Not ne</i>		\$1,965.00 <i>X</i>

Total:- \$2,800.00

405

384-75

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS19017740/AQF3N2

Date: 02/12/2019

REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SFT26A	Insured Vehicle No :	SJN3634J
Date of Loss:	06/10/2019	Nature of Claim:	TP
		Claim No:	DMPC1900260H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFT26A	Engine No:	11497741N52B30AF
Make & Model:	BMW 730LI, 3.0 (A)	Chassis No:	WBAKB22020CN74932
Reg. Date:	29/09/2011 (Man. Year: 2011)	Odometer:	74061 km
Colour:	Blue		
Engine Capacity:	2996 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/50R18	Rear Tyre Size:	245/50R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	22,989.25	9,112.26	13,876.99	60.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,940.00	2,140.00	2,800.00	56.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	27,929.25	11,252.26	16,676.99	59.71
Approved Total (Overridden) (\$\$)		9,000.00		
Nett Amount (\$\$)	27,929.25	9,000.00	18,929.25	67.78

INSPECTION

Date of Assignment:	08/10/2019	
Date Inspected:	08/10/2019	Inspected At:
		Sm Automotive - Kaki Bukit (HQ)
		BLOCK C - 1, KAKI BUKIT AVE 6, #01-43
		Singapore 417883
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Dec 2019)
Parts:	143	BMW 730LI 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFT26A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Dented	1,939.40 F	*1,939.40 FL
2	2		*REAR BOOT LID HINGE	Not Necessary	356.30 F	*- FL
3	1		*REAR BOOT LID EMBLEM LOGO	Necessary	67.80 F	*67.80 FL
4	1		*REAR BOOT LID 730LI LOGO	Necessary	61.05 F	*61.05 FL
5	1		*REAR BOOT LID NUMBER PLATE GARNISH	Deformed	452.05 F	*452.05 FL
6	1		*REAR BOOT LID INNER LOCK	Damaged	425.35 F	*425.35 FL
7	1		*REAR BOOT LID INNER RUBBER	Not Necessary	187.00 F	*- FL
8	2		*REAR BOOT LID SIDE REFLECTOR	Not Necessary	852.30 F	*- FL
9	2		*REAR TAIL LAMP	Cracked	1,443.00 F	*1,443.00 FL
10	2		*REAR TAIL LAMP LOWER BRACKET	Not Necessary	100.40 F	*- FL
11	4		*REAR TAIL LAMP CLIP	Necessary	32.00 F	*32.00 FL
12	1		*REAR BUMPER	Deformed	1,916.10 F	*1,916.10 FL
13	10		*REAR BUMPER CLIP	Necessary	65.00 F	*30.00 FL
14	2		*REAR BUMPER SIDE RETAINER	Cracked	395.90 F	*395.90 FL
15	2		*REAR BUMPER SIDE REFLECTOR	Cracked	90.70 F	*90.70 FL
16	1		*REAR BUMPER TOP BRACKET	Cracked	285.35 F	*285.35 FL
			(2 Pcs)			
17	1		*REAR BUMPER REINFORCEMENT	Dented	781.30 F	*781.30 FL
18	1		*REAR BUMPER REVERSE SENSOR	Damaged (2 Pcs only)	928.00 F	*464.00 FL
			(4 Pcs)			
19	1		*REAR BUMPER REVERSE SENSOR BRACKET HOLDER	Necessary (2 Pcs only)	250.00 F	*125.00 FL
			(4 Pcs)			
20	1		*REAR BUMPER GARNISH COVER	Deformed	219.00 F	*219.00 FL
21	1		*REAR R/H BUMPER UNDER COVER	Torn	283.10 F	*283.10 FL
22	2		*REAR FENDER INNER TRIM BOARD	Not Necessary	873.60 F	*- FL
23	16		*REAR FENDER INNER TRIM BOARD CLIP	Not Necessary	104.00 F	*- FL
24	1		*REAR END PANEL	Repair	941.25 F	*- FL
25	1		*REAR END PANEL TOP GARNISH	Deformed	175.75 F	*175.75 FL
26	1		*REAR SPARE TYRE PANEL TOP COVER	Not Necessary	622.60 F	*- FL
27	1		*REAR SPARE TYRE PANEL SEALANT	Not Necessary	450.00 F	*- FL
28	2		*REAR EXHAUST	Not Necessary	3,092.60 F	*- FL
29	1		*REAR CENTRE EXHAUST	Not Necessary	1,950.95 F	*- FL
30	2		*REAR EXHAUST CHROME PIPE	Not Necessary	596.70 F	*- FL
31	2		*REAR EXHAUST MOUNTING	Not Necessary	125.70 F	*- FL
32	1		*REAR L/H EXHAUST ALUMINIUM COVER	Not Necessary	125.00 F	*- FL
33	2		*REAR BUMPER SIDE BRACKET	Not Necessary	430.00 F	*- FL
34	1		*REAR BUMPER INNER COVER	Cracked	95.00 F	*95.00 FL
35	1		*REAR BUMPER REINFORCEMENT OUTER COVER	Cracked	84.00 F	*84.00 FL
36	1		*REAR ANTENNA	Damaged	226.00 F	*226.00 FL
37	1		*REAR ABSORBER PUMP	Not Necessary	1,965.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$) 22,989.25 9,591.85

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 0.00/5.00% (S\$)					0.00	479.59
Total Parts (S\$)					22,989.25	9,112.26
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT CUSHION	New	280.00	80.00
2	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	80.00
3	TO REMOVE & REFIT REAR & CENTRE EXHAUST	New	380.00	0.00
4	TO RESET COMPUTER	New	450.00	150.00
5	TO CHECK WIRING	New	100.00	30.00
6	TOWING FEE	New	100.00	0.00
7	TUFF KOTE	New	150.00	50.00
8	PANEL BEATING	New	1,600.00	750.00
9	SPRAY PAINTING	New	1,600.00	900.00
10	TO TRANSFER BOOTLID FITTINGS	New	180.00	100.00
Gross Labour Cost (\$\$)			4,940.00	2,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >