

ASSIGNMENT

From: 8/10/19 Date:

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SML 7015U

at Workshop no: premium

of 55 ubi Road 1

Insured:

Policy No:

Claims No:

Sum Insured: 78A \$1,100/- Excess:

(Client's Record)

Make of Veh: 10am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 160k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 04 hrs days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SML 7015U Yr Regd: 2019 May

Type: ☒ M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A4 C.C. 1984

Colour: White A/C: Insured / Std / NI / NA

Sp Reading: 3496 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WA422F4SKA058156

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / ☒ STD A/Rim or

Tyre Size F: 205/60R16

R: 205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 08/10/19

Survey held at Premium

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

00 ALG

Sml 7015 U - X

RECEIVED 21 JAN 2020

09/10/19 @ 12:16 pm revised PA to ALG via memo

09/10/19 @ 13:09 pm mandate requested authorisation report to ALG via memo

11/10/19 @ 14:55 pm mandate approved by ALG

11/10/19 @ 15:15 pm informed CLA to Enver Enver Huzan via email

Date/Time, File Page No:

21/01/20

1) Typ 4

Date/Time, File Page No:

2)

☐ : Prel. Report

☒ : Final Report

Days Of Repair: 4

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp \$5

☐ : Interview \$5

☐ : Tech Insp \$5

☐ : Weekend \$5

Survey Fee:

Transportation:

3) Police

4) Other

5) Other

6) Other

7) Other

200

11

211

Report Format:

Estim Sum / H.R. \$ 4,861.20 RP

Adrian Confirmed P/P \$ 4,861.20 @ 4 days
With Boss. (\$ 14,545.80 Red - 75%)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 09 Oct 2019

Preliminary Advice

Vehicle No	: SML7015U	Accident Date	: 08/09/2019
Make	: AUDI A4	Policy No.	: 1900103049
Assignment Date	: 09/10/2019	Excess	: S\$0.00
Date of Inspection	: 08/10/2019	Est. Duration of Repair	: 4 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,407.00
Revised Amount	:S\$	4,962.00
Check Items (Estimated)	:S\$	965.00
Total	:S\$	5,927.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	160,000.00
COE / PARF Rebate	:S\$	75,662.00
Salvage Value	:S\$	
Margin for Repair	:S\$	84,338.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Re: OD Claim for SML 7015 U on 08/09/2019

Shirley Hiew (LKK Auto)

Fri 11/10/2019 3:15 PM

To: claims@premiumauto.com.sg <claims@premiumauto.com.sg>

Cc: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>

 1 attachments (427 KB)

ESTIMATE.pdf

Hi Ezuwan Huzaini,

As instructed by our client, please proceed to repair the insured vehicle **SML 7015U (Excess \$ 1,100/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte LtdPhone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>**Sent:** Friday, 11 October 2019 9:24 AM**To:** claims@premiumauto.com.sg <claims@premiumauto.com.sg>**Cc:** SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>**Subject:** Re: OD Claim for SML 7015 U on 08/09/2019

Ezuwan Huzaini,

Still pending approval from AIG.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte LtdPhone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

View Received Message

This mail is associated with :

***SML7015U (0888545481SG)**

OD

Sep 8 2019 11:15AM

[POON CHEW HAY]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 11/10/2019 14:55 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$5927.00) - SML7015U - Claim Handler: Gan, Hunchung

Approved:5927.00.

DOCUMENTS SUMMARY

There are no documents.

Nivitha (LKK Auto)

From: Claims <claims@premiumauto.com.sg>
Sent: Friday, 4 October 2019 8:42 AM
To: 'Admin-D (LKKAuto)'; 'Admin A'; 'SUR'
Cc: claims@premiumauto.com.sg
Subject: OD Claim for SML 7015 U on 08/09/2019
Attachments: SML 7015 U - 08092019.PDF

Dear All,

Kindly register OD claim for this vehicle. Attached is the GIA report for your reference.

We will forward you the estimate once it is available.

Please arrange survey on 8/10/2019, 10am. Vehicle is in our compound.

*Please take note that this vehicle change from 3rd Party claim to Own Damage claim due to liability not clear

Thank you.

Best Regards,
Ezuwan Huzaini
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Monday, 16 December 2019 4:22 pm
To: Boo seng yak
Cc: Adrian Ling (LKKAuto); SUR; Carrine Leong; Chang Chee Sing; jiajee.yap@premiumauto.com.sg
Subject: RE: FINAL REVISION - SML7015U - ODAIG - SURVEYED 8 OCT 19

Dear Mr. Boo,

Confirmed final fig \$4,861.20 @ 4 days of repairs before excess \$ 1,100/- & GST.

Kindly expedite the discharge voucher and tax invoice to us for close case.

"Best Wishes for Merry Christmas & Happy New Year 2020"

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Monday, 18 November 2019 9:00 am
To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; Chang Chee Sing <claims@premiumauto.com.sg>; jiajee.yap@premiumauto.com.sg
Subject: FINAL REVISION - SML7015U - ODAIG - SURVEYED 8 OCT 19

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$4861.20 @ 4 days

Your early closure is well appreciated.

Best regards - jb

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	789E
Vehicle Details	
Vehicle No.:	SML7015U
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Oct 2019
Vehicle Make:	AUDI
Vehicle Model:	A4 SEDAN 2.0 TFSI S TRONIC (NAV)
Primary Colour:	White
Manufacturing Year:	2019
Engine No.:	CVK079729
Chassis No.:	WAUZZZF49KA059196
Maximum Power Output:	140.0 kW (187 bhp)
Open Market Value:	\$33,718.00
Original Registration Date:	30 May 2019
First Registration Date:	30 May 2019
Transfer Count:	0
Actual ARF Paid:	\$39,206.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 May 2029
PARF Rebate Amount:	\$29,404.00
Intended COE Rebate Details	
COE Expiry Date:	29 May 2029
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$52,410.00
COE Rebate Amount:	\$46,258.00
Total Rebate Amount:	\$75,662.00

The information contained herein is correct as at 09 Oct 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/09/2019 10:47
Date Of Accident	08/09/2019 11:15
Exact Location Of Accident	355 TANGLIN ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SML7015U
Insured/Policyholder	
Name Of Registered Owner	POON CHEW HAY
NRIC No	S0371789E
Email Address	APOONCH@GMAIL.COM
Mobile Phone No	(LOCAL) +65-81319031
Alternative Phone No	OFFICE-81319031

Vehicle Particulars

Manufacturer	AUDI
Model	A4 SEDAN 2.0 TFSI 8W
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1900103049
Cover Note Number	

Driver

Name of Driver	POON CHEW HAY
NRIC No	S0371789E
Date Of Birth	11/04/1948
Occupation	INDOOR
Date Of Driving Pass	22/04/1971
Driving Experience	48 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81319031
Fax Number	
Contact Number	OFFICE-81319031
Email Address	APOONCH@GMAIL.COM

Address	21 JERVOIS CLOSE #07-03
Postcode	249114
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO MOTORCYCLIST
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : KUAH GEOK AI GENDER: : FEMALE
Passenger 2	NAME: : PHOEBE WANG GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON SEP 8/2019 @ ABOUT 11.15 AM, I SIGNAL LEFT INDICATOR WHEN ABOUT TO TURN INTO GRACE ASSEMBLY CHURCH, TANGLIN ROAD(NEXT TO ESSO STN). A MOTORCYCLE RIDER, MT. MUHAMMAD SIDDIQ BIN ABDUL RAHIM VEHICLE FBG 3790 Y, COMING FROM ESSO STN DIRECTION, RAMMED MY LEFT SIDE AUDI VEHICLE SML 7015 U, MUD GUARD AREA. HIS INSURER IS NTUC INCOME. HE FELL BUT NOT HURT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBG3790Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	
Contact Number	

- Address
- Postcode
- Insurance Company Name
- Nature Of Damage
- No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On Sep 8/2019 @ about 11:15 am, I signal left indicator when about to turn into Grace Assembly church, Tonglin Road (next to Erso Stn), a motorcycle rider Mr. Muhammad Siddiq Bin Abdul Rahim vehicle FBG 3790Y coming from Erso Stn direction rammed my left side Audi vehicle SML 7015U, causing bad dent on my left front wheel mud guard area. His Insurer is NTUC Income. He fell but not hurt.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/IN No.:



See Also: Motor Insurance Act



Name of Policyholder : POON CHEW HAY @ANTHONY POON
Period of Insurance : 30 May 2019 To 29 May 2021
Engine No. : CVK079729
Chassis No. : WAUZZZF49KA059196

Vehicle No. : SML7015U
Policy No. : 1900103049
Endorsement No. : 000000000288903
Issued Date : 04 Jul 2019

Make/Model	: AUDI A4 Sedan 2.0 TFSI S tronic				
Engine Capacity/Tonnage	: 1,984.00 CC	Sum Insured	: Market Value	First Year of Registration	: 2019
Driver Restriction	: NA	Off Peak Car	: No	Insuring with COE/PAF	: Yes

You have to pay an additional sum of \$3,000 as "Young and/or inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1967 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings

POON CHEW HAY @ANTHONY POON - \$2100 (Own Damage)

For other Approved Reporting Centres/AIG Authorised Repairs, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

(We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 108), Part IV of the Road Transport Act 1967 (Malaysia), Road Transport (Amendment) Act 2010 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).)

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 11658

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1100/2019/NS
Date	:	11-Sep-19

Vehicle NOT IN workshop. Kindly arrange for survey.

NTUC Income Insurance Co. Claims Department

73 Bras Basah Road

#05-01 NTUC Trade Union House

Singapore 189556

ALG.

Attn: Motor Claims Dept

Tel: Fax 6338 1504

Owner's Name	:	Mr Poon Chew Hay
Address	:	21 Jervois Close #07-03 Singapore 249114
Telephone	:	(HP) +65 81319031
Type of Claim	:	Own Damage Claim
Policy No.	:	1900103049
Vehicle No	:	SML 7015 U
Model Code	:	Audi A4 Sedan 2.0 TFSI 8W
Model / Year	:	May-19
Engine No	:	CVK 079729
Chassis No	:	WAUZZZF49KA059196
Mileage	:	
Date In	:	
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	8-Sep-19
Place of Accident	:	355 Tanglin Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SML 7015 U

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlight, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	✓
2	To dismantle lhs front door panel trim. To remove and renew lhs wing mirror assy.	\$ 300.00	✓
3	To dismantle front bumper, lhs front fender and lhs headlight. To renew lhs front fender and lhs headlight. Re-organise crash management components. Reinstall all parts removed. ✓ x ✓	\$ 2,450.00	1000.
4	To respray front bumper, bonnet, lhs front fender and lhs wing mirror cover. ✓	\$ 3,500.00	SSOK2 = 1100 Mirror = 150 1250
5	To renew lhs front rim and carry out wheel alignment. To inspect lhs front wheel suspension for further damages.	S/N \$ 280.00	✓
6	To carry out diagnostic checks.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 7,202.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SML 7015 U

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER GUIDE SECTION - LH <i>new</i>	\$ 33.00	X
2	FRONT FENDER - LH <i>Dented</i>	\$ 700.00	✓ 559.60
3	FRONT FENDER ATTACHMENT PARTS <i>Not new</i>	\$ 183.00	? X
4	FRONT FENDER CLOSING ELEMENT - LH <i>Not new</i>	\$ 45.00	? X
5	FRONT FENDER BRACKET - LH <i>Not</i>	\$ 32.00	✓ 25.20
6	FRONT FENDER DEFORMATION ELEMENT BRACKET - LH <i>Not new</i>	\$ 45.00	Not ? X
7	FRONT FENDER BRACKET <i>Not</i>	\$ 31.00	✓ 24.16
8	FRONT FENDER BRACE - LH <i>Not new</i>	\$ 107.00	? X
9	WHEEL HOUSING LINER - LH <i>Defamed.</i>	\$ 223.00	? ✓ 178.40
10	WHEEL HOUSING LINER ATTACHMENT PARTS - FRONT / REAR <i>Not new</i>	\$ 211.00	? X
11	WHEEL SPOILER - LH <i>new</i>	\$ 66.00	+
12	WHEEL SPOILER END PLATE - LH <i>new</i>	\$ 32.00	+
13	STONE CHIP GUARD - LH <i>new</i>	\$ 46.00	✓ 36.64
14	FENDER LEDGE COVER - LH INNER <i>Not new</i>	\$ 28.00	? X
15	FENDER LEDGE COVER - LH OUTER <i>Not new</i>	\$ 21.00	? X
16	LED HEADLIGHT - LH <i>Not new</i>	\$ 7,087.00	X
17	FRONT ALUMINIUM RIM - LH <i>cut</i>	\$ 651.00	✓ 520.80
18	ALUMINIUM RIM RUBBER VALVE <i>Not new</i>	4 \$ 13.00	? X
19	EXTERIOR MIRROR MOUNTING - LH <i>Not new</i>	\$ 999.00	X
20	MIRROR CAP - LH <i>Not</i>	\$ 220.00	X
21	MIRROR GLASS - LH <i>Not new</i>	\$ 1,132.00	X
22	SUNDRIES <i>Not</i>	\$ 300.00	? ✓ 14.40
TOTAL SPARE PARTS		:	\$ 12,205.00
TOTAL LABOUR CHARGES		:	\$ 7,202.00
GRAND TOTAL		:	\$ 19,407.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Ling
Surveyed Date : 08/10/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not authorised, 04 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorised by Repairer

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 11658

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1100/2019/NS
Date	:	11-Sep-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG ASIA PACIFIC INS. PTE. LTD

Hi Adrian

4 days - ok - Jb 18 Nov 19

Owner's Name	:	Mr Poon Chew Hay
Address	:	21 Jervois Close #07-03 Singapore 249114
Telephone	:	(HP) +65 81319031
Type of Claim	:	Own Damage Claim
Policy No.	:	1900103049
Vehicle No	:	SML 7015 U
Model Code	:	Audi A4 Sedan 2.0 TFSI 8W
Model / Year	:	May-19
Engine No	:	CVK 079729
Chassis No	:	WAUZZZF49KA059196
Mileage	:	
Date In	:	
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	8-Sep-19
Place of Accident	:	355 Tanglin Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SML 7015 U

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlight, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N	\$ 480.00	\$ 480.00
2	To dismantle lhs front door panel trim. To remove and renew lhs wing mirror assy.		\$ 300.00	\$ 300.00
3	To dismantle front bumper, lhs front fender and lhs headlight. To renew lhs front fender and lhs headlight. Reorganise crash management components. Reinstall all parts removed.		\$ 2,450.00	\$ 1,000.00
4	To respray front bumper, bonnet, lhs front fender and lhs wing mirror cover.		\$ 3,500.00	\$ 1,250.00
5	To renew lhs front rim and carry out wheel alignment. To inspect lhs front wheel suspension for further damages.	S/N	\$ 280.00	\$ 280.00
6	To carry out diagnostic checks.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 7,202.00</u>	<u>\$ 3,502.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SML 7015 U

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER GUIDE SECTION - LH	\$ 33.00	
2	FRONT FENDER - LH	\$ 700.00	\$ 559.60
3	FRONT FENDER ATTACHMENT PARTS	\$ 183.00	
4	FRONT FENDER CLOSING ELEMENT - LH	\$ 45.00	
5	FRONT FENDER BRACKET - LH	\$ 32.00	\$ 25.20
6	FRONT FENDER DEFORMATION ELEMENT BRACKET - LH	\$ 45.00	
7	FRONT FENDER BRACKET	\$ 31.00	\$ 24.16
8	FRONT FENDER BRACE - LH	\$ 107.00	
9	WHEEL HOUSING LINER - LH	\$ 223.00	\$ 178.40
10	WHEEL HOUSING LINER ATTACHMENT PARTS - FRONT / REAR	\$ 211.00	
11	WHEEL SPOILER - LH	\$ 66.00	
12	WHEEL SPOILER END PLATE - LH	\$ 32.00	
13	STONE CHIP GUARD - LH	\$ 46.00	\$ 36.64
14	FENDER LEDGE COVER - LH INNER	\$ 28.00	
15	FENDER LEDGE COVER - LH OUTER	\$ 21.00	
16	LED HEADLIGHT - LH	\$ 7,087.00	
17	FRONT ALUMINIUM RIM - LH	\$ 651.00	\$ 520.80
18	ALUMINIUM RIM RUBBER VALVE	4 \$ 13.00	
19	EXTERIOR MIRROR MOUNTING - LH	\$ 999.00	
20	MIRROR CAP - LH	\$ 220.00	
21	MIRROR GLASS - LH	\$ 1,132.00	
22	SUNDRIES	\$ 300.00	\$ 14.40
TOTAL SPARE PARTS		: \$ 12,205.00	\$ 1,359.20
TOTAL LABOUR CHARGES		: \$ 7,202.00	\$ 3,502.00
GRAND TOTAL		: \$ 19,407.00	\$ 4,861.20

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SML 7015 U

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1100/2019/NH

20TH JAN 2020

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SML 7015 U, Audi A4 SEDAN 2.0 TFSI.

With reference to the above-mentioned vehicle, no. **SML 7015 U**, claimant, **Mr. Poon Chew Hay**, please find the related document per attached.

1. A copy of the Original invoice no. 85014756 – S\$ 4,024.48.
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – SML 7015 U

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 1183

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6366 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6366 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 15:11

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014756	Account: A0006 (T 0)
	Date : 17/01/2020	AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
	Order : SML7015U	
	Term : 30	

Regn No: SML7015U (V 42048)	Regn Date: 30/05/2019	Mileage: 3621	WIP No.: 11658
Model: A4 SEDAN 2.0 TFSI SW2ADG	Chassis: WAUZZZF49KA059196	Engine: CVK 079729	Dept: U
You have been assisted by :- UB-Tony Foong (33)			

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-1100.00	1.00	-1,100.00
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	480.00	1.00	480.00
S	BODYWORK	M: TO DISMANTLE LHS FRONT DOOR PANEL TRIM. TO REMOVE AND RENEW LHS WING MIRROR ASSY	300.00	1.00	300.00
S	BODYWORK	M: TO DISMANTLE FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. TO RENEW LHS FRONT FENDER AND LHS HEADLIGHT. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	1000.00	1.00	1,000.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND LHS WING MIRROR COVER	1250.00	1.00	1,250.00
S	BODYWORK	M: TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT. TO INSPECT LHS FRONT WHEEL SUSPENSION FOR FURTHER DAMAGES	280.00	1.00	280.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A8W0821105A	FENDER (LAST)	Less 020%	1.00	699.50
X	A8W0821467	BRACKET (SHARE)	Less 020%	1.00	31.50
X	AN 0161857	POP-RIVET	Less 020%	6.00	3.00
X	A8W0821433B	BRACKET (LAST)	Less 020%	1.00	30.20
X	A8W0821171A	WHEEL HOUS (SHARE) AP	Less 020%	1.00	223.00
X	A8W0853823B 989	STONEGUARD (LAST)	Less 020%	1.00	45.80
X	A8W0601025EF	007482/ (V) (GER) WHEEL	Less 020%	1.00	651.00

Parts 1,359.20
Labour 0.00
Sublet 3,502.00
Menus 0.00
Lubricant 0.00

Sub-Total 3,761.20

7% GST 263.28

Grand Total 4,024.48



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SML7015U

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1100/2019/EH
18 October 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A4 SEDAN 2.0 TFSI
Vehicle Chassis No. : WAUZZZF49KA059196
Vehicle Regn No. : SML 7015 U
Vehicle Mileage : 3632 KM
Vehicle Owner : Mr. Poon Chew Hay
Certificate No : 1900103049
Own Damage Excess : \$ 1,177.00 (Inclusive GST)
Accident Date : 8 September 2019
Place : 355 Tanglin Road
Repair Cost : \$ 4024.48
WIP No. : 11658
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time : 6 pm
Date : 18/10/2019

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Sep 2019		09 Oct 2019 10:07 Edit Adj Rpt	S\$4,861.20 Edit Estimates	S\$4,861.20 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	POON CHEW HAY, ID: S0371789E, Tel: +6581319031, Email: APOONCH@GMAIL.COM		
Vehicle Reg. No.:	SML7015U	Date of Loss:	08/09/2019 11:00 - :59 [3 Months and 9 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 0888545481SG	Policy/Cover Note No.:	1900103049 (Comprehensive)
		Excess:	S\$1,100.00
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Gan, Hunchung] Hunchung.Gan@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 18/10/2019]		
Driver/Custodian:	POON CHEW HAY (71 / Male) , NRIC: S0371789E, Tel: +6581319031 Email: APOONCH@GMAIL.COM		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (11/10/2019): Alert - Adj Mandate Approved (S\$5927.00) - SML7015U - Claim Handler: Gan, Hunchu...
- AIG_SG (09/10/2019): SML7015U / OD / 08/09/2019 / Coverage & Excess update

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SML7015U (0888545481SG)

OD

Sep 8 2019 11:15AM

[POON CHEW HAY]

Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Video															1 per page					
No	Finalized On	Premium Automobiles Pte Ltd (UBI)												Thumbnail			Print			
1	09/09/19 11:06	Video - Accident [Linked Accident Report Documents]															Load MP4			
2	09/09/19 11:07	Video - Accident [Linked Accident Report Documents]															Load MP4			
Assessment Reports															1 per page					
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print			
1	09/10/19 12:16	Adjuster Immediate Advice															Load HTM			
Photos/Images															3 per page					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print			
1	09/10/19 13:08	General View															Load JPG			
2	09/10/19 13:08	General View															Load JPG			
3	09/10/19 13:08	General View															Load JPG			
4	09/10/19 13:08	General View															Load JPG			
5	09/10/19 13:08	General View															Load JPG			
6	09/10/19 13:08	General View															Load JPG			
7	09/10/19 13:08	General View															Load JPG			
8	09/10/19 13:08	General View															Load JPG			
9	09/10/19 13:08	General View															Load JPG			
10	09/10/19 13:08	General View															Load JPG			
11	09/10/19 13:08	General View															Load JPG			
12	09/10/19 13:08	General View															Load JPG			
13	09/10/19 13:08	General View															Load JPG			
14	09/10/19 13:08	General View															Load JPG			
Documentation															1 per page					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print			
1	09/10/19 13:07	SML 7015U GIA.pdf															Load PDF			
2	09/10/19 13:07	ESTIMATE.pdf															Load PDF			
3	09/10/19 13:58	DRIVING & CI.pdf															Load PDF			
4	16/12/19 16:19	ESTIMATE MARKED.pdf															Load PDF			
5	22/01/20 10:29	WORKSHOP INVOICE															Load PDF			
6	22/01/20 10:29	DISCHARGE VOUCHER															Load PDF			

Linked Accident Report Documents

										View		View in Browser	
Video										1 per page			
No	Finalized On	Premium Automobiles Pte Ltd (UBI)							Thumbnail	Print			
1	09/09/19 11:06	Video - Accident							Load MP4				
2	09/09/19 11:07	Video - Accident							Load MP4				
Assessment Reports										1 per page			
No	Finalized On	Premium Automobiles Pte Ltd (UBI)							Thumbnail	Print			
1	04/10/19 08:27	Addendum Sheet							Load JPG				
2	06/12/19 18:25	Accident Statement							Load HTM				

Video			1 per page ▾	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
3	06/12/19 18:26	Accident Statement	Load HTM	
4	06/12/19 18:27	Accident Statement	Load HTM	
5	06/12/19 18:29	Accident Statement	Load HTM	
6	06/12/19 18:50	Accident Statement	Load HTM	
7	06/12/19 18:50	Accident Statement	Load HTM	
8	06/12/19 18:51	Accident Statement	Load HTM	
9	06/12/19 18:51	Accident Statement	Load HTM	
Photos/Images			3 per page ▾	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	09/09/19 11:03	Accident Photo	Load JPG	
2	09/09/19 11:03	Accident Photo	Load JPG	
3	09/09/19 11:03	Accident Photo	Load JPG	
4	09/09/19 11:03	Accident Photo	Load JPG	
5	09/09/19 11:03	Accident Photo	Load JPG	
6	09/09/19 11:03	Accident Photo	Load JPG	
7	09/09/19 11:03	Accident Photo	Load JPG	
8	09/09/19 11:03	Accident Photo	Load JPG	
9	09/09/19 11:03	Accident Photo	Load JPG	
10	09/09/19 11:03	Accident Photo	Load JPG	
11	09/09/19 11:03	Accident Photo	Load JPG	
12	09/09/19 11:03	Accident Photo	Load JPG	
13	09/09/19 11:03	Accident Photo	Load JPG	
14	09/09/19 11:03	Accident Photo	Load JPG	
15	09/09/19 11:03	Accident Photo	Load JPG	
16	09/09/19 11:03	Accident Photo	Load JPG	
Documentation			1 per page ▾	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	09/09/19 11:07	Sketch Plan	Load JPG	
2	09/09/19 11:07	Sketch Plan #2	Load JPG	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19017782/ASF3N2

Date: 22/01/2020

REFERENCE

Insured/Claimant:	POON CHEW HAY	Policy No:	1900103049	
Date of Loss:	08/09/2019	Nature of Claim:	OD	Claim No: 0888545481SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML7015U	Engine No:	CVK079729
Make & Model:	AUDI A4, 2.0 TFSI QU S-TRONIC (A)	Chassis No:	WAUZZZF49KA059196
Reg. Date:	30/05/2019 (Man. Year: 2019)	Odometer:	3496 km
Colour:	White		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$160,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,205.00	1,359.20	10,845.80	88.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,202.00	3,502.00	3,700.00	51.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,407.00	4,861.20	14,545.80	74.95
- Excess (S\$)	1,100.00	1,100.00	0.00	0.00
(S\$)	18,307.00	3,761.20	14,545.80	79.45
+ GST 7.00/7.00% (S\$)	1,281.49	263.28	1,018.21	79.46
Nett Amount (S\$)	19,588.49	4,024.48	15,564.01	79.45

INSPECTION

Date of Assignment:	09/10/2019		
Date Inspected:	08/10/2019	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER GUIDE SECTION-LH	Not Necessary	33.00 FS	*- FS
2	1		*FRONT FENDER-LH	Dented	700.00 FS	*559.60 FS
3	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	183.00 FS	*- FS
4	1		*FRONT FENDER CLOSING ELEMENT-LH	Not Necessary	45.00 FS	*- FS
5	1		*FRONT FENDER BRACKET-LH	Bent	32.00 FS	*25.20 FS
6	1		*FRONT FENDER DEFORMATION ELEMENT BRACKET-LH	Not Necessary	45.00 FS	*- FS
7	1		*FRONT FENDER BRACKET	Bent	31.00 FS	*24.16 FS
8	1		*FRONT FENDER BRACE-LH	Not Necessary	107.00 FS	*- FS
9	1		*WHEEL HOUSING LINER-LH	Deformed	223.00 FS	*178.40 FS
10	1		*WHEEL HOUSING LINER ATTACHMENT PARTS-FRONT/REAR	Not Necessary	211.00 FS	*- FS
11	1		*WHEEL SPOILER-LH	Not Necessary	66.00 FS	*- FS
12	1		*WHEEL SPOILER END PLATE-LH	Not Necessary	32.00 FS	*- FS
13	1		*STONE CHIP GUARD-LH	Necessary	46.00 FS	*36.64 FS
14	1		*FENDER LEDGE COVER-LH INNER	Not Necessary	28.00 FS	*- FS
15	1		*FENDER LEDGE COVER-LH OUTER	Not Necessary	21.00 FS	*- FS
16	1		*LED HEADLIGHT-LH	Not Necessary	7,087.00 FS	*- FS
17	1		*FRONT ALUMINIUM RIM-LH	Cut	651.00 FS	*520.80 FS
18	4		*ALUMINIUM RIM RUBBER VALVE	Not Necessary	13.00 FS	*- FS
19	1		*EXTERIOR MIRROR MOUNTING-LH	Not Necessary	999.00 FS	*- FS
20	1		*MIRROR CAP-LH	Repair	220.00 FS	*- FS
21	1		*MIRROR GLASS-LH	Not Necessary	1,132.00 FS	*- FS
22	1		*SUNDRIES	Necessary	300.00 FS	*14.40 FS

F=Franchise part. S=SpcNetl.

Total Parts (\$\$)	12,205.00	1,359.20
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE LHS FRONT DOOR PANEL TRIM,TO REMOVE AND RENEW LHS WING MIRROR ASSY	New	300.00	300.00
3	TO DISMANTLE FRONT BUMPER,LHS FRONT FENDER AND LHS HEADLIGHT.TO RENEW LHS FRONT FENDER AND LHS HEADLIGHT.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,450.00	1,000.00
4	TO RESPRAY FRONT BUMPER,BONNET,LHS FRONT FENDER AND LHS WING MIRROR COVER	New	3,500.00	1,250.00
5	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.TO INSPECT LHS FRONT WHEEL SUSPENSION FOR FURTHER DAMAGES	New	280.00	280.00
6	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (S\$)			7,202.00	3,502.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >