

Vin's

AUTOMOTIVE GROUP

Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722

6453 2121 (4 lines) / 6458 1111 (24 hrs)

6459 9795 / 6459 0433

admin@vinsautogroup.com.sg

www.vinsautogroup.com.sg

Our Ref : TP/102019/4087

Accident date : 5/10/2019

Your Ref : SLZ6686C

Invoice No.:

MOTOR CLAIM DEPARTMENT
AIG ASIA PACIFIC INSURANCE PTE LTD
AIG Building
78 Shenton Way #07-16
Singapore 079120

ESTIMATE COST OF REPAIRS TO

Vehicle No. : SGJ3139D

Model : TOYOTA ESTIMA-2.4 (A)

LKK Auto Consultants hereby certify
the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1 pc	Front bumper <i>monty chrome</i>	\$ 756.10	✓
1 pc	Front bumper RH day light <i>new</i>	\$ 829.10	X
1 pc	Front bumper RH retainer <i>src</i>	\$ 82.81	X
1 pc	Front RH headlamp <i>new</i>	\$ 2,900.00	X
1 pc	Front RH fender <i>new</i>	\$ 645.80	X
1 pc	Front RH fender inner sheild <i>src</i>	\$ 177.10	X
1 pc	Front RH fender lower protector <i>cut</i>	\$ 232.10	✓
1 pc	Front RH door <i>new</i>	\$ 1,286.70	X
1 pc	Front RH sport rim <i>cut</i>	\$ 1,835.00	✓
1 pc	Front RH shock absorber <i>2 disassembled</i>	\$ 380.90	✓
1 pc	Front RH knuckle arm <i>2 disassembled</i>	\$ 474.56	✓
1 pc	Front RH knuckle arm bearing <i>2 new</i>	\$ 467.00	✓
1 pc	Front RH lower arm <i>2 disassembled</i>	\$ 475.74	✓
		\$ 10,542.91	
Less 25%		\$ (2,635.73)	
		\$ 7,907.18	

1 pc	Front RH tyre <i>src</i>	\$ 480.00	X
To check wheel alignment		\$ 150.00	60/-
To transfer front RH door mechanism		\$ 180.00	new
To remove and refix front undercarriage		\$ 280.00	180/-
To repair front RH damages		\$ 780.00	700/-
To spray painting		\$ 880.00	800/-
		\$ 10,657.18	

VIN'S MOTOR PTE LTD

[Signature]

[Signature]

[Signature]

09/10/2019 @ 1700hrs

Nat Antuan

P/Pot 2/sum

Photo 1/4 spray with after spray.
damage parts.