

ALG-LKK - 14/10/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SME 5401 M

Not Authorized
Return By paint

Parts	(a) Cost / List Price Items	\$	5,985.81
	Plus/Less 25%	\$	1,496.45
	Total of Cost / List	\$	4,489.36
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	350.00
Total Parts Cost		\$	4,839.36
Labour		\$	3,420.00
Total		\$	8,259.36

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
Company : CIC
Survey conducted on : 14/10/19 at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ _____

(e) Signature of surveyor : Le Date: 14/10/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SME 5401 M**
Make & Model : **TOYOTA PRIUS ALPHA**
Chassis No : **ZVW400030005**

Submit By : **JENNY**
Year Manufacture : **2018**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front bumper	1	\$496.50		✓
2	Front bumper clip	10	\$38.90		✓
3	Front bumper side retainer LH	1	\$78.60		X
4	Front bumper side retainer RH	1	\$78.60		?
5	Front bumper bracket LH	1	\$208.71		X
6	Front bumper bracket RH	1	\$208.71		X
7	LH front fender	1	\$767.90		X
8	LH front fender undershield	1	\$165.90		X
9	LH front fender undershield clip	10	\$21.10		X
10	LHF fender wording "HYBRID"	1	\$44.17		✓
11	LH front rim	1	\$1,451.50		?
12	LH front tyre	1	\$350.00	S.N	X
13	LHF hup cap	1	\$185.62		✓
14	LH front door	1	\$1,126.90		X
15	Lh rear door	1	\$1,112.70		X
16					
17					
18					
19					
20					
21					
22					
23					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Labour