

(INSUR)

INS. CASE OWNER:

CC 6/III1901 7879, A3

LKK:

IDAC:

Surveyor:

Adrian

DOI:

ASSIGNMENT

8/10/19

Date / Time:

8/10/19

Registered in Merimen:

8/10/19

Pre-assign / CCU / FTE

PA 3676K



Insured Vehicle No.:

Claim No.:

Name of Insured:

YANG YAN XIN BUS SERVICE

Policy No.:

09AMKL001332

Insured Tel No.:

HP:

Make / Model:

ISHAN

Excess Sec II :\$

D.O.A.:

4/10/19

Place of Accident:

SENG PUN RD

Is driver the owner? (YES / NO)

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

ZHANG BOHANG

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

SKB 6637H



INSRS:

WSP:

Tel:

Liability:

RMKS:

WHT



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

8/10/19

8/10/19

9/10/19 - File -> typermacale

2/1/2020 - File -> suci to and DV

3/1/2020 - File pass to me to close.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Machine/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No. : 22

If NO or B 28, Ass. Lia:

Repair Cost:

\$

8025.00

Loss of Rental (LOR):

\$

-

(days)

Loss of Use (LOU):

\$

420.00

(5

x 7

days)

Loss of Income (LOI):

\$

-

(5

x 7

days)

LOR only

LOU only

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

GIA/LTA Search

\$

2.45

Medical:

\$

-

Disbursement:

\$

-

(e.g. Tow/ Independent)

Legal Cost

\$

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$ 600.00

Total:

\$

8452.45

Global Sum \$:

8400.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$

8400.00

Name 1:

New Hock Teck Motor Pte Ltd

Payee 2: (Strike if N.A.)

\$

-

Name 2:

-

Payee 3: (Strike if N.A.)

\$

-

Name 3:

-

ASSIGNMENT

From _____ Date: _____
 Estimated Cost: _____
QD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop no: _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 06 days Res.: Yes or No
 Lum Sum: 2v. % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKB6637H / Regn: 2018 / March
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Mercedes Benz GLA180c 1595
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 20352 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WDC1569422J44870
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size F: 235/50R18
 R: 235/50R18
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Continental
 Front Rear
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 08/10/13
 Survey held at MTA NHT.
 Des. of Damages: Frt / Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	TP III
	US \$ 75W (Rec'd) 19832 / 73%
	MV:
	PV:
	Nett:
	4910

Date/Time, File Path to?

☐ : Prell. Report
☐ : Final Report

1)

Date/Time, File Return to?

3)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp \$
☐ : Interview \$
☐ : Tech. Insp \$
☐ : Other \$

Survey Fee: _____

Transportation

F + P.S. \$

Photos

Other

TOTAL

Report Format: _____

Lump Sum / R.P. \$: _____



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

08/10/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP111

Xiao Tony

Accident date: 08/10/2019

Estimated repair cost for vehicle no: SKB6637H MERCEDES GLA180 1.6 A '18

CHASSIS: WDC1569422J444870

S/n	Qty	Items	U/price	Amount
1	1	Front Bumper <i>Torn</i>		\$1,610.00 ✓
2	10	Front Bumper Clip <i>new</i>	\$8.00	\$80.00 <i>20</i>
3	1	Front R/H Bumper Side Retainer <i>new</i>		\$38.00 ✓
4	1	Front R/H Bumper Sensor <i>new</i>		\$236.00 ✗
5	1	Front R/H Headlamp <i>lit</i>		\$2,635.00 ✓
6	1	Front R/H Headlamp Lower Bracket <i>new</i>		\$84.00 ✗
7	1	Front R/H Fender <i>Damaged</i>		\$875.00 ✓
8	1	Front R/H Fender Cowling <i>torn</i>		\$209.00 ✓
9	8	Front R/H Fender Cowling Clip <i>new</i>	\$8.00	\$64.00 ✓
10	1	Front R/H Fender Protector <i>lit</i>		\$286.00 ✓
11	8	Front R/H Fender Protector Clip <i>new</i>	\$8.00	\$64.00 <i>20</i>
12	1	Front R/H Rim <i>lit</i>		\$1,060.00 ✓
13	1	Front R/H Tyre <i>Not new</i>		\$380.00 ✗
14	1	Front R/H Side Mirror Assembly <i>Damaged</i>		\$1,682.00 ✓
15	1	Front R/H Door <i>Repair</i>		\$1,825.00 ✗
16	2	Front R/H Door Hinge	\$109.00	\$218.00 ✗
17	1	Front R/H Door Lock		\$480.00 ✗
18	1	Front R/H Door Weather Strip		\$375.00 ✓
19	1	Front R/H Door Inner Trim Board		\$1,135.00 ✗
20	1	Front R/H Door Power Window Motor		\$660.00 ✓
21	1	Front R/H Door Window Regulator		\$705.00 ✗
22	1	Rear R/H Door <i>Repair</i>		\$2,010.00 ✗
23	2	Rear R/H Door Hinge	\$109.00	\$218.00 ✗
24	1	Rear R/H Door Lock		\$475.00 ✗
25	1	Rear R/H Door Weather Strip		\$375.00 ✗
26	1	Rear R/H Door Inner Trim Board		\$1,135.00 ✗
27	1	Rear R/H Door Power Window Motor		\$660.00 ✗
28	1	Rear R/H Door Window Regulator		\$705.00 ✗

29	1	R/H Rocker Panel	HEW	\$1,495.00	X
30	1	R/H Rocker Panel Side Skirt	HEW	\$592.00	X
31	12	R/H Rocker Panel Side Skirt Clip	HEW	\$8.00	X

8509

7658.10

Subtotal :- \$22,462.00

Labour charges

To remove & refit cushion & trim board \$380.00 X

To remove & refit front R/H door, lock, rubber, glass, regulator window motor & trim board \$280.00 X

To remove & refit rear R/H door, lock, rubber, glass, regulator window motor & trim board \$280.00 X

To remove & refit ^{front} reverse sensor ~~\$100.00~~ 60

To reset computer ~~\$380.00~~ 60

To check wiring \$100.00 30 1750

Tuff kote \$150.00 X

Panel beating \$1,600.00 600

Spray painting \$1,600.00 1000

Subtotal :- \$4,870.00

Total :- \$27,332.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 9408.10

h/s: 75K

06 Days

7.5K

66 Days

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 491D

Vehicle Details

Vehicle No.: SKB6637H
Vehicle to be Exported: No
Intended Deregistration Date: 04 Oct 2019
Vehicle Make: MERCEDES BENZ
Vehicle Model: GLA180 URBAN (R18 LED)
Primary Colour: Black
Manufacturing Year: 2017
Engine No.: 27091031464743
Chassis No.: WDC1569422J444870
Maximum Power Output: 90.0 kW (120 bhp)
Open Market Value: \$28,494.00
Original Registration Date: 13 Mar 2018
First Registration Date: 13 Mar 2018
Transfer Count: 0
Actual ARF Paid: \$31,892.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 12 Mar 2028
PARF Rebate Amount: \$23,919.00

Intended COE Rebate Details

COE Expiry Date: 12 Mar 2028
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$40,000.00
COE Rebate Amount: \$33,752.00
Total Rebate Amount: \$57,671.00

The information contained herein is correct as at 04 Oct 2019

OK

Claim Audit

AUDIT TRAIL					By
No.	On	Audit	Remarks		
1	09 Oct 2019 15:15	Cim Dtl Modified	Claimant's Name: -> XU JINGBO, Claimant's ID: -> S2636491D.		[A] Lau Shu Pei
2	09 Oct 2019 15:15	Cim Veh Model Changed	(204229) MERCEDES-BENZ GLA180 1.6 (A).		[A] Lau Shu Pei
3	09 Oct 2019 15:15	Cim Created	Reg No: SKB6637H, Acct Date: 2019/10/04, Claim Type: TP, Insurer: India International Insurance Pte Ltd (HQ), TP Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG), Workshop: New Hock Teck Motor Pte Ltd (HQ)		[A] Lau Shu Pei
4	09 Oct 2019 15:15	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):		[A] Lau Shu Pei
5	09 Oct 2019 15:15	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/10/18		[A] Lau Shu Pei
6	09 Oct 2019 15:15	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.		[A] Lau Shu Pei
7	09 Oct 2019 15:16	Label Added	(30653):Direct Settlement.		[A] Lau Shu Pei
8	09 Oct 2019 15:16	Adj Adjuster Assigned	[None] -> ADRIAN LING		[A] Lau Shu Pei
9	11 Oct 2019 09:58	Cim Dtl Modified	Insured Name: -> YANG YUN XIN BUS SERVICE.		[A] Lau Shu Pei
10	14 Oct 2019 16:44	Adj Mandate Request	Cur.Req:0.00:PODS Liability: 100% Remark: Insured driver hit onto third party parked vehicle.		[A] CHEW HSIAO TONG
11	18 Oct 2019 14:45	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/10/18		[I] Lalitha Krishnan
12	18 Oct 2019 14:45	Adj Mandate Set	Approved:0.00.		[I] Lalitha Krishnan
13	10 Dec 2019 16:47	Adj Rpt Initiated			[A] JOANNE LEE KHANG MIN
14	10 Dec 2019 16:47	Cim Dtl Modified	Insured ID: -> -.		[A] JOANNE LEE KHANG MIN
15	10 Dec 2019 16:47	Cim Dtl Modified	JPJ Reg. Date: -> 2018/03/13.		[A] JOANNE LEE KHANG MIN
16	10 Dec 2019 16:47	Cim Details Notified			[A] JOANNE LEE KHANG MIN
17	27 Dec 2019 16:37	Adj Mandate Request	Cur.Req:8452.45:PODS Liability: 100% *Quantum: (a)CORw/GST: \$8,025.00 + (b)LOU(7days x \$60.00): \$4 20.00 + (c)LTA/GIA search fee: \$7.45 = Total: \$8,452.45 *Vehicle Model: Mercedes Benz (1595cc) *6 recom mendation repair days + 1Sunday = 7days *For		[A] CHEW HSIAO TONG

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2308052	10 Oct 2019 08:40:51	TP Case (Insurer)	Motor	LKK Auto Consultants Pte Ltd	India International Insurance Pte Ltd (HQ)	SKB6637H	PA3676K	11.77
2372915	10 Dec 2019 16:47:23	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKB6637H	PA3676K	11.77

Print Received Message

This mail is associated with :

*SKB6637H
[PA3676K]
TP
XU JINGBO
Oct 4 2019 1:00PM
[YANG YUN XIN BUS SERVICE]
New Hock Teck Motor Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 02/01/2020 08:59 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$8452.45) - SKB6637H - Claim Handler: C. Meenachi

Approved:8452.45.

Hsiao Tong (LKKAUTO)

From: Admin nht <admin@nhtmotor.com>
Sent: Thursday, 2 January 2020 10:30 AM
To: Hsiao Tong (LKKAUTO)
Cc: chloe@nhtmotor.com; Admin A
Subject: Re: FW: SKB6637H CLAIMING PA3676K DOA 04.10.19 //LKK REF: CC6/III19017819/Apb3

Without Prejudice

Hi Hsiao Tong


Thanks for your offer.

Out of goodwill, we accept your offer as \$8,400 for this time only as the loss of use should not be \$50-\$60 as our client vehicle is under mercedes GLA180 urban (R18 Led) which is a luxury vehicle.

Please kindly send us the discharge voucher for close case, thanks.

*** Please kindly take note this claim is under "New Hock Teck Motor Pte Ltd" ***

Best Regards,
Sukyi Chong
New Hock Teck Motor Pte Ltd
1 Kaki Bukit Ave 6 Blk C #01-43 Autobay @ Kaki Bukit S(417883)
Tel : 6747 9241 Fax : 6741 7276



On Thu, Jan 2, 2020 at 10:16 AM Hsiao Tong (LKKAUTO) <chewht@lkkauto.com> wrote:

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement at a global sum of **\$8,400.00(all-in)**.

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

"Best Wishes for Merry Christmas, and Happy New Year 2020"

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin nht <admin@nhtmotor.com>

Sent: Friday, 27 December 2019 12:54 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: chloe@nhtmotor.com; Admin A <admin-a@lkkauto.com>

Subject: Re: FW: SKB6637H CLAIMING PA3676K DOA 04.10.19 //LKK REF: CC6/III19017819/Apb3

Without Prejudice

Hi Hsiao Tong

Contents noted with thanks.

Hope to hear from you soon for close case,thanks.


Best Regards,

Sukyi Chong

New Hock Teck Motor Pte Ltd

1 Kaki Bukit Ave 6 Blk C #01-43 Autobay @ Kaki Bukit S(417883)

Tel : 6747 9241 Fax : 6741 7276



On Fri, Dec 27, 2019 at 12:47 PM Hsiao Tong (LKKAUTO) <chewht@lkkauto.com> wrote:

Without Prejudice

Dear Sirs/Mdm,

Thank you for your email.

We are seeking mandate from our principal.

We will expedite the matter and get back to you.

Kindly bears with us for time being.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

"Best Wishes for Merry Christmas, and Happy New Year 2020"

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin nht <admin@nhtmotor.com>

Sent: Friday, 27 December 2019 11:16 AM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: chloe@nhtmotor.com; Admin A <admin-a@lkkauto.com>

Subject: Re: FW: SKB6637H CLAIMING PA3676K DOA 04.10.19 //LKK REF: CC6/III19017819/Apb3

Without Prejudice

Hi Hsiao Tong

Please kindly advise your offer and revert for close case,thanks.


Best Regards,

Sukyi Chong

New Hock Teck Motor Pte Ltd

1 Kaki Bukit Ave 6 Blk C #01-43 Autobay @ Kaki Bukit S(417883)

Tel : 6747 9241 Fax : 6741 7276



On Fri, Dec 13, 2019 at 10:58 AM Admin nht <admin@nhtmotor.com> wrote:

Without Prejudice

Hi Hsiao Tong

Contents noted with thanks.

Hope to hear from you soon.


Best Regards,

Sukyi Chong

New Hock Teck Motor Pte Ltd

1 Kaki Bukit Ave 6 Blk C #01-43 Autobay @ Kaki Bukit S(417883)

Tel : 6747 9241 Fax : 6741 7276



On Fri, Dec 13, 2019 at 10:54 AM Hsiao Tong (LKKAuto) <chewht@lkkauto.com> wrote:

Without Prejudice

Dear Sirs/Mdm,

Thank you for your email.

We are preparing report to seek mandate from Ill.

Kindly bear with us for time being.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

"Best Wishes for Merry Christmas, and Happy New Year 2020"

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin nht <admin@nhtmotor.com>
Sent: Friday, 13 December 2019 9:49 AM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Cc: chloe@nhtmotor.com; Admin A <admin-a@lkkauto.com>
Subject: Re: FW: SKB6637H CLAIMING PA3676K DOA 04.10.19

Without Prejudice

Hi Hsiao Tong

Please kindly advise your offer and revert for close case, thanks.

Best Regards,

Sukyi Chong

New Hock Teck Motor Pte Ltd

1 Kaki Bukit Ave 6 Blk C #01-43 Autobay @ Kaki Bukit S(417883)

Tel : 6747 9241 Fax : 6741 7276

	
---	--

On Tue, Dec 3, 2019 at 5:35 PM Shu Pei (LKKAuto) <shupeil@lkkauto.com> wrote:

Dear Sir / Madam,

Thank you for your email.

Our respective case handler will look into the matter and revert to you in due course.

Please note that: -

LKK ref	Officer in charge
CC6/III19017819/Apb3	Hsiao Tong

To check availability of the case handler, you may contact the undersigned

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

From: Chloe <chloe@nhtmotor.com>
Sent: Friday, 29 November 2019 1:01 PM
To: Admin A <admin-a@lkkauto.com>
Cc: Admin nht <admin@nhtmotor.com>
Subject: SKB6637H CLAIMING PA3676K DOA 04.10.19

Without Prejudice

Dear Motor Claims Department,

Enclosed LOD and supporting documents for your reference.
Originals have been posted out.
Please kindly advise officer in charge and hope to receive offer soon.
Thank you.

***Please note that NEW HOCK TECK MOTOR PTE LTD is now GST-registered**

Regards,

Chloe

New Hock Teck Motor Pte. Ltd.

GST Reg No.: 201718370k

Tel: 67479241 Fax: 67417276

1 Kaki Bukit Ave 6 Blk C #01-43

Singapore 417883

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Dec 2019 16:47 Edit Reg		08 Oct 2019 00:00 Edit Adj Rpt	\$57,500.00 Edit Estimates	\$57,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]
Insured:	YANG YUN XIN BUS SERVICE, Co. Reg. No.: 44258900W	
Main Claimant:	XU JINGBO, ID: S2636491D	
Vehicle Reg. No.:	SKB6637H	Date of Loss: 04/10/2019 13:00 - :59 [18 Months and 21 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:
Vehicle Reg. No. (Insured):	PA3676K	Policy No. (Claimant): 1800021707
		Excess:
Repairer:	New Hock Teck Motor Pte Ltd (HQ) 1 Kaki Bukit Ave 6, Bldg C #01-43 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 6747 9241	
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by C. Meenachi - 6347 6073]	
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 18/10/2019]	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
- III_SG (02/01/2020): Alert - Adj Mandate Approved (\$58452.45) - SKB6637H - Claim Handler: C. Meenachi - III_SG (18/10/2019): Alert - Adj Mandate Approved (\$0.00) - SKB6637H - Claim Handler: C. Meenachi		

ALL ASSOCIATED TASKS		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKB6637H
[PA3676K]
TP
XU JINGBO
Oct 4 2019 1:00PM
[YANG YUN XIN BUS SERVICE]
New Hock Teck Motor Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	04/12/19 09:50	General View		Load JPG	
2	04/12/19 09:50	General View		Load JPG	
3	04/12/19 09:50	General View		Load JPG	
4	04/12/19 09:50	General View		Load JPG	
5	04/12/19 09:50	General View		Load JPG	
6	04/12/19 09:50	General View		Load JPG	
7	04/12/19 09:50	General View		Load JPG	
8	04/12/19 09:50	General View		Load JPG	
9	04/12/19 09:50	General View		Load JPG	
10	04/12/19 09:50	General View		Load JPG	
11	04/12/19 09:50	General View		Load JPG	
12	04/12/19 09:50	General View		Load JPG	
13	04/12/19 09:50	General View		Load JPG	
14	04/12/19 09:50	General View		Load JPG	
15	04/12/19 09:50	General View		Load JPG	
16	04/12/19 09:50	General View		Load JPG	
17	04/12/19 09:50	General View		Load JPG	
18	04/12/19 09:50	General View		Load JPG	
19	04/12/19 09:50	General View		Load JPG	
20	04/12/19 09:50	General View		Load JPG	
21	04/12/19 09:50	General View		Load JPG	
22	04/12/19 09:50	General View		Load JPG	
23	04/12/19 09:50	General View		Load JPG	
24	04/12/19 09:50	General View		Load JPG	
25	04/12/19 09:50	General View		Load JPG	
26	04/12/19 09:50	General View		Load JPG	
27	04/12/19 09:50	General View		Load JPG	
28	04/12/19 09:50	General View		Load JPG	
29	04/12/19 09:50	General View		Load JPG	
30	04/12/19 09:50	General View		Load JPG	
31	04/12/19 09:50	General View		Load JPG	
32	04/12/19 09:50	General View		Load JPG	
33	04/12/19 09:50	General View		Load JPG	
34	04/12/19 09:50	General View		Load JPG	
35	04/12/19 09:50	General View		Load JPG	
36	04/12/19 09:50	General View		Load JPG	
37	04/12/19 09:50	General View		Load JPG	
38	04/12/19 09:50	General View		Load JPG	
39	04/12/19 09:50	General View		Load JPG	
40	04/12/19 09:50	Reinspection Photo		Load JPG	
41	04/12/19 09:50	Reinspection Photo		Load JPG	
42	04/12/19 09:50	Reinspection Photo		Load JPG	
43	04/12/19 09:50	Reinspection Photo		Load JPG	

Photos/Images					3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
44	04/12/19 09:50	Reinspection Photo		Load JPG	☒	
45	04/12/19 09:50	Reinspection Photo		Load JPG	☒	
46	04/12/19 09:50	Reinspection Photo		Load JPG	☒	
47	04/12/19 09:50	Reinspection Photo		Load JPG	☒	
48	04/12/19 09:50	Reinspection Photo		Load JPG	☒	
49	04/12/19 09:50	Reinspection Photo		Load JPG	☒	
50	04/12/19 09:50	Reinspection Photo		Load JPG	☒	
51	04/12/19 09:50	Reinspection Photo		Load JPG	☒	
52	04/12/19 09:50	Reinspection Photo		Load JPG	☒	
53	04/12/19 09:50	Reinspection Photo		Load JPG	☒	
54	04/12/19 09:50	Reinspection Photo		Load JPG	☒	
55	04/12/19 09:50	Reinspection Photo		Load JPG	☒	
56	04/12/19 09:50	Reinspection Photo		Load JPG	☒	
57	04/12/19 09:50	Reinspection Photo		Load JPG	☒	
58	04/12/19 09:50	Reinspection Photo		Load JPG	☒	
59	04/12/19 09:50	Reinspection Photo		Load JPG	☒	
Documentation					1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	09/10/19 17:12	TP GIA REPORT		Load PDF		
2	07/12/19 11:03	TP_ESTIMATE_MARKED		Load PDF		
3	27/12/19 13:28	WORKSHOP INVOICE		Load PDF		
4	27/12/19 13:28	LTA SEARCH		Load PDF		
5	27/12/19 13:28	LOD		Load PDF		
6	09/01/20 10:11	DISCHARGE VOUCHER		Load PDF		
7	09/01/20 10:11	AUTHORISATION TO ACT FORM		Load PDF		
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print	
1	10/10/19 08:38	Singapore Accident Statement		Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) ^ v			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III19017819/APA3Q2

Date: 09/01/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant SKB6637H

Insured Vehicle No : PA3676K

Vehicle No : SKB6637H

Nature of Claim: TP Claim No: N/A

Date of Loss: 04/10/2019

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKB6637H

Make & Model: MERCEDES-BENZ GLA180, 1.6 (A)

Engine No: 27091031464743

Reg. Date: 13/03/2018 (Man. Year: 2017)

Chassis No: WDC1569422J444870

Colour: Black

Odometer: 20352 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50 R18

Rear Tyre Size: 235/50 R18

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,462.00	7,658.10	14,803.90	65.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,870.00	1,750.00	3,120.00	64.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,332.00	9,408.10	17,923.90	65.58
Approved Total (Overridden) (S\$)		7,500.00		
(S\$)	27,332.00	7,500.00	19,832.00	72.56
+ GST 7.00/7.00% (S\$)	1,913.24	525.00	1,388.24	72.56
Nett Amount (S\$)	29,245.24	8,025.00	21,220.24	72.56
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		8,452.45		
Global Sum Settlement (S\$)		8,400.00		

INSPECTION

Date of Assignment: 08/10/2019

Date Inspected: 08/10/2019 Inspected At:

New Hock Teck Motor Pte Ltd (HQ)

1 Kaki Bukit Ave 6, Blk C #01-43

Autobay@Kaki Bukit

Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Dec 2019)
Parts:	M1-SUV	MERCEDES-BENZ GLA180 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKB6637H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	1,610.00 F	*1,610.00 FL
2	10		*FRONT BUMPER CLIP	Necessary	80.00 F	*30.00 FL
3	1		*FRONT R/H BUMPER SIDE RETAINER	Necessary	38.00 F	*38.00 FL
4	1		*FRONT R/H BUMPER SENSOR	Not Necessary	236.00 F	*- FL
5	1		*FRONT R/H HEADLAMP	Cut	2,635.00 F	*2,635.00 FL
6	1		*FRONT R/H HEADLAMP LOWER BRACKET	Not Necessary	84.00 F	*- FL
7	1		*FRONT R/H FENDER	Dented	875.00 F	*875.00 FL
8	1		*FRONT R/H FENDER COWLING	Torn	209.00 F	*209.00 FL
9	8		*FRONT R/H FENDER COWLING CLIP	Necessary	84.00 F	*64.00 FL
10	1		*FRONT R/H FENDER PROTECTOR	Cut	286.00 F	*286.00 FL
11	8		*FRONT R/H FENDER PROTECTOR CLIP	Necessary	84.00 F	*20.00 FL
12	1		*FRONT R/H RIM	Cut	1,060.00 F	*1,060.00 FL
13	1		*FRONT R/H TYRE	Not Necessary	380.00 F	*- FL
14	1		*FRONT R/H SIDE MIRROR ASSEMBLY	Damaged	1,682.00 F	*1,682.00 FL
15	1		*FRONT R/H DOOR	Repair	1,825.00 F	*- FL
16	2		*FRONT R/H DOOR HINGE	Not Necessary	218.00 F	*- FL
17	1		*FRONT R/H DOOR LOCK	Not Necessary	480.00 F	*- FL
18	1		*FRONT R/H DOOR WEATHERSTRIP	Not Necessary	375.00 F	*- FL
19	1		*FRONT R/H DOOR INNER TRIM BOARD	Not Necessary	1,135.00 F	*- FL
20	1		*FRONT R/H DOOR POWER WINDOW MOTOR	Not Necessary	660.00 F	*- FL
21	1		*FRONT R/H DOOR WINDOW REGULATOR	Not Necessary	705.00 F	*- FL
22	1		*REAR R/H DOOR	Repair	2,010.00 F	*- FL
23	2		*REAR R/H DOOR HINGE	Not Necessary	218.00 F	*- FL
24	1		*REAR R/H DOOR LOCK	Not Necessary	475.00 F	*- FL
25	1		*REAR R/H DOOR WEATHERSTRIP	Not Necessary	375.00 F	*- FL
26	1		*REAR R/H DOOR INNER TRIM BOARD	Not Necessary	1,135.00 F	*- FL
27	1		*REAR R/H DOOR POWER WINDOW MOTOR	Not Necessary	660.00 F	*- FL
28	1		*REAR R/H DOOR WINDOW REGULATOR	Not Necessary	705.00 F	*- FL
29	1		*R/H ROCKER PANEL	Not Necessary	1,495.00 F	*- FL
30	1		*R/H ROCKER PANEL SIDE SKIRT	Not Necessary	592.00 F	*- FL
31	12		*R/H ROCKER PANEL SIDE SKIRT CLIP	Not Necessary	96.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$) **22,462.00** **8,509.00**
 - List Item Discount on L Items 0.00/10.00% (\$\$) **0.00** **850.90**

Total Parts (\$\$) **22,462.00** **7,658.10**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT CUSHION & TRIM BOARD	New	380.00	0.00
2	TO REMOVE & REFIT FRONT R/H DOOR LOCK ,RUBBER ,GLASS ,REGULATOR WINDOW MOTOR & TRIM BOARD	New	280.00	0.00
3	TO REMOVE & REFIT REAR R/H DOOR ,LOCK ,RUBBER ,GLASS ,REGULATOR WINDOW MOTOR & TRIM BOARD	New	280.00	0.00
4	TO REMOVE & REFIT FRONT SENSOR	New	100.00	60.00
5	TO RESET COMPUTER	New	380.00	60.00
6	TO CHECK WIRING	New	100.00	30.00
7	TUFF KOTE	New	150.00	0.00
8	PANEL BEATING	New	1,600.00	600.00
9	SPRAY PAINTING	New	1,600.00	1,000.00
Gross Labour Cost (S\$)			4,870.00	1,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >