

Surveyor:

KENNETH

DOI: 14/10/2019

Date / Time: 10/10/2019

Registered in Meritmen:

Pre-assign / CCU / FTE



Insured Vehicle No. : YM 9373A

Claim No. :

Name of Insured : Sri Thuvimuga Garapathy Services

Policy No. :

Insured Tel No. : HP:

Make / Model : TOYOTA HARRIER

Excess Sec II : SS

D.O.A : 08/10/19 17:10

Place of Accident : UPPER THOMSON RD JUNCTION WITH MARYMOUNT ROAD

Is driver the owner?

(YES NO)

Nature of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(V/L YES / NO)

OI GIA REPORT YES NO : TP GIA REPORT YES NO

Insured Liability : % Final ? Yes / No

SLP 7148K



INSRS:
WSP: OPTIMA WERKZ
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time		STAGE	DATE / PIC
	SLP 7148K - X	Non-Reporting ltr (1st):	
	YM 9373A - NJA/MSG10012975/k1; DOA: 01/7/10	Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OI:	26/10/19
		After call ltr to OI:	
		Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup):	
		After call ltr to OI:	
		Authorisation To Act:	
		Release Voucher:	
		Final Repair Bill:	
		Car Rental Invoice:	
		Towing Invoice:	
		LTA / GIA :	
		Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
		LOD	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

PRELIMINARY ADVICE Date/Time:		Sent By:	
FINALIZATION Date/Time:		Confirm with:	
Repair Cost:	SS	(days) Reduction:	%
FINAL SETTLEMENT Date/Time: 12/11/19		Confirm with: Sharon	
Final Liability:	%	(Agreed / Assessed) BOLA S/N No.:	27
Repair Cost:	SS 5829.19		
Loss of Rental (LOR):	SS 599.20	(4 days)	X \$ 140.00
Loss of Use (LOU):	SS -	(\$ x days)	
Loss of Income (LOI):	SS -	(\$ x days)	
LOR only	☐	LOU only	☐
LOR + LOU	☐	LOR + LOI	☐
[Tick only one]			
GIA/LTA Search	SS 2.00		
Medical:	SS -		
Disbursement:	SS -	(e.g. Tow/Independent)	
Legal Cost	SS -		
Total:	SS 6430.39	Global Sum SS:	6430.00
FINAL PAYMENT Date/Time:		Confirm with:	
Payee 1:	SS 6430.00	Name 1:	Optima Werkz Pte Ltd
Payee 2: (Strike if N.A.)	SS	Name 2:	
Payee 3: (Strike if N.A.)	SS	Name 3:	

COPY SENT

1) Claim status: Normal/Reject/Private Settle
2) Report Format: 1/1
3) Survey fee: \$ 400.00

all 14/11/19 PW

REF: EQ1

ASS. REQ. BY:

ASSIGNMENT

From: _____ Date: 14/10/2019

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLP 7148K

at Workshop m/s Optimax Workz

of 9A Seungoon North Ave 5

Insured: _____

Policy No: _____

Claims No: _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Manning

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bot. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 1.81 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{1 up}

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLP 7148K Yr Regn: 06 17

Type: ☒ M. Car / ☐ M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy ^{1st} / ^{2nd} c.c. 1986

Colour: M.P. White A/C: Insured / Std / NI / NA

Sp. Reading: 32593 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZSU 60 - 0092173

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/65R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ M / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 2 mm R/Bal. 3 mm

L/Bal. 2 mm L/Bal. 3 mm

D.O.A. 8/10/19 D.O.I. 14/10/19

Survey held at ☒Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

PIP \$ 54484 (Red \$ 2514.31 / 37%)

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / LBJ: 12

☐ : Prel. Report☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Inve (\$)☐ : Weekend (\$)

Survey Fee: _____

Transportation: _____

3 + RS 31

Photos

Others

TOTAL

Date: 09/10/2019
 Vehicle No: SLP7148K
 Model: TOYOTA HARRIER ELEGANCE 2.0 CVT
 Chassis: ZSU600092173 - 2016
 Reg.Year: 2017

Third Party Insurer: EQ INSURANCE
 Third Party Veh No: YM9373A
 Date of Accident: 08/10/2019

*Not withholder
 Repair B4 pain 5 days*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE <i>1712.02</i>	1		<i>R</i> \$2,126.40
2	REAR TAILGATE "HARRIER" EMBLEM	1		<i>R</i> \$73.70
3	REAR TAILGATE INNER TRIM	1		<i>R</i> \$568.50
4	REAR TAILGATE INNER TRIM CLIPS	8	\$6.80	\$54.40
5	REAR TAILGATE REVERSE LAMP RH	1		<i>CM</i> \$560.30
6	REAR TAILGATE INNER LOCK <i>381.21</i>	1		<i>R</i> \$565.30
7	REAR TAILGATE RUBBER <i>399.11</i>	1		<i>Dix / R</i> \$441.30
8	REAR BUMPER <i>1743.00</i>	1		<i>CM</i> \$1,422.50
9	REAR BUMPER SIDE BRACKET LH	1		\$85.30
10	REAR BUMPER SIDE BRACKET RH	1		\$85.30
11	REAR BUMPER LOWER LIP COVER <i>396.96</i>	1		<i>R</i> \$409.50
12	REAR WINDSCREEN SIDE MOULDING	2	\$38.60	<i>R</i> \$77.20
13	REAR WINDSCREEN LOWER MOULDING	1		<i>R</i> \$51.50
14	REAR BUMPER CLIPS	10	\$5.50	<i>R</i> \$55.00
15	REAR QUARTER PANEL LH	1		REPAIR
16	REAR QUARTER PANEL RH	1		REPAIR
17	REAR END PANEL	1		REPAIR
SUB TOTAL				\$6,576.20
LESS 25%				-\$1,644.05
PARTS TOTAL				\$4,932.15

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER REVERSE SENSOR SET	1	<i>Shot</i>	\$350.00
2	REAR WINDSCREEN SEALANT	1		<i>R</i> \$60.00
S/N TOTAL				\$410.00

LKK Auto Consultants hence notify the Repairer of the following:

- To remedy before/after spray painting
- To display damaged parts during remedy
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal identification is allowed
- Supplementary Part(s) must be remedied and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554506
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
 Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223



Date: 09/10/2019
Vehicle No: SLP7148K
Model: TOYOTA HARRIER ELEGANCE 2.0 CVT
Chassis: ZSU600092173 - 2016
Reg.Year: 2017

Third Party Insurer: EQ INSURANCE
Third Party Veh No: YM9373A
Date of Accident: 08/10/2019

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPAIR, READJUST, REPLACE REAR ACCIDENT AREAS & ETC.	\$800.00	500
LABOUR CHARGES TO REMOVE, REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN SEALANT, REAR WINDSCREEN MOULDING & ETC.	\$150.00	120
LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL CONDITIONS.	\$120.00	80
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR QUARTER PANEL LH, REAR QUARTER PANEL RH & ETC.	\$1,200.00	660
LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.	\$80.00	50
TO TUFF KOTE & UNDERSEAL MATERIALS.	\$150.00	30
TO DIAGNOSIS FAULTY CODE & RESET MEMORY.	\$120.00	20
LABOUR TOTAL	\$2,620.00	

ONG	TOTAL	\$7,962.15
-----	--------------	-------------------

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	480D
Vehicle Details	
Vehicle No.:	SLP7148K
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER ELEGANCE 2.0 CVT
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	3ZRB912256
Chassis No.:	ZSU600092173
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$29,837.00
Original Registration Date:	15 Jun 2017
First Registration Date:	15 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$28,772.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Jun 2027
PARF Rebate Amount:	\$21,579.00
Intended COE Rebate Details	
COE Expiry Date:	14 Jun 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,110.00
COE Rebate Amount:	\$38,487.00
Total Rebate Amount:	\$60,066.00

The information contained herein is correct as at 09 Oct 2019

OK

Nivitha (LKK Auto)

From: sharon@ow.sg
Sent: Friday, 11 October 2019 4:43 PM
To: assignments@lkkauto.com
Cc: 'Admin A'; 'angela.tan'; Lily.loi@ow.sg; hockkong.ong@ow.sg
Subject: RE: TP Claims / Arrange Survey - Accident involving SLP7148K & YM9373A on 08/10/2019 (EQ)

Without Prejudice

Dear Officer,

Please arrange for survey on 14/10/19 (Mon) morning.

Thank you.

Best Regards,

Sharon Ten (Ms.)

Claims Executive, Motor Claims Department

D: +65 6481 1522 | F: +65 6481 1011

OPTIMA//WERKZ PTE. LTD.

Head office: 6 Kung Chong Road Singapore 159143

Branch: 9A Serangoon North Ave 5 Singapore 554800

Branch: 452 Yagore Industrial Ave Singapore 787823

Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Tel: (+65) 6484 0919 Fax: (+65) 6481 1011

Tel: (+65) 6452 6868 Fax: (+65) 6452 9223

www.ow.sg | www.facebook.com/OptimaWerkz

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, you must not copy, distribute or use it for any purpose, nor disclose its contents to any other person.

Please notify the sender if you receive this email in error, and delete the email and its content immediately after which.

From: sharon@ow.sg <sharon@ow.sg>
Sent: Wednesday, 9 October 2019 2:55 PM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>
Cc: 'Admin A' <admin-a@lkkauto.com>; 'angela.tan' <angela.tan@ow.sg>; 'Lily.loi@ow.sg' <Lily.loi@ow.sg>; 'hockkong.ong@ow.sg' <hockkong.ong@ow.sg>
Subject: TP Claims / Arrange Survey - Accident involving SLP7148K & YM9373A on 08/10/2019 (EQ)

Without Prejudice

Your Ref: YM9373A

Our Ref: SLP7148K

Dear Officer,

Has your insured reported?

Please arrange for survey as soon as possible.

Location: 9A Serangoon North Avenue 5

****Please avoid 1PM - 2PM**

Hsiao Tong (LKKAuto)

From: Mei Kwan (LKKAuto)
Sent: Tuesday, 22 October 2019 11:49 AM
To: angela.tan@ow.sg; Hsiao Tong (LKKAuto)
Cc: 'Lily Loi OW'; 'Sharon'; adeline@ow.sg; Admin A
Subject: RE: LOD - ACCIDENT INVOLVING SLP7148K & YM9373A ON 08/10/2019 // Our Ref: TP#928 *** LKK REF: CC6/EQI19017859/Kpa3
Attachments: SLP7148K LOD.pdf

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir / Madam,

Thank you for your email.

Our respective case handler will look into the matter and get back to you in due course.

Hi Hsiao Tong,

Kindly assist.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: angela.tan@ow.sg <angela.tan@ow.sg>
Sent: Tuesday, 22 October, 2019 11:28 AM
To: Admin A <admin-a@lkkauto.com>
Cc: 'Lily Loi OW' <lily.loi@ow.sg>; 'Sharon' <sharon@ow.sg>; adeline@ow.sg
Subject: RE: LOD - ACCIDENT INVOLVING SLP7148K & YM9373A ON 08/10/2019 // Our Ref: TP#928

Our Ref : SLP7148K / TP#928
Your Ref : YM9373A

Without Prejudice

Dear Officer-In-Charge,

We refer to the above mentioned accident.

We are claiming as below:

- Cost of Repair (incl. of GST)	S\$5,829.19
- Loss of Rentals (incl of GST)	S\$856.00 (\$214.00 x 4 days)

- LTA / GIA Search

S\$2.00

Grant Total

S\$6,687.19

=====

Your prompt attention is most grateful and look forward to your speedy settlement.

Thank you.

Angela Tan (Ms.)

Motor Claims Assistant

T: +65 6481 1522 | F: 6481 1011

OPTIMA//WERKZ PTE. LTD.

Head office: 6 Kung Chong Road Singapore 159143

Branch: 9A Serangoon North Ave 5 Singapore 554500

Branch: 452 Tagore Industrial Ave Singapore 787823

Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Tel: (+65) 6484 9919 Fax: (+65) 6481 1011

Tel: (+65) 6452 6868 Fax: (+65) 6452 9223

www.ow.sg | www.facebook.com/OptimaWerkz

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, you must not copy, distribute or use it for any purpose, nor disclose its contents to any other person.

Please notify the sender if you receive this email in error, and delete the email and its content immediately after which.

Hsiao Tong (LKKAuto)

From: sharon@ow.sg
Sent: Thursday, 7 November 2019 4:41 PM
To: Hsiao Tong (LKKAuto)
Cc: Admin A; 'angela.tan'; 'Lily Loi OW'; adeline@ow.sg
Subject: RE: LOD - ACCIDENT INVOLVING SLP7148K & YM9373A ON 08/10/2019 // Our Ref: TP#928 *** LKK REF: CC6/EQI19017859/Kpa3

Without Prejudice

Dear Hsiao Tong,

Please let us have your proposed offer without further delay.

Thank you.

Best Regards,

Sharon Ten (Ms.)

Claims Executive, Motor Claims Department
D: +65 6481 1522 | F: +65 6481 1011

OPTIMA WERKZ PTE. LTD.

Head office: 6 Kung Chong Road Singapore 159143 Tel: (+65) 6472 1313 Fax: (+65) 6472 2112
Branch: 9A Serangoon North Ave 5 Singapore 554500 Tel: (+65) 6484 9919 Fax: (+65) 6481 1011
Branch: 452 Tagore Industrial Ave Singapore 767823 Tel: (+65) 6452 6868 Fax: (+65) 6452 9223

www.ow.sg | www.facebook.com/OptimaWerkz

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, you must not copy, distribute or use it for any purpose, nor disclose its contents to any other person.

Please notify the sender if you receive this email in error, and delete the email and its content immediately after which.

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Tuesday, 22 October 2019 11:49 AM
To: angela.tan@ow.sg; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Cc: 'Lily Loi OW' <lily.loi@ow.sg>; 'Sharon' <sharon@ow.sg>; adeline@ow.sg; Admin A <admin-a@lkkauto.com>
Subject: RE: LOD - ACCIDENT INVOLVING SLP7148K & YM9373A ON 08/10/2019 // Our Ref: TP#928 *** LKK REF: CC6/EQI19017859/Kpa3

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir / Madam,

Thank you for your email.

Our respective case handler will look into the matter and get back to you in due course.

Hi Hsiao Tong,

Kindly assist.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Hsiao Tong (LKKAUTO)

From: sharon@ow.sg
Sent: Monday, 11 November 2019 4:55 PM
To: Hsiao Tong (LKKAUTO)
Cc: Admin A; 'angela.tan'; 'Lily Loi OW'; adeline@ow.sg
Subject: RE: LOD - ACCIDENT INVOLVING SLP7148K & YM9373A ON 08/10/2019 // Our Ref: TP#928 *** LKK REF: CC6/EQI19017859/Kpa3

Without Prejudice

Dear Hsiao Tong,

We accept your offer at \$6,430.00. Please send DV.

Thank you.

Best Regards,

Sharon Ten (Ms.)

Claims Executive, Motor Claims Department
D: +65 6481 1522 | F: +65 6481 1011

OPTIMA WERKZ PTE. LTD.

Head office: 6 Kung Chong Road Singapore 159143
Branch: 9A Serangoon North Ave 5 Singapore 554500
Branch: 452 Tagore Industrial Ave Singapore 787623

Tel: (+65) 6472 1313 Fax: (+65) 6472 2112
Tel: (+65) 6484 9919 Fax: (+65) 6481 1011
Tel: (+65) 6452 8868 Fax: (+65) 6452 9223

www.ow.sg | www.facebook.com/OptimaWerkz

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, you must not copy, distribute or use it for any purpose, nor disclose its contents to any other person. Please notify the sender if you receive this email in error, and delete the email and its content immediately after which.

From: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Sent: Saturday, 9 November 2019 1:04 PM
To: sharon@ow.sg
Cc: Admin A <admin-a@lkkauto.com>; 'angela.tan' <angela.tan@ow.sg>; 'Lily Loi OW' <lily.loi@ow.sg>; adeline@ow.sg
Subject: RE: LOD - ACCIDENT INVOLVING SLP7148K & YM9373A ON 08/10/2019 // Our Ref: TP#928 *** LKK REF: CC6/EQI19017859/Kpa3

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement at a global sum of \$6,430.00(all-in).

Please confirm acceptance.

"Please note that our above settlement is made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured/driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum."

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: sharon@ow.sg <sharon@ow.sg>

Sent: Thursday, 7 November 2019 4:41 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; 'angela.tan' <angela.tan@ow.sg>; 'Lily Loi OW' <lily.loi@ow.sg>; adeline@ow.sg

Subject: RE: LOD - ACCIDENT INVOLVING SLP7148K & YM9373A ON 08/10/2019 // Our Ref: TP#928 *** LKK REF: CC6/EQ19017859/Kpa3

Without Prejudice

Dear Hsiao Tong,

Please let us have your proposed offer without further delay.

Thank you.

Best Regards,

Sharon Ten (Ms.)

Claims Executive, Motor Claims Department

D: +65 6481 1522 | F: +65 6481 1011

OPTIMA WERKZ PTE. LTD.

Head office: 6 Kung Chong Road Singapore 159143

Branch: 9A Serangoon North Ave 5 Singapore 554500

Branch: 482 Tagore Industrial Ave Singapore 787823

Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Tel: (+65) 6464 9919 Fax: (+65) 6481 1011

Tel: (+65) 6462 6868 Fax: (+65) 6462 9223

www.ow.sg | www.facebook.com/OptimaWerkz

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, you must not copy, distribute or use it for any purpose, nor disclose its contents to any other person.

Please notify the sender if you receive this email in error, and delete the email and its content immediately after which.

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>

Sent: Tuesday, 22 October 2019 11:49 AM

To: angela.tan@ow.sg; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: 'Lily Loi OW' <lily.loi@ow.sg>; 'Sharon' <sharon@ow.sg>; adeline@ow.sg; Admin A <admin-a@lkkauto.com>

Subject: RE: LOD - ACCIDENT INVOLVING SLP7148K & YM9373A ON 08/10/2019 // Our Ref: TP#928 *** LKK REF: CC6/EQ19017859/Kpa3

'WITHOUT PREJUDICE'

SAVE AS TO COSTS

Dear Sir / Madam,

Thank you for your email.

Our respective case handler will look into the matter and get back to you in due course.

Hi Hsiao Tong,

Kindly assist.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: angela.tan@ow.sg <angela.tan@ow.sg>

Sent: Tuesday, 22 October, 2019 11:28 AM

To: Admin A <admin-a@lkkauto.com>

Cc: 'Lily Loi OW' <lily.loi@ow.sg>; 'Sharon' <sharon@ow.sg>; adeline@ow.sg

Subject: RE: LOD - ACCIDENT INVOLVING SLP7148K & YM9373A ON 08/10/2019 // Our Ref: TP#928

Our Ref : SLP7148K / TP#928

Your Ref : YM9373A

Without Prejudice

Dear Officer-In-Charge,

We refer to the above mentioned accident.

We are claiming as below:

- Cost of Repair (incl. of GST)	S\$5,829.19
- Loss of Rentals (incl of GST)	S\$856.00 (\$214.00 x 4 days)
- LTA / GIA Search	S\$2.00

Grant Total **S\$6,687.19**

=====

Your prompt attention is most grateful and look forward to your speedy settlement.

Thank you.

Angela Tan (Ms.)

Motor Claims Assistant

T: +65 6481 1522 | F: 6481 1011

OPTIMA//WERKZ PTE. LTD.

Head office: 6 Kung Chong Road Singapore 159143

Branch: 9A Serangoon North Ave 5 Singapore 554600

Branch: 482 Tagore Industrial Ave Singapore 787823

Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Tel: (+65) 6484 9919 Fax: (+65) 6481 1011

Tel: (+65) 6462 6868 Fax: (+65) 6462 9223

www.ow.sg | www.facebook.com/OptimaWerkz

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, you must not copy, distribute or use it for any purpose, nor disclose its contents to any other person.
Please notify the sender if you receive this email in error, and delete the email and its content immediately after which.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 19/11/2019

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	YM 9373A	(Insd Veh)	Your Ref. No. : DM19HO02781-JG
	SLP 7148K	(TP Veh)	Our Ref. No. : CC6/EQI19017859/Kpa3q2
Date of Accident	8/10/2019		

Liability	100%	
Final Repair Cost	: \$ 5,829.19	
Loss of Use	: \$	days
Rental (If any)	: \$ 599.20	4 days
Others:	: \$ 2.00	
	: \$	
	6,430.39	
Final Settlement Sum	: \$ 6,430.00	GLOBAL SUM
Remarks	:	

Payment Instruction: Payee's Breakdown		
1)	OPTIMA WERKZ PTE LTD	: \$ 6,430.00
		: \$

JOANNE LEE

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CC6/EQI19017859/Kpa3q2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 19-11-2019	
			Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YM 9373A	Veh. Inspected	SLP 7148K	
Policy No.	DMCHHQ19-000091	Coverage (\$)	0.00	
Claim No.	DM19HO02781-JG	Excess (\$)	0.00	
Assign From		Assign Date	14/10/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HARRIER (A)	c.c	1986	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	ZSU600092173	Colour	METALLIC PEARL WHITE	
Odometer	32593	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/65 R17	YOKOHAMA	8 mm	
L/H Front Tyre	225/65 R17	YOKOHAMA	8 mm	
R/H Rear Tyre	225/65 R17	YOKOHAMA	3 mm	
L/H Rear Tyre	225/65 R17	YOKOHAMA	3 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/10/2019	Inspection Date	14/10/2019	
Survey held at	OPTIMA WERKZ PTE LTD 9A SERANGOON NORTH AVE 5 SINGAPORE 554500			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 7148K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR TAILGATE	BENT	2,126.40	1,712.02
1	REAR TAILGATE 'HARRIER' EMBLEM	NECESSARY	73.70	73.70
1	REAR TAILGATE INNER TRIM	SERVICEABLE	568.50	-
8	REAR TAILGATE INNER TRIM CLIPS @\$6.80	SERVICEABLE	54.40	-
1	REAR TAILGATE REVERSE LAMP RH	CRACKED	560.30	560.30
1	REAR TAILGATE INNER LOCK	DENTED	565.30	381.71
1	REAR TAILGATE RUBBER	DISTORTED / DENTED	441.30	399.11
1	REAR BUMPER	CRACKED	1,422.50	1,343.00
1	REAR BUMPER SIDE BRACKET LH	SERVICEABLE	85.30	-
1	REAR BUMPER SIDE BRACKET RH	SERVICEABLE	85.30	-
1	REAR BUMPER LOWER LIP COVER	DENTED	409.50	396.90
2	REAR WINDSCREEN SIDE MOULDING @\$38.60	NECESSARY	77.20	77.20
1	REAR WINDSCREEN LOWER MOULDING	NECESSARY	51.50	51.50
10	REAR BUMPER CLIPS @\$5.50	NECESSARY	55.00	55.00
1	REAR QUARTER PANEL LH (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR QUARTER PANEL RH (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR END PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
LESS 25% DISCOUNT			-1,644.05	-1,262.60
			4,932.15	3,787.84
SPECIAL NETT ITEMS				
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	350.00	200.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	60.00	40.00
			410.00	240.00
LABOUR				
LABOUR CHARGES TO REMOVE, REPAIR ,READJUST ,REPLACE REAR ACCIDENT AREAS & ETC.			800.00	500.00

Report Ref No. CC6/EQ19017859/Kpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR CHARGES TO REMOVE,REFIX REAR WINDSCREEN GLASS ,REAR WINDSCREEN SEALANT ,REAR WINDSCREEN MOULDING & ETC.		150.00	120.00
	LABOUR CHARGE TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC .BACK TO ORIGINAL CONDITIONS.		120.00	60.00
	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE ,REAR BUMPER ,REAR QUARTER PANEL LH,REAR QUARTER PANEL RH & ETC.INCLUSIVE OF THE REPAIR OF REAR QUARTER PANEL LH AND REAR QUARTER PANEL RH AND REAR END PANEL .		1,200.00	660.00
	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.		80.00	50.00
	TO TUFF KOTE & UNDERSEAL MATERIALS.		150.00	30.00
	TO DIAGNOSIS FAULTY CODE & RESET MEMORY.	NOT NECESSARY	120.00	-
			2,620.00	1,420.00
GRAND TOTAL			7,962.15	5,447.84
RECOMMENDED COST OF REPAIRS				5,447.84

Report Ref No. CC6/EQ19017859/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.