

183010

INS. CASE OWNER:

CC 4, 11/1901 7874, A

LKK:
IDAC:

Surveyor:

A/nnn

DOI:

ASSIGNMENT

10/10/19

Date / Time:

9/10/19

Registered in Merimen:

9/10/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SME 7997

Claim No.:

Name of Insured:

TAN LI KIANG

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II : \$5

D.O.A.:

9/10/19

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(VA) YES / NO

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SKA 2967 L

INSRS:
WSP:
Tel:
Liability:
RMKS:

VISION

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call GI:

After call ltr to GI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to GI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$5

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

6/2/2020

Confirm with:

Michelle

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

96d

If NO or B 28, Ass. Lia:

Repair Cost: (w/195)

\$5

9630.00

Loss of Rental (LOR):

\$5

-

(days)

Loss of Use (LOU):

\$5

720.00

(\$ 80 x 9 days)

Loss of Income (LOI):

\$5

-

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

(Tick only one)

GIA/LTA Search

\$5

36.45

Medical:

\$5

-

Disbursement:

\$5

120.00

(e.g. Tow/ Independent)

Legal Cost

\$5

-

Total:

\$5

10506.45

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$5

10506.45

Name 1:

Vision Autowork Pte Ltd

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

COPY SENT
26/2/2020

Atg

ASSIGNMENT

From: _____ Date: 10/10/19

Estimated Cost: _____

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To Inspect Vehicle No: SKA 2967L

at Workshop n/s Vision Autowork

of 8kaki Bukit Ave 4 #08-09 premier

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDA: Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 9 days Res.: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS up

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKA 2967L Yt Regn: 2011 Feb.

Type: ☒ Car ☐ M.Cycle ☐ Bus ☐ Van ☐ Lorry ☐ Taxi ☐ Prime Mover /

Truck / Trailer or

Make: Proton Exora c.c 1597

Colour: Red. A/C: Insured / Std / NI / NA

Sp. Reading 408016. T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: PLIFZ6YRRBF051281

Gen. Cond: ☒ Good ☐ Fair ☐ Poor ☐ Burnt

Steering: ☒ In order ☐ Jammed ☐ Leaked ☐ Burnt or

Brake: ☒ In order ☐ Jammed ☐ Leaked ☐ Burnt or

Modi: Nil / ☒ S/Rim ☐ STD A/Rim or

Tyre Size F: 205/55R16.

R: 205/55R16.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Antares.

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 10/10/19.

Survey held at Vision.

Des. of Damages: Frt / Rear / O/S ☒ N/S ☐ UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP A/g.
	45- \$9000 (Red \$ 28369.30 / 761)
	MV: 22K
	PV: 12.8K.
	Nett: 9.2K.

Date/Time, File Part to: ☐ : Prel. Report

1) ☐ : Final Report

Date/Time, File Return to:

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp. (\$)

☐ : Interview (\$)

☐ : Tech. Insp. (\$)

☐ : Witness (\$)

Survey Fee

Transportation

3 + PS. 31

Notes

Other

Other

Other

Repeat Form(s): _____

Long Term / J.B. 15/5

Vision Autowork Pte.Ltd.

(ROC / GST Reg. No. 201500371E)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:visionautowork@gmail.com

DATE : 09.10.19

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SKA2967L**
MODEL : **PROTON EXORA**
DATE OF ACCIDENT : 09.10.19
TIME OF ACCIDENT : 09:45:55HRS

PLIF26YPRBF051281

Stole

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>torn</i>	1	\$ 495.00	\$ 495.00
2	FRONT BUMPER LOWER GRILLE <i>new</i>	1	\$ 130.00	\$ 130.00
3	FRONT BUMPER FOGLAMP COVER <i>new</i>	2	\$ 70.00	\$ 140.00
4	FRONT BUMPER SIDE RETAINER <i>2nd</i>	2	\$ 55.00	\$ 110.00
5	FRONT BUMPER SPONGE <i>2 new</i>	1	\$ 150.00	\$ 150.00
6	FRONT BUMPER UNDER COVER GARNISH	1	\$ 180.00	\$ 180.00
7	RADIATOR GRILLE <i>2 new</i>	1	\$ 295.00	\$ 295.00
8	RADIATOR GRILLE LOGO	1	\$ 45.00	\$ 45.00
9	HEADLAMP <i>LH cracked</i>	2	\$ 590.00	\$ 1,180.00
10	FRONT FENDER LH <i>Distorted</i>	1	\$ 655.00	\$ 655.00
11	FRONT FENDER INNER GARNISH LH <i>new</i>	1	\$ 135.00	\$ 135.00
12	FRONT FENDER COWLING LH <i>2nd</i>	1	\$ 140.00	\$ 140.00
13	FRONT WINDSCREEN TOP MOULDING <i>new</i>	1	\$ 115.00	\$ 115.00
14	FRONT DOOR VIEW MIRROR LH <i>Right</i>	1	\$ 785.00	\$ 785.00
15	FRONT DOOR LH <i>Distorted</i>	1	\$ 1,390.00	\$ 1,390.00
16	FRONT DOOR OUTER MOULDING LH <i>new</i>	1	\$ 129.00	\$ 129.00
17	FRONT DOOR HINGE LH <i>Best</i>	2	\$ 45.00	\$ 90.00
18	FRONT DOOR CHECKER LH <i>new</i>	1	\$ 105.00	\$ 105.00
19	FRONT DOOR WEATHER STRIP LH <i>2</i>	1	\$ 110.00	\$ 110.00
20	FRONT DOOR FRAME WEATHER STRIP RH <i>1st</i>	1	\$ 165.00	\$ 165.00
21	FRONT DOOR WIRE HARNESS LH	1	\$ 765.00	\$ 765.00
22	FRONT DOOR GLASS CHANNEL LH <i>new</i>	1	\$ 95.00	\$ 95.00
23	FRONT DOOR INNER LOCK LH <i>2nd</i>	1	\$ 395.00	\$ 395.00
24	FRONT DOOR LOCK CATCH LH <i>new</i>	1	\$ 25.00	\$ 25.00
25	FRONT DOOR INNER TRIM BOARD LH <i>2nd</i>	1	\$ 690.00	\$ 690.00
26	FRONT DOOR REGULATOR LH <i>1st</i>	1	\$ 285.00	\$ 285.00
27	FRONT DOOR POWER WINDOW MOTOR LH <i>new</i>	1	\$ 565.00	\$ 565.00
28	FRONT DOOR SPEAKER LH <i>new</i>	1	\$ 135.00	\$ 135.00

590

1150

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SKA2967L**
 MODEL : **PROTON EXORA**
 DATE OF ACCIDENT : 09.10.19
 TIME OF ACCIDENT : 09:45:55HRS

29	FRONT QUARTER GLASS C/W MOULDING LH <i>new</i>	1	\$ 325.00		
30	FRONT DOOR PILLAR LH (OUTER) <i>Repair</i>	1	\$ 890.00	\$ 890.00	X
31	FRONT ABS SENSOR <i>NE new</i>	2	\$ 265.00	\$ 530.00	X
32	FRONT CROSSMEMBER <i>2 new</i>	1	\$ 1,320.00	\$ 1,320.00	X
33	FRONT DRIVESHAFT <i>1 new</i>	2	\$ 965.00	\$ 1,930.00	X
34	FRONT LINKAGE <i>LH Bent</i>	2	\$ 95.00	\$ 190.00	85
35	FRONT KNUCLE ARM <i>Bent</i>	2	\$ 490.00	\$ 980.00	✓
36	FRONT KNUCLE BEARING <i>new</i>	2	\$ 130.00	\$ 260.00	✓
37	FRONT WHEEL HUP <i>Damaged</i>	2	\$ 275.00	\$ 550.00	✓
38	FRONT SHOCK ABSORBER <i>Bent</i>	2	\$ 295.00	\$ 590.00	✓
39	FRONT LOWER ARM <i>Bent</i>	2	\$ 380.00	\$ 760.00	✓
40	FRONT STEERING RACK AND PINION <i>Not new</i>	1	\$ 1,495.00	\$ 1,495.00	X
41	REAR DOOR LH <i>Distorted</i>	1	\$ 1,280.00	\$ 1,280.00	✓
42	REAR DOOR OUTER MOULDING LH <i>new</i>	1	\$ 118.00	\$ 118.00	X
43	REAR DOOR HINGE LH <i>new</i>	2	\$ 45.00	\$ 90.00	X
44	FRONT DOOR CHECKER LH <i>new</i>	1	\$ 105.00	\$ 105.00	+
45	REAR DOOR WEATHER STRIP LH <i>new</i>	1	\$ 125.00	\$ 125.00	+
46	REAR DOOR LOCK CATCH LH <i>new</i>	1	\$ 25.00	\$ 25.00	+
47	REAR DOOR SPEAKER LH <i>new</i>	1	\$ 135.00	\$ 135.00	+
48	REAR DOOR INNER LOCK LH <i>new</i>	1	\$ 395.00	\$ 395.00	+
49	REAR DOOR GLASS REGULATOR GEAR MOTOR LH <i>new</i>	1	\$ 565.00	\$ 565.00	+
50	REAR DOOR GLASS REGULATOR GEAR LH <i>?</i>	1	\$ 285.00	\$ 285.00	X
51	REAR DOOR GLASS CHANNEL LH <i>new</i>	1	\$ 90.00	\$ 90.00	X
52	REAR DOOR INNER TRIM BOARD LH <i>new</i>	1	\$ 640.00	\$ 640.00	X
53	REAR DOOR FRAME WEATHER STRIP LH	1	\$ 105.00	\$ 105.00	X
54	REAR FENDER LH <i>Distorted</i>	1	\$ 985.00	\$ 985.00	✓
55	REAR FENDER GLASS MOULDING LH <i>new</i>	1	\$ 120.00	\$ 120.00	80
56	REAR ABS SENSOR LH <i>new</i>	1	\$ 265.00	\$ 265.00	+
57	REAR AXLE <i>new</i>	1	\$ 1,485.00	\$ 1,485.00	X
58	REAR SHOCK ABSORBER LH <i>new</i>	1	\$ 295.00	\$ 295.00	+
59	REAR WHEEL HUP <i>new</i>	1	\$ 275.00	\$ 275.00	+

TOTAL PRICE \$ 26,377.00
 LESS 10% \$ 2,637.70
SUB TOTAL PRICE \$ 23,739.30

9205
 828450

TO : AIG MOTOR CLAIMS DEPTS
 VEHICLE NO : SKA2967L
 MODEL : PROTON EXORA
 DATE OF ACCIDENT : 09.10.19
 TIME OF ACCIDENT : 09:45:55HRS

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIP (SET) <i>Na</i>	1	\$ 80.00	\$ 80.00
2	FRONT BUMPER UNDER COVER GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
3	FRONT BUMPER LED LIGHT (SET) (SPECIAL TYPE) <i>new</i>	1	\$ 280.00	\$ 280.00
4	RADIATOR GRILLE CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
5	FRONT FENDER INNER GARNISH CLIP LH (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
6	FRONT FENDER COWLING CLIP (SET) <i>Na</i>	1	\$ 50.00	\$ 50.00
7	FRONT WINDSCREEN SEALANT <i>3 MP</i>	1	\$ 80.00	\$ 80.00
8	FRONT WINDSCREEN INNER SHIELD <i>new</i>	1	\$ 60.00	\$ 60.00
9	FRONT WHEEL RIM <i>let</i>	2	\$ 650.00	\$ 1,300.00
10	FRONT WHEEL TYRE <i>let Front</i>	2	\$ 380.00	\$ 760.00
11	REAR FENDER SEALANT LH <i>2</i>	1	\$ 150.00	\$ 150.00
12	REAR FENDER GLASS SEALANT LH <i>new</i>	1	\$ 150.00	\$ 150.00
13	REAR FENDER GLASS INNER SEAL LH	1	\$ 80.00	\$ 80.00
14	REAR WHEEL RIM LH <i>let</i>	1	\$ 850.00	\$ 850.00
15	REAR WHEEL TYRE LH <i>new</i>	1	\$ 380.00	\$ 380.00
16	WHEEL CAP (SET) <i>2</i>	1	\$ 120.00	\$ 120.00
17	POWER STEERING OIL <i>1</i>	1	\$ 180.00	\$ 180.00
18	BRAKE OIL	1	\$ 30.00	\$ 30.00

1060 TOTAL \$ 4,730.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD, CUT, ADJUST, KNOCK	\$ 2,800.00	1000
2	TO SPRAY PAINT	\$ 2,400.00	1200
3	TUFF COAT	\$ 250.00	60
4	WIRING, BULB CHECKING	\$ 180.00	30
5	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	x
6	REMOVE & REFIX FRONT WINDSCREEN	\$ 120.00	x
7	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 650.00	220
8	TO PRESS FRONT WHEEL BEARING	\$ 80.00	x

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SKA2967L**
 MODEL : **PROTON EXORA**
 DATE OF ACCIDENT : 09.10.19
 TIME OF ACCIDENT : 09:45:55HRS

9	REMOVE AND REFIX POWER STEERING RACK AND PINION	\$ 350.00	X
10	REMOVE & REFIX FRONT QUARTER GLASS RH	\$ 80.00	40
11	TRANSFER FRONT DOOR MECHANISM	\$ 80.00	✓
12	TRANSFER REAR DOOR MECHANISM	\$ 80.00	✓
13	REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 650.00	X
14	FOUR WHEEL ALIGNMENT	\$ 120.00	80.
15	RESET ABS LIGHT	\$ 350.00	X
16	CONDUCT WATER LEAKAGE TEST	\$ 180.00	X
17	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL ²⁷⁹⁰ \$ **8,900.00**

ESTIMATE REPORT

TOTAL PARTS COST : \$ 28,469.30
 TOTAL LABOUR COST : \$ 8,900.00
 TOTAL REPAIR COST : \$ 37,369.30

Adrian Lim
L/S 10/10/19.

09 Days.

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
 PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY
 SERVICE ADVISOR
 ABBY
 HP : 9856 4815

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to negotiation
- Third party survey is on a "without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be notified and is subject to final approval from insurance Company

Acknowledged by Repairer:
 Signature:
 Date:

Nett Value : 9K

SS.

total 12134.50

L/S: 9K (Nett Value)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC
684B

Owner ID:

Vehicle Details

Vehicle No.:

5KA2967L

Vehicle to be Exported:

No

Intended Deregistration Date:

09 Oct 2019

Vehicle Make:

PROTON

Vehicle Model:

EXORA1.6AMLM

Primary Colour:

Red

Manufacturing Year:

2010

Engine No.:

54PHQX7564

Chassis No.:

PL1FZ6YRRBF051281

Maximum Power Output:

93.0 kW (124 bhp)

Open Market Value:

\$14,119.00

Original Registration Date:

15 Feb 2011

First Registration Date:

15 Feb 2011

Transfer Count:

0

Actual ARF Paid:

\$14,119.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

14 Feb 2021

PARF Rebate Amount:

\$7,765.00

Intended COE Rebate Details

COE Expiry Date:

14 Feb 2021

COE Category:

A - Car (1600cc & below)

COE Period(Years):

10

QP Paid:

\$37,124.00

COE Rebate Amount:

\$5,005.00

Total Rebate Amount:

\$12,770.00

15/02/2011

\$ 10030.00

The information contained herein is correct as at 09 Oct 2019

OK



CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)


proton exora

Price Range

Depreciation

Year Reg

Vehicle Type


[sgCarMart Connect](#)
[Home](#) » [Used Cars](#) » [Direct Owners](#) » Proton Exora 1.6A M-Line

Proton Exora 1.6A M-Line

[Overview](#)
[Financial](#)
[Insurance](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)
[DIRECT OWNER](#)

Price \$22,800

Depreciation \$11,630 /yr
View models with similar depre

Reg Date 15-Feb-2011
(1yr 4mths 5days COE left)

Mileage N.A.

Manufactured 2010

Road Tax \$742 /yr

Transmission Auto

Dereg Value \$12,790 as of today (change)

OMV \$14,119

COE \$37,124

ARF \$14,119

Engine Cap 1,597 cc

Power 93.0 kW (124 bhp)

Curb Weight 1,422 kg

No. of Owners 1

Type of Vehicle MPV

Features

View specs of the Proton Exora (2009-2015)

Description

No Repairs Needed, Excellence Condition! No Gimmick, Smooth And Quite Engine.

Category

PARF Car, Direct Owner Sale

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. [Find out more.](#)



Car Valuation - Free

Find out the market value of your existing car for free. [Get started!](#)



NO IMAGE AVAILABLE

100% FREE
PAPERWORK
SUPPORT FOR
BOTH BUYER
& SELLER

[Shortlist](#)
[Compare](#)
[Add note](#)
[Report Error](#)
[More Actions](#)

Seller Information

Contact Person(s)

Kayden

Enquiry

[Contact Seller](#)

ESSENTIAL TRANSACTION FORMS

» Indemnity form

» Sales agreement

» Receipt

» Hand-over form

» Ownership Transfer



GET HELP WITH
PAPERWORK



sgCarMart Connect handles your transaction paperwork - send us your completed Sales Agreement, and we'll help with **Car Loans, Insurance, Payments & Ownership Transfer**. FREE for all sgCarMart Advertised Vehicles.

[upload your Sales Agreement](#)

[Read our 8 Step Guide for Direct Buyers & Sellers](#)

Posted on: 09-Oct-2019 | Last Updated on: 09-Oct-2019

Upfront Payment

Transfer Fee \$25

Down Payment \$6,840 (change)

Maximum 70% Loan

1st Instalment \$1,037

Based on 2.99% interest rate

Insurance \$1,005 onwards

Not at fault? No upfront payment required! (Get a quote)
Quote assumes a standard profile. "Get a quote" No exact figure.

Total Upfront Payment \$8,907

Check with seller for exact figure

Powered by



Compare



(New 5-yr COE)

Cheapest In The Market! Comfortable And Spacious MPV! Flexible Loan Package And Trade-In Available! Call Us Now.

PREMIUM AD

Posted: 30-Aug-2019 Tags: 2009 Proton Exora, 2009 proton exora, Proton Exora, proton exora, Proton, Exora, exora, Used Proton



Proton Exora 1.6A M-Line (New 5-yr COE)

\$33,900

\$6,770 /yr

01-Oct-2009

1,597 cc

-

MPV

Available

\$0 Down Payment. 100% Loan Approval. Excellent Condition Most Affordable 7 Seater MPV! Low Mileage, Good Condition, Clean Interior, No Repair Needed. Buy With Trust And Confidence. Trade In Welcome.

Posted: 24-Aug-2019 Tags: 2009 Proton Exora, 2009 proton exora, Proton Exora, proton exora, Proton, Exora, exora, Used Proton



Proton Exora 1.6A M-Line (New 5-yr COE)

\$34,800

\$6,950 /yr

26-Oct-2009

1,597 cc

86,000 km

MPV

Available

1st Owner, 1 Year In House Warranty, Full/ High Loan Available, Free 2 x Servicing, Warranty Not By 3rd Party Workshop, Price Stated Above Is Actual Selling Price, New Paintwork, Fully Refurbished, Guarantee Accident Free, Sta Or Vicom Evaluation Are Welcome, Purcha...

Carway

Posted: 06-Oct-2019 Tags: 2009 Proton Exora, 2009 proton exora, Proton Exora, proton exora, Proton, Exora, exora, Used Proton



Proton Exora 1.6M M-Line (New 5-yr COE)

\$28,800

\$5,750 /yr

25-Jan-2010

1,597 cc

123,000 km

MPV

Available

Only 1 Malay Owner With 2 Cars.Full Loan Available. Wife Drive This For Kids Only. Manual Most Reliable And Fuel Economical. Comes With New Paint And Warranty. Must Drive To Feel It Condition. Kindly Call For Viewing.

Posted: 26-Aug-2019 Tags: 2010 Proton Exora, 2010 proton exora, Proton Exora, proton exora, Proton, Exora, exora, Used Proton



Sell your Car for \$3,000 More

Owners who sell with Quotz typically get up to \$3,000 above market value. Sell your Car for the Highest Price Today.

Find out more!



Proton Exora 1.6A M-Line (New 10-yr COE)

\$44,000

\$4,400 /yr

26-Jan-2010

1,597 cc

150,000 km

MPV

Available

Cheapest MPV You Can Find In SG! Comes With Rear Aircon Blowers Better Than Jap MPV! Low Maintenance And Consumption! Free Grooming Package! High Loan And High Trade In Available! \$29000 For New 5 Years COE! Call For Appointment Now!

Posted: 04-Oct-2019 Tags: 2010 Proton Exora, 2010 proton exora, Proton Exora, proton exora, Proton, Exora, exora, Used Proton



Proton Exora 1.6A M-Line (OPC) (New 10-yr COE)

\$47,800

\$4,780 /yr

02-Mar-2010

1,597 cc

120,000 km

MPV

Available

Well Maintain By Previous Owner. Accident-Free, Good Fuel Efficient 7 Seater Mpv. Low Mileage. High Loan Available Or In House Loan Rate Reasonable

Posted: 06-Sep-2019 Tags: 2010 Proton Exora, 2010 proton exora, Proton Exora, proton exora, Proton, Exora, exora, Used Proton



Proton Exora 1.6A M-Line

\$13,999

N/A

23-Mar-2010

1,597 cc

-

MPV

Available

Engine Just Overhauled. Road Tax Paid Until COE Expires. Good For Future COE Renewal. Factory Fitted 2nd And 3rd Rows Aircon. 4 x New Made In Japan Tires.

DIRECT OWNER

Posted: 23-Sep-2019 Tags: 2010 Proton Exora, 2010 proton exora, Proton Exora, proton exora, Proton, Exora, exora, Used Proton



Proton Exora 1.6A M-Line (COE till 09/2029)

\$42,800

\$4,290 /yr

27-Jul-2010

1,597 cc

-

MPV

Available

Can Do Zero Downpayment. 100% Full Loan. Easy Approval Bank Loan And Inhouse Loan. Mthly Fr. \$400-\$900. Bad Credit Are Welcome. All Car Comes With Warranty. Low Mileage. Can Convert To PHV. Viewing 10am-10pm Everyday. Call To Confirm Appointment. Loan Am...

Posted: 19-Jun-2019 Tags: 2010 Proton Exora, 2010 proton exora, Proton Exora, proton exora, Proton, Exora, exora, Used Proton



Proton Exora 1.6A M-Line

\$22,800

\$11,680 /yr

15-Feb-2011

1,597 cc

-

MPV

Available

No Repairs Needed, Excellence Condition! No Gimmick. Smooth And Quite Engine.

DIRECT OWNER

Posted: 19-Oct-2019 Tags: 2011 Proton Exora, 2011 proton exora, Proton Exora, proton exora, Proton, Exora, exora, Used Proton

Save this search criteria, to get email alerts whenever a match is found.

Save Search

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

MARKETLISTED HOTTOPIC

Compare

one car classified for parallel import car, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports 24, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark info & car

PRE-REPAIR INSPECTION REQUEST – SKA2967L vs SME795J (OI) on D.O.A: 09/10/2019

From: Hor, Yinrul
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, Subramaniam, Divy
Sent: 10/9/2019 4:07:27 PM
Attachments: 09102019153214.pdf

Hi,

Please refer to the enclosed request from **Vision Autowork**.
Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.
Kindly assist to assign **ADRIAN LING** as Single Joint Expert as requested.

Thanks & Regards,

Hor Yin Rul (Viviane)
AIG
FNOL Adjuster I
Singapore FNOL | Claims Operations – Auto

Tel: 8001206556 | Ext: 1002208
Yinrul.Hor@aig.com | www.aig.sg

q.sang 10/10/19
p: Michelle
VNT

From: visionautowork@gmail.com [mailto:visionautowork@gmail.com]
Sent: Wednesday, October 09, 2019 4:05 PM
To: Hor, Yinrul
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divyashni
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SME795J AND SKA2967L ON 09/10/2019

Dear All,

Thanks for reply.

Please arrange LKK AUTO CONSULTANTS PTE LTD -ADRIAN LING to survey the above vehicle.

Michelle

From: Hor, Yinrul
Sent: Wed, 9 Oct 2019 07:52:30 +0000
To: visionautowork@gmail.com
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, Subramaniam, Divyashni
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SME795J AND SKA2967L ON 09/10/2019

Without Prejudice

Your Reference : SKA2967L
Our Reference : SME795J

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Junny Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiang	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd

Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marek Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufik	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Keneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rul (Viviane)
AIG
FNOL Adjuster |
Singapore FNOL | Claims Operations – Auto

Tel: 8001206556 | Ext: 1002208
Yinrul.Hor@aig.com | www.aig.sg

From: Vision Autowork [<mailto:visionautowork@gmail.com>]
Sent: Wednesday, October 09, 2019 3:37 PM
To: Hor, Yinrul; Lim, Sheng Yang; Abu Kassim, Noor Mariesa
Subject: [EXTERNAL] SKA2967L (Pre-inspection) / Your vehicle : SME795J

This message is from an external sender; be cautious with links and attachments.

Dear person in charge,

Please refer to attach file and arrange for pre-inspection.
Hope we can do Direct Settle and please provide the surveyor firm or surveyor name list to conduct the joint pre-repair survey as a single joint expert

**** PLEASE ADVISE LIABILITY and GIA report will e-mail to your once receive from my client****

Thank You

Yours faithfully,

Michelle
Hp: 9856 4815

8 Kaki Bukit Avenue 4,
#08-09, Premier @ Kaki Bukit,
Singapore 415875
Tel: 6341 6789
Fax: 6341 6778

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

View Received Message

This mail is associated with :

***SKA2967L (8238928311SG)
[SME795J]**

TP
AJIR BTE ABDUL SALAM
Oct 9 2019 9:00AM
[TAN LI KIANG]
Vision Autowork Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 05/02/2020 19:46 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$10506.45) - SKA2967L - Claim Handler: Chan, Kian-Meng

Approved:10506.45.

DOCUMENTS SUMMARY

There are no documents.

VISION AUTOWORK PTE. LTD.

8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, S'PORE 415875

Tel: 6341 6789 Fax: 6341 6778

Co. Reg. No. : 201500371E

Authorization To Act

I, Ajir Bte Abdul Salam ("the third party claimant") of
Blk 111 Bedok North Road # 13-323 Singapore 460111
(address), owner of SKA 2967L (vehicle no.) hereby
authorize vision Autowork Pte. Ltd.
("the workshop") to act for me with respect to my claim for repair
costs and/or rental and/or loss of use ("claim") for my vehicle
no. SKA 2967L that was damaged pursuant to the accident which
occurred on 09/10/2019 (date) along Junction of East Coast Park
Service Road and Marine Parade Flyover (ECP) (location) involving
vehicle no/s SME 795 J
("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that
they deem fit and the workshop is further authorized to receive payment further to
settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on
a without prejudice and without admission of liability basis in so far as the
driver/owner/insurers of the other vehicle/s is concerned.

Dated this 09 day of 10 (month) 20 19 (year)



Signed by "the third party claimant"



Signed by "the workshop"

VISION AUTOWORK PTE. LTD.
8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, S'PORE 415875
Tel: 6341 6789 Fax: 6341 6778
Co. Reg. No. : 201500371E

Letter of Authorisation & Indemnity

Accident Involving Vehicle no. SKA2967L and SME795J On 09/10/2019

At Junction of East Coast Park Service Road and Marine Parade Flyover (ECP)

1. I/We, the owner of vehicle no. SKA2967L hereby instruct and authorize Vision Autowork Pte Ltd. ("the workshop") to commence repairs to the said vehicle. Pending the outcome of my/our claim against the third party, I/we forthwith pay you the sum of \$_____ being refundable deposit of the repair to my/our said vehicle.
2. You are further authorized to appoint solicitors on my/our behalf and give the solicitors full instructions as if the appointment is made and instructions are given by me/us with respect to the conduct of my/our claim against the third party driver and/or his insurers including if necessary, to commence legal proceedings in court in my/our name against the third party.
3. You have my/our full authority to instruct my/our solicitors to negotiate a settlement with the third party and/or his insurers on such terms as you deem fit.
4. Upon resolving my/our claim, you are authorized to agree with my/our solicitors on the amount of their professional costs and disbursement for acting for me/us and to receive payment of the balance of the settlement sum on my/our behalf directly into your account. In the event that my/our claim or legal costs of the third party as well as the professional costs and disbursements of my/our solicitors notwithstanding that my/our solicitors were appointed by you on our behalf.
5. I/we also hereby instruct and authorise you deduct directly from the claim monies received from the third party all outstanding balances that are still owing to you, namely the balance of repair costs and rental of substitute vehicles.
6. In the event that I/we am/are required to attend at my/our solicitors office or to attend court in connection with my/our claim, I/we shall render full co-operation.
7. In the event that my/our claim against the third party and/or his insurers is not successful or cannot be proceeded with and/or if any Judgement or settlement is not honoured or satisfied by the third party, I/we authorise you to revert the claim against my/our own insurers for the cost of repairs and any other losses recoverable under my/our policy of insurance. In this respect, I/we understand and accept that the excess amount applicable under policy of insurance shall be borne by me/us.
8. If for whatever reasons, my/our insurers reject my/our claim for indemnity for the cost of repairs and/or any other losses recoverable under the policy of insurance or make an offer to pay less than the amount claimed by you, I/we agree and undertake to pay the full amount of your repair bill and survey fees and any other expenses reasonably incurred on my/our behalf or to pay you the difference in amount, as the case may be.
9. I/we shall keep you informed of any correspondences and/or summons that I may receive due to this action agreeing to pay or receive any monies due to this claim.

Dated this 09 day of 10 2019

Signature of vehicle owner Aji



Witnessed by:

Name - Aji Bte Akbul Salam

IC No : 5215 06 843

(Company stamp, if applicable)

Address: BLK 111 Bedok North Road

#13-323 Singapore 460111

Tel: 9722 0676

Ashmy

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Oct 2019 Edit Reg		09 Oct 2019 00:00 Edit Adj Rpt	S\$9,000.00 Edit Estimates	S\$9,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	TAN LI KIANG, ID: S7014693B								
Main Claimant:	AJIR BTE ABDUL SALAM, ID: S2150684B								
Vehicle Reg. No.:	SKA2967L	Date of Loss:	09/10/2019 09:00 - :59 [103 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 8238928311SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SME795J	Policy No. (Claimant):	DMPPHQ19-001124						
		Excess:							
Repairer:	Vision Autowork Pte Ltd (HQ) 8 KAKI BUKIT AVE 4, #08-09 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 6341 6789								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng]								
Claimant's Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 21/10/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG_EXPRESS (05/02/2020): Alert - Adj Mandate Approved (S\$10506.45) - SKA2967L - Claim Handler: Chan, Kian...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKA2967L (82389283115G)
[SME795J]**

TP

AJIR BTE ABDUL SALAM

Oct 9 2019 9:00AM

[TAN LI KIANG]

Vision Autowork Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page			☒		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print			
1	(Draft)	Third Party Express Settlement - Payment Breakdown															Edit			
															1 per page			☒		
Assessment Reports															1 per page			☒		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print			
1	29/11/19 10:02	Adjuster Immediate Advice															Load HTM			
															3 per page			☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print			
1	25/11/19 17:34	General View															Load JPG ☒			
2	25/11/19 17:34	General View															Load JPG ☒			
3	25/11/19 17:34	General View															Load JPG ☒			
4	25/11/19 17:34	General View															Load JPG ☒			
5	25/11/19 17:34	General View															Load JPG ☒			
6	25/11/19 17:34	General View															Load JPG ☒			
7	25/11/19 17:34	General View															Load JPG ☒			
8	25/11/19 17:34	General View															Load JPG ☒			
9	25/11/19 17:34	General View															Load JPG ☒			
10	25/11/19 17:34	General View															Load JPG ☒			
11	25/11/19 17:34	General View															Load JPG ☒			
12	25/11/19 17:34	General View															Load JPG ☒			
13	25/11/19 17:34	General View															Load JPG ☒			
14	25/11/19 17:34	General View															Load JPG ☒			
15	25/11/19 17:34	General View															Load JPG ☒			
16	25/11/19 17:34	General View															Load JPG ☒			
17	25/11/19 17:34	General View															Load JPG ☒			
18	25/11/19 17:34	General View															Load JPG ☒			
19	25/11/19 17:34	General View															Load JPG ☒			
20	25/11/19 17:34	General View															Load JPG ☒			
21	25/11/19 17:34	General View															Load JPG ☒			
22	25/11/19 17:34	General View															Load JPG ☒			
23	25/11/19 17:34	General View															Load JPG ☒			
24	25/11/19 17:34	General View															Load JPG ☒			
25	25/11/19 17:34	General View															Load JPG ☒			
26	25/11/19 17:34	General View															Load JPG ☒			
27	25/11/19 17:34	General View															Load JPG ☒			
28	25/11/19 17:34	General View															Load JPG ☒			
29	25/11/19 17:34	General View															Load JPG ☒			
30	25/11/19 17:34	General View															Load JPG ☒			
31	25/11/19 17:34	General View															Load JPG ☒			
32	25/11/19 17:34	General View															Load JPG ☒			
33	25/11/19 17:34	General View															Load JPG ☒			
34	25/11/19 17:34	General View															Load JPG ☒			
35	25/11/19 17:34	General View															Load JPG ☒			
36	25/11/19 17:35	Reinspection Photo															Load JPG ☒			

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
37	25/11/19 17:35	Reinspection Photo		☒
38	25/11/19 17:35	Reinspection Photo		☒
39	25/11/19 17:35	Reinspection Photo		☒
40	25/11/19 17:35	Reinspection Photo		☒
41	25/11/19 17:35	Reinspection Photo		☒
42	25/11/19 17:35	Reinspection Photo		☒
43	25/11/19 17:35	Reinspection Photo		☒
44	25/11/19 17:35	Reinspection Photo		☒
45	25/11/19 17:35	Reinspection Photo		☒
46	25/11/19 17:35	Reinspection Photo		☒
47	25/11/19 17:35	Reinspection Photo		☒
48	25/11/19 17:35	Reinspection Photo		☒
49	25/11/19 17:35	Reinspection Photo		☒
50	25/11/19 17:35	Reinspection Photo		☒
51	25/11/19 17:35	Reinspection Photo		☒
52	25/11/19 17:35	Reinspection Photo		☒
53	25/11/19 17:35	Reinspection Photo		☒
54	25/11/19 17:35	Reinspection Photo		☒
55	25/11/19 17:35	Reinspection Photo		☒
56	25/11/19 17:35	Reinspection Photo		☒
57	25/11/19 17:35	Reinspection Photo		☒
58	25/11/19 17:35	Reinspection Photo		☒
59	25/11/19 17:35	Reinspection Photo		☒
60	25/11/19 17:35	Reinspection Photo		☒
61	25/11/19 17:35	Reinspection Photo		☒
62	25/11/19 17:35	Reinspection Photo		☒
63	25/11/19 17:35	Reinspection Photo		☒
64	25/11/19 17:35	Reinspection Photo		☒
65	25/11/19 17:35	Reinspection Photo		☒
66	25/11/19 17:35	Reinspection Photo		☒
67	25/11/19 17:35	Reinspection Photo		☒
68	25/11/19 17:35	Reinspection Photo		☒
69	25/11/19 17:35	Reinspection Photo		☒
70	25/11/19 17:35	Reinspection Photo		☒
71	25/11/19 17:35	Reinspection Photo		☒
72	25/11/19 17:35	Reinspection Photo		☒
73	25/11/19 17:35	Reinspection Photo		☒
74	25/11/19 17:35	Reinspection Photo		☒
75	25/11/19 17:35	Reinspection Photo		☒
76	25/11/19 17:35	Reinspection Photo		☒
77	25/11/19 17:35	Reinspection Photo		☒
78	25/11/19 17:35	Reinspection Photo		☒
79	25/11/19 17:35	Reinspection Photo		☒
80	25/11/19 17:35	Reinspection Photo		☒
81	25/11/19 17:35	Reinspection Photo		☒
82	25/11/19 17:35	Reinspection Photo		☒
83	25/11/19 17:35	Reinspection Photo		☒
84	25/11/19 17:35	Reinspection Photo		☒
85	25/11/19 17:35	Reinspection Photo		☒
86	25/11/19 17:35	Reinspection Photo		☒
87	25/11/19 17:35	Reinspection Photo		☒
88	25/11/19 17:35	Reinspection Photo		☒
89	25/11/19 17:35	Reinspection Photo		☒
90	25/11/19 17:35	Reinspection Photo		☒
91	25/11/19 17:35	Reinspection Photo		☒
92	25/11/19 17:35	Reinspection Photo		☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
93	25/11/19 17:35	Reinspection Photo		☒
94	25/11/19 17:35	Reinspection Photo		☒
95	25/11/19 17:35	Reinspection Photo		☒
96	25/11/19 17:35	Reinspection Photo		☒
97	25/11/19 17:35	Reinspection Photo		☒
98	25/11/19 17:35	Reinspection Photo		☒
99	25/11/19 17:35	Reinspection Photo		☒
100	25/11/19 17:35	Reinspection Photo		☒
101	25/11/19 17:35	Reinspection Photo		☒
102	25/11/19 17:35	Reinspection Photo		☒
103	25/11/19 17:35	Reinspection Photo		☒
104	25/11/19 17:35	Reinspection Photo		☒
105	25/11/19 17:35	Reinspection Photo		☒
106	25/11/19 17:35	Reinspection Photo		☒
107	25/11/19 17:35	Reinspection Photo		☒
108	25/11/19 17:35	Reinspection Photo		☒
109	25/11/19 17:35	Reinspection Photo		☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/10/19 14:22	EMAIL FROM AIG DD 09102019		
2	10/10/19 14:22	TP GIA REPORT		
3	28/11/19 09:21	TP_ESTIMATE-MARKED-FINAL		
4	28/11/19 14:42	LOD		
5	28/11/19 14:42	LTA/GIA Search Fee		
6	28/11/19 14:42	TOWING INV		
7	02/03/20 09:17	WORKSHOP INVOICE		
8	02/03/20 09:17	AUTHORISATION TO ACT FORM		
9	02/03/20 09:17	Release Voucher		
10	02/03/20 09:17	LETTER TO OI		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	11/10/19 15:08	OI GIA REPORT		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SME795J (Insd veh)	Model:	PROTON EXORA 1.6 (M)
	SKA2967L (TP veh)		
Date of Accident:	09/10/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	40,298.13
Final Repair Cost	:	\$	9,630.00
Loss of Use	:	\$	720.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	36.45
Others:Towing Fee	:	\$	120.00
	:	\$	
Final Settlement Sum	:	\$	10,506.45

9.00 days at \$80.00 per day
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____100_____(%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____(%) Assessed Liability (*): _____(%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Vision Autowork Pte Ltd	:	\$ 10,506.45
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

02 Mar
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19017874/ADS3Q2

Date: 02/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant

Vehicle No : SKA2967L

Insured Vehicle No : SME795J

Date of Loss: 09/10/2019

Nature of Claim: TP

Claim No: 8238928311SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKA2967L

Make & Model: PROTON EXORA, 1.6 (M)

Engine No: S4PHQX7564

Reg. Date: 15/02/2011 (Man. Year: 2010)

Chassis No: PL1FZ6YRRBF051281

Colour: Red

Odometer: 408016 km

Engine Capacity: 1597 cc

Market Value/New Car

N/A

Price:

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size:

205/55 R16

Front Left Side: Antares 6 mm

Rear Left Side:

Antares 6 mm

Front Right Side: Antares 6 mm

Rear Right Side:

Antares 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,761.80	9,344.50	19,417.30	67.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,900.00	2,790.00	6,110.00	68.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	37,661.80	12,134.50	25,527.30	67.78
Approved Total (Overridden) (\$\$)		9,000.00		
(\$\$)	37,661.80	9,000.00	28,661.80	76.10
+ GST 7.00/7.00% (\$\$)	2,636.33	630.00	2,006.33	76.10
Nett Amount (\$\$)	40,298.13	9,630.00	30,668.13	76.10
+ Loss of Use (9.0 x S\$80.00/day) (\$\$)		720.00		
+ Doc/Search Fee (\$\$)		36.45		
+ Other Costs (\$\$)		120.00		
Nett Liability (\$\$)		10,506.45		

INSPECTION

Date of Assignment: 09/10/2019

Date Inspected: 10/10/2019 Inspected At:

Vision Autowork Pte Ltd (HQ)
8 KAKI BUKIT AVE 4., #08-09
PREMIER @ KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 9.0 days

Adjuster: ADRIAN LING**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	495.00 FL	*495.00 FL
2	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	130.00 FL	*- FL
3	2		*FRONT BUMPER FOGLAMP COVER	Not Necessary	140.00 FL	*- FL
4	2		*FRONT BUMPER SIDE RETAINER	Damaged	110.00 FL	*110.00 FL
5	1		*FRONT BUMPER SPONGE	Not Necessary	150.00 FL	*- FL
6	1		*FRONT BUMPER UNDER COVER GARNISH	Not Necessary	180.00 FL	*- FL
7	1		*RADIATOR GRILLE	Not Necessary	295.00 FL	*- FL
8	1		*RADIATOR GRILLE LOGO	Not Necessary	45.00 FL	*- FL
9	1		*HEADLAMP	N/S Cracked	1,180.00 FL	*590.00 FL
10	1		*FRONT FENDER LH	Distorted	655.00 FL	*655.00 FL
11	1		*FRONT FENDER INNER GARNISH LH	Not Necessary	135.00 FL	*- FL
12	1		*FRONT FENDER COWLING LH	Deformed	140.00 FL	*140.00 FL
13	1		*FRONT WINDSCREEN TOP MOULDING	Not Necessary	115.00 FL	*- FL
14	1		*FRONT DOOR VIEW MIRROR LH	Repair	785.00 FL	*- FL
15	1		*FRONT DOOR LH	Distorted	1,390.00 FL	*1,150.00 FL
16	1		*FRONT DOOR OUTER MOULDING LH	Not Necessary	129.00 FL	*- FL
17	2		*FRONT DOOR HINGE LH	Bent	90.00 FL	*90.00 FL
18	1		*FRONT DOOR CHECKER LH	Not Necessary	105.00 FL	*- FL
19	1		*FRONT DOOR WEATHER STRIP LH	Not Necessary	110.00 FL	*- FL
20	1		*FRONT DOOR FRAME WEATHER STRIP	Not Necessary	165.00 FL	*- FL
21	1		*FRONT DOOR WIRE HARNESS LH	Not Necessary	765.00 FL	*- FL
22	1		*FRONT DOOR GLASS CHANNEL LH	Not Necessary	95.00 FL	*- FL
23	1		*FRONT DOOR INNER LOCK LH	Damaged	395.00 FL	*395.00 FL
24	1		*FRONT DOOR LOCK CATCH LH	Not Necessary	25.00 FL	*- FL
25	1		*FRONT DOOR INNER TRIM BOARD LH	Not Necessary	690.00 FL	*- FL
26	1		*FRONT DOOR REGULATOR LH	Not Necessary	285.00 FL	*- FL
27	1		*FRONT DOOR POWER WINDOW MOTOR LH	Not Necessary	565.00 FL	*- FL
28	1		*FRONT DOOR SPEAKER LH	Not Necessary	135.00 FL	*- FL
29	1		*FRONT QUARTER GLASS C/W MOULDING LH	Not Necessary	325.00 FL	*- FL
30	1		*FRONT DOOR PILLAR LH (OUTER)	Repair	890.00 FL	*- FL
31	2		*FRONT ABS SENSOR	Not Necessary	530.00 FL	*- FL
32	1		*FRONT CROSSMEMBER	Not Necessary	1,320.00 FL	*- FL
33	2		*FRONT DRIVESHAFT	Not Necessary	1,930.00 FL	*- FL
34	1		*FRONT LINKAGE	N/S Bent	190.00 FL	*95.00 FL
35	2		*FRONT KNUCKLE ARM	Bent	980.00 FL	*980.00 FL
36	2		*FRONT KNUCKLE BEARING	Necessary	260.00 FL	*260.00 FL
37	2		*FRONT WHEEL HUP	Damaged	550.00 FL	*550.00 FL
38	2		*FRONT SHOCK ABSORBER	Bent	590.00 FL	*590.00 FL
39	2		*FRONT LOWER ARM	Bent	760.00 FL	*760.00 FL
40	1		*FRONT STEERING RACK AND PINION	Not Necessary	1,495.00 FL	*- FL
41	1		*REAR DOOR LH	Distorted	1,280.00 FL	*1,280.00 FL
42	1		*REAR DOOR OUTER MOULDING LH	Not Necessary	118.00 FL	*- FL
43	2		*REAR DOOR HINGE LH	Not Necessary	90.00 FL	*- FL
44	1		*FRONT DOOR CHECKER LH	Not Necessary	105.00 FL	*- FL
45	1		*REAR DOOR WEATHER STRIP LH	Not Necessary	125.00 FL	*- FL
46	1		*REAR DOOR LOCK CATCH LH	Not Necessary	25.00 FL	*- FL
47	1		*REAR DOOR SPEAKER LH	Not Necessary	135.00 FL	*- FL
48	1		*REAR DOOR INNER LOCK LH	Not Necessary	395.00 FL	*- FL
49	1		*REAR DOOR GLASS REGULATOR GEAR MOTOR LH	Not Necessary	565.00 FL	*- FL
50	1		*REAR DOOR GLASS REGULATOR GEAR LH	Not Necessary	285.00 FL	*- FL
51	1		*REAR DOOR GLASS CHANNEL LH	Not Necessary	90.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*REAR DOOR INNER TRIM BOARD LH	Not Necessary	640.00 FL	*- FL
53	1		*REAR DOOR FRAME WEATHER STRIP LH	Not Necessary	105.00 FL	*- FL
54	1		*REAR FENDER LH	Distorted	985.00 FL	*985.00 FL
55	1		*REAR FENDER GLASS MOULDING LH	Necessary	120.00 FL	*80.00 FL
56	1		*REAR ABS SENSOR LH	Not Necessary	265.00 FL	*- FL
57	1		*REAR AXLE	Not Necessary	1,485.00 FL	*- FL
58	1		*REAR SHOCK ABSORBER LH	Not Necessary	295.00 FL	*- FL
59	1		*REAR WHEEL HUP	Not Necessary	275.00 FL	*- FL
60	1		*SET FRONT BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
61	1		*SET FRONT BUMPER UNDER COVER GARNISH CLIP	Not Necessary	50.00 FS	*- FS
62	1		*SET FRONT BUMPER LED LIGHT (SPECIAL TYPE)	Not Necessary	280.00 FS	*- FS
63	1		*SET RADIATOR GRILLE CLIP	Not Necessary	50.00 FS	*- FS
64	1		*SET FRONT FENDER INNER GARNISH CLIP LH	Not Necessary	80.00 FS	*- FS
65	1		*SET FRONT FENDER COWLING CLIP	Necessary	50.00 FS	*30.00 FS
66	1		*FRONT WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
67	1		*FRONT WINDSCREEN INNER SHIELD	Not Necessary	60.00 FS	*- FS
68	2		*FRONT WHEEL RIM	Cut (1 PCS ONLY)	1,300.00 FS	*400.00 FS
69	1		*FRONT WHEEL TYRE	Front Cut	760.00 FS	*200.00 FS
70	1		*REAR FENDER SEALANT LH	Not Necessary	150.00 FS	*- FS
71	1		*REAR FENDER GLASS SEALANT LH	Not Necessary	150.00 FS	*- FS
72	1		*REAR FENDER GLASS INNER SEAL LH	Not Necessary	80.00 FS	*- FS
73	1		*REAR WHEEL RIM LH	Cut	850.00 FS	*400.00 FS
74	1		*REAR WHEEL TYRE LH	Not Necessary	380.00 FS	*- FS
75	1		*SET WHEEL CAP	Not Necessary	120.00 FS	*- FS
76	1		*POWER STEERING OIL	Not Necessary	180.00 FS	*- FS
77	1		*BRAKE OIL	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	31,432.00	10,265.00
- List Item Discount on L Items 10.00/10.00% (S\$)	2,670.20	920.50
Total Parts (S\$)	28,761.80	9,344.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT, WELD, CUT ADJUST ,KNOCK	New	2,800.00	1,000.00
2	TO SPRAY PAINT	New	2,400.00	1,200.00
3	TUFF COAT	New	250.00	60.00
4	WIRING BULB CHECKING	New	180.00	30.00
5	REMOVE & REFIX CUSHION SEAT /UPHOLSTERY &ROOF LINING TO FACILITATE REPAIR	New	350.00	0.00
6	REMOVE & REFIX FRONT WINDSCREEN	New	120.00	0.00
7	REMOVE AND REFIX FRONT UNDERCARRIAGE	New	650.00	220.00
8	TO PRESS FRONT WHEEL BEARING	New	80.00	0.00
9	REMOVE AND REFIX POWER STEERING RACK AND PINION	New	350.00	0.00
10	REMOVE & REFIX FRONT QUARTER GLASS RH	New	80.00	40.00
11	TRANSFER FRONT DOOR MECHANISM	New	80.00	80.00
12	TRANSFER REAR DOOR MECHANISM	New	80.00	80.00
13	REMOVE AND REFIX REAR UNDERCARRIAGE	New	650.00	0.00
14	FOUR WHEEL ALIGNMENT	New	120.00	80.00
15	RESET ABS LIGHT	New	350.00	0.00
16	CONDUCT WATER LEAKAGE TEST	New	180.00	0.00
17	TO CHECK DIAGNOSTIC OF VEHICLE MANAGEMNET /CONTROL UNITS ,RESET MERORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (S\$)			8,900.00	2,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >