

CC3/AIG 19017875/Asf302

Assoc. Ref. By:

Mrimm

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OO RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop ref: _____

of: _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____

Excess: _____

\$0/-

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

125K.

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

06/08

days

Res: _____

Yes or No

Lum Sum: _____

%

3 Val: _____

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLX 125E . 1st Regn: 2018 Feb.

Type: ☒ M.Cat / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: _____

Audi A4

CC 1984

Colour: _____

Black

A/C: Insured / Std / NI / NA

Sp. Reading: _____

18379

Ti/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

WAUZZZ2F41JA075570

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size: _____

F: _____

245/40R18.

R: _____

245/40R18.

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: _____

06

mm

R/Bal: _____

06

mm

L/Bal: _____

06

mm

L/Bal: _____

06

mm

D.O.A. _____

9.10.2019

D.O.A. _____

10/10/19.

Survey held at _____

Premium

Des. of Damages: ☐ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ UIC / ☐ Rooftop or

Front N/S.

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	OD AIG.
	SLX 125E - X
14/10/19	@ 10:46 am received PA to AIG via mrimm
	MV:
	PV:
	Nett:
14/10/19	@ 10:49 am mandate received author. repair to AIG via mrimm
15/10/19	@ 16:50 pm mandate approved by Victor Koh via mrimm
15/10/19	@ 12:06 pm informed cl to Ray by email via email
Date/Time, File Path 107	☐ : Prel. Report
10/03/20	☒ : Final Report
10/03/20	Days Of Repair: 6
10/03/20	Resurvey No. of Trip: 1
10/03/20	Survey Fee
10/03/20	Transportation
10/03/20	200
10/03/20	11
10/03/20	211
10/03/20	211

Add Fee: ☐ Site Insp. IS☐ Interview IS☐ Tech. Insp. IS☐ Wheel track IS

Report Form:

Time Spent: 16.851.28 P/P

Adrian Continued P/P \$ 16,851.28 @ 6 days
with Boss. C \$ 9,705.72 Red - 37%)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 14 Oct 2019

Preliminary Advice

Vehicle No	: SLX125E	Accident Date	: 09/10/2019
Make	: AUDI A4	Policy No.	: 1800017018
Assignment Date	: 10/10/2019	Excess	: S\$0.00
Date of Inspection	: 10/10/2019	Est. Duration of Repair	: 6 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	24,010.00
Revised Amount	:S\$	16,813.00
Check Items (Estimated)	:S\$	1,330.00
Total	:S\$	18,143.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	125,000.00
COE / PARF Rebate	:S\$	64,541.00
Salvage Value	:S\$	
Margin for Repair	:S\$	60,459.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Gan, Hunchung

Date: 07 Nov 2019

Preliminary Advice

Vehicle No	: SLX125E	Accident Date	: 09/10/2019
Make	: AUDI A4	Policy No.	: 1800017018
Assignment Date	: 10/10/2019	Excess	: S\$0.00
Date of Inspection	: 10/10/2019	Est. Duration of Repair	: 6 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	25,360.00 (inclusive supp)
Revised Amount	:S\$	17,663.00 (inclusive supp)
Check Items (Estimated)	:S\$	1,330.00
Total	:S\$	18,993.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	125,000.00
COE / PARF Rebate	:S\$	64,541.00
Salvage Value	:S\$	
Margin for Repair	:S\$	60,459.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Supplementary amount is \$ 850.00.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Monday, 24 February 2020 11:59 am
To: Carrine Leong; Boo seng yak
Cc: Adrian Ling (LKKAuto); SUR; Chang Chee Sing; jiajee.yap@premiumauto.com.sg
Subject: RE: FINAL REVISION - SLX125E - OD AIG - SURVEYED 10 OCT 19

Dear Carrine,

Total amount of the labour is \$ 5,202.00 instead of \$ 5,232.00.

Confirmed final fig \$ 16,851.28 instead of \$ 16,881.28 @ 6 days of repairs before excess \$ 0/- & GST.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>

Sent: Tuesday, 18 February 2020 2:54 pm

To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; Chang Chee Sing <claims@premiumauto.com.sg>; jiajee.yap@premiumauto.com.sg

Subject: FINAL REVISION - SLX125E - OD AIG - SURVEYED 10 OCT 19

Hi Adrian and all,

Revised estimate and photographs attached.

Please confirm repair cost of \$16,881.28 @ 6 days of repairs exclude 1 Sunday.

Re: OD CLAIMS FOR SLX 125 E, DOA: 09/10/2019

Shirley Hiew (LKK Auto)

Tue 15/10/2019 5:06 PM

To: Claims <claims@premiumauto.com.sg>

Cc: SUR <sur@lkkauto.com>

Hi Troy,

As instructed by our client, please proceed to repair the insured vehicle **SLX 125E (Excess S 0/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Sent: Monday, 14 October 2019 3:16 PM

To: Claims <claims@premiumauto.com.sg>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: Re: OD CLAIMS FOR SLX 125 E, DOA: 09/10/2019

Hi Troy,

Enclosed attached for your requested.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>

Sent: Friday, 11 October 2019 6:15 PM

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Friday, 8 November 2019 5:26 pm
To: glory.tan@premiumauto.com.sg; SUR
Cc: allan.wu@premiumauto.com.sg; 'Claims'
Subject: RE: Supplementary labour and check item photos for SLX 125 E
Attachments: SUPP.pdf

Dear Glory,

Supplementary approved by AIG.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: glory.tan@premiumauto.com.sg <glory.tan@premiumauto.com.sg>
Sent: Thursday, 7 November 2019 2:57 pm
To: SUR <sur@lkkauto.com>
Cc: allan.wu@premiumauto.com.sg; 'Claims' <claims@premiumauto.com.sg>
Subject: Supplementary labour and check item photos for SLX 125 E

Hi all,

Please refer to the attached for supplementary labour and check item photos for SLX 125 E.

Check item in marked estimate,

- 5. Front bumper air guide LH.
- 6. Front bumper air guide grille LH.
- 7. Front bumper guide section LH.
- 18. Front fender closing element LH.
- 23. Front wheel housing liner LH.
- 25. Wheel spoiler.
- 33. Fender ledge cover LH.
- 34. Bonnet cover LH.

By the way, already arranged surveyor to go down to Sin Ming to do resurvey on 7/11/2019.

View Received Message

This mail is associated with :

***SLX125E (6072821156SG)**
OD

Oct 9 2019 4:00PM
[CHEOW ENG KIAT KENNETH]
Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 08/11/2019 16:55 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$17663.00) - SLX125E - Claim Handler: Gan, Hunchung

Approved:17663.00:Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

***SLX125E (6072821156SG)**

OD

Oct 9 2019 4:00PM

[CHEOW ENG KIAT KENNETH]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 15/10/2019 16:50 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$16813.00) - SLX125E - Claim Handler: Khoo, Kay-Eng

Approved:16813.00:Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	273H
Vehicle Details	
Vehicle No.:	SLX125E
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Oct 2019
Vehicle Make:	AUDI
Vehicle Model:	A4 SEDAN 2.0 TFSI S TRONIC (NAV)
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	CVK050794
Chassis No.:	WAUZZZF41JA075570
Maximum Power Output:	140.0 kW (187 bhp)
Open Market Value:	\$33,419.00
Original Registration Date:	06 Feb 2018
First Registration Date:	06 Feb 2018
Transfer Count:	0
Actual ARF Paid:	\$38,787.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Feb 2028
PARF Rebate Amount:	\$29,090.00
Intended COE Rebate Details	
COE Expiry Date:	05 Feb 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,661.00
COE Rebate Amount:	\$35,451.00
Total Rebate Amount:	\$64,541.00

The information contained herein is correct as at 14 Oct 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/10/2019 14:22
Date Of Accident	09/10/2019 16:20
Exact Location Of Accident	ROBINSON ROAD AND TELEGRAPH STREET JUNCTION
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLX125E
Insured/Policyholder	
Name Of Registered Owner	CHEOW ENG KIAT KENNETH
NRIC No	S8339273H
Email Address	KENNETH.CHEOW@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97509100
Alternative Phone No	OFFICE-97509100

Vehicle Particulars

Manufacturer	AUDI
Model	A4 SEDAN 2.0 TFSI 8W
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800017018
Cover Note Number	

Driver

Name of Driver	CHEOW ENG KIAT KENNETH
NRIC No	S8339273H
Date Of Birth	05/12/1983
Occupation	INDOOR
Date Of Driving Pass	04/10/2005
Driving Experience	14 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97509100
Fax Number	
Contact Number	OFFICE-97509100
Email Address	KENNETH.CHEOW@GMAIL.COM

Address	935 BUKIT TIMAH ROAD #08-34
Postcode	589645
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	YES
Foreign Vehicle Registration Number	WVQ2246 (PRIVATE CAR)
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : GLENDA LEE GENDER: : FEMALE
Passenger 2	NAME: : CLAIRE TAN GENDER: : FEMALE
Passenger 3	NAME: : DESIREE LEE GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER BACK TO POLICE REPORT T/20191009/7041

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	WVQ2246
-----------------------------	---------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 20/10

Driver's Signature

(if driver is not the policyholder)

Date & Time:


Reporting Centre Person's Signature

Name: Goh Shu Hao, Day

NRIC/FIN No.: G82 7992 K

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer back to police report T/2019/009/704/ ✓

[The remaining lines of the section are crossed out with a diagonal line.]

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature

Date & Time: 10/10

CGR0302 SketchPlanForm_V0

Driver's Signature

(If driver is not the policyholder)

Date & Time:




Reporting Centre Personnel's Signature

Name: 

NRIC/FIN No.: A55974026

Sketch Plan #3

Sketch



Accident Photo



**SINGAPORE
POLICE FORCE**



1/20191009/7041

1 of 4

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408805
Tel No: 65470000

Report No: 1/20191009/7041

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 09/10/2019 22:48		Vide Report No:		Station Diary No:	
Informant's Particulars					
Name of Informant: CHEOW ENG KIAT KENNETH			Address: 935 BUKIT TIMAH ROAD #08-34 SINGAPORE 589645		
ID Type / ID No: NRIC NO / S6339273H			Contact No.: Home/Office		Mobile: 97509100
Nationality: SINGAPORE CITIZEN			Email: kenneth.cheow@gmail.com		
Sex: Male	Age: 35	Date of Birth: 05/12/1983	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Advocate/Solicitor			Driving Licence Information: Class:		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 09/10/2019 16:20	Type of Location: T-Junction
Location: ROBINSON ROAD				
Weather:		Road Surface:	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision:				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
SLX125E	Car	AUDI	A4 SEDAN 2.0 TFSI S TRONIC (NAV)	Gray		0
WVO2240	Motorcycle					0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLX125E	AIG ASIA PACIFIC INSURANCE PTE LTD.	1800017018	06/02/2018	06/02/2020

Accident Photo



**SINGAPORE
POLICE FORCE**



T201910057041

2 of 4

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No: T201910057041

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	CHEOW ENG KIAT KENNETH	ID No.	S6339273H
Related Vehicle	SLX125E (Car)	Contact No.	97509100
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Rider			
Name	MUHAMAD AL AHNAF BIN AKBAR	ID No.	G3075017P
Related Vehicle	WVQ2246 (Motorcycle)	Contact No.	86605870
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight

Brief Details:

- On 9 October 2019 around 4.20 p.m., I was driving my car (SLX125E) along Robinson Road on the right-most lane.
- I was approaching the junction between Robinson Road and Telegraph Street.
- I wish to highlight that:
 - the vehicles in my lane (i.e. the right-most lane) are allowed to go straight or turn right into Telegraph Street.
 - the vehicles in the lane to my left (i.e. the second lane from the right) are only allowed to go straight.
- I was driving straight in my lane (i.e. the right-most lane), and there was no vehicle ahead of me.
- However, there was a motorcycle (WVQ2246) travelling on the lane to my left (i.e. the second lane from the right).
- The motorcycle suddenly tried to turn right into Telegraph Street from his lane.
- As a result, my car collided with the motorcycle.
- I wish to highlight that the motorcycle was NOT allowed to turn right into Telegraph Street from

Accident Photo



SINGAPORE
POLICE FORCE

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408665
Tel No: 65470000



T201910097041

3 of 4

Report No: T201910097041

CONTINUATION OF REPORT

his lane.

9. I got off the car to check on the motorcyclist (Muhamad Al Ahnaf bin Akbar).

10. I helped him to get up, and I noticed that he had a cut on his palm, and some parts of his jeans were torn.

11. I asked if he was alright and needed to see a doctor. He replied that he was fine.

12. I also asked where he was going. He replied that he was working and was on his way to carry out system installation works.

13. He called his friend and his employer about the accident.

14. We exchanged phone numbers, and took photos of each other's identification cards and the damage to our vehicles.

15. I noted from his employment pass that he is Malaysian and works for Viewquest.

16. I also noted that the bumper on the left side of my car is dented, and the exhaust pipe on the right side of his motorcycle is dented.

17. Please contact me for the videos of the accident (from my car camera) and the photos that I have taken. Each of them are more than 2MB, and cannot be uploaded to your system.

Accident Photo



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408665
Tel No: 65470000



T/20191009/7041

4 of 4

Report No: T/20191009/7041

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPB /
MCHAMAD ZULFAZLI BIN ABDULLAH
Contact No : 65476204

Authentication Stamp
14-183

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
09/10/2019 22:48

Classification Of Case:

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 15438

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1229/2019/NS
Date	:	11-Oct-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Cheow Eng Kiat Kenneth
Address	:	935 Bukit Timah Road #08-34 Singapore 589645
Telephone	:	HP +65 97509100
Type of Claim	:	Own Damage Claims
Policy No.	:	1800017018
Vehicle No	:	SLX 125 E
Model Code	:	Audi A4 SEDAN 2.0 TFSI
Model / Year	:	6/2/2018
Engine No	:	CVK 050794
Chassis No	:	WAUZZZF41JA075570
Mileage	:	
Date In	:	
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	9-Oct-19
Place of Accident	:	Robinson Road And Telegraph Street Junction

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLX 125 E

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	
2	To dismantle and renew front bumper, lhs front fender, bonnet and lhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 3,150.00 1750 .	
3	To respray front bumper, bonnet and lhs front fender. ✓	\$ 3,000.00 1650	
4	To renew lhs front rim and tyre. To carry out wheel alignment.	S/N \$ 280.00 ✓	
5	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: <u>\$ 7,102.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 125 E

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>deformed</i>	\$ 1,999.00	✓ 1599.20
2	FRONT BUMPER FIXING PARTS <i>not nec</i>	\$ 258.00	X
3	FRONT BUMPER GRILLE - CENTRE <i>not nec</i>	\$ 178.00	X
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>not nec</i>	\$ 191.00	X
5	FRONT BUMPER AIR GUIDE - LH <i>not to be used</i>	\$ 56.00	? ✓ 44.40
6	FRONT BUMPER AIR GUIDE GRILLE - LH <i>not to be used</i>	\$ 333.00	X ✓ 266.00
7	FRONT BUMPER GUIDE SECTION - LH <i>2 needed</i>	\$ 33.00	? ✓ 26.08
8	FRONT BUMPER FOAM FILLER PIECE <i>not nec</i>	\$ 113.00	X
9	FRONT BUMPER CARRIER <i>not nec</i>	\$ 733.00	X
10	FRONT BUMPER LOCK CARRIER BRACKET <i>not nec</i>	\$ 125.00	? X
11	FRONT BUMPER SUPPORT - LH / RH <i>not nec</i>	2 \$ 52.00	? X
12	HORN - LH HIGH TONE <i>not nec</i>	\$ 37.00	? X
13	HORN SPRING SHACKLE - LH <i>not nec</i>	\$ 26.00	? X
14	FRONT PARKING AID SENSOR - INNER / OUTER <i>not nec</i>	2 \$ 462.00	X
15	FRONT PARKING AID SEAL RING <i>not nec</i>	4 \$ 12.00	X
16	FRONT FENDER - LH <i>Dented</i>	\$ 700.00	✓ 559.60
17	FRONT FENDER ATTACHMENT PARTS <i>not nec</i>	\$ 183.00	? X
18	FRONT FENDER CLOSING ELEMENT - LH <i>Damaged</i>	\$ 45.00	? ✓ 36.00
19	FRONT FENDER BRACKET - LH <i>not nec</i>	\$ 32.00	? X
20	FRONT FENDER DEFORMATION ELEMENT BRACKET - LHG <i>not nec</i>	\$ 45.00	? X
SUB TOTAL SPARE PARTS		\$ 5,613.00	

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 125 E

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
21	FRONT FENDER BRACKET <i>2H NEE</i>	\$ 29.00	? X
22	FRONT FENDER BRACE - LH <i>2H NEE</i>	\$ 107.00	? X
23	FRONT WHEEL HOUSING LINER - LH <i>torn</i>	\$ 223.00	X ✓ 193.40
24	WHEEL HOUSING LINER ATTACHMENT PARTS <i>2H NEE</i>	\$ 82.00	X
25	WHEEL SPOILER <i>cracked</i>	\$ 66.00	X ✓ 52.32
26	SPOILER - LH <i>not on</i>	\$ 32.00	X
27	STONE CHIP GUARD - LH <i>new</i>	\$ 46.00	✓ 36.64
28	BONNET <i>Dented</i>	\$ 2,554.00	✓ 2043.20
29	BONNET ATTACHMENT PARTS <i>2H NEE</i>	\$ 111.00	? X
30	BONNET IMPACT PROTECTION - LH / RH / CENTRE <i>new 3</i>	\$ 75.00	✓ 59.44
31	BONNET STRIKER - LH <i>not on</i>	\$ 46.00	X
32	BONNET LID LOCK <i>not on</i>	\$ 196.00	X
33	FENDER LEDGE COVER - LH <i>new</i>	\$ 28.00	? ✓ 22.24
34	BONNET COVER - LH <i>new</i>	\$ 21.00	? ✓ 16.16
35	LED HEADLIGHT - LH <i>cut</i>	\$ 7,087.00	✓ 5669.60
36	LIFT CYLINDER - LH <i>2H NEE</i>	\$ 192.00	X X
37	FRONT RIM - LH <i>cut</i>	1197 TBC	✓ 957.60
38	FRONT TYRE - LH <i>2H NEE</i>	TBC	X
39	SUNDRIES <i>NEE</i>	\$ 400.00	? ✓ 82.40
TOTAL SPARE PARTS		\$ 16,908.00	
TOTAL LABOUR CHARGES		\$ 7,102.00	
GRAND TOTAL		\$ 24,010.00	26557

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

:

Adrian King

Surveyed Date

:

10/10/19

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

:

Not Authorised, Ob Pays.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/1229/2019/NS

Date

7-Nov-19

Service Advisor

Glory Tan

Pages

1 of 1

Regn No

SLX 125 E

Model No

Audi A4 SEDAN 2.0 TFSI

Quantity	Description	Unit Price	Amount
Labours			
1	To dismantle lhs front door panel trim. To remove and reinstall lhs wing mirror assy.	S/N \$ 300.00	✓
2	To respray lhs front door.	\$ 1,050.00	550.
TOTAL		\$ 1,350.00	

For Premium Automobiles Pte Ltd

Adrian Ling
H.S.

Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 15438

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1229/2019/NS
Date : 11-Oct-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

6 days exclude 1* Sunday

jb 18 Feb 20

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Cheow Eng Kiat Kenneth
Address : 935 Bukit Timah Road
#08-34
Singapore 589645
Telephone : HP +65 97509100
Type of Claim : Own Damage Claims
Policy No. : 1800017018
Vehicle No : **SLX 125 E**
Model Code : Audi A4 SEDAN 2.0 TFSI
Model / Year : 6/2/2018
Engine No : CVK 050794
Chassis No : WAUZZZF41JA075570
Mileage :
Date In :
Estimated By : Johnny Boo / Allan Wu
Accident Date : 9-Oct-19
Place of Accident : Robinson Road And Telegraph Street Junction

Premium Automobiles

65 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLX 125 E

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$	480.00	\$ 480.00
2	To dismantle and renew front bumper, lhs front fender, bonnet and lhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$	3,150.00	\$ 1,750.00
3	To respray front bumper, bonnet and lhs front fender.	\$	3,000.00	\$ 1,650.00
4	To renew lhs front rim and tyre. To carry out wheel alignment.	S/N \$	280.00	\$ 280.00
5	<i>Added labour - see attached</i>	\$	1,350.00	\$ 880.00
6	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 8,452.00</u>	<u>\$ 5,232.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 125 E

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		<u>S/Nett</u>	<u>Remarks</u>
1	FRONT BUMPER	\$ 1,999.00	\$ 1,599.20
2	FRONT BUMPER FIXING PARTS	\$ 258.00	
3	FRONT BUMPER GRILLE - CENTRE	\$ 178.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 191.00	
5	FRONT BUMPER AIR GUIDE - LH	\$ 56.00	\$ 44.40
6	FRONT BUMPER AIR GUIDE GRILLE - LH	\$ 333.00	\$ 266.00
7	FRONT BUMPER GUIDE SECTION - LH	\$ 33.00	\$ 26.08
8	FRONT BUMPER FOAM FILLER PIECE	\$ 113.00	
9	FRONT BUMPER CARRIER	\$ 733.00	
10	FRONT BUMPER LOCK CARRIER BRACKET	\$ 125.00	
11	FRONT BUMPER SUPPORT - LH / RH	2 \$ 52.00	
12	HORN - LH HIGH TONE	\$ 37.00	
13	HORN SPRING SHACKLE - LH	\$ 26.00	
14	FRONT PARKING AID SENSOR - INNER / OUTER	2 \$ 462.00	
15	FRONT PARKING AID SEAL RING	4 \$ 12.00	
16	FRONT FENDER - LH	\$ 700.00	\$ 559.60
17	FRONT FENDER ATTACHMENT PARTS	\$ 183.00	
18	FRONT FENDER CLOSING ELEMENT - LH	\$ 45.00	\$ 36.00
19	FRONT FENDER BRACKET - LH	\$ 32.00	
20	FRONT FENDER DEFORMATION ELEMENT BRACKET - LHG	\$ 45.00	
SUB TOTAL SPARE PARTS		\$ 5,613.00	\$ 2,531.28

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 125 E

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remarks
			\$	2,531.28
21	FRONT FENDER BRACKET		\$ 29.00	
22	FRONT FENDER BRACE - LH		\$ 107.00	
23	FRONT WHEEL HOUSING LINER - LH		\$ 223.00	\$ 178.40
24	WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 82.00	
25	WHEEL SPOILER		\$ 66.00	\$ 52.32
26	SPOILER - LH		\$ 32.00	
27	STONE CHIP GUARD - LH		\$ 46.00	\$ 36.64
28	BONNET		\$ 2,554.00	\$ 2,043.20
29	BONNET ATTACHMENT PARTS		\$ 111.00	
30	BONNET IMPACT PROTECTION - LH / RH / CENTRE	3	\$ 75.00	\$ 59.44
31	BONNET STRIKER - LH		\$ 46.00	
32	BONNET LID LOCK		\$ 196.00	
33	FENDER LEDGE COVER - LH		\$ 28.00	\$ 22.24
34	BONNET COVER - LH		\$ 21.00	\$ 16.16
35	LED HEADLIGHT - LH		\$ 7,087.00	\$ 5,669.60
36	LIFT CYLINDER - LH		\$ 192.00	
37	FRONT RIM - LH		\$ 1,197.00	\$ 957.60
38	FRONT TYRE - LH		TBC	
40	SUNDRIES		\$ 400.00	\$ 82.40
TOTAL SPARE PARTS			\$ 18,105.00	\$ 11,649.28
TOTAL LABOUR CHARGES			\$ 8,452.00	\$ 5,232.00
GRAND TOTAL			\$ 26,557.00	\$ 16,881.28

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

5202
16851.28

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1229/2019/NS 7-Nov-19 Glory Tan 1 of 1 SLX 125 E Audi A4 SEDAN 2.0 TFSI
Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	To dismantle lhs front door panel trim. To remove and reinstall lhs wing mirror assy.	S/N \$ 300.00	\$ 300.00
2	To respray lhs front door.	\$ 1,050.00	\$ 550.00
TOTAL		\$ 1,350.00	\$ 850.00

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLX 125 E

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1229/2019/NH

9th March 2020

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SLX 125 E, Audi A4 SEDAN 2.0 TFSI.

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

With reference to the above-mentioned vehicle, no. **SLX 125 E**, claimant, **Mr. Cheow Eng Kiat Kenneth**, please find the related document per attached.

1. A copy of the Original invoice no. 85014951 – S\$ 18,030.87.
2. A copy of the Discharge Voucher duly signed by client.

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – SLX 125 E

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6838 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1163

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 11:04

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 65014951 Date : 05/03/2020 Order : SLX0125E Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SLX0125E (V 36155)	Regn Date: 06/02/2018	Mileage: 20317	WIP No.: 15438
Model: A4 SEDAN 2.0 TFSI 8W2ADG (NAV)	Chassis: WAUZZZF41JAG75570	Engine: CVK 050794	Dept: U
You have been assisted by :- UB-Nora (11)			

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	480.00	1.00	480.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER,LHS FRONT FENDER,BONNET AND LHS HEADLIGHT. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	1750.00	1.00	1,750.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER,BONNET AND LHS FRONT FENDER	1650.00	1.00	1,650.00
S	BODYWORK	M: TO RENEW LHS FRONT RIM.TO CARRY OUT WHEEL ALIGNMENT	280.00	1.00	280.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
S	BODYWORK	M: TO DISMANTLE LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY	300.00	1.00	300.00
S	BODYWORK	M: TO RESPRAY LHS FRONT DOOR	550.00	1.00	550.00
X	A8W0807065D GRU	COVER	Less 020%	1.00	1999.00
X	A8W0121763	AIR DUCT AP	Less 020%	1.00	55.50
X	A8W0807681A RN4	GRILL AP	Less 020%	1.00	332.50
X	A8W0807283	GUIDE AP	Less 020%	1.00	32.60
X	A8W0821105A	FENDER	Less 020%	1.00	699.50
X	A8W0821091	PLATE AP	Less 020%	1.00	45.00
X	AN 0161857	POP-RIVET	Less 020%	6.00	3.00
X	A8W0821171A	WHEEL HOUS AP	Less 020%	1.00	223.00
X	A8W0853887E	SPOILER AP	Less 020%	1.00	65.40
X	A8W0853823B 989	STONEGUARD	Less 020%	1.00	45.80

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6368 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6368 2323
Main Telefax 6541 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 2 11:04

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014951 Date : 05/03/2020 Order : SLX0125E Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SLX0125E (V 36155) Regn Date: 06/02/2018 Mileage: 20317 WIP No.: 15438

Model: A4 SEDAN 2.0 TFSI 8W2ADG (NAV, Chassis: WAUZZZF41JA075570 Engine: CVE 050794 Dept: U

You have been assisted by :- UB-Nora (11)

		Details		Qty	Unit Price	Amount
X	ASW0823029A	HOOD	Less 020%	1.00	2554.00	2,043.20
X	ASW0823124	PROTECTION	Less 020%	1.00	24.70	19.76
X	ASW0823125	(A) (SK) PROTECTION 17	Less 020%	1.00	24.90	19.92
X	ASW0823126	PROTECTION	Less 020%	1.00	24.70	19.76
X	ASW0820581C	COVER AP	Less 020%	1.00	27.80	22.24
X	ASW0823745	COVER AP	Less 020%	1.00	20.20	16.16
X	ASW0941773A	HEADLIGHT	Less 020%	1.00	7087.00	5,669.60
X	ASW0807681B 9B9	GRILL AP	Less 020%	1.00	42.50	34.00
X	ASW0601025BA	WHEEL	Less 020%	1.00	1197.00	957.60
X	ASW0601170B	WHEEL CAP	Less 020%	1.00	42.50	34.00

Parts 11,649.28
Labour 0.00
Sublet 5,202.00
Menus 0.00
Lubricant 0.00

Sub-Total 16,851.28

7% GST 1,179.59

Grand Total 18,030.87



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLX 125 E

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1229/2019/TG
12 November 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE: CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A4 SEDAN 2.0 TFSI 8W
Vehicle Chassis No. : WAUZZZF41JA075570
Vehicle Regn No. : **SLX 125 E**
Vehicle Mileage : 19104 KM
Vehicle Owner : Mr. Cheow Eng Kiat Kenneth
Certificate No : 1800017018
Own Damage Excess : Waived
Accident Date : 09 October 2019
Place : Robinson Road and Telegraph Street Junction
Repair Cost : S\$ 18,030.87
WIP No. : 15438
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time : 17.45pm
Date : 12/11/2019

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Oct 2019		10 Oct 2019 17:18 Edit Adj Rpt	S\$16,851.28 Edit Estimates	S\$16,851.28 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by Insurer]

Insured:	CHEOW ENG KIAT KENNETH, ID: S8339273H, Tel: +6597509100, Email: KENNETH.CHEOW@GMAIL.COM		
Vehicle Reg. No.:	SLX125E	Date of Loss:	09/10/2019 16:00 - :59 [20 Months and 3 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 6072821156SG	Policy/Cover Note No.:	1800017018 (Comprehensive)
		Excess:	S\$0.00
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Gan, Hunchung] Hunchung.Gan@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 21/10/2019]		
Driver/Custodian:	CHEOW ENG KIAT KENNETH (35 / Male), NRIC: S8339273H, Tel: +6597509100 Email: KENNETH.CHEOW@GMAIL.COM		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (08/11/2019): Alert - Adj Mandate Approved (S\$17663.00) - SLX125E - Claim Handler: Gan, Hunchu...
- AIG_SG (15/10/2019): Alert - Adj Mandate Approved (S\$16813.00) - SLX125E - Claim Handler: Khoo, Kay-E...
- AIG_SG (14/10/2019): SLX125E / OD / 09/10/2019 / Coverage & Excess update

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLX125E (6072821156SG)
OD
Oct 9 2019 4:00PM
[CHEOW ENG KIAT KENNETH]
Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Video															1 per page					
No	Finalized On		Premium Automobiles Pte Ltd (UBI)												Thumbnail		Print			
1	10/10/19 14:35		Video - Accident [Linked Accident Report Documents]												Load MP4					
Assessment Reports															1 per page					
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	14/10/19 10:46		Adjuster Immediate Advice												Load HTM					
2	07/11/19 16:38		Adjuster Immediate Advice												Load HTM					
Photos/Images															3 per page					
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	14/10/19 10:51		General View												Load JPG					
2	14/10/19 10:51		General View												Load JPG					
3	14/10/19 10:51		General View												Load JPG					
4	14/10/19 10:51		General View												Load JPG					
5	14/10/19 10:51		General View												Load JPG					
6	14/10/19 10:51		General View												Load JPG					
7	14/10/19 10:51		General View												Load JPG					
8	14/10/19 10:51		General View												Load JPG					
9	14/10/19 10:51		General View												Load JPG					
10	14/10/19 10:51		General View												Load JPG					
11	14/10/19 10:51		General View												Load JPG					
12	14/10/19 10:51		General View												Load JPG					
13	14/10/19 10:51		General View												Load JPG					
14	14/10/19 10:51		General View												Load JPG					
15	14/10/19 10:51		General View												Load JPG					
16	14/10/19 10:51		General View												Load JPG					
17	14/10/19 10:51		General View												Load JPG					
18	14/10/19 10:51		General View												Load JPG					
19	14/10/19 10:51		General View												Load JPG					
20	14/10/19 10:51		General View												Load JPG					
21	14/10/19 10:51		General View												Load JPG					
22	14/10/19 10:51		General View												Load JPG					
23	14/10/19 10:51		General View												Load JPG					
24	14/10/19 10:51		General View												Load JPG					
25	21/02/20 09:02		Reinspection Photo												Load JPG					
26	21/02/20 09:02		Reinspection Photo												Load JPG					
27	21/02/20 09:02		Reinspection Photo												Load JPG					
28	21/02/20 09:02		Reinspection Photo												Load JPG					
29	21/02/20 09:02		Reinspection Photo												Load JPG					
30	21/02/20 09:02		Reinspection Photo												Load JPG					
31	21/02/20 09:02		Reinspection Photo												Load JPG					
32	21/02/20 09:02		Reinspection Photo												Load JPG					
33	21/02/20 09:02		Reinspection Photo												Load JPG					
34	21/02/20 09:02		Reinspection Photo												Load JPG					

Video			1 per page	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
35	21/02/20 09:02	Reinspection Photo		
36	21/02/20 09:02	Reinspection Photo		
37	21/02/20 09:02	Reinspection Photo		
38	21/02/20 09:02	Reinspection Photo		
39	21/02/20 09:02	Reinspection Photo		
40	21/02/20 09:02	Reinspection Photo		
41	21/02/20 09:02	Reinspection Photo		
42	21/02/20 09:02	Reinspection Photo		
43	21/02/20 09:02	Reinspection Photo		
44	21/02/20 09:02	Reinspection Photo		
45	21/02/20 09:02	Reinspection Photo		
46	21/02/20 09:02	Reinspection Photo		
47	21/02/20 09:02	Reinspection Photo		
48	21/02/20 09:02	Reinspection Photo		
49	21/02/20 09:02	Reinspection Photo		
50	21/02/20 09:02	Reinspection Photo		
51	21/02/20 09:02	Reinspection Photo		
52	21/02/20 09:02	Reinspection Photo		
53	21/02/20 09:02	Reinspection Photo		
54	21/02/20 09:02	Reinspection Photo		
Documentation			1 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/10/19 10:46	SLX 125E GIA.pdf		
2	14/10/19 10:46	POLICE REPORT.pdf		
3	14/10/19 10:46	DRIVING.pdf		
4	14/10/19 10:46	ESTIMATE.pdf		
5	07/11/19 16:40	SUPP.pdf		
6	24/02/20 11:51	ESTIMATE & SUPP MARKED.pdf		
7	11/03/20 11:12	WORKSHOP INVOICE		
8	11/03/20 11:12	DISCHARGE VOUCHER		

Linked Accident Report Documents

Video			1 per page	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	10/10/19 14:35	Video - Accident		
Assessment Reports			1 per page	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	06/12/19 18:57	Accident Statement		
2	06/12/19 18:59	Accident Statement		
3	06/12/19 19:01	Accident Statement		
4	06/12/19 19:04	Accident Statement		
Photos/Images			3 per page	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	10/10/19 14:33	Accident Photo		
2	10/10/19 14:33	Accident Photo		
3	10/10/19 14:33	Accident Photo		
4	10/10/19 14:33	Accident Photo		
5	10/10/19 14:33	Accident Photo		
6	10/10/19 14:33	Accident Photo		
7	10/10/19 14:33	Accident Photo		
8	10/10/19 14:33	Accident Photo		
9	10/10/19 14:33	Accident Photo		

Video			1 per page ▼	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
10	10/10/19 14:33	Accident Photo		☒
11	10/10/19 14:33	Accident Photo		☒
12	10/10/19 14:33	Accident Photo		☒
13	10/10/19 14:33	Accident Photo		☒
14	10/10/19 14:33	Accident Photo		☒
15	10/10/19 14:33	Accident Photo		☒
16	10/10/19 14:33	Accident Photo		☒
17	10/10/19 14:33	Accident Photo		☒
18	10/10/19 14:33	Accident Photo		☒
19	10/10/19 14:49	Accident Photo		☒
20	10/10/19 14:49	Accident Photo		☒
21	10/10/19 14:49	Accident Photo		☒
22	10/10/19 14:49	Accident Photo		☒
Documentation			1 per page ▼	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	10/10/19 14:48	Sketch Plan		☒
2	10/10/19 14:48	Sketch Plan #2		☒
3	10/10/19 14:48	Sketch Plan #3		☒

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19017875/ASF3N2

Date: 11/03/2020

REFERENCE

Insured/Claimant: CHEOW ENG KIAT KENNETH Policy No: 1800017018
Date of Loss: 09/10/2019 Nature of Claim: OD Claim No: 6072821156SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLX125E
Make & Model: AUDI A4, 2.0 TFSI QU S-TRONIC (A) Engine No: CVK050794
Reg. Date: 06/02/2018 (Man. Year: 2017) Chassis No: WAUZZZF41JA075570
Colour: Black Odometer: 18379 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$125,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40R18 Rear Tyre Size: 245/40R18
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,105.00	11,649.28	6,455.72	35.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,452.00	5,202.00	3,250.00	38.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	26,557.00	16,851.28	9,705.72	36.55
+ GST 7.00/7.00% (S\$)	1,858.99	1,179.59	679.40	36.55
Nett Amount (S\$)	28,415.99	18,030.87	10,385.12	36.55

INSPECTION

Date of Assignment: 10/10/2019
Date Inspected: 10/10/2019 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Deformed	1,999.00 FS	*1,599.20 FS
2	1	*FRONT BUMPER FIXING PARTS	Not Necessary	258.00 FS	*- FS
3	1	*FRONT BUMPER GRILLE-CENTRE	Not Necessary	178.00 FS	*- FS
4	1	*FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	Not Necessary	191.00 FS	*- FS
5	1	*FRONT BUMPER AIR GUIDE-LH	Cracked	56.00 FS	*44.40 FS
6	1	*FRONT BUMPER AIR GUIDE GRILLE-LH	Cracked	333.00 FS	*266.00 FS
7	1	*FRONT BUMPER GUIDE SECTION-LH	Cracked	33.00 FS	*26.08 FS
8	1	*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	113.00 FS	*- FS
9	1	*FRONT BUMPER CARRIER	Not Necessary	733.00 FS	*- FS
10	1	*FRONT BUMPER LOCK CARRIER BRACKET	Not Necessary	125.00 FS	*- FS
11	2	*FRONT BUMPER SUPPORT-LH/RH	Not Necessary	52.00 FS	*- FS
12	1	*HORN-LH HIGH TONE	Not Necessary	37.00 FS	*- FS
13	1	*HORN SPRING SHACKLE-LH	Not Necessary	26.00 FS	*- FS
14	2	*FRONT PARKING AID SENSOR-INNER/OUTER	Not Necessary	462.00 FS	*- FS
15	4	*FRONT PARKING AID SEAL RING	Not Necessary	12.00 FS	*- FS
16	1	*FRONT FENDER-LH	Dented	700.00 FS	*559.60 FS
17	1	*FRONT FENDER ATTACHMENT PARTS	Not Necessary	183.00 FS	*- FS
18	1	*FRONT FENDER CLOSING ELEMENT-LH	Damaged	45.00 FS	*36.00 FS
19	1	*FRONT FENDER BRACKET-LH	Not Necessary	32.00 FS	*- FS
20	1	*FRONT FENDER DEFORMATION ELEMENT BRACKET-LHG	Not Necessary	45.00 FS	*- FS
21	1	*FRONT FENDER BRACKET	Not Necessary	29.00 FS	*- FS
22	1	*FRONT FENDER BRACE-LH	Not Necessary	107.00 FS	*- FS
23	1	*FRONT WHEEL HOUSING LINER-LH	Torn	223.00 FS	*178.40 FS
24	1	*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	82.00 FS	*- FS
25	1	*WHEEL SPOILER	Cracked	66.00 FS	*52.32 FS
26	1	*SPOILER-LH	Not Necessary	32.00 FS	*- FS
27	1	*STONE CHIP GUARD-LH	Necessary	46.00 FS	*36.64 FS
28	1	*BONNET	Dented	2,554.00 FS	*2,043.20 FS
29	1	*BONNET ATTACHMENT PARTS	Not Necessary	111.00 FS	*- FS
30	1	*BONNET IMPACT PROTECTION-LH/RH/CENTRE (3 Pcs)	Necessary	75.00 FS	*59.44 FS
31	1	*BONNET STRIKER-LH	Not Necessary	46.00 FS	*- FS
32	1	*BONNET LID LOCK	Not Necessary	196.00 FS	*- FS
33	1	*FENDER LEDGE COVER-LH	Necessary	28.00 FS	*22.24 FS
34	1	*BONNET COVER-LH	Necessary	21.00 FS	*16.16 FS
35	1	*LED HEADLIGHT-LH	Cut	7,087.00 FS	*5,669.60 FS
36	1	*LIFT CYLINDER-LH	Not Necessary	192.00 FS	*- FS
37	1	*FRONT RIM-LH	Cut	1,197.00 FS	*957.60 FS
38	1	*FRONT TYRE-LH (NPA)	Not Necessary	0.00 FS	*- FS
39	1	*SUNDRIES	Necessary	400.00 FS	*82.40 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	18,105.00	11,649.28
--------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER,LHS FRONT FENDER,BONNET AND LHS HEADLIGHT.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	3,150.00	1,750.00
3	TO RESPRAY FRONT BUMPER,BONNET AND LHS FRONT FENDER	New	3,000.00	1,650.00
4	TO RENEW LHS FRONT RIM AND TYRE.TO CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
6	TO DISMANTLE LHS FRONT DOOR PANEL TRIM.TO REMOVE AND REINSTALL LHS WING MIRROR ASSY	New	300.00	300.00
7	TO RESPRAY LHS FRONT DOOR	New	1,050.00	550.00
Gross Labour Cost (\$\$)			8,452.00	5,202.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >