

Jla Le

LCRF PTE LTD
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Store (LKK) with Paper 10/10/19, 1.30 pm

Ms AIG Asia Pacific Insurance Pte Ltd
Date: 10/10/2019
Attn : MOTOR CLAIMS DEPT

ESTIMATE

5 day
L/S
Ry AL SM

VEHICLE NO. SLQ7280E
CHASSIS NO : RU31227027
MAKE / MODEL : Honda Vezel Hybrid 1.5 X CVT
DATE OF ACCIDENT : 07/10/2019
YOUR INSURED VEHICLE NUMBER : SLB8555K
MILEAGE : 193359 km

	<u>PARTS DeSCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	Rear tailgate / 00	1PC	\$1,450.00	\$1,450.00 1100/
2	Rear tailgate Vezel emblem / MK	1PC	\$86.80	\$86.80 /
3	Rear tailgate Honda emblem / MK	1PC	\$81.30	\$81.30 /
4	Rear tailgate windscreen moulding / MK	1PC	\$195.00	\$195.00 /
5	Rear tailgate weatherstrip / CR4	1PC	\$155.00	\$155.00 /
6	Rear tailgate lock / BT	1PC	\$550.00	\$550.00 230/
7	Rear tailgate lock catch X N/A	1PC	\$180.00	\$180.00 X
8	Rear end panel / 00	1PC	\$830.00	\$830.00 580/
9	Rear end panel top garnish / CR4	1PC	\$155.00	\$155.00 130/
10	Rear bumper / 00	1PC	\$955.00	\$955.00 900/
LIST TOTAL S\$:				\$4,638.10
20.00% DISCOUNT S\$:				\$927.62
				\$3,710.48

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

3458.10
 - 20%
 2766.48

Supplementary

Rear bumper R/L reflector lens

Rear smart buzzer

\$120 / GR

\$150 / GR

270
 - 20%
 216

SPECIAL NETT

1	Rear bumper clips	✓ MK	1 SET	\$80.00	30
2	End panel top garnish clips	✓ MK	1 SET	\$80.00	10
3	Reverse sensor	✓ SHM	1PC	\$490.00	290
4	Body sealant	✓ MK	1set	\$300.00	30
5	Windscreen sealant	✓ MK	1PC	\$2,100.00	49
Special Nett Total S\$:				\$3,050.00	310

LABOUR CHARGES

1	To labour charge for removing rear tailgate, rear end panel, rear bumper out to facilitate repairs and replacement of damaged parts		\$900.00	200 800
2	To respray rear tailgate, end panel and spare tyre panel	✓ Gump MK	\$1,000.00	600 700
	To conduct a standard of operating procedures post repairs scan test as arequirement upon completion of collision repairs		\$300.00	150
3	To remove and install rear tailgate glass		\$160.00	120
4	To deactivate and activate hybrid high voltage battery as a safety precatons		\$300.00	200
4	To apply rustproofing on all damaged parts		\$180.00	30
5	To check wiring system		\$100.00	30

LABOUR TOTAL S\$: \$2,940.00
TOTAL S\$: \$9,700.48 2030
7% GST \$679.03
GRAND TOTAL S\$: \$10,379.51

P- 2982-48

NI- 310

L - 2030

5322-48

L/S- 4257-98

= 4250

Vehicle Details	
Make	
Model	
Year	
Colour	
Engine	
Transmission	
Drive	
Vehicle Identification Number (VIN)	
Date	