

ASS. REC. BY:

REF: CS/PC1 19017935 / vt f3

Special Instruction:

Survivor:

Marcus

ASSIGNMENT (Office)

From (Person):

Joanny

of

FCL

Date/Time: 11.10.19 9030.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLW 2680K

Insured:

SH 9287M

at Workshop m/s

Kah Moho

Tel:

96796493

of 15 Ubi Road 4

Policy No:

Claim No:

D19006490 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

8.10.2019

CA / REV / REP. / REV 24 HRS

wp

H.O.D. Endorsement:

Date/Time: 11.10.19 9300.m

Person Contacted:

Po Soon

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLW 2680K - X

SH 9287M - NS/INC 17062464/ Hlvbr2

D.O.A - 06/04/2017

16/10 @ 9:51am - Revised via preli advise. email

REP: FCI

ASS. REC. BY:

Marcus

ASSIGNMENT

From:

Date:

14/10/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLW 2680K

at Workshop m/s

Kah Motor

of

15 ubi Road 4

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

oic: PO Soon

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

0.60k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR-Seen:

Consistent? : Yes or No

Est. Repairs:

3 days

Res.: Yes or No

Lump Sum:

1.51

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS / up

LTA 47447

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLW 2680K

Yr Regn:

2 / 18

Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA

Make:

Honda Jazz

c.c

1498

Colour

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

46349

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JHM6K5850JX 201549

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

8/10/19

D.O.I.

14/10/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

6/11/19 continue final by \$1575.52 with rollover

(Red: 1542.21, 49%)

RECEIVED 06 NOV 2019

Date/Time, File Pass to?

☐

: Preli. Report

1) 6/11 Typist

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Report Format:

TP

Lump Sum / 12: (\$)

1575.52

Survey Fee:

Transportation:

3 + RS. SI

Photos

Others

TOTAL

130

50

14

194



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19006498MFSH

Date: 16/10/2019

Our Ref: CS/FCI19017935/Uff3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLW 2680K

Please be informed that we had conducted the inspection of the abovementioned vehicle 14/10/2019 at the premises of M/s Kah Motor have the following to report: -

Workshop Estimate Amount	: S\$ <u>3,117.73</u>
Revised Estimate Amount	: S\$ <u>1,575.52</u>
"Check" Items Amount	: S\$ <u>0.00</u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the
O/S Front portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully
Marcus
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	10-10-2019	Our Ref No. D19006498MFSH
Accident Date	08-10-2019	Claim Type. Third Party
Insured Vehicle	SH9287M	Third Party Vehicle. SLW2680K
Survey Location	15 UBI ROAD 4	
Contact Person.	YOU PO SOON	
Contact No.	0/ 96786493	Fax No. 0
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	KAH MOTOR CO SDN BHD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 16 October 2019 9:51 AM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments; SUR
Cc: 'Joanne Yong'
Subject: RE: SURVEY ASSESSMENT - D19006498MFSH/1
Attachments: PRELI ADVISED OF SLW 2680K.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLW 2680K**
Number of days (estimated) : 3 days

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Friday, 11 October 2019 9:33 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Joanne Yong' <JoanneYong@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19006498MFSH/1

Dear Sir/Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Sent: Friday, 11 October, 2019 9:03 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong <JoanneYong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19006498MFSH/1

Dear Sir/Mdm,

Get More Cash for Your Car, Post an Ad Today

Receive a higher selling price by selling your car yourself.
Advertise it for sale at just \$58, list till sold.

Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Qashqai 2.0A Premium Sunroof Model

Superb Well Maintain Condition
Inside Out. High Loan Available,
Min Cash Upfront
Auto Induz3 StarAd

PRIME MOTOR & LEASING
(CHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES)
With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Browse by Category








Sort by Date Posted

20 results/page

11 vehicles

jazz

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	jazz		Any	Any	2018	Any	Any	Any	Available
	Honda	Jazz 1.5A RS	\$72,800	\$7,310 /yr	31-Jul-2018	1,498 cc	14,085 km	Hatchback	Available
Well Taken Care By 1 Owner. Still Under Kah Motor Warranty. Must View To Appreciate. We Offer Very High Trade In. Loan From 2.28%... Mayfair Motoring Posted: 14-Oct-2019 Tags: 2018 Honda Jazz, 2018 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda									
	Honda	Jazz 1.3A	\$64,800	\$6,990 /yr	15-Aug-2018	1,318 cc	7,388 km	Hatchback	Available
Comes With 5years Warranty With Unlimited Mileage, Free Servicing Till 14 Aug 2021, No Gimmicks. Attractive Loan Package Interest Fr... Autotruster Traders Pte Ltd Posted: 14-Oct-2019 Tags: 2018 Honda Jazz, 2018 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda									
	Honda	Jazz 1.3A	\$65,500	\$6,910 /yr	01-Nov-2018	1,318 cc	9,000 km	Hatchback	Available
1 Owner, As Good As New, Interior And Exterior 3 Years Of Warranty, Unit From Kah Motor At Ubi, Very Low Mileage, Park Under Shade... 360 VR Cars Posted: 12-Oct-2019 Tags: 2018 Honda Jazz, 2018 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda									
	Honda	Jazz 1.5A RS	\$67,800	\$7,230 /yr	09-Jan-2018	1,498 cc	33,000 km	Hatchback	Available
Cheapest Unit, Not A PHV Unit, 5 Years Unlimited Mileage Warranty By Kah Motor, 1 Owner, Keyless Entry, Reverse Camera, Bluetooth,... Posted: 12-Oct-2019 Tags: 2018 Honda Jazz, 2018 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda									
	Air Filter (Honda Jazz GK) Air Filter for Honda Jazz GK 2013-on. More info about this product								
	Honda	Jazz 1.3A	\$66,800	\$7,050 /yr	08-Nov-2018	1,318 cc	16,000 km	Hatchback	Available
1 Owner Agent Unit With Warranty Till 2023. Extremely Spacious Cabin And Very Versatile Rear Seats To Cater To Your Different Carryin... Posted: 12-Oct-2019 Tags: 2018 Honda Jazz, 2018 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda									
	Honda	Jazz 1.5A RS	\$79,800	\$8,140 /yr	17-Jul-2018	1,498 cc	26,000 km	Hatchback	Available
Cheapest In The Market, Extremely Well Taken Care Of. Agent Maintained Since Day 1, Look And Smell Just Like A Brand New Car, Acci... Heritage Auto Enterprise Pte Ltd Posted: 12-Oct-2019 Tags: 2018 Honda Jazz, 2018 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda									
	Honda	Jazz 1.5A RS	\$69,800	\$7,190 /yr	26-Apr-2018	1,498 cc	37,500 km	Hatchback	Available
COE Up, Price Lowest In RS Market, Warranty Till 2021. Full Service History With Agent. Sparking Rouge Amethyst Metallic Exterior Cou... Car Buyers Automotive Pte Ltd									

Compare

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	369J
Vehicle Details	
Vehicle No.:	SLW2680K
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Oct 2019
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.5 CVT
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	L15B33110650
Chassis No.:	JHMGK5850JX201549
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$16,368.00
Original Registration Date:	05 Feb 2018
First Registration Date:	05 Feb 2018
Transfer Count:	0
Actual ARF Paid:	\$16,368.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Feb 2028
PARF Rebate Amount:	\$12,276.00
Intended COE Rebate Details	
COE Expiry Date:	04 Feb 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,339.00
COE Rebate Amount:	\$35,171.00
Total Rebate Amount:	\$47,447.00

The information contained herein is correct as at 14 Oct 2019

OK



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: MS FIRST CAPITAL INSURANCE LIMITED 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877
Registration No	: SLW2680K
Chassis No	: JHMGK5850JX201549
Model	: JAZZ 1.5VTIR CVT 18YM (EURO 6)
Owner's Name	: ANUAR BIN MOHAMED SAID
Ins Policy No.	:
Date of Accident	: 8/10/2019

Document No. : SQT19004446
Date : 9. Oct 2019
Customer No. : WZF002
Svc Advisor : YOU PO SOON
Engine No : L15B33110650
Date | Time : 9. Oct 2019 5:15:34 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Date of Accident				LKK Auto Consultants hence notify	0% GST	Amount	Amount	Amount incld GST
Item	Description	Qty	Unit Price	Disc %	Vinyl Amount			
	TP DIRECT SETTLEMENT (J/NO:) OWNER: ANUAR BIN MOHAMED SAID OWNER INSURER: TOKIO MARINE INSURANCE ACC DATE: 08/10/2019 SURVEYED BY: DATE: REF NO: TP INSURER: MS FIRST CAPITAL INSURANCE LIMITEDMS F TP VEH: SH9287M							
04715-T5B-J50ZZ	FACE,R.R.BUMPER	r 1	502.50	X 25		376.87	26.38	403.25
71593-T5A-J50	SPACER,R.RR.BUMPER SIDE	n n 1	16.90	x 25		12.67	0.89	13.56
71598-T5A-J50	SPACER,L.RR.BUMPER SIDE	n n 1	16.90	x 25		12.67	0.89	13.56
91505-TM8-003	CLIP,BUMPER	net 9	2.30	/ 25		15.52	1.09	16.61
Sum Item						417.73	29.25	446.98
BOSUN	SUNDRIES	m 1	50.00	20	*	50.00	3.50	53.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	100.00	80	*	100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	n n 1	150.00	x	*	150.00	10.50	160.50
BKFE21K	STRAIGHTEN ALIGN RR L FENDER.	1	1300.00	50	*	1300.00	91.00	1391.00
BP02R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (2P)	1	1100.00	900	*	1100.00	77.00	1177.00
Sum Labor						2700.00	189.00	2,889.00

Survey By

Date & Time

Excess

Status

Total Amount	3,117.73	218.25	3,335.98
---------------------	----------	--------	----------

Total (Inclusive of GST)	3,335.98
---------------------------------	-----------------

Printed on 9/10/2019 5:23:31 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer	: MS FIRST CAPITAL INSURANCE LIMITED 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877	Document No.	: SQT19004446	Page	2
Registration No	: SLW2680K	Date	: 9. Oct 2019		
Chassis No	: JHMGK5850JX201549	Customer No.	: WZF002		
Model	: JAZZ 1.5VTIR CVT 18YM (EURO 6)	Svc Advisor	: YOU PO SOON		
Owner's Name	: ANUAR BIN MOHAMED SAID	Engine No	: L15B33110650		
Ins Policy No.	:	Date Time	: 9. Oct 2019 5:15:34 PM		
Date of Accident	: 8/10/2019	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Signature	_____						

Printed on 9/10/2019 5:23:31 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**HONDA**

Attn: Marcus Chua

SERVICE PRE-INVOICE**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0054366 / MS FIRST CAPITAL
 Chassis No: JHMGK5850JX201549
 License No: SLW2680K
 Mileage: 47017
 Engine No: L15B33110650

Document No: SVO19068568
 Printed By: PSYOU
 Order Date: 23. October 2019
 Order Time: 11:06:37 AM
 Service Advisor: YOU PO SOON

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount Incd GST
	TP DIRECT SETTLEMENT (J/NO: 73645) OWNER: ANUAR BIN MOHAMED SAID OWNER INSURER: TOKIO MARINE INSURANCE ACC DATE: 08/10/2019 SURVEYED BY: Marcus Chua DATE: 14-10-19 REF NO: D19006498MFSH TP INSURER: MS FIRST CAPITAL INSURANCE LIMITEDMS F TP VEH: SH9287M						
91505-TM8-003	CLIP,BUMPER	9	2.30	25	15.52	1.09	16.61
	SUM PARTS:				15.52	1.09	16.61
BOSUN	0760	1	20.00		20.00	1.40	21.40
	SUNDRIES						
BML02I	0626	1	80.00		80.00	5.60	85.60
	INSPECT FR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)						
BKFE21K	0626	1	560.00		560.00	39.20	599.20
	STRAIGHTEN ALIGN RR L FENDER.						
BP02R	EXT-YBH	1	900.00		900.00	63.00	963.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(2P)						
	SUM LABOUR:				1,560.00	109.20	1,669.20
	TOTAL SGD				1,575.52	110.29	1,685.81

Total Payable (SGD)**1,685.81**

GST Amount is calculated from individual line(s)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19017935/Ulf3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 12-11-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SH 9287M	Veh. Inspected	SLW 2680K
	Policy No.		Coverage (\$)	0.00
	Claim No.	D19006498MFSH	Excess (\$)	1,000.00
	Assign From	JOANNE YONG	Assign Date	11/10/2019
2. Vehicle Particulars & Condition				
	Make & Model	HONDA JAZZ (A)	c.c	1498
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	JHMGK5850JX201549	Colour	BLUE
	Odometer	46349	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/60 R15	BRIDGESTONE	8 mm
	L/H Front Tyre	205/60 R15	BRIDGESTONE	8 mm
	R/H Rear Tyre	205/60 R15	BRIDGESTONE	8 mm
	L/H Rear Tyre	205/60 R15	BRIDGESTONE	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	08/10/2019	Inspection Date	14/10/2019
	Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610		
5a. Remarks				
	A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLW 2680K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FACE,RR BUMPER (SN)	TO REPAIR SEE LABOUR	376.87	-
1	SPACER,R RR BUMPER SIDE (SN)	NOT NECESSARY	12.67	-
1	SPACER,L RR BUMPER SIDE (SN)	NOT NECESSARY	12.67	-
9	CLIP,BUMPER (SN)	NECESSARY	15.52	15.52
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
			467.73	35.52
LABOUR				
	INSPECT RR LIGHTING MECHANISMS.PERFORM WATER.		100.00	80.00
	REMOVE & RENEW REVERSE SENSORS-4 PCS.	NOT NECESSARY	150.00	-
	STRAIGHTEN ALIGN RR L FENDER.INCLUSIVE OF THE REPAIR OF FACE,RR BUMPER.		1,300.00	560.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (2P).		1,100.00	900.00
			2,650.00	1,540.00
GRAND TOTAL			3,117.73	1,575.52
RECOMMENDED COST OF REPAIRS				1,575.52

Report Ref No. CS/FC19017935/Utf3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.