

ASSIGNMENT

Surveyor:

MARCUS

DOI: 11/10/2019

Date / Time: 11/10/2019

Registered in Merimen: 11/10/2019

Pre-assign / CCU / FTE



Insured Vehicle No. : SJD 5756E
 Name of Insured : TAN JEE HENG
 Insured Tel No. : HP: +65-90054303
 Excess Sec II :SS D.O.A : 10/10/2019
 Is driver the owner? (YES / NO) Nature of Accident :

Claim No. : 223083712SG
 Policy No. : 2100333936
 Make / Model : TOYOTA RUSH
 Place of Accident : ECP TWDS CITY

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

SLD 8168J



INSRS:
WSP: FASTECH
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	☐
	After call ltr to OI:	☐
	Authorisation To Act:	☐
	Release Voucher:	☐
	Final Repair Bill:	☐
	Car Rental Invoice:	☐
	Towing Invoice:	☐
	LTA / GIA :	☐
	Medical Bill:	☐
	PIR:	☐
	Mandate/Reject Instruction:	☐
	LOD	☐
	Payment Breakdown Form:	☐
	Post-Repair Photos:	☐
	Others:	☐
PRELIMINARY ADVICE Date/Time:	Sent By:	Confirm by:
FINALIZATION Date/Time:	Confirm with:	Confirm by:
Repair Cost: SS	(days) Reduction: %	Email ☐ Call ☐
FINAL SETTLEMENT Date/Time: 12/3/2020	Confirm with: Ong Shiny	Email ☐ Call ☐
Final Liability: % 100	(Agreed / Assessed) BOLA S/N No. : 28	If NO or B 28, Ass. Lia : 01
Repair Cost: (w/431) SS 7704.00		3rd C.C. 02 was 2nd
Loss of Rental (LOR): SS 450.00	(3 days) x \$150	
Loss of Use (LOU): SS -	(\$ x days)	
Loss of Income (LOI): SS -	(\$ x days)	
LOR only ☒ LOU only ☐	LOR + LOU ☐ LOR + LOI ☐ [Tick only one]	
GIA/LTA Search: SS 2.00		
Medical: SS -		
Disbursement: SS -	(e.g. Tow/ Independent)	
Legal Cost: SS -		
Total: SS 8156.00	Global Sum SS: 8000.00	
FINAL PAYMENT Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1: SS 8000.00	Name 1: Fastech Auto Pte Ltd	
Payee 2: (Strike if N.A.) SS	Name 2:	
Payee 3: (Strike if N.A.) SS	Name 3:	

COPY SENT 19/3/2020

FASTECT AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46,48,50 AUTOBAY
SINGAPORE 417883

VEHICLE NO: SLD 81683

QTY	PARTICULAR
1 PCS	BOOTLID 1562.00
1 PCS	BOOTLID REAR LOGO 75.00
1 PCS	BOOTLID '528 EMBLEM
1 PCS	BOOTLID INNER LOCK 299.08
2 PCS	BOOTLID REFLECTORS @\$685.00
1 PCS	BOOTLID WEATHERSTRIP 293.66
1 PCS	BOOTLID INNER TRIM
1 SET	BOOTLID INNER TRIM CLIPS
2 PCS	TAILLAMPS @\$750.00 590.00
1 PCS	REAR BUMPER (R) 1615.00
1 PCS	REAR BUMPER LOWER SPOILER
1 PCS	REAR BUMPER TOW COVER
4 PCS	REAR BUMPER PDC SENSORS @\$313.0 215x2=430
1 PCS	REAR BUMPER PDC SENSOR WINE
1 PCS	REAR BUMPER REINFORCEMENT 640.93
2 PCS	REAR BUMPER REINFORCEMENT STAY BRACKETS @\$140.00
1 PCS	REAR BUMPER LOWER GUIDE
2 PCS	REAR BUMPER SIDE RETAINERS @\$195.00
1 SET	REAR BUMPER CLIPS
2 PCS	REAR BUMPER REFLECTORS @\$115.00
1 PCS	REAR BUMPER INNER PAD
1 PCS	REAR BUMPER INNER FRAME GARNISH 266.00
1 PCS	REAR END PANEL
1 PCS	REAR END PANEL TOP GARNISH
1 PCS	REAR EXHAUST
1 PCS	REAR EXHAUST HEAT SHIELD
2 PCS	REAR EXHAUST MOUNTING @\$60.00
1 PCS	REAR FLOOR PANEL
1 PCS	REAR FLOOR PANEL TOP BOARD
2 PCS	REAR FENDER INNER TRIMS @\$397.00

S.NETT

1 PCS	REAR END PANEL SEALANT
1 PCS	REAR EXHAUST CHROME
1 PCS	REAR LICENCE PLATE W/HOLDER

LABOUR CHARGES:

TO CHECK WIRING	
TO DISMANTLE & REPLACING REVERSE SENSOR	
TO TRANSFER BOOTLID MECHANISM	
TO DISMANTLE & REFIX REAR EXHAUST	
TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY	
TO SPRAY RUST PROOFING	
LABOUR FOR PANEL BEATING & REPLACING PARTS	
TO PUTTY & SPRAY PAINTING	

Net Amount
Rue
2/5 7200
11/10/19
Sdy.

Body/nerap	\$1,866.10
shu	\$85.00
NF	\$57.00 X
shu/tw	\$315.00
11	\$1,370.00 X
tw	\$366.00
11	\$365.00 X
11	\$50.00 X
0/500	\$1,500.00 120
DO/02	\$1,658.00
de/nerap	\$423.65
11	\$36.00 X
shu	\$1,252.00 200
11	\$386.00 X
shu	\$685.00
NF	\$280.00 X
NF	\$185.00 X
11	\$390.00 X
11	\$60.00
11	\$230.00 X
NF	\$268.00 X
11	\$335.00
300/00	\$1,018.50
tw	\$388.00
11	\$1,980.00 X
11	\$245.00 X
11	\$120.00 X
11	\$1,495.00 X
11	\$485.00 X
11	\$794.00 X
	\$18,688.25

11	\$50.00
50	\$200.00 X
11	\$50.00 X

	\$80.00 30
	\$80.00 50
	\$80.00 60
11	\$150.00 X
	\$120.00 80
	\$100.00 60
	\$1,080.00 800
	\$1,500.00 1000

LKK Auto Consultants hence notify the Repairer of the following:
Total = 22178.25

- Immediately before/after spray painting
- Damaged part(s) during resurvey
- Repairs subject to confirmation
- Repairs on a "Without Prejudice" basis
- Repairs (work) is allowed
- Supplementary repairs must be resurveyed
- Subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date

7661.82

608.63

9074.63

7/20


> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	330I
Vehicle Details	
Vehicle No.:	SLD8168J
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Oct 2019
Vehicle Make:	B.M.W.
Vehicle Model:	528I A
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	08137580N53B30A
Chassis No.:	WBAFS52060C276287
Maximum Power Output:	190.0 kW (254 bhp)
Open Market Value:	\$48,763.00
Original Registration Date:	17 Mar 2011
First Registration Date:	17 Mar 2011
Transfer Count:	4
Actual ARF Paid:	\$48,763.00 24381
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Mar 2021
PARF Rebate Amount:	\$26,819.00
Intended COE Rebate Details	
COE Expiry Date:	16 Mar 2021
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$62,001.00
COE Rebate Amount:	\$8,816.00
Total Rebate Amount:	\$35,635.00

The information contained herein is correct as at 14 Oct 2019

OK



bmw 528

Price Range

Depreciation

Year Reg

Vehicle Type

Home » Used Cars » Karz Automobile » BMW 5 Series 528i Sunroof

BMW 5 Series 528i Sunroof

- Overview
- Financial
- Insurance
- Accessories
- Similar
- Research
- Photos
- Map



Price	\$71,988		
Depreciation	\$17,370 /yr View models with similar depre	Reg Date	03-Aug-2012 (2yrs 9mths 19days COE left)
Mileage	N.A.	Manufactured	2011
Road Tax	\$1,210 /yr	Transmission	Auto
Dereg Value	\$51,218 as of today (change)	OMV	\$46,592
COE	\$83,000	ARF	\$46,592
Engine Cap	1,997 cc	Power	180.0 kW (241 bhp)
Curb Weight	1,695 kg	No. of Owners	5
Type of Vehicle	Luxury Sedan		

Features

Powerful And Responsive 2.0L Twin Powered Turbo Engine With 8 Speed Auto Transmission, Airbags, Traction Control. View specs of the BMW 528i

Accessories

Keyless Entry/Start, Bluetooth, GPS, Reverse Camera, Paddle Shifters, Auto Rear Blind, Eisenmann Exhaust, 19 Inch Rims On P Zero, 6WB Digital Cluster.

Description

Tastefully Done Up F10 528 With Tons Of Upgraded Accessories, A Unit That Strikes An Excellent Balance Between Comfort And Agility, Roomy Cabin Space With Top Notch Interior Layout, Nice Setup For Your Daily Drive With A Peace Of Mind, Decent Mileage Clocked With Very Regular Maintenance, High Trade In, Various Loan Pac
Miss The Chance To Own This Unit, Call Us Now.

Compare



- Shortlist
- Compare
- Report Error
- More

Seller Information

Company	Karz Aut » dealer's » 9 vehs s
Address	31 West C Search car
Location	West Coast
Office No	62882454
Contact Person(s)	Dave

New CarsUsed CarsSell My CarDirectoryProductsInsuranceArticlesForum

2-HR
FREE
WEEKDAY PARKING



Spend \$30 to qualify
NOW TILL 15 NOV 2019
[MON - FRI, 6PM - 10PM]

CLICK TO FIND OUT MORE

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an AdAdvertiser LoginWays of Selling

Toyota Vios 1.5A E (COE Till 01/2024).



Excellent Condition With New
Leather And Paint Job.
Direct Owner Staraid

Think One Automobile

NEW & USED
COMMERCIAL VEHICLES



Browse by Category

Sort by Date Posted

3 vehicles

bmw 520

Advanced Search

Make:ModelPriceDepreciationReg DateEng CapMileageVeh T

Search Selection

bmw 520

Any

Any

2011

Any

Any

/



BMW 5 Series 520i

\$56,000

\$16,350 /yr

31-Oct-2011

1,997 cc

-

Lu

Luxury Comfort Sedan With Clean And Nice Spacious Interior. Recently Underwent Worth \$8k With Receipts Of Maintenance And Repair Work. Parked Under Shelter All The Time. Nice Carplate. Consignment Unit. Viewing By Appointment Only. STA/VICOM/AA Evaluation Fri...

Posted: 12-Oct-2019 Tags: 2011 BMW 520i, 2011 bmw 520i, BMW 520i, bmw 520i, BMW, 520i, Used BMW



BMW 5 Series 520i

\$58,688

\$16,760 /yr

08-Dec-2011

1,997 cc

-

Lu

All Time Favourite Luxury Sedan Powered By A 2.0 Twin Scroll Turbo Charged Engine, Roomy Cabin Space With High Comfort Level. Owned By A Lady Accountant. Selling Due To Upgrading, Super Safe Buy, Selling Near To Scrap Value. Owner Consignment Unit, High T...

Karz Automobile

Posted: 11-Oct-2019 Tags: 2011 BMW 520i, 2011 bmw 520i, BMW 520i, bmw 520i, BMW, 520i, Used BMW



BMW 5 Series 520i

\$53,383

\$15,030 /yr

01-Nov-2011

1,997 cc

-

Lu

Immaculate Conditions. 01 Expatriate Owner, Consignment Unit. Car In Showroom, View Anytime. New 6 Months Road Tax. Genuine Low Mileage, With Absolutely No Repairs Needed. Highest Offer For All Trade In. STA/VICOM, Workshop Inspection, Anytime Welcome. Bank...

Posted: 04-Oct-2019 Tags: 2011 BMW 520i, 2011 bmw 520i, BMW 520i, bmw 520i, BMW, 520i, Used BMW

Save this search criteria, to get email alerts whenever a match is found.

Make:ModelPriceDepreciationReg DateEng CapMileageVeh T

For old advertisements, view Expired ads

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car insurance. Find buy used bmw 520, bmw 520 Singapore, used bmw 520 Singapore, used bmw 520, used vehicles Singapore or even buy used bmw 520 Singapore comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our page for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & CC

All information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but not accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of the information.

https://www.sgcarmart.com/used_cars/listing.php?RGD=2011&MOD=bmw 520&RPG=20&VEH=0&AVL=2

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 330I

Vehicle Details

Vehicle No.: SLD8168J
Vehicle to be Exported: No
Intended Deregistration Date: 11 Oct 2019
Vehicle Make: B.M.W.
Vehicle Model: 528I A
Primary Colour: White
Manufacturing Year: 2010
Engine No.: 08137580N53B30A
Chassis No.: WBAF552060C276287
Maximum Power Output: 190.0 kW (254 bhp)
Open Market Value: \$48,763.00
Original Registration Date: 17 Mar 2011
First Registration Date: 17 Mar 2011
Transfer Count: 4
Actual ARF Paid: \$48,763.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 16 Mar 2021
PARF Rebate Amount: \$26,819.00

Intended COE Rebate Details

COE Expiry Date: 16 Mar 2021
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$62,001.00
COE Rebate Amount: \$8,866.00
Total Rebate Amount: \$35,685.00

The information contained herein is correct as at 11 Oct 2019

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)
Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Oct 2019 Edit Reg		11 Oct 2019 00:00 Edit Adj Rpt	\$57,200.00 Edit Estimates	\$57,200.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS				[Created by adjuster]	
Insured:	TAN JEE HENG, ID: S74254811				
Main Claimant:	KWEK CHENG SENG, ID: S71253301				
Vehicle Reg. No.:	SLD8168J	Date of Loss:	10/10/2019 17:00 - :59 [102 Months and 23 Days From LTA Reg Date (Man Yr)]		
Claim Type:	TP / 6223083712SG	Policy/Cover Note No.:	2100333936 (Comprehensive)		
Vehicle Reg. No. (Insured):	SJD5756E	Policy No. (Claimant):	GA468737/1		
		Excess:			
Repairer:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405				
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com				
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888				
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 22/10/2019]				

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

• AIG_SG_EXPRESS (17/03/2020): Alert - Adj Mandate Approved (\$58000.00) - SLD8168J - Claim Handler: Tan, Bennie...

• AIG_SG (14/10/2019): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLD8168J (6223083712SG)
[SJD5756E]
TP
KWEK CHENG SENG
Oct 10 2019 5:00PM
[TAN JEE HENG]
Fastech Auto Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

Letters/Correspondences

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/10/19 18:10	Odometer Reading		Load JPG
2	11/10/19 18:10	Chassis Number		Load JPG
3	11/10/19 18:10	General View		Load JPG
4	11/10/19 18:10	General View		Load JPG
5	11/10/19 18:10	General View		Load JPG
6	11/10/19 18:10	General View		Load JPG
7	11/10/19 18:10	General View		Load JPG
8	11/10/19 18:10	General View		Load JPG
9	11/10/19 18:10	General View		Load JPG
10	11/10/19 18:10	General View		Load JPG
11	11/10/19 18:10	General View		Load JPG
12	11/10/19 18:10	General View		Load JPG
13	11/10/19 18:10	General View		Load JPG
14	11/10/19 18:10	General View		Load JPG
15	11/10/19 18:10	General View		Load JPG
16	11/10/19 18:10	General View		Load JPG
17	11/10/19 18:18	General View		Load JPG
18	11/10/19 18:18	General View		Load JPG
19	11/10/19 18:18	General View		Load JPG
20	11/10/19 18:18	General View		Load JPG
21	11/10/19 18:18	General View		Load JPG
22	11/10/19 18:18	General View		Load JPG
23	11/10/19 18:18	General View		Load JPG
24	11/10/19 18:18	General View		Load JPG
25	11/10/19 18:18	General View		Load JPG
26	11/10/19 18:18	General View		Load JPG
27	11/10/19 18:18	General View		Load JPG
28	11/10/19 18:18	General View		Load JPG
29	11/10/19 18:18	General View		Load JPG
30	11/10/19 18:18	General View		Load JPG
31	11/10/19 18:18	General View		Load JPG
32	11/10/19 18:18	General View		Load JPG
33	11/10/19 18:18	General View		Load JPG
34	11/10/19 18:18	General View		Load JPG
35	11/10/19 18:18	General View		Load JPG
36	11/10/19 18:18	General View		Load JPG
37	11/10/19 18:18	General View		Load JPG
38	11/10/19 18:18	General View		Load JPG
39	11/10/19 18:18	General View		Load JPG
40	11/10/19 18:18	General View		Load JPG

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
41	11/10/19 18:18	General View	 Load JPG	☒
42	11/10/19 18:18	General View	 Load JPG	☒
43	11/10/19 18:18	General View	 Load JPG	☒
44	11/10/19 18:18	General View	 Load JPG	☒
45	11/10/19 18:18	General View	 Load JPG	☒
46	11/10/19 18:18	General View	 Load JPG	☒
47	11/10/19 18:18	General View	 Load JPG	☒
48	11/10/19 18:18	General View	 Load JPG	☒
49	11/10/19 18:18	General View	 Load JPG	☒
50	11/10/19 18:18	General View	 Load JPG	☒
51	11/10/19 18:18	General View	 Load JPG	☒
52	11/10/19 18:18	General View	 Load JPG	☒
53	11/10/19 18:18	General View	 Load JPG	☒
54	11/10/19 18:19	Reinspection Photo	 Load JPG	☒
55	11/10/19 18:19	Reinspection Photo	 Load JPG	☒
56	11/10/19 18:19	Reinspection Photo	 Load JPG	☒
57	11/10/19 18:19	Reinspection Photo	 Load JPG	☒
58	11/10/19 18:19	Reinspection Photo	 Load JPG	☒
59	11/10/19 18:19	Reinspection Photo	 Load JPG	☒
60	11/10/19 18:19	Reinspection Photo	 Load JPG	☒
61	11/10/19 18:19	Reinspection Photo	 Load JPG	☒
62	11/10/19 18:19	Reinspection Photo	 Load JPG	☒
63	11/10/19 18:19	Reinspection Photo	 Load JPG	☒
64	11/10/19 18:19	Reinspection Photo	 Load JPG	☒
65	11/10/19 18:19	Reinspection Photo	 Load JPG	☒
66	11/10/19 18:19	Reinspection Photo	 Load JPG	☒
67	11/10/19 18:19	Reinspection Photo	 Load JPG	☒
68	11/10/19 18:19	Reinspection Photo	 Load JPG	☒
69	11/10/19 18:19	Reinspection Photo	 Load JPG	☒
70	11/10/19 18:19	Reinspection Photo	 Load JPG	☒
71	11/10/19 18:19	Reinspection Photo	 Load JPG	☒
72	11/10/19 18:19	Reinspection Photo	 Load JPG	☒
73	11/10/19 18:19	Reinspection Photo	 Load JPG	☒
74	11/10/19 18:19	Reinspection Photo	 Load JPG	☒
75	11/10/19 18:19	Reinspection Photo	 Load JPG	☒
76	11/10/19 18:19	Reinspection Photo	 Load JPG	☒
77	11/10/19 18:19	Reinspection Photo	 Load JPG	☒
78	11/10/19 18:19	Reinspection Photo	 Load JPG	☒
79	11/10/19 18:19	Reinspection Photo	 Load JPG	☒
80	11/10/19 18:19	Reinspection Photo	 Load JPG	☒
81	11/10/19 18:19	Reinspection Photo	 Load JPG	☒
82	11/10/19 18:19	Reinspection Photo	 Load JPG	☒
83	11/10/19 18:19	Reinspection Photo	 Load JPG	☒
84	11/10/19 18:19	Reinspection Photo	 Load JPG	☒
85	11/10/19 18:19	Reinspection Photo	 Load JPG	☒
86	11/10/19 18:19	Reinspection Photo	 Load JPG	☒
87	11/10/19 18:19	Reinspection Photo	 Load JPG	☒
88	11/10/19 18:19	Reinspection Photo	 Load JPG	☒
89	11/10/19 18:19	Reinspection Photo	 Load JPG	☒
90	11/10/19 18:19	Reinspection Photo	 Load JPG	☒
91	11/10/19 18:19	Reinspection Photo	 Load JPG	☒
92	11/10/19 18:19	Reinspection Photo	 Load JPG	☒
93	11/10/19 18:19	Reinspection Photo	 Load JPG	☒
94	11/10/19 18:19	Reinspection Photo	 Load JPG	☒
95	11/10/19 18:19	Reinspection Photo	 Load JPG	☒

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
96	11/10/19 18:19	Reinspection Photo		Load JPG	☒
97	11/10/19 18:19	Reinspection Photo		Load JPG	☒
98	11/10/19 18:19	Reinspection Photo		Load JPG	☒
99	11/10/19 18:19	Reinspection Photo		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	14/10/19 17:05	TP GIA REPORT		Load PDF	
2	21/01/20 10:22	RENTAL RECEIPT		Load PDF	
3	21/01/20 10:22	GIA SEARCH		Load PDF	
4	21/01/20 10:22	LOD		Load PDF	
5	21/01/20 10:22	LETTER TO OI		Load PDF	
6	22/01/20 08:54	TP_ESTIMATE-MARKED		Load PDF	
7	20/03/20 09:41	WORKSHOP INVOICE		Load PDF	
8	20/03/20 09:41	AUTHORISATION TO ACT FORM		Load PDF	
9	20/03/20 09:41	Release Voucher		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	14/10/19 12:00	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SJD5756E (Insd veh)	Model:	BMW 528i 3.0 (A)
	SLD8168J (TP veh)		
Date of Accident:	10/10/2019		

Global Sum Settlement	:	☒ [X] Yes	☐ [] No
Repair Estimate	:	\$	23,730.73
Final Repair Cost	:	\$	8,000.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	3 days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	8,000.00
Is Third Party Workshop GIA Registered? ☐ [] YES ☒ [X] NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ 0 _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Fastech Auto Pte Ltd	:	\$ 8,000.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

20 Mar
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19017947/UDA3Q2

Date: 20/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100333936
 Claimant Vehicle No : SLD8168J Insured Vehicle No : SJD5756E
 Date of Loss: 10/10/2019 Nature of Claim: TP Claim No: 6223083712SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLD8168J
 Make & Model: BMW 528i, 3.0 (A) Engine No: 08137580N53B30A
 Reg. Date: 17/03/2011 (Man. Year: 2010) Chassis No: WBAFS52060C276287
 Colour: Blue Odometer: 164430 km
 Engine Capacity: 2996 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 245/40Z R19 Rear Tyre Size: 275/35Z R19
 Front Left Side: Nexen 6 mm Rear Left Side: Sumitomo 6 mm
 Front Right Side: Nexen 6 mm Rear Right Side: Sumitomo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,988.25	6,945.64	12,042.61	63.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,190.00	2,080.00	1,110.00	34.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,178.25	9,025.64	13,152.61	59.30
Approved Total (Overridden) (S\$)		7,200.00		
(S\$)	22,178.25	7,200.00	14,978.25	67.54
+ GST 7.00/7.00% (S\$)	1,552.48	504.00	1,048.48	67.54
Nett Amount (S\$)	23,730.73	7,704.00	16,026.73	67.54
+ Car Rental (3.0 x S\$150.00/day) (S\$)		450.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		8,156.00		
Global Sum Settlement (S\$)		8,000.00		

INSPECTION

Date of Assignment: 11/10/2019
 Date Inspected: 11/10/2019 Inspected At: Fastech Auto Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, #01-46/48/50
 Autobay
 Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent / Warped	1,866.10 F	*1,562.00 FL
2	1		*BOOTLID REAR LOGO	Necessary	85.00 F	*75.00 FL
3	1		*BOOTLID 528 EMBLEM	Not fitted	57.00 F	*- FL
4	1		*BOOTLID INNER LOCK	Shorted / Twisted	315.00 F	*299.08 FL
5	2		*BOOTLID REFLECTORS	Not Necessary	1,370.00 F	*- FL
6	1		*BOOTLID WEATHERSTRIP	Twisted	366.00 F	*293.66 FL
7	1		*BOOTLID INNER TRIM	Not Necessary	365.00 F	*- FL
8	1		*SET BOOTLID INNER TRIM CLIPS	Not Necessary	50.00 F	*- FL
9	1		*TAILLAMPS	O/S Cracked	1,500.00 F	*590.00 FL
10	1		*REAR BUMPER	Dented / Deformed	1,658.00 F	*1,615.00 FL
11	1		*REAR BUMPER LOWER SPOILER	Deformed / Warped	423.65 F	*423.65 FL
12	1		*REAR BUMPER TOW COVER	Not Necessary	36.00 F	*- FL
13	4		*REAR BUMPER PDC SENSORS	Shorted (2 PCS ONLY)	1,252.00 F	*430.00 FL
14	1		*REAR BUMPER PDC SENSOR WINE	Not Necessary	386.00 F	*- FL
15	1		*REAR BUMPER REINFORCEMENT	Bent	685.00 F	*640.93 FL
16	2		*REAR BUMPER REINFORCEMENT STAY BRACKETS	No such part	280.00 F	*- FL
17	1		*REAR BUMPER LOWER GUIDE	Not fitted	185.00 F	*- FL
18	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	390.00 F	*- FL
19	1		*SET REAR BUMPER CLIPS	Necessary	60.00 F	*60.00 FL
20	2		*REAR BUMPER REFLECTORS	Not Necessary	230.00 F	*- FL
21	1		*REAR BUMPER INNER PAD	Not fitted	268.00 F	*- FL
22	1		*REAR BUMPER INNER FRAME GARNISH	Cracked	335.00 F	*266.00 FL
23	1		*REAR END PANEL	Badly Dented	1,018.50 F	*1,018.50 FL
24	1		*REAR END PANEL TOP GARNISH	Twisted	388.00 F	*388.00 FL
25	1		*REAR EXHAUST	Repair	1,980.00 F	*- FL
26	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	245.00 F	*- FL
27	2		*REAR EXHAUST MOUNTING	Not Necessary	120.00 F	*- FL
28	1		*REAR FLOOR PANEL	Not Necessary	1,495.00 F	*- FL
29	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	485.00 F	*- FL
30	2		*REAR FENDER INNER TRIMS	Not Necessary	794.00 F	*- FL
31	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
32	1		*REAR EXHAUST CHROME	Serviceable	200.00 FS	*- FS
33	1		*REAR LICENCE PLATE W/HOLDER	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	18,988.25	7,711.82
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	766.18
Total Parts (S\$)	18,988.25	6,945.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	TO TRANSFER BOOTLID MECHANISM	New	80.00	60.00
4	TO DISMANTLE & REFIX REAR EXHAUST	New	150.00	0.00
5	TO DISMANTLE & REFIX SEAT ,CUSHION UPHOLSTERY	New	120.00	80.00
6	TO SPRAY RUST PROOFING	New	100.00	60.00
7	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	1,080.00	800.00
8	TO PUTTY & SPRAY PAINTING	New	1,500.00	1,000.00
Gross Labour Cost (S\$)			3,190.00	2,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >