

CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5018
cmmotors@singnet.com.sg

Our Ref: EST364/19/TP

Your Ref: TP claim against GBC6077A

9-Oct-19

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#08-16

Singapore 409179

Attn: Motor Claims Department

Dear Sir/Ms,

WBAJAS2010WA34697

TP AIG

Vic

Re: Estimated cost of repair to BMW 530i no: SFS2829S

Date of accident: 01-10-2019

Parts supply:

1 pc Boot <i>2ented</i>	S\$	2,450.60 ✓
1 pc Boot emblem - Logo <i>3mc</i>		71.25 ✓
1 pc Boot emblem - 530i <i>3mc</i>		66.80 ✓
2 pcs Boot hinges @\$118.80 <i>3mc</i>		237.60 +
2 pcs Boot damper @\$485.00 <i>3mc</i>		970.00 +
1 pc Boot inner lock <i>3mc</i>		385.00 +
1 pc Boot insulator <i>3mc</i>		229.50 +
8 pcs Boot insulator clips@\$5.00 <i>mc</i>		40.00 +
3 pcs Boot stoppers @\$26.70 <i>mc</i>		80.10 +
2 pcs Boot lamps @\$489.50 <i>RH 3mc</i>		979.00 +
2 pcs Boot side garnish @\$65.80 <i>mc</i>		131.60 +
1 pc Boot weatherstrip <i>mc</i>		216.50 +
2 pcs Boot no. plate lamps @\$25.40 <i>mc</i>		50.80 +
2 pcs Taillamps @\$787.50 <i>LH 3mc, RH 2mc</i>		1,575.00 ✓
2 pcs Taillamp clip @\$12.50 <i>mc</i>		25.00 -
2 pcs Taillamp side garnish @\$68.90 <i>mc</i>		131.80 +
1 pc Rear bumper <i>Dehd</i>		1,852.20 ✓
1 pc Rear bumper reinforcement <i>Best</i>		857.75 ✓
1 pc Rear bumper chrome <i>3mc</i>		356.80 ✓
2 pcs Rear bumper side brackets @\$133.50 <i>mc</i>		267.00 +
2 pcs Rear bumper side retainers @\$145.50 <i>mc</i>		291.00 ✓
2 pcs Rear bumper reflectors @\$45.70 <i>RH 3mc</i>		91.40 ✓
1 pc Rear bumper tow cover <i>Missing</i>		81.55 ✓
4 pcs Rear bumper PDC sensor @\$248.70 <i>2 pieces damaged</i>		994.80 ✓
6 pcs Rear bumper PDC sensor holder @\$23.80 <i>3mc</i>		142.80 ✓
1 pc Rear bumper PDC wireharness <i>mc</i>		232.85 +
1 pc Rear bumper inner centre garnish (3) <i>3mc</i>		168.50 ✓
1 pc Rear bumper inner garnish (5) <i>3mc</i>		188.50 ✓
1 pc Rear end panel <i>3mc</i>		1,417.15 ✓
1 pc Rear end panel garnish <i>3mc</i>		169.80 ✓
2 pcs Rear exhaust outer cover @\$185.45 <i>3mc</i>		185.45 ✓
1 pc Rear exhaust muffler <i>Best</i>		1,658.50 ✓
		16,596.60
	Less 10%:	(1,659.66)
		14,936.94

10469.80

9422.82

CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5018
cmmotors@singnet.com.sg

Re: Estimated cost of repair to BMW 530i no: SFS2829S

Date of accident: 01-10-2019

Parts supply:

Balance b/f: S\$ 14,936.94

S/Nett Items

1 pc Rear no. plate with cover (S/Nett) *run* 80.00 *+*

Labour charges:

To panel beating, welding, removing damaged parts and replacement of the parts as mentioned above etc.

To respray affected part.

To apply underseal.

To remove & refit rear reverse sensor

To reset fault code after repair.

To remove & refit of wirings.

1390

900.00	<i>500</i>
1,000.00	<i>600</i>
60.00	<i>+</i>
60.00	<i>✓</i>
100.00	<i>✓</i>
30.00	<i>✓</i>
S\$	<u>17,166.94</u>

Adm ✓
L/s 10/10/19

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Supplementary : 1489.50

total: 12302.32

L/s: 9.8K

振明摩哆 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5018
cmmotors@singnet.com.sg

Our Ref: EST364/19/TP

Your Ref: TP claim against GBC6077A

ESTIMATE

9-Oct-19

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#08-16

Singapore 409179

Attn: Motor Claims Department

Dear Sir/Ms,

Re: Supplementary cost of repair to BMW 530i no: SFS2829S

Date of accident: 01-10-2019

Parts supply:

1 pc Boot kick open sensor *2nd*
1 pc Boot kick open wire harness *2nd*
1 pc Boot kick open control unit *1 unit*
1 pc Rear bumper lower garnish (top) *found*
1 pc Rear bumper lower garnish (lower)
1 pc Exhaust shield (centre) *3 completed*
1 pc Exhaust shield (R/h)

S\$	280.00	✓
	120.00	✓
	650.00	✓
	180.00	✓
	140.00	✓
	190.00	✓
	95.00	✓
	<u>1,655.00</u>	
Less 10%:	(165.50)	
S\$	<u><u>1,489.50</u></u>	

Adrian S
H.S.

Supplementary: 1489.50.