

LEXUS

TAX INVOICE

Borneo Motors (Singapore) Pte Ltd

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

www.lexus.com.sg

Lexus Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

ESTIMATE

Account Detail		Account No	Customer Detail	
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICC11	Mr Ng Eng Teck 370H Alexandra Road #06-07 The Anchorage Singapore 159961	
Document No		0	Mobile: 96511111	
Document Date		08/10/2019		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	AEXGB	S1	AXZH10R 22/01/2019	SMH3997H	0	17782	40D/SMH3997H/07101
Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On		
JTHB21B1802019526	A25A5098998	60	Wally Tan G H	08/10/2019	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.: DMPCSN1903571900 ACC DATE: 07.10.19 TOW/DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:		Rasul Hp 90010068 6 days 14/10/19 @ 1010 EXCESS: 1000		50 80.00
2	B	BP-LAB3 CHECK WIRING SYSTEM AND FOCUS HEADLAMP. (ETT)				216.50
3	B	BP-LAB3 REMOVE/REFIX FRONT PARKING SENSORS. (NETT)				216.50
4	B	BP-MECH3 REMOVE/REFIX AIR-CON CONDENSER, RECEIVER DRYER, GAS PIPES TO ENABLE REPAIRING AND FIT NEW PARTS. (NETT)				866.00
5	B	BP-LAB3 REMOVE ALL NECESSARY PARTS, TO ENABLE REPAIRING AND STRAIGHTEN FRONT SUPPORT PANEL, R/H AND L/H HEADLAMP PANELS AND FIT NEW PARTS.		Repair before paint		2578 3464.00
6	B	BP-RES3 SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.				2226 2597.00

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
Please acknowledge receipt of vehicle		Parts Labour Materials Lubrication/Fluid Others	Less
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			Amount Due

TO SECURITY GUARD
PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 08/10/2019
TIME 16:49

VEHICLE NO SMH3997H

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	Mr Ng Eng Teck 370H Alexandra Road #06-07 The Anchorage Singapore 159961
	Document No 0	Mobile: 96511111
	Document Date 08/10/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	AEXGB	S1	AXZH10R	22/01/2019	SMH3997H	0	17782 40D/SMH3997H/07101
Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On		
JTEB21B1802019526	A25A5098998	60	Wally Tan G H	08/10/2019	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
7	2	BP-SLANT SUPPLY SEALANT (NETT)				100.00
8	B	BP-ECU3 TO RESET ECU & REPROGRAMME. (NETT)				216.50
9	L	BP-LPO SUPPLY REGN PLATE (PO#)				96.00
		FRONT (NETT)				
10	1	L81145-33F21 UNIT, HEADLAMP	1.00	3702.20		3702.20
11	2	L81185-33F21 UNIT, HEADLAMP	1.00	3702.20		3702.20
12	3	L81136-33J00 RIM, HEADLAMP	1.00	17.50		17.50
13	4	L81176-33J00 RIM, HEADLAMP	1.00	17.50		17.50
14	5	L81137-33J00 RIM, HEADLAMP	1.00	46.50		46.50
15	6	L81177-33J00 RIM, HEADLAMP	1.00	28.80		28.80
16	7	L53301-33260 HOOD SUB-ASSY	1.00	2962.10		2962.10
17	8	T90467-09050 CLIP	9.00	2.90		26.10
18	9	T88723-33170 LABEL, COOLER	1.00	4.20		4.20
19	0	T11293-36070 LABEL, ENGINE	1.00	7.30		7.30
20	1	TG9275-12010 LABEL, BATTERY	1.00	9.20		9.20
21	2	L53101-33670 GRILLE SUB-ASSY, CR	1.00	1660.70		1660.70
22	3	L53112-33390 GRILLE, RADIATOR	1.00	223.40		223.40
23	4	L53141-33180 GARNISH, RADIATOR	1.00	2100.70		2100.70
24	5	L88210-33120 SENSOR ASSY	1.00	2125.80		2125.80
25	6	L52115-33110 SUPPORT, FR BUMPER	1.00	43.00		43.00

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 08/10/2019
TIME 16:49

VEHICLE NO SMH3997H

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Inchcape

Borneo Motors

LEXUS

TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388


Page 2 of 3

Account Detail		Account No	Customer Detail	
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1	Mr Ng Eng Teck 370H Alexandra Road #06-07 The Anchorage Singapore 159961	
		Document No	Mobile: 96511111	
		Document Date		
		08/10/2019		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	AEXGB	S1	AXZH10R	22/01/2019	SMH3997H	0	17782 40D/SMH3997H/07101
Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On		
JTHB21B1802019526	A25A5098998	60	Wally Tan G H	08/10/2019	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
26	7	L52116-33100				
27	8	L52021-33240				
28	9	L52148-33040				
29	0	L52611-33330				
30	1	L52620-50010				
31	2	L53114-33050				
32	3	L52521-33100				
33	4	L52542-33010				
34	5	L52119-3T943				
35	6	L52127-33905				
36	7	L52114-33520				
37	8	L52618-33090				
38	9	T53879-33030				
39	0	T47749-33030				
40	1	L89348-50130				
41	2	T90467-07217				
		SUPPORT, FR BUMPER	1.00	43.00		43.00
		REINFORCEMENT ?	1.00	909.60		909.60
		BRACKET, FR BUMPER ?	1.00	503.30		503.30
		ABSORBER, FR BUMPER ?	1.00	112.40		112.40
		CHAMBER ASSY, ?	1.00	790.30		790.30
		GRILLE, RADIATOR, ?	1.00	199.30		199.30
		RETAINER, FR BUMPER, ne	2.00	19.20		38.40
		SEAL, FR BUMPER, CTR	1.00	92.50		92.50
		COVER, FR BUMPER de	1.00	1046.20		1046.20
		COVER, FR BUMPER ?	1.00	54.20		54.20
		BRACKET, FR BUMPER ne	1.00	161.10		161.10
		ABSORBER, FR BUMPER, ?	1.00	281.30		281.30
		RETAINER, FR FENDER ne	6.00	12.20		73.20
		CLIP, PIN HOLD ne	6.00	8.60		51.60
		RETAINER, ULTRASONIC ne	2.00	19.20		38.40
		CLIP ne	7.00	2.50		17.50

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	28,942.00
	Please acknowledge receipt of vehicle	Parts 21,089.50	GST 7.00%	2,025.94
		Labour 7,756.50		
		Materials 96.00	Less	0.00
		Lubrication/Fluid 0.00		
		Others 0.00		
			Amount Due	30,967.94

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

DATE 08/10/2019
TIME 16:49

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES

VEHICLE NO SMH3997H

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

CUSTOMER