LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

То : AIG Asia Pacific Insurance Pte. Ltd.

Attn : Syed-Yusoff, Saliha

: 1856303831SG Your Ref

Our Ref : CC6/AIG19017967/UHA3

Date : 18 Jan 2020 "WITHOUT PREJUDICE"

ACCIDENT INVOLVING SDB1089E & SLT7762R ON 07/10/2019

Refer to the above accident.

The accident occurred when Insured vehicle rear-ended TP vehicle (BOLA 27). A letter was sent out to the Insured to notify TP claim and that his/her NCD would be affected.

On behalf of AIG Asia Pacific Insurance Pte. Ltd., we have successfully / not successfully carried out TP Express Settlement between your insured (vehicle no. SDB1089E) and third party claimant (vehicle no. SLT7762R).

Summary of offer made to workshop Fastech Auto Pte Ltd is as follows:

		Claimed		Revised
Cost of Repairs (w/gst)	\$	20,668.12	\$	6,848.00
Loss of Lisa (\$60 x 0 days)	Φ.	540.00	Φ	480 00 (¢

480.00 (\$60 x 8 days) Loss of Use (\$60 x 9 days)

GIA Search Fee \$ 2.00 \$ 2.00 TOTAL \$ 21,210.12 \$ 7,330.00

Amount of claim at Liability 100% 7,330.00

TOTAL NO. OF DAYS = 6 Recommended days + 2 days weekends/downtime

Enclose herewith the relevant supporting documents for your perusal.

For your approval please.

Regards,

VIC ALPEH

LKK Auto Consultants Pte Ltd