

COMFORTDELGRO ENGINEERING PTE LTD

VEHICLE NO : SHC 626J

DATE 10/10/2019 11:33

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper X <i>nyon</i>			\$ 578.40
	Rear Bumper Clip X <i>m</i>			\$ 22.00
	Rear Bumper Protector (RH) X <i>nyon</i>			\$ 38.00
	SUB TOTAL			\$ 638.40
	LESS 20%			\$ 127.68
	DISCOUNTED TOTAL			\$ 510.72
	Rear Bumper Rubber Mat X <i>m</i>			\$ 50.00 Nett
				\$ 50.00
	Labour Charge			240
	Panel Beating			\$ 300.00
	Spray Painting Charge			\$ 200.00 <i>200</i>
	Wiring Charge			\$ 50.00 <i>X m</i>
	Remove/Refix Reverse Sensor			\$ 120.00 <i>X m</i>
	TOTAL LABOUR			\$ 670.00
	ESTIMATE TOTAL			\$ 1,230.72
<p><i>Kalin 16/11/19</i></p> <p><i>10/10/19 1345 hr</i></p> <p><i>2 Days</i></p> <p><i>U/S</i></p> <p><i>After Repair photo</i></p>				
<p>LKK Auto Consultant's hence notify the Resurveyer of the following:</p> <ul style="list-style-type: none"> • To resurvey the area of spray painting • To identify damaged parts during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				