

03/04/20
delay

11/10/2019
SMN5843Z
BMW 218I M SPORT
WBA2D320405E76623 - 2017
2017
DMPCSN3067141900
nt: 04/10/2019

TO MOT
CHINA T.

ESTIMATE

DESCRIPTION	QTY	
BONNET ACTUATOR LH	1	
BONNET ACTUATOR RH	1	
BONNET HINGE LH	1	
BONNET HINGE RH	1	
HEADLIGHT LH	1	
HEADLIGHT RH	1	
HEADLIGHT BRACKET LH	1	
HEADLIGHT BRACKET RH	1	
BUMPER	1	
BUMPER SIDE RETAINER LH	1	
BUMPER SIDE RETAINER RH	1	
BUMPER SIDE RETAINER INSERT LH	1	
BUMPER SIDE RETAINER INSERT RH	1	
BUMPER FOG LAMP SUPPORT LH	1	
BUMPER BRAKE AIR CHANNEL COVER LH	1	
UNDERBONNET SCREEN PROTECTOR	1	
BUMPER RILLE RH	1	
BUMPER RILLE LH	1	
BUMPER BUMPER MIDDLE	1	
BUMPER AIR DUCT	1	
BUMPER REINFORCEMENT	1	
BUMPER TOP IMPACT ABSORBER	1	
AC-CON CONDENSER	1	
APERTURE RADIATOR	1	
APERTURE RADIATOR BRACKET	2	
FAN ASSY	1	
NET	1	

S
C
PARIS

310. +
310. +
620. +
620. +
1,150. +
78. +
98. +
98. +
156. +
216. +
288. +
65. +
720. +
504. +
528. +
780. +
148. +
~~230. +~~
267. +
267. +
=
~~7,453. *~~
7223
~~7,453. *~~
15. %
~~1,117.95 *~~
1083.45

315
310
310

7223
1083.45
~~7,453. +~~
~~1,117.95 +~~
=
~~8,570.95 *~~
8306.45

45. +
550. +
500. +
100. +
100. +
=
1,295. *

8306.45
~~8,570.95 +~~
1,295. +
=
9,865.95 *

P/P
9601.45

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 / Fax: (+65) 6481 1011

Branch

551 Upper
Tel: (+65) 6

Singapore 159143
Tel: (+65) 6472 2112